



Systems 9 - Photo 34. Airplane 15. B747 degraded foam in raceway clamp above potable water bottle. Wires on hardened adhesive. Blue fluid on clamp to right and along bottom of floor beam. Brown corrosion inhibitor is visible. Paper fragment on wire.