



Systems 9 - Photo 36. Airplane 16. B-747 wire insulation outboard of (P6) circuit breaker panel is split and dark brown where it comes from the connector. Copper conductor is visible. Note plug missing two holes