



Systems 9 - Photo 4. Airplane 5. Hardware (washer) on circuit breaker and lint accumulation. Location is inside of opened circuit breaker panel in Airbus A-300 cockpit.