



Systems 9 - Photo 43. Airplane 19. B-767 wires within the woven (Varglas) sleeve that the burned wires laid against. The wire insulation is bubbled and blackened.