



Systems 9 - Photo 48. Airplane 21. B-757 compensator with arrows pointing to where impressions were found in wiring. (Top of compensator is near "12")