



Systems 9 - Photo 49. (Feb. 21-25, 1998) B-747 W985 and other wire installations at forward corner of cockpit emergency escape (right) door. Visible ae trash, metal shavings, dirt, and flud stains. (View is down. Outboard is to right. Photo top is fwd.