



Systems 9 - Photo 50. (Feb. 21-25, 1998) B-747 station 400 (right), viewed aft from the right of the nose landing gear. Wires for #4 fuel flow and CWT FQIS signal are in the center opening. Visible are corrosion-inhibitor (brown drips) and blue stains.