



Systems 9 - Photo 6. Airplane 5. A-300 electrical compartment beneath cockpit. Wires in clamp shown with rivet fragments and drill shavings. Also visible are lint and wadded paper.