



Systems 9 - Photo 6. View looking forward of the right main landing gear. Note the left inboard tire is still pressurized. (Photo by FAA)