

INSPECTION REPORT

Inspector's Name Wolfe, Nathan			Inspector's Signature NATHAN AARON WOLFE <small>Digitally signed by NATHAN AARON WOLFE DN: c=US, o=U.S. Government, ou=DOT FR=AtlantaGA, ou=FRA, email=NA@atlantaGA, cn=NATHAN AARON WOLFE Date: 2017.07.06 17:06:10 -0400</small>				Inspector's ID No. 		Report No. 124		Date yy mm dd 2017 07 06		
Railroad/Company Name & Address CSX TRANSPORTATION 500 TAYLOR STREET CAYCE SC 29033					R/C R	Division FLOREN		RR/Co. Representative (Receipt Acknowledged) Name ANTONIO FOLK Title TRACK INSPECTOR Email Signature _____					
From: City WOODFORD		Codes 2940		Destination City & County				Codes	From Latitude				
State SC		45		City CAYCE				0370	From Longitude				
County ORANGEBURG		C075		County LEXINGTON				C063	To Latitude				
Mile Post: From S0385.60 To S0362.10			Inspection Point MAIN LINE HEAT INSPECTION						To Longitude				
Activity Code:	TOM	MTW	RWP	RMM	CWRP	MSB	ENSS	DER	MTH				
Units:	4	1	1	1	1	3	1	1	23				
Sub Units:	0	0	1	0	0	0	1	0	0				
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	S0381.10	MAIN	M	213	0037	A	50	4	BRIDGE	N	N	1	MTH
Description COMBUSTIBLE VEGETATION AROUND TRACK-CARRYING STRUCTURES.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	S0364.80	MAIN	M	213	0037	A	60	4	BRIDGE	N	N	1	MTH
Description COMBUSTIBLE VEGETATION AROUND TRACK-CARRYING STRUCTURES.													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):				Comments on back?			

INSPECTION REPORT

(Continuation)

Inspector's ID No. <div style="background-color: black; width: 20px; height: 10px; margin: 2px;"></div>	Report No. 124	Report Date 7/6/2017
--	-------------------	-------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/ USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	S0364.40	MAIN	M	213	0037	A	60	4	BRIDGE	N	N	1	MTH

Description
COMBUSTIBLE VEGETATION AROUND TRACK-CARRYING STRUCTURES.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
--	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	<input style="width: 20px; height: 20px;" type="text"/> <input style="width: 20px; height: 20px;" type="text"/> <input style="width: 20px; height: 20px;" type="text"/>	Date(mm/dd/yyyy):	<input style="width: 80px; height: 20px;" type="text"/>	Comments on back?
--	----------------------	---	-------------------	---	-------------------