



Axle #2-Left



Photo 12 – 2004 Mack Truck – Cracks in Lower Rear Brake Pad on Left Side of Axle #2