

H Photo 14 – 2004 Mack Truck – Crack in Lower Rear Brake Pad on Right Side of Axle #2