



VEHICLE FACTORS GROUP CHAIRMAN'S FACTUAL REPORT

Vehicle Attachment – Van Hool CX45 – TXDPS Level 5 Inspection

Biloxi, Mississippi

HWY17MH010

(3 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

TXDPS COMMERCIAL VEHICLE ENFORCEMENT

Report Number: TX4SSDHQE1C8
Inspection Date: 12/12/2016
Start: 12:05 PM CT End: 12:20 PM CT
Inspection Level: V - Terminal
HM Inspection Type: None

ECHO TRANSPORTATION
9314 W JEFFERSON BLVD # 295
DALLAS, TX 75211
USDOT#: 02172280 Phone#:
MC/MX#: 755212 Fax#:
State#: 0831209

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Location: 9314 W JEFFERSON BLV
Highway:
County:

MilePost: Shipper:
Origin: Bill of Lading:
Destination: Cargo:

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate #, Equipment ID, VIN, GVWR, CVSA #, New CVSA #, OOS#. Row 1: 1, BU, OTHR, 2016, TX, T08842, 8419, YE2XC81B2G3, 54,000, 23703684.

BRAKE ADJUSTMENTS: No Brake Measurements Recorded.

VIOLATIONS

HazMat: No HM Transported.

Placard: No Cargo Tank:

Special Checks:

Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000.

Signature Of Repairer X: Facility: Date:

Carrier Verify Text

Signature Of Motor Carrier X: Title: Date:

Report Prepared By:
DELETED

Badge #:
L0475

Copy Received By:



02172280 TX TX4SSDHQE1C8

X

X

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

TXDPS COMMERCIAL VEHICLE ENFORCEMENT

Report Number: TX4SSDHQE1C8
Inspection Date: 12/12/2016
Start: 12:05 PM CT End: 12:20 PM CT
Inspection Level: V - Terminal
HM Inspection Type: None

ECHO TRANSPORTATION
9314 W JEFFERSON BLVD # 295
DALLAS, TX 75211
USDOT#: 02172280
MC/MX#: 755212
State#: 0831209

Phone#:
Fax#:

Driver:
License#:
Date of Birth:
CoDriver:
License#:
Date of Birth:
State:
State:

Inspection Notes

NO VIOLATIONS DISCOVERED

Special Studies No Special Study Data Recorded

Report Prepared By:
DELETED

Badge #:
L0475

Copy Received By:

Page 2 of 2



02172280 TX TX4SSDHQE1C8

X_____

X_____