



**VEHICLE FACTORS GROUP CHAIRMAN'S
FACTUAL REPORT**

Vehicle Attachment – Tire Replacement Work Order #5683

Tempe, Arizona

HWY18MH010

(3 pages)



Uber ATG

Work Order Number: #5683

Invoice Number:

PO Number:

WORK ORDER DETAILS

Issue Date:	Thu Mar 15, 2018 10:48 PM	Krypton0145 2017 Volvo XC90	
Start Date:	Thu Mar 15, 2018	VIN/SN:	YV4BC0PL5H1149667
Completion Date:	Thu Mar 15, 2018	License Plate:	CBC9557
Duration:		Operator:	N/A
Status:	Completed	Type:	Krypton
Issued By:	[REDACTED]	Group:	PHX
Assigned to:			Uber /
Vendor:		Odometer:	23,946 mi
Cause Code:		Secondary Meter:	
Customer Symptom Code:			
Operation Number:			
Phabricator Ticket Number:	https://code.int.uberatc.com/T190790		
Technical Journal:			

LINE ITEMS

Item	Labor	Parts	Subtotal
Install TPMS Sensors Fleet Rollout #190637 Installed TPMS into all four wheels	[REDACTED]		[REDACTED]
[REDACTED] (Contact)	0.5 hrs [REDACTED]		[REDACTED]
2299200 (Part) · PHX - Technician Inventory 275/45R20XL PIRELLI SCORPION VERDE ALL SEASON TIRE KRYPTON		4 ea [REDACTED]	[REDACTED]
31414092 (Part) · PHX - Technician Inventory TIRE PRESSURE MONITOR SYSTEM SENSOR KIT (INCLUDES 4 SENSORS), tpms		1 ea [REDACTED]	[REDACTED]



Uber ATG

Work Order Number: #5683

Invoice Number:

PO Number:

DESCRIPTION

<https://code.int.uberatc.com/T190790>

SUMMARY

Subtotal	[REDACTED]
Labor	[REDACTED]
Parts	[REDACTED]
Discount	- \$0.00 (0.0%)
Tax	+ \$0.00 (0.0%)
Total	[REDACTED]