



VEHICLE PHOTOS

Concan, TX

HWY17MH0011

(6 pages)



Vehicle Photograph 1 - A right-side view of the 2007 Dodge Ram 3500 pickup truck



Vehicle Photograph 2 - A view of the drivers' footwell area of the 2007 Dodge Ram 3500 pickup truck



Vehicle Photograph 3 - A view of the drivers' compartment area of the 2007 Dodge Ram 3500



Vehicle Photograph 4 - A view of front suspension of the 2007 Dodge Ram 3500 pickup truck



Vehicle Photograph 5 - A Left Side View of the 2007 Dodge Ram 3500 showing the front displacement



Vehicle Photograph 6 - A view of the front end of the 2004 Turtle Top bus showing extensive front end damage



Vehicle Photograph 7 - A rear view of the 2004 Turtle Top bus, showing emergency rear exit door



Vehicle Photograph 8 - A Rightside view of the 2004 Turtle bus, showing the front-loading door and emergency exit windows



Vehicle Photograph 9 - A view of the driver's control and instrument cluster of the 2004 Turtle Top bus