

Ser# _____

UTILITIES DIVISION WORK ORDER

Date Received: 10-17-89 Date Started: 10-17-89

Time: _____ Date Completed: 10-18-89

Name & Address: 627 + 649 Sixth Tel: _____

Acct #: _____ Final Reading: _____ Meter # _____

- | | | |
|---------------------------|---|-----------------------|
| <u>Located</u> | <u>Nature of Work</u> | |
| () Street | <input checked="" type="checkbox"/> Main Leak, Size <u>4"</u> | () Pressure Problems |
| () Driveway | () Meter Leak, Size _____ | () Turbidity |
| () Cement | () Meter Set | () Taste & Odor |
| () Lawn | () Meter Change | () Backfill |
| () Other _____ | () Meter Box Replacement | () Loc./Mark. Lines |
| | () Main Tap, Size _____ | () Chlor.-Residuals |
| <u>Customer Notified</u> | () Valve Leak, Size _____ | () Daily Rounds |
| () Verbal | () Valve Repair, Size _____ | () Shutoff/Repair |
| () Hang Tag | () Valve Box Replacement | () Turn Bk On/Repair |
| () None | () Hydrant Pickup | () Backflow Valve |
| () Other (like neighbor) | () Hydrant Repair | () Control Valve |
| | () Service Change | () Regulator Valve |
| <u>Trucks Used</u> | () Set Sod | () Dig Out |
| | () Water Samples | () In-House Project |
| | () Other _____ | |

- | | | |
|---|-------|----------|
| | Reg | OT |
| () 7322 | _____ | _____ |
| () 7322A | _____ | _____ |
| () 7322B | _____ | _____ |
| () 7323 | _____ | _____ |
| () 7312 | _____ | _____ |
| <input checked="" type="checkbox"/> 7313 | _____ | <u>3</u> |
| () 7314 | _____ | _____ |
| () 7315 | _____ | _____ |
| <input checked="" type="checkbox"/> 7316 | _____ | <u>7</u> |
| <input checked="" type="checkbox"/> 7316A | _____ | <u>2</u> |
| 8 7317 | _____ | <u>6</u> |
| 8 7318 | _____ | <u>2</u> |
| <input checked="" type="checkbox"/> 7319 | _____ | <u>7</u> |
| () 7319A | _____ | _____ |
| 8 7349A | _____ | <u>6</u> |

~ AFTER HOURS ~

Total Men Used 7

Total Hours Worked _____

Total O.T. Hours Worked 38

Remarks _____

VAN

Job Supervisor



Ser# _____

UTILITIES DIVISION WORK ORDER

Date Received: 10-18-89 Date Started: 10-18-89

Time: 627 6th Ave Date Completed: 10-18-89

Name & Address: Water Samples Tel: _____

Acct #: _____ Final Reading: _____ Meter # _____

- | | | |
|---|---|--|
| <u>Located</u> | <u>Nature of Work</u> | |
| <input type="checkbox"/> Street | <input type="checkbox"/> Main Leak, Size _____ | <input type="checkbox"/> Pressure Problems |
| <input type="checkbox"/> Driveway | <input type="checkbox"/> Meter Leak, Size _____ | <input type="checkbox"/> Turbidity |
| <input type="checkbox"/> Cement | <input type="checkbox"/> Meter Set | <input type="checkbox"/> Taste & Odor |
| <input type="checkbox"/> Lawn | <input type="checkbox"/> Meter Change | <input type="checkbox"/> Backfill |
| <input checked="" type="checkbox"/> Other <u>Hose bib</u> | <input type="checkbox"/> Meter Box Replacement | <input type="checkbox"/> Loc./Mark. Lines |
| | <input type="checkbox"/> Main Tap, Size _____ | <input type="checkbox"/> Chlor.-Residuals |
| <u>Customer Notified</u> | <input type="checkbox"/> Valve Leak, Size _____ | <input type="checkbox"/> Daily Rounds |
| <input type="checkbox"/> Verbal | <input type="checkbox"/> Valve Repair, Size _____ | <input type="checkbox"/> Shutoff/Repair |
| <input type="checkbox"/> Hang Tag | <input type="checkbox"/> Valve Box Replacement | <input type="checkbox"/> Turn Bk On/Repair |
| <input type="checkbox"/> None | <input type="checkbox"/> Hydrant Pickup | <input type="checkbox"/> Backflow Valve |
| <input type="checkbox"/> Other (like neighbor) | <input type="checkbox"/> Hydrant Repair | <input type="checkbox"/> Control Valve |
| | <input type="checkbox"/> Service Change | <input type="checkbox"/> Regulator Valve |
| <u>Trucks Used</u> | <input type="checkbox"/> Set Sod | <input type="checkbox"/> Dig Out |
| | <input checked="" type="checkbox"/> Water Samples | <input type="checkbox"/> In-House Project |
| | <input type="checkbox"/> Other _____ | |

Earthquake ~~caused~~ caused main breaks: samples taken for water quality.

P/U Results from S.F. Water for Leak @ 727 6th AVE

- | | | |
|--|-------|-------|
| | Reg | OT |
| <input type="checkbox"/> 7322 | _____ | _____ |
| <input type="checkbox"/> 7322A | _____ | _____ |
| <input type="checkbox"/> 7322B | _____ | _____ |
| <input type="checkbox"/> 7323 | _____ | _____ |
| <input type="checkbox"/> 7312 | _____ | _____ |
| <input checked="" type="checkbox"/> 7313 | _____ | _____ |
| <input type="checkbox"/> 7314 | _____ | _____ |
| <input type="checkbox"/> 7315 | _____ | _____ |
| <input type="checkbox"/> 7316 | _____ | _____ |
| <input type="checkbox"/> 7316A | _____ | _____ |
| <input type="checkbox"/> 7317 | _____ | _____ |
| <input type="checkbox"/> 7318 | _____ | _____ |
| <input type="checkbox"/> 7319 | _____ | _____ |
| <input type="checkbox"/> 7319A | _____ | _____ |
| <input type="checkbox"/> 7349A | _____ | _____ |

Total Men Used 1

Total Hours Worked 1.5

Total O.T. Hours Worked N/A

Remarks Sample taken to S.F Lab

Results Pending -

B Timko
Job Supervisor



Ser# _____

UTILITIES DIVISION WORK ORDER

Date Received: 10-19-89 Date Started: 10-19-89

Time: _____ Date Completed: 10-19-89

Name & Address: 627 6th AVE. Tel: _____

Acct #: _____ Final Reading: _____ Meter # _____

Located

- Street
- Driveway
- Cement
- Lawn
- Other _____

Nature of Work

- Main Leak, Size _____
 - Meter Leak, Size _____
 - Meter Set
 - Meter Change
 - Meter Box Replacement
 - Main Tap, Size _____
 - Valve Leak, Size _____
 - Valve Repair, Size _____
 - Valve Box Replacement
 - Hydrant Pickup
 - Hydrant Repair
 - Service Change
 - Set Sod
 - Water Samples
 - Other haul away mud from
- Pressure Problems
 - Turbidity
 - Taste & Odor
 - Backfill
 - Loc./Mark. Lines
 - Chlor.-Residuals
 - Daily Rounds
 - Shutoff/Repair
 - Turn Bk On/Repair
 - Backflow Valve
 - Control Valve
 - Regulator Valve
 - Dig Out
 - In-House Project

Customer Notified

- Verbal
- Hang Tag
- None
- Other (like neighbor)

Trucks Used

- | | Reg | OT |
|--|-------|-------|
| <input type="checkbox"/> 7322 | _____ | _____ |
| <input type="checkbox"/> 7322A | _____ | _____ |
| <input type="checkbox"/> 7322B | _____ | _____ |
| <input type="checkbox"/> 7323 | _____ | _____ |
| <input type="checkbox"/> 7312 | _____ | _____ |
| <input type="checkbox"/> 7313 | _____ | _____ |
| <input type="checkbox"/> 7314 | _____ | _____ |
| <input type="checkbox"/> 7315 | _____ | _____ |
| <input checked="" type="checkbox"/> 7316 | _____ | _____ |
| <input type="checkbox"/> 7316A | _____ | _____ |
| <input checked="" type="checkbox"/> 7317 | _____ | _____ |
| <input type="checkbox"/> 7318 | _____ | _____ |
| <input type="checkbox"/> 7319 | _____ | _____ |
| <input type="checkbox"/> 7319A | _____ | _____ |
| <input type="checkbox"/> 7349A | _____ | _____ |

Total Men Used 3

Total Hours Worked 2 1/2

Total O.T. Hours Worked _____

Remarks will back fill later

CB + KS
Job Supervisor

ENTERED
OCT 20 1989

UTILITIES DIVISION WORK ORDER Ser# _____

Date Received: 10-19-89 Date Started: 10-24-89

Time: _____ Date Completed: 10-26-89

Name & Address: 627 Sixth Ave Tel: _____

Acct #: _____ Final Reading: _____ Meter # _____

Located

Nature of Work

- | | | |
|--------------------------------------|---|--|
| <input type="checkbox"/> Street | <input type="checkbox"/> Main Leak, Size _____ | <input type="checkbox"/> Pressure Problems |
| <input type="checkbox"/> Driveway | <input type="checkbox"/> Meter Leak, Size _____ | <input type="checkbox"/> Turbidity |
| <input type="checkbox"/> Cement | <input type="checkbox"/> Meter Set | <input type="checkbox"/> Taste & Odor |
| <input type="checkbox"/> Lawn | <input type="checkbox"/> Meter Change | <input checked="" type="checkbox"/> Backfill |
| <input type="checkbox"/> Other _____ | <input type="checkbox"/> Meter Box Replacement | <input type="checkbox"/> Loc./Mark. Lines |
| | <input type="checkbox"/> Main Tap, Size _____ | <input type="checkbox"/> Chlor.-Residuals |
| | <input type="checkbox"/> Valve Leak, Size _____ | <input type="checkbox"/> Daily Rounds |
| | <input type="checkbox"/> Valve Repair, Size _____ | <input type="checkbox"/> Shutoff/Repair |
| | <input type="checkbox"/> Valve Box Replacement | <input type="checkbox"/> Turn Bk On/Repair |
| | <input type="checkbox"/> Hydrant Pickup | <input type="checkbox"/> Backflow Valve |
| | <input type="checkbox"/> Hydrant Repair | <input type="checkbox"/> Control Valve |
| | <input type="checkbox"/> Service Change | <input type="checkbox"/> Regulator Valve |
| | <input type="checkbox"/> Set Sod | <input type="checkbox"/> Dig Out |
| | <input type="checkbox"/> Water Samples | <input type="checkbox"/> In-House Project |
| | <input type="checkbox"/> Other _____ | |

Customer Notified

- Verbal
- Hang Tag
- None
- Other (like neighbor)

Trucks Used

- | | Reg | OT |
|--|----------|----------|
| <input type="checkbox"/> 7322 | _____ | _____ |
| <input type="checkbox"/> 7322A | _____ | _____ |
| <input type="checkbox"/> 7322B | _____ | _____ |
| <input type="checkbox"/> 7323 | _____ | _____ |
| <input type="checkbox"/> 7312 | _____ | _____ |
| <input type="checkbox"/> 7313 | _____ | _____ |
| <input checked="" type="checkbox"/> 7314 | <u>2</u> | <u>3</u> |
| <input type="checkbox"/> 7315 | _____ | _____ |
| <input type="checkbox"/> 7316 | _____ | _____ |
| <input type="checkbox"/> 7316A | _____ | _____ |
| <input type="checkbox"/> 7317 | _____ | _____ |
| <input type="checkbox"/> 7318 | _____ | _____ |
| <input checked="" type="checkbox"/> 7319 | <u>2</u> | <u>3</u> |
| <input type="checkbox"/> 7319A | _____ | _____ |
| <input type="checkbox"/> 7349A | _____ | _____ |

Per 7316 & 19

PUMPED OUT HOLE
 AM - PM 1 HR. EST. TIME
 Pump HOLE; - 3 LOADS
 SAND; SET Sod; Clean
 AREA; pick up barricades
 plywood etc. set
 new meter

Total Men Used 2

Total Hours Worked ~~15~~ 4

Total O.T. Hours Worked 6

Remarks _____

RC & KS

Job Supervisor
