

Victim Interviews HWY-07-MH-025 Minneapolis, MN

The following pages contain information on the 190 people identified as victims of the I-35W bridge collapse. Interview notes are in order of the identification number assigned to that person's vehicle during recovery efforts.

(413 pages)

T MRK	YEAR		MODEL	COLOR	VEHICLE LOCATION	OCCUPANT(S)	OCCUPANT CONDITION	TOTAL # of OCCUPANTS	# INJURED	# Fatal
			Resurfacer	Silver	NB, closed lanes, southend	Unoccupied Construction Equipment (PCI Contract)	N/A		0	0
			Water Tank	Silver	NB, closed lanes, southend	Unoccupied Construction Equipment (PCI Contract)	N/A		0	0
:			RW600 Tractor	White	NB, closed lanes, southend	Unoccupied Construction Equipment (PCI Contract)	N/A		0	0
:			Slurry Tailer	Silver	NB, closed lanes, southend	Unoccupied Construction Equipment (PCI Contract)	N/A		0	0
- ;			4Runner	Black	NB, right lane, Southend	Panner, Douglas Charles (driver)	None reported		1	0
	4 2		Corolla	White	NB, left lane, Southend	Kummer, Christine (driver)	St Joseph ER - Walk in with back and neck pain		1	1
			Skidsteer	Yellow	SB, closed lanes, southend	Unoccupied Construction Vehicle PCI Unit # 25-235	N/A		0	0
(6 ′	1995 Ingersoll Rand	Compressor	White	SB, closed lanes, southend	Unoccupied Construction Equipment PCI Unit #13-176	N/A		0	0
	7 ′	1995 Sullair	Compressor	Green	SB, closed lanes, southend	Unoccupied Construction Equipment (PCI Rental)	N/A		0	0
- 1	8 2	2002 Case	Skidsteer	Yellow	SB, closed lanes, southend	Unoccupied Construction Vehicle PCI Unit # 25-242	N/A		0	0
	9 2	2000 Chevy	Blazer	Blue	NB, right lane, southend	Rogers, Louis (driver)	None reported		1	0
10	0 2	2006 Ford	F350	White	NB, right lane, southend	Klug, Steve (driver) Hollman, Terry (frnt pass) PCI Unit #41-319	Klug, None / Hollman, minor muscle		2	2
1	1 2	2003 Chevy	Silverado	Blue	NB, left lane, Southend	Babineau, Gary (driver)	Columbia Park Medical, Serious back injury		1	1
1:	2 2	2008 Ford	F350	Maroon	SB, closed lanes, southend	Unoccupied Construction Worker POV	See A10		0	0
1:			Cavalier	Green	NB, right lane, Southend	Hendrickson, Emily (driver)	Minor injuries, not transported		1	1
1.			Grand AM	Green	NB, left lane, Southend	Oaks, Zeke (driver)	Serious, back, Unity		1	1
1		•	Pacifica	Silver	NB, right lane, Southend	Gannon, Andrew (driver)	Minor head, not transported		1	1
10			Explorer	Red	NB, right lane, Southend	Torrance, Nevada (driver)/Torrance, Theresa (pass)/Corrie & Taylor	Minor 2 adults, not transported		4	2
1			Prius	Silver	NB, right lane, Southend	Forster, Jean (driver)	None reported		1	0
	1 - 1	2000 TOYOLA	1 1103	Olivei	NB, right lane, Southerid	Winegar, Dennis Richard (driver), Winedgar, Jamie (frt psgr), Logan, Kelly (rr	None reported		1	
1:	8 1	2007 Chrysler	300	Black	NB. left lane. Southend	psgr), Winegar, Logan (Ir psgr), Winegar Jake (cr psgr)	None reported		5	0
1			TL	Black	NB, left lane, Southend	Siddons, Peter (driver)	T&R @ St. Johns NE, leg/shoulder contusions		1	1
2			SL1	Blue	NB, left lane, Southend	Swanson, Melvin (driver)	None reported		1	0
2			Expedition	Blue	·	, , ,			1	1
2					NB, right lane, Southend	Paquin, Mark (driver)	Minor, not transported		1	1
			325xi	Blue	NB, left lane, Southend	Simmons, Laura (driver)	Minor, not transported		1	1
2:			Caprice	Red	NB, left lane, center span	Mundy, Sarah	Minor, airbag and bruises U of M		1	
2	_		CRV	Silver	NB, right lane, center span	Himmelman-Christopher, Hannah E. (driver)	Minor, not transported		1	1
2			Silverado 2500	White	SB, closed lanes, Southend	Unoccupied Construction Vehicle PCI Unit #41-297	N/A		0	0
2			Accord	Silver	SB, left lane, Southend	Knop, Shari (driver)	U of M, chest/back pain		1	_1
2	_		F250	Black	SB, closed lanes, Southend	Unoccupied, Robert Rucker's Truck see P17	N/A		0	0
2		2002 Jeep	Liberty	Black	SB, left lane, Southend	Moe, Steve Roy (driver)	Minor, not transported		1	_1
2	9 2		Camry	Blue	SB, left lane, Southend	Karic, Jasminka (driver)	Minor, not transported		1	_1
3	0 2	2003 International	School Bus	Yellow	SB, right lane, Southend	Dahl, Kimmy (bus driver)	See school bus reports	(63	53
3	1 2	2003 International	Tractor	White	SB, left lane, Southend	Eickstadt, Paul (driver) DOA	Fatal		1	0
3	1 1	1998 Great Dane	Trailer	White	SB, left lane, Southend	Trailer	N/A		0	0
3:	2 2	2000 International	Tractor	White	SB, right lane, Southend	Wagner, Wilfred (driver)	Wagner, serious HCMC		1	1
3:	2 L	JNK Great Dane	Trailer	White	SB, right lane, Southend	Trailer	N/A		0	0
			Impala	Silver	NB, right lane, center span	Sturgill, Brian	injuried - back		1	1
			CTS	Silver	NB, left lane, center span	Abuabara, Omar (driver)	Lung/rib/shoulder/hands walk in U of M		1	1
		2001 Saturn	L300	Silver	NB, left lane, center span	Whittlinger, Kelly (driver) / Brown, Kim Doenier (front psgr)	Methodist transport, injuried		2	2
1			TrailBlazer	Black	NB, right lane center span	West, Kristin (driver)	Concussion, not transported		1	1
			Pathfinder	Silver	NB, right lane, center span	Blundell, Suzanne / Wunderlich, Elizabeth	U of M, injuried necks/backs		2	2
+ :	_		Grand Prix	Black	NB, right lane, center span	Paden, Emily Ann (driver)	North Memorial. L1-T12 FX's, not transported		1	1
† :			Sebring	Black	NB, left lane, center span	Ostrowski, David (driver)	U of M, compr fracture		1	1
+ .	_	2002 Chrysler 2002 Saturn	L200	Blue	NB, left lane, center span		Bruised knee, back and neck		1	1
+ :						Lindholm, Amy (driver)			1	1
+			Grand Marque	Black	NB, left lane, center span	Kopelke, Kevin (driver)	Minor injuries, not transported		1	1
1 1			Explorer	Black	NB, right lane, center span	Helgason, Eric (driver)	U of M walkin knee/back injuries		1	1
1			Scootcrete	Orange	SB closed lanes, 4 wheel buggy	PCI Unit #23-111 Possibly construction worker SEE P7	N/A		U	U
1:	_		Scootcrete	Orange	SB closed lanes, 4 wheel buggy	PCI Unit #23-109 Possibly construction worker SEE P11	N/A		U	U
1:			Scootcrete	Orange	SB closed lanes, 4 wheel buggy	Unoccupied Construction Vehicle PCI Unit #23-112	N/A		0	0
1.			Scootcrete	White	SB closed lanes, 4 wheel buggy	Unoccupied Construction Vehicle PCI Unit #23-118	N/A		0	0
1:		1995 Ford	LT9000	White	SB closed lanes, cement mix	Unoccupied Construction Vehicle PCI Unit #59-109	N/A		0	0
10	6		F8300	White	SB closed lanes, cement tank	Unoccupied Construction Vehicle PCI Unit #58-116	N/A		0	0
10	6	1964 Fruehauf	900CF	Gray	SB closed lanes, cement tank	Unoccupied Construction Vehicle PCI Unit #93-108	N/A		0	0
1			Camry	Tan	SB, left lane, north center span	Din, Sherez Omar (driver) / Nguyen, Tina T. (front psgr)	U of M, leg/feet both injuried		2	2
18			Focus	Red	SB, right lane, north center span	Ebling, Garrett (driver)	HCMC L5 vert. Fx, R hand and arm fx's, rupt. dia	ì	1	1
1:		•	Outback	Green	NB, left lane, north center span	Koyrakh, Roman (driver)	Transp to North Memorial, Lac's, hip cont.		1	1
2			Sentra	Ivory	NB, left lane, north center span	King, Wen-Yan (driver)	U of M chest/shoulder lacerated hands		1	1

T MRK	YEAR	MAKE	MODEL	COLOR	VEHICLE LOCATION	OCCUPANT(S)	OCCUPANT CONDITION	TOTAL # of OCCUPANTS	# INJURED	# Fatal
3 2		unk Getman	Scootcrete	Gray	SB closed lanes, 3 wheel buggy	Unoccupied Construction Vehicle PCI Unit #23-121	N/A		0	0
;	1 19	991 Volvo	740 Wagon	Red	SB, left lane, Northend	Miller, Sara Christine (driver)	Minor injuries, not transported		1	1
;	2 1	997 Ford	Explorer	White	SB, right lane, Northend	Peters, Brad (driver) / Peters, Seth Daniel (front psgr)	Minor, whiplash transport to St. Johns		2	2
;	3 2	000 Pontiac	Grand Prix	Blue	SB, left lane, Northend	Frederickson, Danielle (driver)	Back injury, drove to Fairview Ridges		1	1
;	4 2	001 Saab	93E	Black	SB, right lane, Northend	Brown, David (driver)	U of M, back injuries		1	1
;	5 20	002 Pontiac	Grand Prix	Silver	SB, left lane, Northend	Gwilliam, Erica (driver)	Back/stomach injury walk in at Abbott		1	1
;	6 2	002 Ford	Explorer	Gray	SB, right lane, Northend	Toivonen, Bernt (driver)	None reported		1	0
:			Civic	White	SB, right lane, Northend	Shelton, Jesse (driver)	Mult. Vert fx's, hospitalized at NMMC		1	1
			Riviera	Red	NB, right lane, northend	Welman, Lois (driver)	United Hospital with broken back		1	1
,		999 GMC	Jimmy	Tan	NB, left lane, Northend	Weese, Michael (driver)	HCMC 3 lower back fx vertebrae, 2 fx ribs		1	1
, ,			Silverado	Black	NB, right lane, Northend				4	4
<u>, </u>						Hughes, Tom (driver)	back/wrist fractures U of M			1
) 1			SL1	Black	NB, left lane, Northend	Holmes, Patrick (driver) DOA	Fatal		1	0
) 1			F150	White	SB, right lane, Northend	Blackhawk, Julia DOA/Trinidad-Mena, Artemio DOA	Fatal		2	0
1		007 Jeep	Compass	Green	SB, right lane, Northend	Olsen, Karge (driver)	U of M, Spine fractures/concussion		1	1
1	_		Taurus	Gray	SB, left lane, Northend	Hickman, Tina pregnant had baby c-section after collapse	Unconscious, injured, delivered baby, baby cour	11	1	1
1			Tool Trailer	White	SB, closed Lanes	Unoccupied Construction Vehicle PCI Unit #21-166	N/A		0	0
1		004 Dodge	Caravan	Blue	SB, left lane, Northend	Paul, Linda Suzanne (driver)	HCMC factured eye socket and back injuries		1	1
1			Escort	Black	NB, left lane, northend	Gorden, Mercedes (driving)	U of M, fractures to legs and back		1	1
) 1		000 Toyota	Camry	Tan	NB, left lane, northend	O'Neal (Sokolowski), Ana (driver)	HCMC, back and shoulder factures		1	1
1			Odyssey	Tan	NB, right lane, northend	Coulter Family (Brianna, Brandy, Paula, Brad - driver)	All injuried, back fractures, HCMC / Brad @ No.	rt	4	4
2			Voyager	Blue	SB, left lane, Northend	Cruz, Marcelo (driver) Handicaped Driver	Not Injured - HCMC to get checked		1	0
2			Xterra	Gray	SB, right lane, Northend	Cermak, Daniel (driver) Cermak, Sandra Marie (frnt pas)	Minor - sore backs		2	1
2		002 Chevy	Malibu	Silver	SB, right lane, Northend	Hilshorst, Amanda (driver)	Minor - sore back		1	1
2			CRV	Black	SB, left lane, Northend	Ferguson, Stacy (driver)	None reported		1	0
2		003 Sterling	LT9500	White	SB, closed lanes	Unoccupied Construction Vehicle PCI Unit #51-119	N/A		0	0
2	_	001 Infiniti	130t	Silver	SB, right lane, northend	Carlson, Robert Bradley (driver)	None reported		1	0
2			330i	Silver	SB, left lane, northend	Mogush, John Jeffery (driver)	None reported		1	0
2			XJ6	Green	SB, right lane, northend	Olson, Brent (driver) / Olson, Christine (frt pass) (wife)	None reported		2	0
2	8 2	005 Ford	Expedition	Gold	SB, left lane, northend	Lundquist, Matthew (driver)	Minor neck/back, walk in Apple Valley Clinic		1	1
2	9 2	003 Ford	F450	White	SB, closed lanes	Unoccupied Construction Vehicle PCI Unit #42-283	N/A		0	0
3	0 2	003 Chev	Silverado 2500	White	SB, closed lanes	Unoccupied Construction Vehicle PCI Unit #41-298	N/A		0	0
3	1 2	004 Ford	Freestar	Silver	SB, right lane, northend	Mohammud, Mohammed (driver)	U of M lower back, ankle, momentary unconciou	ıs	1	1
3	2 2	002 Ford	F-350	Blue	SB, closed lanes	Unoccupied - belonged to construction worker P2	N/A		0	0
3	3 19	997 Ford	Escort	Red	SB, right lane, northend	Hughes, Melissa (driver)	Minor -neck/back/shoulder		1	1
3	4 2	000 GMC	Sierra	Black	SB, right lane, northend	Dahlgren, Aron (driver)	U of M, minor -hands/knees		1	1
3	5 2	006 Jeep	Commander	Silver	SB, left lane, northend	Paulsen, Erik (driver) / Noe, Adam (frt passenger)	HCMC, back and neck injuries		2	2
3	6 2	000 Toyota	Sienna	Silver	SB, left lane, northend	Wong, Angela (driver) / Tang, Myles (frt passenger)	Minor injury driver, son fractured shoulder		2	2
3	7 1		Paver	Yellow	SB, closed lanes	Unoccupied Construction Vehicle PCI Unit #66-172	N/A		0	0
)	1 2	001 Chrysler	Town and Country	Tan	SB, center / water	Hausmann, Peter (driver) DOA	Fatal		1	0
			SL1	Black	SB, left lane, center / water	Probst, Justin (driver) / Cole, Derrik (frt passenger)	Minor - head/neck		2	2
)			Passat	Silver	SB, left lane, center / water	Petterson, Lindsay (driver)	U of M, Serious neck/face		1	1
			Maxima	Black	SB, right lane, center / water	Babatz, Alicia (driver)	back/face/hip injuries		1	1
			G35X	Silver	SB, left lane, center / water	Yankelevish, Catherine (driver)	Muscle injury/ walkin day after		1	1
	_		Silverado 2500	White	SB, left lane, center / water	Schutte, Jeremy (driver)	None reported		1	1
	7 1	994 Jeep	Grand Cherokee	Green	SB, center / water	Manning, Crystal / Stoner, Michael	U of M		2	2
		002 Mazda	MPV	White	SB, center / water	Vo, Thuy Thanh (driver)	U of M, Incapaciating Injuries		1	1
	_		SLK280	Silver	NB, right lane, center span	Engebretsen, Sherry (driver) DOA	Fatal		1	0
1			Camry	Blue	SB, left lane, center / water	Sahel, Abdi (driver)	HCMC, neck/rib/lung		1	1
1			Altima	Silver	SB, right lane, center / water	Andic, Dijana (driver)	U of M, Cuts/Bruises		1	1
1			Highlander	White	SB, center / water	Sahal, Sadiya DOA / Sahal, Hana DOA	2 Fatal plus possibly 5 month pregnancy		2	0
1			CRV	Green	SB, center / water	Vera Peck (driver) / Richard Chit (frnt pass) DOA	2 Fatal plus		2	0
1			XL7	White	SB, center / water	Sacorafas Mosher, Christina DOA	Fatal		1	0
1		003 Case	Skidsteer	Yellow	SB, closed lanes	Unoccupied Construction Vehicle PCI Unit #25-247 Jolstad's	N/A		0	0
1		990 Ford	LT9000	White	SB, closed lanes	Unoccupied Construction Vehicle PCI Unit #50-117	N/A		0	0
1			Sonata	White	SB, center / water	Sathers, Scott DOA	Fatal		1	0
		006 Acura	TL	Pewter	NB, right lane, northend	Bennet-Kilander, Sheila (driver)	Neck/back/headaches		1	1
			SL2	Purple	NB, right lane, northend	Mishler, Justin (driver)	Comprsn facture/back		1	1
		002 Saturn	L200	Silver	NB, left lane, northend	McLane, Michele (driver)	None reported		1	0
_		003 Nissan	Altima	Silver	NB, left lane, northend	Lach, Jamie (driver)	Injuried arm	1	1	1

ST	MRK	YEAR	MAKE	MODEL	COLOR	VEHICLE LOCATION	OCCUPANT(S)	OCCUPANT CONDITION	TOTAL # of OCCUPANTS	# INJURED	# Fatal
E	5	2000	Dodge	Intrepid	unk	NB, left lane, Northend	Scharnhorst, Dave (driver)	None reported		1	0 0
Е	6	1999	9 Subaru	Forester	Green	SB, right lane, Southend	Hoffman, Charles (driver)	None reported		1	0 0
Р	1	N/A	N/A	N/A	N/A	Was about 800 feet north of the sta	ging area walking south	Right knee and leg		1	1 0
Р	2	N/A	N/A	N/A	N/A	Working at northend of bridgeover	railroad tracks in closed lanes, heard Steve yell "run", his truck is A	Cuts/ bruises /scrapes/back		1	1 0
Р	3	N/A	N/A	N/A	N/A	NB on southend in lanes with gene	ral public with T. Hollman in A10. Got out, slid down pavement and fell.	See A10 Minor Back injury		0	0 0
Р	4	N/A	N/A	N/A	N/A	Was with Wayne Khron and Luis Do	el Rio when the collapse occurred, heard someone yell run	Left shoulder elbow and back		1	1 0
Р	5	N/A	N/A	N/A	N/A	Was on the northend of the bridge	when the collapse occurred, heard Steve yell run	Left hand/elbow andback/knee		1	1 0
Р	6	N/A	N/A	N/A	N/A	Walking toward the northend in the	SB lanes, heard Steve yell to run, came down and injured his arm	Injuried arm/back/neck and left shoulde		1	1 0
Р	7	N/A	N/A	N/A	N/A	Was on a Mustang buggy, believed	I he was facing south. In area with Roger, Jolstad, and Jeff	Unconcious/ Injuried back. Concussior		1	1 0
Р	8	N/A	N/A	N/A	N/A	At northend in SB lanes walking fro	m southend with Gene Weidendorf ended up near railroad cars	Shoulder and arm		1	1 0
Р	9	N/A	N/A	N/A	N/A	Between mixer and cement truck.	He says he remembers being with Bob, Jolly,Roger, Jeff, and Josh	Elbow, shoulder and back		1	1 0
Р	10	N/A	N/A	N/A	N/A	Walking near where the bridge cros	sses over the rail line, northend, heard steve yelled run	Both knees/right arm/ lower back		1	1 0
Р	11	N/A	N/A	N/A	N/A	On diesel buggy southbound at wor	rk site, broken kneecap and abrasions on legs.	Knee/leg/facial abrasions & bruises		1	1 0
Р	12	N/A	N/A	N/A	N/A	Working on deck machine, ran to no	orthend, struck by Bidwell trailer ended up near railroad side	Facial and fractured Ankle/shoulde		1	1 0
Р	13	N/A	N/A	N/A	N/A	Walking north from the southend hi	s uncle, Hector, was walking in front of him	Upper back and neck		1	1 0
Р	14	N/A	N/A	N/A	N/A	NB on southend in the traffic lanes	in vehicle A10 with Steve Klug. POV A12	See A10 Back neck and shoulder injuries		0	0 0
Р	15	N/A	N/A	N/A	N/A	interview? Severely injured		ICU Ruptured diagphram/spleen/left arm fx's		1	1 0
Р	16	N/A	N/A	N/A	N/A	Walking north between cement mix	er and tanker, ended up under tanker, MN DOT inspector	Fractured ribs/elbow/pneumothora:		1	1 0
Р	17	N/A	N/A	N/A	N/A	According to coworker statements h	he was last seen out of the skidloader - SEE D15	Fatal		1	0 1

ŃΑ

AB

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-7-07 Time: 9:20 Am

Interviewer: SA Joseph Malhor (FBI)

DRIVER

Driver's License Number: State: M N

Full Name DOUGIAS CHARIES PANNEY DOB:

Full Address

Telephone Home: Work: 612-436-4640 Cell:

Compliance with DL restrictions: Glasses, etc YES NO

Seat Position: Front Seat Driver Center Right
Middle Seat Left Center Right
Rear Seat Left Center Right

Bus occupants see diagram

Ejected: YES NO

Safety Equipment used: Belts: LAP SHOULDER BOTH

Transported to Hospital YES (NO) Walk-in Hospital What Ambulance Service:

Nature of Injury (Circle): N/A

A Incapacitating injury – broken bones, hospitalized, severe cuts

An inability to perform a task they could do before injury.

B Non-incapacitating injury - Cuts, bruises, scrapes

C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

South side, NB LANU closer. To commina. Trapped was stapped

were they doing?	le were around you? (Color, no front of Buchul Color), while soday (Chro		-		CI
a sensation is described – mo - Radio on Did - Folt some Wibsan	and smell relative to the crassovement left to right, forward were the constructions, more than a constructions, more than a construction of Shaker, al	h? (Please ask and back, up or	for spe	etc.)	<i>F</i> (
What vehicle were you in?					
Make Toyoto Plate:	Model 4 Rouna Year Owner: KATHOVAN Park	2000 Color gs (favora)	Black, Om	n wife	
Insurance Company: <u>\[\frac{1}{1476} \] \]</u>	FALM Policy Number	er:		_·	
Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)				
2.	Seat Position (See above)	Injured?	YES	NO	
3.	Seat Position (See above)	Injured?	YES	NO	
4.	Seat Position (See above)	Injured?	YES	NO	
5	Seat Position (See above)	Injured?	YĖS	NO	

Additional notes/comments:

6.

Seat Position (See above)

Injured?

YES NO

NOTEO.

ISTH-35W Bridge Collapse Interview Questionnaire

12 111 be w Bridge Compse Interview Questionnane
Date of Interview: 8-6-07 Time: 5-30pm
Interviewer: SA Joseph Malhor T (FBI)
DRIVER
Driver's License Number State: MN
Full Name CHRISTINE ANN KUMMER DOB:
Full Address
Telephone Home: Work: 952-322-2469 Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right
Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES (NO)
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO (Walk-in) Hospital ST. Joseph ER. What Ambulance Service: 47, PAUL, MW
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible BACK + NECK PALIU

Please explain where you were on the bridge –(direction of travel NB SB], which lane, refer to bridge diagram):

- SOUTH KND OF BRINGE, NB

Blow Plu in front of Mes Bridge split UNDER iT + BEST IT IN The Middle. DARU colored. HIT MY CAR SUV Bohund MU What other vehicles or people were around you? (Color, make, model, description), what were they doing? - white PU work Truck (Stated ON Fire) To my Right -> Hulped mu out of my con Truck went in how we From the Man OVANGO CONSTURO UCSTR. What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.) - For I'M' a Train was going under The Bridge + hand Loud Sound, sounded lite a Trappic teridant. For a Drop Pause, Biggar Drop. SAW Bridge Cronible in Front of MU. And poll April Right Barbor I Dropped **VEHICLE:** What vehicle were you in? Model Corolla Year 2006 Color White Make 104074 Owner: Christinus & PAUI (DAD) KUMMER Insurance Company: Anarcan Fandy Policy Number: Who else was in the vehicle with you? (Name, address, phone, DOB) Injured? Seat Position (See above) YES NO 2. Seat Position (See above) Injured? YES NO 3. Seat Position (See above) Injured? YES NO

4.

5.

6.

Additional notes/comments:

Seat Position (See above)

Seat Position (See above)

Seat Position (See above)

Injured?

Injured?

Injured?

YES

YĚS

YES

NO

NO

NO

NOTEO.

Al

Joseph D Louis A Rogers

DAVING A Morthbound or thud

HEARD A "POP" on NE side of Bridge

SAW bridge Sway on South side

- Something shot up in air

- Bridge Collapsed

- Middle Section fell straight down

2000 Chevy Blazer, dark blue for went down into crevice in the road.

Exited vehicle, climbed incline and non into traffic to stop other NB traffic. White consumers white consumers and side not see anyone inside went to command center. West new road & told to leave Aved by MPD.

NE End bridge was point of initial

PASS. IN PARA AID OWNS personel veh (A-12)
owns persond veh(A-12)
ISTH-35W Bridge Collapse Interview Questionnaire
Date of Interview: 8-28-07 Time: 320
Interviewer: Ron K
DRIVER PASS TERRY HOllman
Driver's License Number: State:
Full Name DOB:
Full Address 62 ZZS
Telephone Home: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH NO
Transported to Hospital YES NO Walk-in Hospital Alling MEDICAL CT
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB], which lane,

refer to bridge diagram): I was w/ Steve Kluy in a white p/4
Truck HDG N/B

******	ble were around you? (Color, 1			
were they doing? N/B	ACross from	bus se	emi	that burned
woman in	white car re	x+ tous	, 9	y in suv behind us DAKIK
What did you see, feel, hear a sensation is described - m	, and smell relative to the cras	sh? (Please ask and back, up or	for spe	cifics if
Tust getting &	ont bridge	More	ht	we hera buy
VEHICLE: START	ve. Bridge 1.K ed fælling, god woman in u	out rale	Dy	at we wife helped
What vehicle were you in?	woman in u	shite con	L.	
Make FORD Plate:	Model F250 Year Owner:	Color	Wh	ite.
Insurance Company:	Policy Numb	er:	<u></u>	
Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)	e, address, phon Injured?		3) NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5	Seat Position (See above)	Injured?	YES	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

Necle & back pain muscle Strain

Iwas passerged driving N/B in white p/u

Steve Klug

I had just pked yellow cement tanker gony to get water truck

All

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8/6/07 Time: 5:44 pm 6:15 pm.
Interviewer: John F. Bonhage (FB1) NT
DRIVER DL in truck.
Driver's License Number: State: MN
Full Name 1947 Thomas Babineau DOB:
Full Address Wife: Elizabeth Lansing
Telephone Home: Work: Cell: Advanced Terrazo & Tile - Blaine
Compliance with DL restrictions: Glasses, etc (YES) NO NA
Seat Position: Front Seat Driver Center Right 2003 blue chery Middle Seat Left Center Right Prickup. Rear Seat Left Center Right
Bus occupants see diagram no passengers.
Ejected: YES NO
Ejected: YES NO Safety Equipment used: Belts: Yes LAP SHOULDER BOTH Transported to Hamital (FES) NO (VIII)
What Ambulance Service: Walk-in Hospital Blaine
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes - back injury
B Non-incapacitating injury - Cuts, bruises, scrapes - back injury masular, now spike C Complaint of injury with no obvious injury visible harts.
Please explain where you were on the bridge –(direction of travel NB SB], which lane, refer to bridge diagram):

* His wallet, DI into it still in the vehicle *

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

I woman helped off bridge - unknown rehide.

White pickup - right chay

Pickup- 1eft (south bound side) there

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

Felt bridge shake (like someone had a jackhammer next to you) for a 1/2 second, saw bridge falling, disappearing into the dust, think my airburgs ment off choking from dust. Not much noise, even falling, but thundering booms after hit the ground. VEHICLE: and it completely gave out. After land heard sweaming ble the bas. Helped lady jump down to rocks. As got down saw the but

What vehicle were you in?

Make Chevy

Year 2003 Color

Insurance Company: American Family Policy Number:

Insurance Who else was in the vehicle with you?

(Name, address, phone, DOB)

1.	seat Position (see above)	injurea?	YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO

Seat Position (See above) Injured? YĚS NO

6. Seat Position (See above) Injured? YES NO

Then tried to see if anyone in the trucks.

Additional notes/comments:

Ran to the east, got off the bridge and then under bridge to the wish and then dimbed up to general guardrail to help Kids. After help Kids ran down to the lock. But there was a fence. Didn't see anybody needing help Recall middle of bridge fall first and sun cars dissapeur. Nose dire down.

NOTEO.

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8/4/07 Time: 130pm -> 8:00 pm.
Interviewer: SA John F. Bonhage (FBI-MP) NAT Roland Sulzer.
DRIVER
Driver's License Number: tate: WI
Full Name Emily A Hendrickson DOB:
Full Address
Telephone Home: N/A. Work: (612) 378-9731 Cell: KT1 Inc. 2401 West 66 in st. Linkeld 15423. Compliance with DL restrictions: Glasses, etc. YES (NO) NA
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right no Middle Seat Left Center Right Passengers.
Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES (NO)
Safety Equipment used: Belts: (Yes) LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital
What Ambulance Service: went to chiropractor, sore back.
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB] SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

Across from her was red truck (bread), behind was a blue truck and a white truck. There was a car in front of her, but does not recall the make.

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

Priving, saw a lot of dust and then felt myself falling. No Warning before falling; a second of dust and then free falling. Smell concrete and smoke after car fell lot out of car, stold there, went with unknown make east (right) side VEHICLE: down outo the rocks. Was on cell phone w/ sisker, had to tell had gotten engaged. Fiance came to get her.

What vehicle were you in?

Make Chevrolot Model Caralier Year 1997 Color Green Plate: W. Owner: Emily Hendrickson.

Insurance Company: America		_Policy Number	r:		
Who else was in the vehicle v	vith you?	(NA) (Name	, address, phon	e, DOB	3)
1.	Seat Position	· / ·	Injured?	YES	NO
2.	Seat Position	(See above)	Injured?	YES	NO
3.	Seat Position	(See above)	Injured?	YES	NO
4.	Seat Position	(See above)	Injured?	YES	NO
5.	Seat Position	(See above)	Injured?	YĖS	NO
			•		
6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:

Toing 10-15 mph. No reaction, just reflex.

NOTEC








DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	24

RECORD OF INTERVIEW Zeke Oaks

Interviewed August 7, 2007 at Mr. Oaks' place of business in Edina, Minnesota Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Zeke Oaks (6'1", 180 lbs.)



Mr. Oaks stated he was driving northbound traveling around 15 m.p.h., in the left lane towards the south end of the bridge in a green 2001 Pontiac Grand Am. According to Mr. Oaks, the first thing he felt was the bridge rumbling. Mr. Oaks said he then saw a part of the bridge ahead of him fall and saw another northbound vehicle go off the bridge and immediately felt himself start falling.

Mr. Oaks stated that he grabbed his wallet and briefcase and exited his vehicle. Upon exiting he started helping others nearby until he heard children crying on a school bus in the southbound lanes. Mr. Oaks stated that he and another driver climbed off the east edge of the bridge, ran under and climbed back up on the southbound side and started helping children down from the bridge to the roadway that was approximately four feet below the bridge rail.

According to Mr. Oaks, he sustained a fracture to his thoracic spine. - unity Hosp.

(A-14)

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: $8 - 1$ Time: 10^{-20}
Interviewer: Lon K
DRIVER
Driver's License Number:
Full Name Zeke OAKS DOB:
Full Address
HT. 6'1 WT. 180
Telephone Home: Work: Cell
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Respectively.
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital Usfm then What Ambulance Service: Unity
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge - (direction of travel [NB SB], which lane, refer to bridge diagram): Going N/B in far Clane towards south en of bridge.

What other vehicles or people were around you? (Color, make, model, description), what what other vehicles or people were around you? (Color, make, model, description), what were they doing? white plu in front of me that went down.

Green Cruplier behind me in Blane. I helped her Chrysler faction in front of me in Blane. Black plu In Blane (Garry, he was on news) Steve MOE in black whenly What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if in 5/B/me. a sensation is described - movement left to right, forward and back, up or down etc.) going 15 mph windows open. Felt a Rumbling in front of me I saw a part ahead of me falling. I saw a N/B car do a Nose dive off. then I felt myself start falling. Then a thud. Landing. VIN **VEHICLE:** What vehicle were you in? Make Port Model Grand And Year 2001 Color GREEN Owner: Hallie Hemric Insurance Company: Liberty Mutuar Policy Number: IN CAR Who else was in the vehicle with you? (NA) (Name, address, phone, DOB) Seat Position (See above) Injured? 2. Seat Position (See above) Injured? YES NO 3. Seat Position (See above) Injured? YES NO 4. Seat Position (See above) Injured? YES NO 5. Seat Position (See above) YĖS NO Injured? 6. Seat Position (See above) Injured? YES NO

Additional notes/comments:

girlfried drove me to unity.

2 Fx vert thoracic want to unity Hosp walked to U of M Hosp. Then went to unity Hosp walked is released. to clouded @ u of m so that's why I went to unity.

steve

Steve hefped guy in UPS truck, He brought him off bank. I helped load Kids from bus down to street. Garaf Barbinen helped we wy Kids.

I grabbed wallet i Briefcase I saw people needed helpso I helped a sy in white The here is bloody. We show
neared screams from school bus. We went under bridge
to help kids. The pear door of bus open. We went to
bridge pailing and help dropp the kids clown to the
pridge pailing and help dropp the Kids clown to the
approved. I then went book to get my stuff from where I
laid it or otherside of bridge.

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 80(67)Time: 540pm Interviewer: Amanda J. Kney, FBI DRIVER State: Utah Driver's License Number: Full Name Andrew Thomas Gannon DOB: Full Address Work:(612)2882125 Cell Telephone Home Compliance with DL restrictions: Glasses, etc. NA YES Seat Position: Front Seat (Driver) Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES Safety Equipment used: Belts: SHOULDER LAP Walk-in Transported to Hospital YES Hospital What Ambulance Service: Burnsville Family Physicians > Friday Nature of Injury (Circle): Incapacitating injury - broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. В Cuts, bruises, scrapes - het head on roof-top Non-incapacitating injury -C Complaint of injury with no obvious injury visible Please explain where you were on the bridge -(direction of travel (NB) SB], which lane,

NB lane next to closed lane

refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Car behind - black or dkblue sedan

- Car in front - red Suv

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.).

1st heard a boom-not explosion, then joiled and what it is night side—
then heard another boom to crack, then dropped. Then swayed side to side
then heard another boom to crack, then dropped. Then swayed side to side
then heard another boom to crack, then dropped to be more
cutour severe on East side than west side of bindge. Then dropped takker

Cutour standard after - still moving after 15tdrop

VEHICLE:


What vehicle were you in?

Make: Chrysler Model Pacifica Year 2004 Color Silver Plate: Owner: Andrew Gannon and Kinkberry Shaff

Insurance Company: American Family Policy Number:

Who else was in the vehicle	with you? (NA) (Name	e, address, phon	e, DOB	3)
1.	Seat Position (See above)	Injured?	YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:



ANDREW THOMAS GANNON
DOB
612-288-2125 (work)

GANNON stated he was driving alone in a silver 2004 Chrysler Pacifica in the northbound lane of Interstate 35W on Wednesday, August 1, 2007. GANNON was driving in the outermost open lane of traffic, next to the lanes closed for construction. GANNON explained he was on the south end of the I-35W bridge when the bridge collapsed.

GANNON stated he first heard a boom, not an explosion. GANNON explained that at first he thought it might have been something (a boat or barge) hitting a bridge support in the water. He was unaware at the time that there was no structural supports of the I-35W bridge in the Mississippi River. Immediately following the noise, GANNON was jolted to his right side. Then, GANNON heard another boom and a crack, then felt a small jolt as he dropped a short distance. GANNON explained the crack sounded like the demolition of a building. GANNON was still moving forward on the bridge when the first drop occurred. After the first drop, GANNON said he felt the bridge sway from side to side, then he said the bridge buckled from the north, coming towards him. GANNON stated the buckling motion seemed to be more severe on the east side than the west side of the bridge. GANNON said the buckling sent cars airborne, then they would drop back onto the bridge surface. After the buckling, GANNON stated he dropped again, much farther than the first drop. It was then that the section of the bridge GANNON was on fell to the roadway below.

GANNON recalled that the vehicle behind his on the bridge was a black or dark blue sedan. He was unsure of the make or model. GANNON stated the vehicle in front of his on the bridge was a red SUV. He was unsure of the make or model. GANNON did not recall any other vehicles around him on the bridge.

GANNON was wearing his seatbelt, shoulder harness and lap belt. GANNON was not ejected from his vehicle. GANNON explained that he was not seriously injured; he hit his head on the roof of the vehicle as it dropped the second and final time. GANNON did not immediately seek medical attention. On Friday, August 3,

2007, GANNON was seen at Burnsville Family Physicians. He stated he has no lingering negative effects from hitting his head.

GANNON stated his vehicle insurance is through American Family, policy number

HUUTTO-KUU! IK.44

Alb

FEDERAL BUREAU OF INVESTIGATION

provided the following information:

Date of transcription 08/16/2007

Nevada Michael Torrance, date of birth

residing at I

residing at I

telephone

employed as an operator at the Stora
Enso Paper Mill, 100 North Central Avenue, Duluth, Minnesota 55807,

telephone (218) 628-5100, was advised of the identity of the interviewing agent and the purpose of the interview. Torrance

- 1 -

Torrance advised that he, his wife, Theresa, his 18-yearold stepson, Corrie, and his 13-year-old stepdaughter, Taylor, were traveling northbound on I-35 en route to their home from a day at Valley Fair amusement park when they took part in the I-35 bridge catastrophe. Torrance advised that he recalled passing the exit for Washington Avenue South near the Metrodome and merged into the slow lane of two lanes that headed north to Duluth, Minnesota, when all of a sudden he saw the middle of the I-35 bridge collapse. Torrance advised he is not sure of what section he was on; but upon review of the bridge diagram provided him by the interviewer, Torrance indicated a spot that he thought he vehicle was when the bridge collapsed. Torrance advised that seconds before the fall, his wife was dozing in the front passenger seat of the vehicle, his stepson was seated in the rear right behind his mother and was sleeping and Torrance's stepdaughter was seated behind him with headphones on viewing a DVD movie.

Torrance advised that the fall felt like three separate drops over a two- to three-second period when they ultimately stopped. Torrance advised that he believed his family and vehicle were still suspended in the air because he could see a bridge section below in front of him and one section above his section behind him. Torrance advised that he estimated their stopped vehicle to be approximately 10 feet from the edge of the bridge section he was on. Torrance advised when he saw the bridge collapse in front of him, he applied his brakes until the vehicle stopped as it fell. Torrance advised that he told everybody in his vehicle to leave their seatbelts on, left the vehicle in drive for safety reasons in case the vehicle had to move in any direction or that the bridge had not finished collapsing.

Investi	gation o	n 08/0	08/2007	at Du	Luth, MN		
	•	 H-MP - 692	278			Date dictated	08/08/2007
			-	Tisak,	Sr.:kaf		

This document contains neither recommendations nor conclusions of the FBI. It is the property of the FBI and is loaned to your agency; it and its contents are not to be distributed outside your agency.

308H-MP-69278

	Dara Mayrance	, On <u>08/08/2007</u> . Page <u>2</u>	
Continuation of FD-302 of	Nevada Michael Torrance		

Torrance advised that in the front of him he saw a middle-aged white male next to what he recalled to be a white sedan using his cell phone approximately 100 feet ahead of his vehicle on a separate bridge section and that he was close to the river. Torrance stated that as he recalled what to do, that he did not apply the emergency brake or put the vehicle in park because he had heard a car screech from behind their vehicle and thought they may Torrance advised have to back up to a safer section of the bridge. that he saw a white male directly behind his vehicle talking on his cell phone. Torrance advised he could not recall what this individual looked like but this same person was on a TV interview on Channel 10 and was possibly in his mid-30s. Torrance advised that this individual suggested that he and his family leave their vehicle and again Torrance advised he was hesitant to do so because he was not sure that the catastrophe had ended.

Torrance advised that once they decided they would exit the vehicle, they all tried to do so at the same time, unbuckling their seatbelts with Theresa leaving on one side with Corrie and Torrance leaving on the other side with Taylor. Torrance recalled that at this particular time he did put the vehicle in park but was not sure if he applied the emergency brake before they left. Torrance advised that he and his family walked southbound on the two outer lanes that had collapsed and rested on a bike path and road that was beneath his section of the bridge near his vehicle. Torrance advised that he recalled a white female with dark curly hair in her mid-40s that appeared as if her vehicle had just traveled underneath the bridge on the road beneath it and had just missed having the bridge collapse on her as she was near a silver four-door compact car that was larger than a Geo Metro type vehicle. Torrance advised that this individual had helped him and his family slide down the depressed part of the road onto the road her vehicle was on. Torrance advised that once on the road, his stepson was hysterical and among several things he had said he repeated over and over that "we should be dead." Torrance stated that Taylor kept crying and would not stop.

Torrance advised he told his wife that he wanted to go help anyone who had fallen into the river, but his wife told him not to and that they agreed that the family should be taken to safety. Torrance advised he has guilty feelings of him not going to the river to help anyone who may have been in need. Torrance advised that while on the road he saw a four-door crew cab Ford advised that while on the road he saw a four-door crew cab Ford pickup truck trying to back up the grade on the bridge and did not make it and that four people that he believed to be construction

308H-MP-69278

Continuation of FD-302 of	Nevada Michael	Torrance	,	On <u>08/08/</u>	2007 . P	1ge <u>3</u>
Continuation of Pro-202 of						

workers exited the vehicle. Torrance advised that one of the workers went to a side of the bridge to look over and the other three construction workers told him explicitly to get away from that side of the bridge. Torrance advised he saw a blue Blazer SUV on the bridge and heard a horn sound as it was a car alarm and believed this vehicle skidded and came in contact at the rear portion of a white car when the SUV stopped. Torrance estimated that this SUV and white car was possibly 50 to 70 yards behind where his vehicle was.

Torrance advised that he saw a fire start in the cab of a semi truck that belonged to a bread manufacturer stating that the trailer was above where the cab was and that the fired smelled horribly.

Torrance advised that he and his wife thought that they should move the family from this scenario, worried of what they and their children might be exposed to that would hurt them emotionally, psychologically or physically. They walked up a bike path as they saw emergency responders of law enforcement and firemen coming down the bike path on the road where they had met the female that had helped them heading towards the disaster. Torrance advised he was greatly impressed with the law enforcement response he and his family witnessed.

Torrance that he and his family walked up the bike path towards the University of Minnesota passed a softball game that was in progress and saw a sign on the side of the building advertising Grandma's Restaurant. Torrance advised he used to work for Grandma's Restaurant in Duluth and thought it a good idea to go into the establishment for he and his family to collect themselves. Torrance recalled that Corrie had no shoes on and that Torrance went into the establishment to ask the manager whether it was okay for them to come into the restaurant despite Corrie not having shoes on. Torrance advised he remembered the manager of the restaurant as a manager he had worked for in Duluth being a white female named Abby last name unknown. Torrance advised they were on the deck of the restaurant at the time and Abby had welcomed them into the establishment.

Torrance advised that he recalled his children had eaten chicken wings and ordered water and he had two or three drinks of rum and Coke and his wife drank water. Torrance advised that any time he makes a trip to or below the Cities, he normally waits to

308H-MP-69278

MOG...TO SAA! TS...A

	Townson	. On	08/08/2007	, Page	<u>4</u>
Continuation of FD-302 of	Nevada Michael Torrance				

pass the metropolitan area before stopping to obtain fuel or snacks at the Forest Lake exit on I-35.

Torrance advised that as they walked to the restaurant they had made several phone calls to family members to include his father, who was golfing. Torrance advised he was not able to talk to his father but talked to his father's girlfriend, Rhonda, who had a son, Al Church, who lives in the Twin Cities area. Torrance advised that Church traveled to the disaster scene, approximately one mile from Grandma's Restaurant, where he walked, met Torrance and family and drove them to North Branch, Minnesota. At North Branch, Torrance met with his stepfather and mother, who drove them to their home in Carlton, Minnesota. Torrance advised he estimates their ordeal lasted approximately two to three hours before they were on their way home.

Torrance advised that either Channel 9 or Channel 5 interviewed him telephonically at Grandma's Restaurant. Torrance advised that he believed that national media had called local businesses looking for survivors who would provide an interview to them. Torrance further stated he had been contacted by ABC World News Radio, at which time he talked to an individual who ultimately put him on hold and transferred him to Charlie Gibson on ABC World News Tonight, who interviewed Torrance while on TV.

Torrance advised that other news stations have called the restaurant and asked for an interview of him, of which he declined to do. Torrance advised that once he had gotten home, other news stations kept contacting him for an interview and he did provide a Duluth News Tribune representative an interview and his grandmother had also provided the newspaper with an interview. Torrance advised that during the course of these interviews he did not realize at the time but does now that he was under stress, great anxiety, shock as appropriate to someone who would experience such as he and his family did; and given the opportunity again, he would decline any interviews to any news stations and wish that he did not talk to anyone about the ordeal.

Torrance advised that his uncle, Mike Little, gave out Torrance's telephone numbers to many media outlets against Torrance's wishes. Torrance advised that his uncle is a very nice individual but may have thought Torrance's dilemma may have been an opportunity for himself to be in the limelight.

308H-MP-69278

Continuation of FD-302 of Nevada Michael Torrance On 08/08/2007 Page 5

Torrance advised he was hoping that he and his family would receive some type of help from outside agencies with their concerns. Torrance advised that he and his family have their hearts going out to the victims and the victims' families of the catastrophe and that they feel bad possibly because they had survived the ordeal. Torrance advised that he and his family would just like to get back to their life as if nothing had happened. Torrance advised that he needs the items that are in his vehicle as well as the vehicle itself because his daughter will start school in approximately three weeks and she will be attending school in Proctor, Minnesota, and they need a vehicle to travel back and forth with her as well as work and any other life matters they have to take care of.

Torrance advised that he and his family would just like to get back to a normal lifestyle.

Torrance advised they had left the catastrophe without going to the hospital for what he believed to be a number of reasons, to include that they were vitalized with adrenaline, given the situation, and overlooked a lot of pain they may have had at the time that they would have considered to be minor. Torrance stated he and his wife imagined the hospital facilities in the area to have been overrun with priority patients and they ultimately just wanted to get back to their 13-month-old daughter, Presley, whom they did not take to the amusement park with them.

Torrance advised that on August 3, 2007, the Friday after the disaster, he and his wife had alternated staying at home with the children and going to the St. Mary's Hospital Emergency Room in Duluth, Minnesota, where they were not pleased at all with the assistance they were provided. Torrance advised his wife complained of a headache and that a CAT scan was conducted and the results came back and she was told to go home. Torrance advised that when he went to th Emergency Room he complained of neck and back pain and the doctor did a cursory manual check of his back and indicated there was nothing wrong. Torrance advised that they were aware both he and his wife were victims from the I-35 bridge catastrophe and in his situation there were not x-rays or anything else done that would be considered a thorough exam. Torrance advised Taylor has an appointment with their family physician on August 9, 2007, where he was going to receive further evaluation of a previous injury to her wrist. Torrance advised their personal physician was consulted on the matter and given the description of

308H-MP-69278

Continuation of FD-302 of	Nevada	Michael	Torrance	 , On <u>08</u>	3/08/2007	, Page	6

their symptoms, their physician advised that they come in with the daughter during her regular scheduled appointment.

Torrance advised that Corrie appears to be extremely withdrawn and just associates with his friends. Torrance advised that his insurance company, Integrity Mutual, has been exceptionally well with them in their situation; and they hope once the insurance assessors are able to look at their vehicle, they may be able to have some type of assistance concerning any damages.

ISTH-35W Bridge Collapse Interview Questionnaire OH10

g P
Date of Interview: 8/6/07 Time: 5:11PM - 5:45P
Interviewer: GA Dean A. Scheidler - FBI
DRIVER (Helphonie interview via cell phone for Ohio - she on vacation- Mohican state Park
Driver's License Number: State: MN
Full Name Jean Lois Forster DOB:
Full Address
Telephone Home: N/A Work: \$612/626-8864- UNIV. OF MN [Selephone Home: N/A Work: \$612/626-8664-Cell: 1300 S. 2ND St. Ste. 300
Compliance with DL restrictions: Glasses, etc YES NO NA MPS, 55454 Corrective lenges - glasses - was wearing
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Ejected:
Safety Eq. Please review OULDER BOTH
Transport the end of attached Hospital Hospital
Nature of potential leads or ones, hospitalized, severe cuts
uts, bruises, scrapes
Dean Scheibler vious injury visible NO INJURY
Please explain where you were on the bridge –(direction of travel [NB SB], which lane,

traveling North- far right og left two lanes going to get off on Hennepin Aver

What other vehicles or people were around you? (Color, make, model, description), what were they doing? really crowded, probably 15 mph, knew of was busy, that recall of the cars

N	What did you see, feel, hear, a sensation is described—mo Sawa wave in fact on at war wort alarmed very alarmed very falked—what vehicle were you in? Make Toyota Plate Insurance Company: State	rement left to right, forward of her - un shing for - had until falling amenediately call lecided to stay in Model Prins Yes Owner: JLF	and back, up or dulated in to move to benew to be friend and friend are 2006 Color	down en for over bridge to the constant of the	tc.) of her fast fast e collaps less - Ma alum 5 tro lould	ma_
	msurance company.	1 0110) 1 (41			=	-
	Who else was in the vehicle 1.	with you? NA (N Seat Position (See above)	ame, address, phor) Injured?		B) NO	
	2.	Seat Position (See above) Injured?	YES	NO	
-	3.	Seat Position (See above)	Injured?	YES	NO	
	4.	Seat Position (See above)) Injured?	YES	NO	
	5	Seat Position (See above)) Injured?	YĖS	NO	
	6.	Seat Position (See above) Injured?	YES	NO	

Additional notes/comments:

Obry helpful & caline walked over to bicycle path

near University - rescue personnel coming - delict |

ent to seedeal bodies - thought that they didn't meed to

k to her - Many Dressel of Paule MN - pioked her up by

NOTEC

FEDERAL BUREAU OF INVESTIGATION

Date of transcription <u>08/07/2007</u>

telephonically interviewed on her cell phone while while she was on vacation in Mohican State Park, Loudonville, Ohio. Forster was advised of the identity of the interviewing agent as well as the purpose of the interview. She then voluntarily provided the following information:

Forster is employed by the University of Minnesota as a Professor in the Department of Epidemiology & Community Health, West Bank Office Building, 1300 South 2nd Street, Suite 300, Minneapolis, Minnesota 55454, work number 612/626-8864. At the time of the bridge collapse, Forster was driving her silver 2006 Toyota Prius, Minnesota license plate She was wearing glasses in accordance with the restrictions on her driver's license and she was wearing her seat belt. She was the only occupant of the vehicle. She is insured by State Farm and her policy number is Her valid Minnesota driver's license number is

She entered I-35W northbound from Washington Avenue and remembered that she had to immediately move over to the left lanes on the bridge because construction work had closed the right 2 lanes. She was traveling in the right hand lane of the open lanes and had planned to exit on Hennepin Avenue. She remembered traffic being very congested and thought that she was traveling approximately 10-15 miles per hour. She remembered noticing construction workers on the side of the road, but could not recall how many were there or what they might have been doing. As she made here way onto the bridge itself, she saw a "wave" move along the bridge deck toward her car. The bridge deck "undulated" in an up and down movement toward her, but ended before she came to it. The next thing she recalled is a feeling of falling and she immediately knew that the bridge was collapsing. She did not remember feeling alarmed until she felt her car falling. She does not have "vivid memories" or remember exact details about the specific chain of events of how her car ended up in its final position on the bridge deck. Her airbags did not go off and she was not ejected from the car. She immediately used her cell phone

Investi	gation	on	08/0	06/2007	at	Minneapolis,	Minnesota	(telephonically)
File #	308	3H-MP	-692	278			Date dictated	08/07/2007
by _	SA	Dean	Α.	Scheidle	er:	das 39		

308H-MP-69278

Continuation of FD-302 of Jean Lois Forster , On 08/06/2007 , Page 2

and called a friend of hers - Mary Dressel of Saint Paul. discussed whether she should leave her car and whether the bridge was stable enough to walk around on. She finally decided to stay in her car until she saw "two nice calm strong young men" who walked up to her car and told her it was okay to get out. told her that she should probably get off the bridge deck and they helped her off the bridge and over to the river bank. She then walked along the bicycle path towards the University of Minnesota. She could hear and see first responders arriving at the scene and she kept walking away from the scene because she did not want to see any dead bodies. She recalled thinking that she was uninjured and that she should not stop any of the first responders and tell them that she had been on the bridge because they had "other priorities" and wouldn't need to talk to her. She again called her friend Mary Dressel and made arrangements for Dressel to pick her up on the street near Fairview Riverside's medical complex. Forster did not want to spend the evening alone so she went to Dressel's house and spent the rest of the night watching news coverage of the disaster.

As previously mentioned, Forster was reached on her cell phone as she was traveling on vacation to Mohican State Park in Ohio. As such, she was not able to be shown the bridge diagram to precisely indicate her location on the bridge at the time of the collapse. She plans to return to the Twin Cities on the evening of Sunday, August 12th. Forster was asked whether she was feeling any pain now that several days had passed since the accident and she stated that she has no injuries whatsoever.

Forster was asked for any additional information and she volunteered that several people at her work told her that they had seen "big huge chunks of concrete" that had fallen onto the ground under the south end of the bridge near West River Parkway on the day before the bridge collapsed (Tuesday, July 31, 2007). Although she did not personally witness this, she guessed that the concrete chunks were probably about the size of a car tire and were larger than any normal pieces that might fall or flake off the bridge during the course of normal wear and tear. She thought that this was unusual in and of itself and also for the fact that each of the following individuals came to her independently of the others to tell her about this. In fact, she believed that some of these individuals do not even work in the same area as the others and may not even know each other. She identified her co-workers who could shed more light on this incident as Eileen Harwood (home telephone number of the property of t number of

FD-302a (Rev. 10-6-95)

308H-MP-69278

Continuation of FD-302 of <u>Jean Lois Forster</u>, On <u>08/06/2007</u>, Page <u>3</u>

addition, she believed that another co-worker - Pamela Schreiner - witnessed the accident from inside the building and could possibly provide additional eyewitness information.

Date of Interview: 08/06/2007 Time	: 5:50p,m (telephonic)
Interviewer: 5A Scott L. Zimmer	man, FBI -tel#
DRIVER	
Driver's License Number:	State: Texas
Full Name Dennis Richard Winegar	DOB:
Full Address	
Telephone Home:	Cell:
Compliance with DL restrictions: Glasses, etc	YES NO NA
Seat Position: Front Seat Oriver Middle Seat Left Rear Seat Left Bus occupants see diagram	Center Right Center Right Center Right
Ejected: YES NO	
Safety Equipment used: Belts: LAP	SHOULDER BOTH
Transported to Hospital YES NO Walk-What Ambulance Service: Nature of Injury (Circle): A Incapacitating injury – broke An inability to perform B Non-incapacitating injury - C Complaint of injury with no	Ked out by Red Cross on scene injuries, the allowed to leave scene. complain of sore neck, bick, etc. but en bones, hospitalized, severe cuts mothing rm a task they could do before injury. Cuts, bruises, scrapes

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

Traveling northbound in left hind I ne next to barrier. Were "pprox. 150ft back from where bridge completely broke off.

Ended up on the "crack" between sections of bridge and on top of a black Acura. See diagram for perceived location, Be Perved then were frarelling 20-25 mph.

7 7					•
			-		
("	What other vehicles or peop	le were around you? (Color, m	nake, model, des	scriptio	on), what
\	Tropo there doing?				1
Remem	bers two small a	cars in front of	Them in	7 9E 3	some 14116g 4
Silver	at han lane B-	min right land, a	A a nas	7 61	of their and
1003	1 top of (17A) h	nd been behind	Hem.	vnic	en they enaca
	What did you see, feel, hear,	nin cight lone, a lieves the black ad been behind and smell relative to the crash	n? (Please ask	for spe	cifics if
	a sensation is described – mo	ovement left to right, forward	and back, up or	down	etc.)
beard a	loud bing. Then si	of him + Slommed on an a car up front i	brines c	ne d	10 4 Stop, [1/2]
Then he	eard another lova	bang + started to	Fall	ndo	d theatwood
vertica	gand fellaggin	bang + started to	A ALUCA Z	エッナ	ot / believes A)
	VEHICLE:	0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	le of MSF	Air	and from I
	What vehicle were you in?	Rented below rehico Dollar Car Rental	10 41 71137	/ //	Z Z
1-1-1	8A ch. 100	DOLLAR CAR HEALT	7007	D.I	./
abelea I	Plate:	Model 300 Year	200/ Color	15/90	ch and
	1 1410.	Owner: Dollar Rent.	Restalca	n Fin	anzel)
	Insurance Company:	Policy Number	er:		-
	Who also were in the reshiple		11		D)
(fe)	1. To mis Wine no C	with you? NA (Name Seat Position (See above)	e, adoress, pnon Injured?	YES	NO)
,	DoB!	Front Seit-Right			
h 111		,	T . 10	*****	
Daughter)	2. Logan Winegar	Seat Position (See above)	Injured?	YES	NO
		Rear Seat-Let 7			
Nephew)	3. Jake Winegal	Seat Position (See above)	Injured?	YES	NO
	DOB!	Rear Seat-Center			
Relative)	4. Kelly Logos	Seat Position (See above)	Injured?	YES	(NO)
	4. Kelly Logar Approx: 7141301d	Rear Seat-Right	,		
		<i>y</i>	T ! 10	T TO C	NO
	5	Seat Position (See above)	Injured?	YĖS	NO
	6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

(v) he heard it loud brings and believes they fell in two (and possibly 3) stages, Nepher colled 911 + 6:0+p.m. Daughter took pictures dight away after getting out of car. (He ise-mailing them to ne.) I also tolked with wife. Her recollection was similar but did not remember as many details.

NOTEC



FEDERAL BUREAU OF INVESTIGATION

Date of transcription 08/07/2007 Dennis Richard Winegar, DOB: cellular was telephonically interviewed. After being advised of the identity of the interviewing agent and the purpose of the interview, Winegar provided the following information: Winegar was traveling northbound in the left-hand lane (next to the barrier) over the I-35W bridge when it collapsed on 08/01/2007. Winegar was driving a black 2007 Chrysler 300M, MN Winegar had rented the vehicle from Dollar Rental license Car at the Minneapolis-St. Paul International Airport. Winegar advised that he has seen from photos that his vehicle has been labeled 18A. The other occupants in Winegar's vehicle were as follows: Jamie Winegar (wife), DOB: passenger (right) front seat Logan Winegar (daughter), DOB: rear driver-side (left) seat Jake Winegar (nephew), DOB: rear center seat Kelly Logan (relative), approximately 71 years old, rear passenger-side (right) seat Winegar's vehicle was on the south side of the bridge when it collapsed. Winegar believes he was traveling approximately 20 to 25 miles per hour when he first felt the collapse. Winegar was approximately 150 feet back from where the bridge completely broke off. Winegar's vehicle ended up on the "crack" between two sections of the bridge and on top of a black Acura. Winegar remembers two small cars were traveling in front of him in the same lane. A silver car was next to him in the right lane, and a blue Ford Explorer was also in the right lane. Winegar believes the black Acura that they ended up on top of must have been traveling behind them. Winegar's first indication of the bridge collapse was when he saw white smoke in front of him. Winegar then slammed on his brakes, and believes he came to a stop. Winegar then heard a at Minneapolis, MN (telephonically) 08/06/2007 Investigation on Date dictated 08/06/2007 File # 308H-MP-69278

This document contains neither recommendations nor conclusions of the FBI. It is the property of the FBI and is loaned to your agency; it and its contents are not to be distributed outside your agency.

SA Scott L. Zimmerman

308H-MP-69278

Continuation of FD-302 of Dennis Richard Winegar , On 08/06/2007 , Page 2

loud bang, felt a momentary shake, and then saw a car in front of him in the right lane disappear (fall). Winegar then heard another loud bang and his vehicle started to fall. His vehicle briefly landed, turned vertical, and fell again. Winegar's vehicle ended up landing on the black Acura in a somewhat vertical position, on the "crack" between two sections of the bridge. Winegar remembers hearing four loud bangs in total and believes they fell in at least two, and possibly three, stages.

After landing, Winegar's nephew called 911. Winegar advised the call was made at 6:04 pm. After ensuring everyone was OK and discussing what to do, Winegar and the other occupants were all able to exit the vehicle. Various first responders were already at the scene at this time. Winegar's daughter Logan had her camera with her and took several photographs shortly after exiting the vehicle. Winegar advised he would have these photographs e-mailed to interviewing agent.

Winegar and the other occupants of his vehicle got off the bridge on the east side and eventually walked to the Bohemian Flats parking lot. They attempted to go to the Red Cross building, but were not able to make it through the police who were blocking off the area. Red Cross paramedics eventually came to where they were located and examined Winegar and the other occupants. The paramedics cleared them all to leave, and they then received a ride home. Winegar advised that he and the other occupants do not appear to have suffered any significant injuries from the incident.

;	Date of Interview: 08/06/2007 Time: 4:10 p.M.
	Interviewer: SA Scott L. Zimmerman, FBI tel#
	DRIVER
	Driver's License Number
	Full Name Peter George Siddons DOB:
	Full Address
	Telephone Home Work £12-3/2-4282 Cell:
	Compliance with DL restrictions: Glasses, etc YES NO NA
	Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
	Ejected: YES NO
	Safety Equipment used: Belts: LAP SHOULDER BOTH
	Transported to Hospital YES NO Walk-in Hospital St. John's Maplewood What Ambulance Service: Wife drove him to hospital after he Nature of Injury (Circle):
	A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
	B Non-incapacitating injury - Cuts, bruises, scrapes some neck & shoulder, C Complaint of injury with no obvious injury visible
	C Complaint of injury with no obvious injury visible
Frayel Ender	Please explain where you were on the bridge - (direction of travel [NB SB], which lane, refer to bridge diagram): Ing North bound on South end of bridge in left hand lane. Ing hanging over 2nd "break" in bridge (from bouthend) neigh a changler 300M. Also ended up hitting a light 16lue pick up truck, See bridge diagram for sperceived 47
10001	· · · · · · · · · · · · · · · · · · ·

	What other vehicles or peop	le were around you? (Color, n	nake, model, descr	iption), what
02	were they doing? In remembers to and hitting a hand hitting a ha	he Chinsler 300A	which ende	ed up on top of
hin	rand hitting a ha	iting a light silver	Iblu pickup	truck. Does not
ren	nember where the	30 or other vehicles	were who	n initially
C	What did you see, feel, hear,	and smell relative to the crash	n? (Please ask for	r specifies if
Me Tils	bridge The remoting,	"and and and com	inf the b	ridae com as towar
in fr	om the North. The	n saw seations b	f the boil	dge fall ahead of
in Cto.	North)-Then hés ; VEHICLE:	rehicle fell dow	opertue	1, and thentell
	99411	rest of way and	dended y	b hitting a pick-u
	What vehicle were you in?	of his year	nad a Chry	him from the North ridge coming toward dge fall ahead of y, and then tell b hitting a pick-u nsler 300 M on top
abeled	17A Make Acura	Model / Year.	ZOOT Color L	1901
apeled i	Plate:	Owner: Peter Georg	ge Siddong	3
	Insurance Company: A7	Policy Number	er:	<u>:</u> .
	Who else was in the vehicle	with you? (NA) (Nam	e, address, phone,	DOB)
	1.	Seat Position (See above)		YES NO
	2.	Seat Position (See above)	Injured? Y	ES NO
•	3.	Seat Position (See above)	Injured? Y	YES NO
	4.	Seat Position (See above)	Injured? Y	TES NO
	5	Seat Position (See above)	Injured? Y	TES NO
		,	J	
	6.	Seat Position (See above)	Injured? Y	TES NO
	~ ·	Start control (Dec accre)		

Additional notes/comments:

He received a ride home from Michael Debbie Pung.

He received a ride home from Michael Debbie Pung.

The Pungs were just getting on 35W-N from Wishington Ave.

bottoge ramp when bridge fell and may be potential

witnesses. Siddons provided Michael Pung's work

to lephone # as K17-768-5603-

NOTEC.

FEDERAL BUREAU OF INVESTIGATION

Peter George Siddons, DOB: Telephone Was interviewed at his place of employment wells Pargo Home Mortgage, 2801 Wells Way, Minneapolis, MN. After being advised of the identity of the interviewing agent and the purpose of the interview, Siddons provided the following information: Siddons was traveling northbound in the left-hand lane over the I-35W bridge when it collapsed on 08/01/2007. Siddons was traveling alone in his black 2004 Acura TL, MN license Siddons has seen from photographs taken of the scene that his car has been labeled 17A. Siddons was on the south side of the bridge when it collapsed. Siddons did not remember which vehicles were traveling in front of or otherwise in relation to him when the bridge collapsed. Siddons does remember that he ended up hitting a light blue or silver pick-up truck and that a black Chrysler 300M ended up on top of his car. Siddons, however, did not remember this car actually hitting his vehicle. Siddons anded up hanging over what he believes was the second "break" in the bridge from the south end. Traffic was traveling slowly when the bridge collapsed, but it wasn't quite "stop and go". Siddons first heard a rumbling/roaring sound coming from the north end of the bridge. Siddons then saw the bridge "rolling" and "buckling" towards him from the north. Siddons felt that the bridge was falling from the north as it was coming towards him. Siddons started to see sections of the bridge fall in front of him. Siddons' vehicle ther fell part way, briefly stopped, and then fell again. Siddons remembers his fall occurring in two parts, and that he ended up hanging over the second "break" in the bridge. Siddons believes he had slammed on his brakes because his legs were hurting after the collapse. Siddons was unsure if his vehicle had actually stopped when the bridge collapsed, but advised that his car was still running and in drive after the fall. Siddons thus put the car in park and turned it off. Siddons called			
telephone was interviewed at his place of employment Wells Fargo Home Mortgage, 2801 Wells Way, Minneapolis, MN. After being advised of the identity of the interviewing agent and the purpose of the interview, Siddons provided the following information: Siddons was traveling northbound in the left-hand lane over the I-35W bridge when it collapsed on 08/01/2007. Siddons was traveling alone in his black 2004 Acura TL, MN license Siddons has seen from photographs taken of the scene that his car has been labeled 17A. Siddons was on the south side of the bridge when it collapsed. Siddons does remember which vehicles were traveling in front of or otherwise in relation to him when the bridge collapsed. Siddons does remember that he ended up hitting a light blue or silver pick-up truck and that a black Chrysler 300M ended up on top of his car. Siddons, however, did not remember this car actually hitting his vehicle. Siddons ended up hanging over what he believes was the second "break" in the bridge from the south end. Traffic was traveling slowly when the bridge collapsed, but it wasn't quite "stop and go". Siddons first heard a rumbling/roaring sound coming from the north end of the bridge. Siddons then saw the bridge "rolling" and "buckling" towards him from the north. Siddons felt that the bridge was falling from the north as it was coming towards him. Siddons started to see sections of the bridge fall in front of him. Siddons' vehicle ther fell part way, briefly stopped, and then fell again. Siddons remembers his fall occurring in two parts, and that he ended up hanging over the second "break" in the bridge collapsed, but advised that his car was still running and in drive after the fall. Siddons thus put the car in park and turned it off. Siddons called the fall accurs of the part of the		Date of transcription	08/07/2007
Wells Fargo Home Mortgage, 2801 Wells Way, Minneapolis, MN. After being advised of the identity of the interviewing agent and the purpose of the interview, Siddons provided the following information: Siddons was traveling northbound in the left-hand lane over the I-35W bridge when it collapsed on 08/01/2007. Siddons was traveling alone in his black 2004 Acura TL, MN license Siddons has seen from photographs taken of the scene that his car has been labeled 17A. Siddons was on the south side of the bridge when it collapsed. Siddons did not remember which vehicles were traveling in front of or otherwise in relation to him when the bridge collapsed. Siddons does remember that he ended up hitting a light blue or silver pick-up truck and that a black Chrysler 300M ended up on top of his car. Siddons, however, did not remember this car actually hitting his vehicle. Siddons ended up hanging over what he believes was the second "break" in the bridge from the south end. Traffic was traveling slowly when the bridge collapsed, but it wasn't quite "stop and go". Siddons first heard a rumbling/roaring sound coming from the north end of the bridge. Siddons then saw the bridge "rolling" and "buckling" towards him from the north. Siddons felt that the bridge was falling from the north as it was coming towards him. Siddons started to see sections of the bridge fall in front of him. Siddons' vehicle thereful part way, briefly stopped, and then fell again. Siddons remembers his fall occurring in two parts, and that he ended up hanging over the second "break" in the bridge. Siddons believes he had slammed on his brakes because his legs were hurting after the collapse. Siddons was unsure if his vehicle had actually stopped when the bridge collapsed, but advise that his car was still running and in drive after the fall. Siddons thus put the car in park and turned it off. Siddons called			, cellular
over the I-35W bridge when it collapsed on 08/01/2007. Siddons was traveling alone in his black 2004 Acura TL, MN license Siddons has seen from photographs taken of the scene that his car has been labeled 17A. Siddons was on the south side of the bridge when it collapsed. Siddons did not remember which vehicles were traveling in front of or otherwise in relation to him when the bridge collapsed. Siddons does remember that he ended up hitting a light blue or silver pick-up truck and that a black Chrysler 300M ended up on top of his car. Siddons, however, did not remember this car actually hitting his vehicle. Siddons ended up hanging over what he believes was the second "break" in the bridge from the south end. Traffic was traveling slowly when the bridge collapsed, but it wasn't quite "stop and go". Siddons first heard a rumbling/roaring sound coming from the north end of the bridge. Siddons then saw the bridge "rolling" and "buckling" towards him from the north. Siddons felt that the bridge was falling from the north as it was coming towards him. Siddons started to see sections of the bridge fall in front of him. Siddons' vehicle therefell part way, briefly stopped, and then fell again. Siddons remembers his fall occurring in two parts, and that he ended up hanging over the second "break" in the bridge. Siddons believes he had slammed on his brakes because his legs were hurting after the collapse. Siddons was unsure if his vehicle had actually stopped when the bridge collapsed, but advised that his car was still running and in drive after the fall. Siddons thus put the car in park and turned it off. Siddons called	Wells Fargo Home Mortgage, 2801 Wells Way being advised of the identity of the inter purpose of the interview, Siddons provided	, Minneapolis, rviewing agent	, MN. After and the
collapsed. Siddons did not remember which vehicles were traveling in front of or otherwise in relation to him when the bridge collapsed. Siddons does remember that he ended up hitting a light blue or silver pick-up truck and that a black Chrysler 300M ended up on top of his car. Siddons, however, did not remember this car actually hitting his vehicle. Siddons ended up hanging over what he believes was the second "break" in the bridge from the south end. Traffic was traveling slowly when the bridge collapsed, but it wasn't quite "stop and go". Siddons first heard a rumbling/roaring sound coming from the north end of the bridge. Siddons then saw the bridge "rolling" and "buckling" towards him from the north. Siddons felt that the bridge was falling from the north as it was coming towards him. Siddons started to see sections of the bridge fall in front of him. Siddons' vehicle them fell part way, briefly stopped, and then fell again. Siddons remembers his fall occurring in two parts, and that he ended up hanging over the second "break" in the bridge. Siddons believes he had slammed on his brakes because his legs were hurting after the collapse. Siddons was unsure if his vehicle had actually stopped when the bridge collapsed, but advised that his car was still running and in drive after the fall. Siddons thus put the car in park and turned it off. Siddons called stigation on 08/06/2007 at Minneapolis, MN	over the I-35W bridge when it collapsed of traveling alone in his black 2004 Acura TI Siddons has seen from photographs taken of	n 08/01/2007. L, MN license	Siddons was
but it wasn't quite "stop and go". Siddons first heard a rumbling/roaring sound coming from the north end of the bridge. Siddons then saw the bridge "rolling" and "buckling" towards him from the north. Siddons felt that the bridge was falling from the north as it was coming towards him. Siddons started to see sections of the bridge fall in front of him. Siddons' vehicle therefell part way, briefly stopped, and then fell again. Siddons remembers his fall occurring in two parts, and that he ended up hanging over the second "break" in the bridge. Siddons believes he had slammed on his brakes because his legs were hurting after the collapse. Siddons was unsure if his vehicle had actually stopped when the bridge collapsed, but advised that his car was still running and in drive after the fall. Siddons thus put the car in park and turned it off. Siddons called stigation on 08/06/2007 at Minneapolis, MN	collapsed. Siddons did not remember which in front of or otherwise in relation to he collapsed. Siddons does remember that he blue or silver pick-up truck and that a blue on top of his car. Siddons, however, actually hitting his vehicle. Siddons end he believes was the second "break" in the	h vehicles wer im when the br ended up hitt lack Chrysler did not rememb ded up hanging	re traveling ridge ting a light 300M ended per this car gover what
legs were hurting after the collapse. Siddons was unsure if his vehicle had actually stopped when the bridge collapsed, but advised that his car was still running and in drive after the fall. Siddons thus put the car in park and turned it off. Siddons called stigation on08/06/2007 _atMinneapolis, MN	but it wasn't quite "stop and go". Siddon rumbling/roaring sound coming from the not Siddons then saw the bridge "rolling" and from the north. Siddons felt that the bringer north as it was coming towards him. Siddon sections of the bridge fall in front of his fell part way, briefly stopped, and then remembers his fall occurring in two parts	ns first heard rth end of the "buckling" to idge was falls ons started to im. Siddons' fell again. So and that he	d a bridge. wards him ing from the see vehicle ther Siddons
	legs were hurting after the collapse. Sic vehicle had actually stopped when the bric that his car was still running and in driv	ddons was unsu dge collapsed, ve after the b	ure if his , but advised [all.
	stigation on 08/06/2007 at Minneapolis, MN		
		oate dictated 08/06/	2007

SA Scott L. Zimmerman

308H-MP-69278

Continuation of FD-302 of	Peter	George Siddons	, On <u>0</u>	8/06	/2007	, Page	_2_

911 but could not get through. Siddons advised this call registered on his cellular phone as being placed at 6:05 pm.

Siddons eventually was able to open his door and get out of his car. Siddons crawled up the southbound lane and walked towards the bus, where first responders were already helping the children. Siddons helped calm some of the kids down and got off the bridge onto West River Road. Siddons then remembers the truck starting on fire.

Siddons then "mulled around" for a while, and was approached by various media. Siddons was interviewed by the Star Tribune and other media representatives. Siddons advised he subsequently also gave a detailed interview which is now available on npr.org.

Siddons eventually received a ride home from Michael and Debbie Pung. The Pungs told Siddons that they had just gotten onto 35W (northbound) from the Washington Avenue on-ramp when the bridge collapsed. Siddons provided a business card for Michael J. Pung, Fair Isaac Corporation, 901 Marquette Ave., Suite 3200, Minneapolis, MN, telephone 612-758-5603.

Siddons arrived home at approximately 7:00 pm. Siddons' wife took him to St. John's Hospital in Maplewood at approximately 10:30 pm. Siddons was discharged that evening as he only had minor bruises and cuts, and a sore neck and shoulder. Siddons did not have any broken bones or other serious injuries.

AZO

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-7-07 Time: 1300	
Interviewer: Sgt. Ivel Sandborg	
DRIVER MILVIN John Swanson	
Driver's License Number: State: MN	-
Full Name DOB:	
Full Address Swanson	
Telephone Home: Work: None Cell: None	
Compliance with DL restrictions: Glasses, etc YES NO NA	
Seat Position: Front Seat Driver Center Right	
Middle Seat Left Center Right Rear Seat Left Center Right	
Rear Seat Left Center Right Bus occupants see diagram	
Ejected: YES NO	
Safety Equipment used: Belts: LAP SHOULDER BOTH	-
Transported to Hospital YES NO Walk-in Hospital What Ambulance Service:	
Nature of Injury (Circle):	
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.	
B Non-incapacitating injury - Cuts, bruises, scrapes	
C Complaint of injury with no obvious injury visible	
Reports no injuries	
Please explain where you were on the bridge —(direction of travel [NB SB], which lane, refer to bridge diagram):	
Ow South and of bridge TRAVElling in No.	cth.
bound Lane. Fell, Perhaps, 40 FT while	مسر

bridge - TRAFFIC WAS MOVING VERY Slow- 15-20 MAH

Laptop computer STILL in Vehicle

What other vehicles or people were around you? (Color, make, model, description), what were they doing?


What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

Make Saturn Plate:	Model SL1 Year Owner: MeLvin S.	2002 Colon	Blu	e
Insurance Company:	Tage Farm Policy Numb	er:		
1.	with you? NA (Nam Seat Position (See above)	Injured?	ne, DOI YES	•
2. in Vehicle	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YÈS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:



NOTES.

Interview with 35W bridge collapse victim Melvin Swanson

Mr. Swanson states that he was traveling in the Northbound lane, but was in his vehicle at the South-end of the bridge. Mr. Swanson states that before the bridge collapsed, he could feel "Waving..and going in all different directions before it dropped. There were some side to side motions before it dropped". There was a "Free fall before it landed, but there was a lot of motion".

Mr. Swanson states that he knew the bridge was falling, so he held onto his steering wheel and went with the fall while still in his vehicle. Mr. Swanson advises that after coming to a rest, while still in his vehicle, he got out of his vehicle uninjured. It appears that Mr. Swanson may have fell approx. 40 ft. Mr. Swanson reports that he got out of his vehicle, a blue Saturn, and could hear crying and screaming. Mr. Swanson crawled through some rubble to a vehicle that was behind him, but in the Southbound lane "On the very edge of the bridge...it looked like it was sitting on the frame". Mr. Swanson reports that there was one lone female in this vehicle. Mr. Swanson helped this woman out of her car and he reports she was A'ok. Mr. Swanson then went to another car that was behind him. There were a total of three people in this car. The driver of this vehicle had already gotten out of this car. Mr. Swanson believed that this vehicle may have been resting on top of another car, but he is not sure. "There was a young boy, a young lady, teenager in her 20's and then there was a Grandma in the backseat". "None of them were really hurt; the vehicle seemed to be stable".

Mr. Swanson then reports that after helping these people, he could hear some yelling from the Eastside (?) of the bridge. Mr. Swanson reports looking over the Eastside of the collapsed bridge where he could see some smoke. Mr. Swanson reports seeing a truck on fire and remembers hearing voices yelling at him to get away "Because it is about to blow".

Mr. Swanson states that he had called his son who came down to the bridge site. Mr. Swanson then left the bridge and met his son. Both Mr. Swanson and his son left the bridge area and went home. Mr. Swanson states that his personal laptop was left in his vehicle and he needs his computer back for his work.

Date of Interview:	8 8 07 Time:	10:00	
Interviewer: Tom	Quinlan - MPLS	· FBI /J	TTF
DRIVER MARI	K PAQUIN		
Driver's License Nun	pher .	State: M	V
Full Name MARK Alle	W PAOUM	DOB:	
Full Address			•
Telephone Home:	· Work: 9525621	Cell:	
Compliance with DL	restrictions: Glasses, etc	YES NO	AND TO THE PARTY OF THE PARTY O
Seat Position:	Front Seat Driver Middle Seat Left	Center Center	Right Right
Days a sammants	Rear Seat Left	Center	Right
Bus occupants			
Ejected: YES	NO	•	
Safety Equipment use	ed: Belts: LAP	SHOULDER	BOTH
Transported to Hospit What Ambulance Ser		in Hospit	al
Nature of Injury (Circ	ole):		
A	Incapacitating injury – broken An inability to perform		
В	Non-incapacitating injury -	Cuts, bruises,	scrapes
0	Complaint of injury with no	obvious injury	visible
Please explain where refer to bridge diagram	you were on the bridge –(direction):	ction of travel	[NB SB], which lane,
North Bo	und in right le	east) la	ne.
Next to	a light color	BMW	•
Gold Car	und in right le a light color in front of	him.	

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) Aware of cars merging on to the bridge from, he thinks, washington Ave. His first sensation was a vibration of the roadway. Then nothing still.

EHICLE: (See back page) **VEHICLE:** What vehicle were you in? Model Expedition Year 2007 Color Blue Owner: MARK PAQUIN Insurance Company: St. Farm Policy Number: (Name, address, phone, DOB) Who else was in the vehicle with you? Seat Position (See above) Injured? YES NO 2. Seat Position (See above) Injured? YES NO 3. Seat Position (See above) Injured? YES NO Injured? 4. Seat Position (See above) YES NO 5. Seat Position (See above) Injured? YĖS NO 6. Seat Position (See above) Injured? YES NO

Additional notes/comments:

NOTEC.



Date of Interview: $\sqrt{7/07}$ Time: 13:30
Interviewer: T. Quinlan SPPD JTTF - MPLS FBI
DRIVER
Driver's License Number:
Full Name Laura Ann Simmons Mears DOB:
Full Address
Telephone Home: Work: N/A Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital N/A What Ambulance Service: N/A .
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.

Please explain where you were on the bridge –(direction of travel (NB) SB], which lane, refer to bridge diagram):

В

Non-incapacitating injury - Cuts, bruises, scrapes

Complaint of injury with no obvious injury visible

NB on left lane (west lane) south end of bridge

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

Woman in red car was immediately in front, Mrs. Mears car struck red car man in black Suv was first observed after the crash to right (east) of Mrs. Mears

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.)

Noticed seeing something to right, road in front of her seemed to come up in Front of her, but she stayed horizontal. Fell 4 times 2nd or 3nd time she dumped into red car. Falls were violent, Saw smoke from truck behind her. Scream only of VEHICLE:

Woman in red car. No side to side movement.

What vehicle were you in?

Make BMW Model 325 Year '04 Color B Plate: Owner: Lawra Mears

Insurance Company: Farr	ners Polic	y Number	<u>:_</u>		
Who else was in the vehicle 1.	with you? NA Seat Position (See a	•	, address, phone Injured?	e, DOB YES) NO
2.	Seat Position (See a	above)	Injured?	YES	NO
3.	Seat Position (See a	above)	Injured?	YES	NO
4.	Seat Position (See a	above)	Injured?	YES	NO
5. .	Seat Position (See a	above)	Injured?	YĖS	NO
6.	Seat Position (See a	above)	Injured?	YES	NO

Additional notes/comments:

Cell phone had been thrown into back seat. Originally in lap. Glasses stayed on face, no airbag deployment.

Car stopped near port-a-potty.

NOTEC.







DATE OF COLLEGION THAT (2700)						
08/01/07 1801 G. Van Etten R. Kaminski HWY-07-MH-024 18	DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
	08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	18

RECORD OF INTERVIEW

Sarah E.Mundy

Interviewed August 6, 2007 at Ms. Mundy's residence Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Sarah E. Mundy (5'8" 155 lbs.)

Ms. Mundy stated she was driving northbound going about 30 m.p.h. in the far left lane at the south end of the bridge in her red 1994 Chevrolet Caprice (VIN According to Ms. Mundy, the first thing she observed was the bridge span she was on crumble ahead of her, then seeing the car in front of her disappear. Ms. Mundy said that her vehicle stopped with her front wheels hanging over the front edge of the span. According to Ms. Mundy, she was able to pry her door open and crawled down to the bike trail were she was helped.

According to Ms. Mundy, she sustained a chipped tooth, air bag burn and abrasion to her left forearm, and a bruise to the right side of her rib cage from her seatbelt.



Date of Interview: 8-6-0/ Time: 4/5
Interviewer: RonK
DRIVER
Driver's License Number State: M/N
Full Name Sarah E. Mundy DOB:
Full Address
Telephone Home: Work / W CAR
Compliance with DL restrictions: Glasses, etc VES NO NA contacts
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH + AIR BAGS
Safety Equipment used: Belts: LAP SHOULDER BOTH + AIR BAGS Transported to Hospital What Ambulance Service: Walk-in Hospital Walk-in Hospital
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

I was NB in FAR DLANE on S. end of bridge by bike path.

Theld note S/W I wasn't some steacht down T

I held onto 5/W I wasn't gong straight down. I felt like I was hithy things while gong down. Alkbags went off on 2nd Hit. Front Zwheels hanging over endge. Iwas Able to pry my door open. As Igot out Pubble around we. I climbed up behind my vehicle 160 Kpng around. taking it in. Crawled up wore where a biker came down to help me, Helped me up. I was in a doze

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Silver CAR in front of me. Silver compact behind me woman driving,

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.)

Front of me disappear. Then I went down. .

going 30mph not in stop? go traffic. VEHICLE:

What vehicle were you in?

Make Chevy Model Cappace Year 94' Color Red
Plate: Owner:

Insurance Company: State FARM Policy Number:

Who else was in the vehicle 1.	with you? NA (Name Seat Position (See above)	e, address, phor Injured?	ne, DOF YES	B) NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

Bruised Rib (BSIDE (seatbelt) Chipped Tooth AIR bag burn & bruise & forearm.

Date of Interview: 8/6/07

Time:

6:00 PM

Interviewer: SA Paul Magnussen

DRIVER

Driver's License Number:

State: MN

Full Name Mannah E. Himmelman - Christopher DOB:

Full Address

Telephone

Home:

Work: 957- 471

Cell:

Compliance with DL restrictions: Glasses, etc

YES NO -

NA

Seat Position:

Front Seat Driver

Center

Right

Middle Seat

Rear Seat

Left Left

Center Center Right Right

Bus occupants see diagram

Ejected:

YES NO

Safety Equipment used:

Belts:

LAP SHOULDER BOTH

Transported to Hospital What Ambulance Service: YES

Walk-in

Hospital France Are Family Physician

Nature of Injury (Circle):

Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.

В Non-incapacitating injury - Cuts, bruises, scrapes

Complaint of injury with no obvious injury visible - sore

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

Traveling NB on the Bridge in the right lane of travel.

She was behind a marcon car with a female driver.

There was a white car that was possible to her left or somewhere in front of her vehicle.

What other vehicles or people were around you? (Color, make, model, description), what were they doing? See front page for additional descriptions.

There was a black car that sped in Front of her car and to the left prior to the bridge collapse. Additionally there was a white car in front of her rehale.

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.)

She had her car radio on so she heard nothing. She initially saw the vehicles directly in front of her vehicle suddenly drop down and out of sight. Then have car moved violently back and forth (side to side), She saw the road separate in front of her vehicle. Then her vehicle dropped down several times to the ground.

VEHICLE:

What vehicle were you in?

Make Honda	Model	CRV	Year 2001	Color	Silver/ white
Plate:	Owner:		- Carol Him		

1 1000	Christopher Care	of Himmelma	n	
Insurance Company: State	Farm Policy Number	er:_		
Who else was in the vehicle		e, address, phoi	ne, DOI	3)
1. N/A	Seat Position (See above)	Injured?	YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
-	Sout I obligation (See accive)	iijui va.	120	110
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
	· · · · · · · · · · · · · · · · · · ·		120	1.0
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

She remembers seeing dust and rubble in the air and on the ground.

She smelled the airbug after it deployed.

The female in the maroon vehicle helped her exit her vehicle.

Trooper Jeremey Solie #89 stationed out of bolden Valley, MN made contact with her

NOTEO

Time: 0924 hrs

Date of Interview: 8-31-07

	Interviewer:	Tom Hendric	KSon #2	960	, M	inneco	2-115	Police	
Shar	DDIVED	1/ -			MN		0113		-
Sha	run Name Full Address	nn Knop		DOB:					
					$M_{i_{\mathbf{n}}}$	nea Da	DS, N	1N 5540	
	Telephone	Home:	Work:		Cell:		¥	5540	8
	Compliance v	with DL restrictions: (Glasses, etc	YES	NO	NA			٠
	Seat Position:	: Front Seat Middle Seat Rear Seat	Driver Left Left	Center Center Center		Right Right Right			
	Bus o	ccupants see diagram	Loit	Contor		Right			
•	Ejected:	YES NO							
į	Safety Equipn	nent used: Belts:	LAP	SHOUL	LDER (вотн)			
	Transported to What Ambula	Hospital YES	NO Walk-in	n]	Hospita	Mof	M		
1	Nature of Inju	A Incapacitating	injury – broken bility to perform						·
		B Non-incapacit	ating injury -	Cuts, br	uises, so	rapes	•		
	(C Complaint of i	njury with no ol	ovious i	njury vi ーシング し	sible Belt-a	irbag		
r	efer to bridge	where you were on the diagram):	e bridge –(direct	ion of tr	avel [N	NB SB], wh	nich lane,	^	
sk	a Knof e was	was four	Thlow	Um	the	I-35	WBr	Q -	
wit	Pat la	ne she u	JUMP	H. 3		Janno	of ren	nomb	4
M	1s Kno	P State 171	lat sel	e Kel	Ta	very	Powe	rful	
2N	rong y	and move	ment to	OF I	he.	ording	e.	. .	

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) See statement

VEHICLE:

What vehicle were you in?

Make Plate:	Model Owner:	Year	Color			
Insurance Company: Fam	news	_Policy Number	er:			
Who else was in the vehicle 1.	with you? Seat Position	•	e, address, pho Injured?	ne, DOI YES	B) NO	
2.	Seat Position	(See above)	Injured?	YES	NO	-
3.	Seat Position	(See above)	Injured?	YES	NO	
4.	Seat Position	(See above)	Injured?	YES	NO	
5.	Seat Position	(See above)	Injured?	YES	NO	

Seat Position (See above)

Injured?

YES


NO

Additional notes/comments:

6.

MOTEC.

28M



Date of Interview: 8-7-0 — Time:
Interviewer: Detective Kirty / X/ XA
Date of Interview: 8-7-0 Time: Interviewer: Letter Him Held Stephen DRIVER Steve Roy Moe
Driver's Lie
Full Name
Full Address
Telephone Home 789 Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER ROTH
Transported to Hospital YES NO Walk-in Hospital Cluber - What Ambulance Service: Hospital Hospital Walk-in Hospital Hosp
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NR SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

Make Jees	Model Lil	year Year	2 <i>00</i> 2 Color	7 J_	l z
Insurance Company:	Dwner:	Yame Policy Number	r:		_•
Who else was in the vehicle v		•	e, address, phon		
1.	Seat Position	(See above)	Injured?	YES	NO
2.	Seat Position	(See above)	Injured?	YES	NO
3.	Seat Position	(See above)	Injured?	YES	NO
4.	Seat Position	(See above)	Injured?	YES	NO
5	Seat Position	(See above)	Injured?	YÈS	NO
6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:

29A

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-6-07 Time: 1850
Date of Interview: 8-6-07 Time: 1850 Interviewer: Detective Hirlor / NC50
DRIVER Jasmenka Harie
Driver's License Number: State:
Full Name DOB:
Full Address
651-
Telephone Home: Work: 792 Cell: 6
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital Hospital Walk-in Hospital H
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB]) which lane, refer to bridge diagram):
 rear-ended.
Behard school Bus

What other vehicles or peopl were they doing?	e were around you? (Color, n	. 1	n), what
Head U	.P.S tuck	Hon.	bing
What did you see, feel, hear, a sensation is described – mo	vement left to right, forward	and back, up or down	cifics if etc.)
Dehund Stop X	Hotras 0-20 mi	Mic	
VEHICLE:	o-zomi	- bers	rups
What vehicle were you in?	s much.	house	J- Kids
Make Plate:	Model Year Owner:	Color	word
Insurance Company:	Policy Numb	er:	⁻
Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)	ne, address, phone, DO Injured? YES	B) NO
1.	· · · · · · · · · · · · · · · · · · ·	injurea.	
2.	Seat Position (See above)	Injured? YES	NO ·
3.	Seat Position (See above)	Injured? YES	NO
4.	Seat Position (See above)	Injured? YES	NO
5	Seat Position (See above)	Injured? YĖS	NO
6.	Seat Position (See above)	Injured? YES	NO

Additional notes/comments:





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	19

Kimmy Dahl, School bus driver

Interviewed August 6, 2007 at the Old Spaghetti Factory restaurant in Minneapolis. Present during the interview were Mrs. Dahl's husband David Dahl, her attorney, NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Kimmy Dahl (5'7" 190 lbs.)

Mrs. Dahl stated she was driving southbound in the right lane at the south end of the bridge in the school bus (VIN According to Mrs. Dahl, the first thing she observed was the bridge start swaying and then hearing rumbling prior to dropping down. She recalled the front right side of the bus hit something then the back right side hit something.

According to Mrs. Dahl, she initially couldn't turn the ignition off and get the bus in park. Mrs. Dahl said that Julie Graves, another adult helper seated in the front right seat and was injured when she was thrown into the loading door stairwell, crawled back up and was able to turn off the ignition while she lifted her leg to engage the parking brake.

According to Mrs. Dahl, she had her two children in the bus with her. Her 5-year-old son was seated in the row directly behind her with her 10-year-old daughter seated in the right front row near the window. According to Mrs. Dahl, her son complained of neck and shoulder pain while her daughter bruised her chin and complained of right shoulder pain. Mrs. Dahl stated that she sustained compression fractures to her spine at T-12 and L1, a left leg laceration, a rotator cuff injury to her left shoulder, and lap belt bruises to her abdomen.






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	67

RECORD OF INTERVIEW Amar Elghorab, school bus passenger

Amar Elghorab (5'2" 82 lbs)



Amar stated he was seated on the right side towards the front. According to Amar, he heard a noise like the bus was going over a bump. Amar stated that Jeremy opened the back door and saved everyone.

According to Amar, he hurt the left side of his back and went to his doctor two times.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	25

Julie Graves, School bus helper

Interviewed August 8, 2007 at HCMC in Minneapolis. Present during the interview were Ms. Graves' fiancé, NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Julie Graves (5'3" 130 lbs.)

Ms. Graves stated she was a seated in the front right seat of the school bus. According to Ms. Graves the first thing she felt was a falling sensation. She believes the bridge fell three times.

According to Ms. Graves, she flew over the padded courtesy panel and landed in the loading stairwell, breaking one of the door windows. Ms. Graves stated that she was able to lift herself up and assisted the bus driver, Kimmy Dahl in shutting of the ignition. Due to her injuries another teenage helper named Jeremy Hernandez, helped carry her off through the back of the bus.

Ms. Graves stated that she sustained compression fractures to her spine at T-12 and L1, an avulsion laceration to her right triceps, a deep laceration to her right forearm, a right ankle fracture, a right foot fracture, a left big toe fracture, and several deep lacerations to her right leg and shin.






H30°	ř
------	---

DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	29

Angela Haeny, School bus helper

Interviewed August 9, 2007 at her residence

Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD



Ms. Haeny stated she was seated in the 5th or 6th row behind the bus driver; playing games with Ricardo and Zach when she felt the bus drop then drop again. Ms. Haeny recalled moving to her left and right during the drops. She then proceeded to help the kids get off the bus through the back door.

According to Ms. Haeny, she sustained a sore neck a chin bruise and she bit her lip.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	30

James Hanson, School bus helper

Interviewed August 9, 2007 at his residence

Present during the interview were NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

James Hanson (5'11" 215 lbs.)

Mr. Hanson stated he was a seated in the second behind the driver near the aisle, when he felt the bus drop. Mr. Hanson stated he felt the bus drop again after the first one. According to Mr. Hanson, he was leaning forward prior to the first drop and then hit his seatback and on the second drop he was thrown to the right. Mr. Hanson said he was initially confused but helped Jenny up since he had landed on top of her. Mr. Hanson stated that he got off the bus but went back on to help the bus driver off. Mr. Hanson stated that he helped the bus driver turn off the ignition while she applied the parking brake.

According to Mr. Hanson, he sustained contusions to the left side of his chest, upper back, chin, and broke a couple teeth. In addition Mr. Hanson stated he had a slight concussion.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	27

Jeremy Hernandez, School bus helper

Interviewed August 8, 2007 at his aunts residence Present during the interview were NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Jeremy Hernandez (5'11" 141 lbs.)

Mr. Hernandez stated he was a seated in the second or third row from the back on the right side near the window of the school bus. According to Mr. Hernandez the first thing he heard was a loud bang then felt the bridge drop. He then felt it drop farther down. Mr. Hernandez could not recall if he went over his seat or not. Mr. Hernandez stated that immediately afterwards the bus was filled with dust and it was hard to see anything. After it cleared, he saw other kids on top of seat backs. According to Mr. Hernandez, he told the kids to exit out the back emergency door. He then went to the back door, moved some coolers out of the way, and opened the door and started handing the kids down to the roadway. He recalled that the bridge still seemed to be shaking. After all the kids were out he said he went and helped carry Julie Graves out the back of the bus. After getting off the bus Mr. Graves stated that he and another man started handing kids off the bridge down to the street below.

According to Mr. Hernandez, he sustained a lower lip laceration, a very sore middle back, and some hip pain.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	43

RECORD OF INTERVIEW Saiku M. Kennah, school bus passenger

Saiku M. Kennah (5'2", 119 lbs)



Saiku stated he thought he was seated in the middle on the left side, with Mohammed and David. According to Saiku, he was sleeping when he awoke to a big bumping. After it stopped, Jeremy started helping everyone out.

According to Saiku, he sustained pain to his upper back and neck. Saiku stated that he was treated and released from Children's Hospital.




08/01/07



RECORD OF INTERVIEW Michelle Klouda, school bus passenger and helper

Michelle Klouda (5'4", 120 lbs)



Michelle stated she thought she was seated in the 3rd row on the right side with Itati and Mary-Juanita. According to Michelle, she though the bus dropped 2-3 times. She recalled flying out of her seat. Michelle stated that after it stopped she grabbed the girls seated with her and started moving off the bus.

According to Michelle, she sustained a neck and middle back strain. Michelle stated that she was treated and released from HCMC.



08/01/07



RECORD OF INTERVIEW Mary-Juanita Leonard, school bus passenger

Mary-Juanita Leonard (4'7", 78 lbs)



Mary stated she thought she was seated in the 3rd row on the right side, with Michele and Itati. According to Mary, she was drifting off to sleep awoke to a loud crash and it felt like the bus was falling. After it stopped it started rolling forward. Mary stated that people were bleeding and falling out of their seats, and then a lot of dust came into the windows. Mary stated that Jeremy cleared the back exit and started helping everyone out.

According to Mary, she was not hurt.







DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	45

RECORD OF INTERVIEW Randi L. Leonard, school bus passenger

Randi L. Leonard (4'1", unk lbs)



Randi stated she thought she was seated in the middle on the right side, with Olivia and Jasmine. According to Randi, she was playing games with her friends when the bus started falling. Randi stated that a lot of dust came into the bus. Randi stated that Jeremy helped everyone out.

According to Randi, she was not hurt.





RECORD OF INTERVIEW Samantha Calderone, school bus passenger

Samantha Calderone (Unknown height and weight)



Samantha stated she was seated in the second row on the left side with Mariella. According to Samantha, she felt big bump then it seemed like she was falling on a roller coaster ride. Samantha said everyone was flying off his or her seats.


According to Samantha, she hurt her ribs, back and had a cut on her chin. Samantha stated that she was treated and released from North Memorial Hospital that day.





RECORD OF INTERVIEW Betsy Calle-Naula, school bus passenger

Betsy Calle-Naula (4'0", 70 lbs)




Betsy stated she thought she was seated in the 3rd row from the back on the left side, with Damaris. According to Betsy the bridge separated and the bus went boom-boom and they all started crying and screaming. Betsy stated that her older cousin and Jeremy helped opened the back door and helped her got out.

According to Betsy, she sustained a hip and shoulder injury. Betsy did not recall were she was treated but that her aunt took her.




08/01/07




RECORD OF INTERVIEW Leyton Guallpa-Naula, school bus passenger

Leyton Guallpa-Naula (unk, 115 lbs)



According to Leyton, he bit his tongue when he hit the seat in front of him. Leyton stated that he was treated the next day and released from Children's Hospital.





RECORD OF INTERVIEW Amy S. Naula-Carillo, school bus passenger

Amy S. Naula-Carillo (5'2" Unk lbs)




Amy stated she was seated on the left side in the middle playing games when she felt some bumps and then it felt like she was falling. Amy thought she was going to fall in the water.

According to Amy, she hurt has a mid back strain and went to HCMC.




08/01/07



RECORD OF INTERVIEW

Jeisy J. Aguaiza, school bus passenger

Jeisy J. Aguaiza (5'3" Unk lbs.)



Jeisy stated she was seated on the right side in the 10th row with TJ. According to Jeisy, she was sleeping and heard a semi honk his horn and the next thing she knew was the bus falling. Then she could hear banging like things hitting the bus. When they stopped there was a lot of dust in the air. Jeisy stated that Jeremy opened the back door and started helping everyone out.

According to Jeisy, she went for x-rays at Children's Hospital and was called back the next day for a back brace because she had a fractured vertebrea.





RECORD OF INTERVIEW Ronal Miguel Aguiza, school bus passenger


Ronal Miguel Aguiza (Unknown height and weight)



Ronal stated he thought he was seated on the left side towards the middle. According to Ronal, he felt the bus jump.


According to Ronal, he sustained a bruise above his left ear and a laceration to his tongue.





RECORD OF INTERVIEW Jazmine Angeles, school bus passenger

Jazmine Angeles (Unknown height and weight)



Jazmine stated she thought she was seated towards the back on the right side with Olivia. According to Jazmine, she heard a noise and the bus started to fall. According to Jazmine they were lifted off her seats. She added that it felt like the bus was sliding.

According to Jazmine, she had pain to her back, ribs and foot. Jazmine said she went for x-rays 8 days later at North Point Hospital.








DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	50

Jonathon Angeles-Sanchez, school bus passenger

Jonathon Angeles-Sanchez (unknown height and weight)



Jonathon stated he didn't remember what happened. Jonathon stated that he only remembered the bus on its side.

According to Jonathon, he was sustained a contusion to the left side of his ribs. He said he was treated and released from North Point Medical Center.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	53

RECORD OF INTERVIEW Aylene Carina-Calderone, school bus passenger

Aylene Carina-Calderone (Unk", 65 lbs)

Aylene stated she was seated in the middle on the left side with Naomi. According to Aylene, she though the bus hit a lot of bumps then she went flying and fell into the aisle.

According to Aylene, she hurt her ribs, back and buttocks. Aylene stated that she was treated and released from HCMC the next day.






i	DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
	08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	60

RECORD OF INTERVIEW Fernanda Araujo-Calderone, school bus passenger

Fernanda Araujo-Calderone (Unknown height and weight)



everyone out.

up and down four times. Fernanda stated that Jeremy kicked open the back door and he helped

According to Fernanda, she had a sore bottom and was bleeding between her legs. Fernanda stated that she was hospitalized at HCMC for two nights.






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	61

RECORD OF INTERVIEW Ivan A. Luna-Calderond, school bus passenger and helper

Ivan A. Luna-Calderone (5'9" 145 lbs.)



Ivan stated he was seated on the right side in the aisle seat behind Jeremy, at the rear of the bus. According to Ivan, they were driving slower than normal when he heard a loud "Boom". Then he couldn't hear anything for a few more seconds, then it felt like he was floating. He said they went up and down four times. When they stopped there was a lot of dirt and rocks flying at them. Ivan stated that the fourth time they went down was when they hit the concrete side of the bridge, with the bus ending up on an angle. Ivan said he landed in his seat. Ivan stated that Jeremy jumped over his seat and kicked open the back door and started helping everyone out.

According to Ivan, he had a sore bottom and sore body. Ivan stated that he went to HCMC the next day to get checked out.








DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	40

RECORD OF INTERVIEW Olivia J. Reynolds, school bus passenger

Olivia J. Reynolds (4'0", 78 lbs)



Olivia stated she thought she was seated in the middle on the right side, with Randi and Jasmine. According to Olivia, she felt the bus shake and then it fell. After it stopped, it started to roll forward. Olivia stated that a lot of dust came into the windows. Olivia stated that Jeremy kicked open the back door and he helped everyone out.

According to Olivia, she hurt her chest and got whiplash. Olivia stated that she was treated and released from North Memorial Hospital.

A30






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	66

RECORD OF INTERVIEW Ricardo Rameriz-Averez, school bus passenger

Ricardo Rameriz-Averez (Unknown height and weight)



According to Ricardo, he sustained a bruise to the underside of his left arm but did not go to a hospital.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
	1 ' '		1	TTTTTTT OF BETT OAA	1 /2
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	0.5
00/01/07	1001	G. , wil Etter		<u> </u>	

RECORD OF INTERVIEW Aisha Ali Roble, school bus passenger

Aisha Roble (Unknown height and weight)



Aisha stated she was seated in row two by the window. According to Aisha, she was sleeping and the next thing she knew kids were screaming and Julie Graves was bleeding. Aisha stated that Jeremy kicked opened the back door and she got out.

According to Aisha, she went to Children's Hospital but was not injured.








DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	51

RECORD OF INTERVIEW
Feys al Roble, school bus passenger

Feysol Roble (4'0", 50 lbs)



Feysol stated he thought he was seated in the 3rd or 4th row on the right side, in the middle with two other kids. According to Feysol, he was almost asleep when he heard a "bang, bang," and the bus dropped and almost fell on its side. Feysol stated that he ended up on the floor and sat there for a while because he thought it was fun.

According to Feysol, he sustained a scratch to his forehead but was not treated.






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	65

RECORD OF INTERVIEW Mohammed Ali Roble, school bus passenger

Mohammed Roble (5'8" 124 lbs.)



Mohammed stated he was seated in the middle on the left side next to David. According to Mohammed, he heard a noise like steel bending prior to the accident. He said the bus slid to the right and stopped at the bridge wall. Mohammed said he saw the semi truck crash in front of them and start on fire.

According to Mohammed, he went to HCMC by ambulance and sustained an injured right scapula, and a bump over his left eye..




08/01/07



RECORD OF INTERVIEW Sagal Ali Roble, school bus passenger

Sagal Ali Roble (5'0", 105 lbs)




Sagal stated he was seated in the 10th row on the left side, with two little kids. According to Sagal, he felt like the bus drop like a ride at Valley Fair. Sagal stated that he fell to the floor and everyone froze because they were scared. Sagal said that a lot of dust and smoke came into the windows. Sagal stated that someone opened the back exit and helped everyone out.

According to Sagal, he sustained a sore neck, and his right foot hurt. He was treated and released from Abbott-Northwestern Hospital.




08/01/07



RECORD OF INTERVIEW Zach Roble, school bus passenger

Zach Roble (5'0", 65 lbs)



Zach stated he thought he was seated with Angie Haeny. According to Zach, he felt the bus fall and tip to the right. Zach stated that he had two sisters on the bus with him.

According to Zach, he sustained a bruise on his left cheek.






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
			75 77 1 11	HWY-07-MH-024	2/
08/01/07	1801	G. Van Etten	R. Kaminski	H W 1-07-MIH-024	34

Demaris Montoya-Mendoza, school bus passenger

Interviewed August 11, 2007 at her parents residence

Present during the interview was her mother, NTSB Investigator Ron Kaminski, and Sgt. Steve Wagner with the Minneapolis PD

Demaris Montoya-Mendoza



Ms. Montoya-Mendoza stated she was seated in the 3rd row from the back, behind the bus driver, when she felt the bus hit a big bump and then fall. Ms. Montoya-Mendoza stated that she thought the bus was going to tip over. She then proceeded off the bus through the back door.

According to Ms. Montoya-Mendoza, she sustained only a sore back.








DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	37

Tyrone Taylor-Levet Mattson Jr., school bus passenger

Tyrone Taylor-Levet Mattson Jr. (5'0", 84 lbs)



Tyrone (aka TJ) stated he thought he was seated in the 4th row from the back on the right side, with Jeisy Aguiza and Kameron Price. According to TJ, the bus hit some bumps and he flew into the air hitting his head on the ceiling. TJ stated that Terrance kicked open the back door and everyone got out. TJ said that after exiting the bus, Kim and Julie were still on the bus so Jimmy Hanson helped them off.

According to TJ, he sustained a bruise on his backside, and his head, with pain to his right shoulder. TJ stated that he was treated and released from HCMC.







RECORD OF INTERVIEW Cristian Martinez, school bus passenger

Cristian Martinez (4'5", 70 lbs)



Cristian stated he didn't remember much about the collapse other than while they were crossing the bridge it all fell. He did recall that Jeremy helped everyone out.

According to Cristian, he was sore to his left knee and buttocks, and sustained a black eye. He said he was treated and released from HCMC.




08/01/07



RECORD OF INTERVIEW Canaan H. Mattson, school bus passenger

Canaan H. Mattson (4'3" 59 lbs)



Canaan indicated that he was seated on the right side behind Monica Segura. According to Canaan, they started falling and when they landed dust came in the bus

According to Canaan, he had scratches on his neck and his knees got banged up. Canaan stated that he was treated and let go at Children's Hospital.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	36

RECORD OF INTERVIEW Isaiah Mattson, school bus passenger

Isaiah Mattson (3'8", 38 lbs)



Isaiah stated he thought he was seated in the 6^{th} row from the front on the right side, with Creole Taylor and Monica Segura. According to Isaiah, he felt two bumps, one little and one big. Isaiah stated that everyone was screaming and then Jeremy kicked open the back door and he helped everyone out.


According to Isaiah, he sustained a scrape to his right lower leg and a bruise on his right foot. Isaiah stated that he was treated and released from Children's Hospital.



A DA A ON					
DATE OF COLLISION 08/01/07	TIME (2400) 1801	INVESTIGATOR-IN-CHARGE G. Van Etten	GROUP CHAIRPERSON R. Kaminski	CASE NUMBER HWY-07-MH-024	PAGE 71

RECORD OF INTERVIEW Creole Ava Taylor, school bus passenger and helper

Creole Ava Taylor (3'11" 55 lbs.)



According to Creole she had a pain in her legs and went to Children's Hospital to get checked out.







					
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	38

RECORD OF INTERVIEW

Imahni Naylor Taylor-Henderson, school bus passenger

Th man!

Imahri Naylor Taylor-Henderson (5'4", 119 lbs)

Imahni stated she was seated in the last row on the right side, with Joaquin Vences. According to Imahni, the bus hit a bump and she felt like they were falling. Imahni stated the bus hit a bigger bump and there was a cloud of dust. Imahni stated that Jeremy opened the back door and everyone got out.

According to Imahni, her mom took her to Children's Hospital but she didn't have any injuries.






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	68

RECORD OF INTERVIEW Ana Vences, school bus passenger

Ana Vences (5'2" Unk lbs)




Ana stated she was seated on the left side in the back row. According to Ana, she didn't remember the crash but did recall that Alexis Martinez ended up under the seat. She also recalled that Jeremy kicked opened the back door.

According to Ana, she hurt her back and went to a Chiropractor after being seen at Abbott Hospital.








DATE OF COLL	ISION TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/0		G. Van Etten	R. Kaminski	HWY-07-MH-024	49

RECORD OF INTERVIEW Elfego Vences-Garcia, school bus passenger

Elfego Vences-Garcia (5'8", 150 lbs)



Elfego indicated that he was seated around the 9th row on the right side with Dianna Segura. According to Elfego, he thought they hit a speed bump and then he could feel himself dropping. Then it stopped and there was a lot of smoke in the air. Elfego stated that Jeremy opened the door and started helping everyone out. According to Elfego, after he got out he helped his sister who was hyperventilating.

According to Elfego, he sustained injuries to his middle back and had a bruised nose. Elfego stated that he was treated and released from Children's Hospital the next day.





D.	ATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
	08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	44
			·			

RECORD OF INTERVIEW Joaquin Vences-Garcia, school bus passenger

Joaquin Vences-Garcia (5'8", 138 lbs)

Joaquin stated he was seated in the very back row on the right side with Ihamni. According to Joaquin, he remembers hitting a bump then everyone went up in the air. Then it stopped and started again a couple times. When they stopped Joaquin stated that it was quit with a lot of dust in the air. Joaquin stated that Jeremy jumped over some seats, cleared away the coolers and started helping everyone out. According to Joaquin, after he got out he was looking for his brother and sister while trying to calm the other kids that were crying.

According to Joaquin, he sustained injuries to his upper back and neck. Joaquin stated that he was treated and released from Children's Hospital the next day.






			-		
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	64

RECORD OF INTERVIEW Ryan H. Watkins, school bus passenger and helper

Ryan H. Watkins (5'5" 115 lbs.)




Ryan stated he was seated on the left side, two rows from the back, in the aisle seat with Nina. According to Ryan, he felt two bounces and fell to his right across the aisle but did not hit the floor. He saw Nina slumped in her seat to the left. He initially thought they were in an accident. Ryan stated that Jeremy opened the back door and started helping everyone out.

According to Ryan, he had a sore neck and had a bad headache for 2 days. Ryan stated that he called the health partners phone line for advice.



08/01/07



RECORD OF INTERVIEW

Jenny Xiong, School bus helper

Interviewed August 8, 2007 at her parents residence

Present during the interview were NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD


Jenny Xiong (4'8" 100 lbs.)



Ms. Xiong stated she was a seated in the second row in the aisle seat on the right side of the school bus. According to Ms. Xiong the first thing she felt was free. She only felt one hit when the bus hit the ground. Ms. Xiong stated that following the drop she inhaled some dust and had trouble breathing. She then walked out the back of the bus.


According to Ms. Xiong, she sustained compression fractures to her lumbar spine and an abrasion to her right ankle.





RECORD OF INTERVIEW Diana Segura, school bus passenger and helper

Diana Segura (Unknown height and weight)



Diana stated she thought she was seated towards the back on the right side with Elfego. According to Diana, she though the bus hit a speed bump and then she felt it falling down.


According to Diana, she sustained a bruise on her knee. Diana stated that she was not treated.





RECORD OF INTERVIEW Elsa Segura, school bus passenger


Elsa Segura (5'0", 110 lbs)



According to Elsa, she sustained a neck strain, and both knees were bruised. Elsa Stated that she was treated and released from Children's Hospital the next day.




08/01/07



RECORD OF INTERVIEW

Monica Guadalupe-Segura, school bus passenger and helper

Monica Guadalupe-Segura (5'4", 140 lbs)



Monica stated she was seated in the 6^{th} row on the right side with Isaiah and Creole. According to Monica, she initially thought the bus was hit from behind. She recalled that the bus dropped then dropped again. According to Monica, after the second drop dust came in through the windows. She said Jeremy opened the rear door and helped all the kids off. Monica stated that she didn't realize that the bridge had collapsed until she got off the bus.

According to Monica, she sustained a bruised chest and some internal bleeding, and middle back strain. Monica stated that she was treated and released from Abbott Northwestern three days later.



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interv	iew: 6	96		Time:	23	b		
Interviewer:	-							
DRIVER	Kimi	my DAI	1	*	, I			
Driver's Lice	nse Nun	nber:			State:	MIN		
Full Name					DOD.			
Full Address								
		5 /	140 16	S				
Telephone	Home	:	Work:			Cell:		
Compliance v	vith DL	restrictions:	Glasses, e	etc	YES (NO	NA	
Seat Position		Front Seat Middle Seat Rear Seat	Left	>	Center Center Center		Right Right Right	
Bus o	ccupant	s see diagram						
Ejected:	YES	NO						
Safety Equip	ment use	ed: Belts	s:	LAP	SHOU	LDER	вотн	
Transported t What Ambula	_) NO	Walk-i	n	Hospita	al	_
Nature of Inju	ıry (Cir							
	(A)	_					alized, severe cu ould do before in	
	В	Non-incapa	citating in	jury -	Cuts, b	ruises,	scrapes	
	С	Complaint of	of injury w	vith no o	obvious	injury v	visible	

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

IN Rt lane going SIB, All the sudden bridge started swaying (5102 to 8102) HEARD Rumbling started tipping down. The front of bus hit and back Hit. Big Semi was on @ passing us. Italie Graves in B front row sout Kids waving to truckdriver Hewared back Honked his hora.

Barlaneau, from another vehicle Assisted helping Kids of bus. He Also helped person in Another vehicle.

I've driven these Kids during the past 4 summers.

I couldn't shut bus off. I couldn't put in PARK. I was afrend of polling back into Kids. I was able to lift my leg and get parking brake down. Julie shut the bus off my 2 Kids on bus son-5 neck shoulder pain Daughter-10-Chin bruised B shoulder pain CT scan done. Son behind me directly the 31d down under seat. daughter on B front next to Julie.

And she ended up in strikwell upside down w/bacl towards driver she is @ Hanc 612 721-1681 waite

Jimmy diso on bus w/ Nonich shasha Jimmy helped we off bus. What other vehicles or people were around you? (Color, make, model, description), what were they doing? semi passing on ups was behind me

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:				
What vehicle were you in?	VIN			
Make Plate:	Sched Model Bus Owner:	Year Color	ye	llow
Insurance Company: Amek	Home Assurance Policy	Number:_		
Who else was in the vehicle	with you? NA	(Name, address, phor		•
1. 62 total 2 from waste He	Seat Position (See ab	oove) Injured?	YES	NO
Gran WAIte He	use plus	myselt		
2.71000 2011	Seat Position (See ab	ove) Injured?	YES	NO
3.	Seat Position (See ab	oove) Injured?	YES	NO
4.	Seat Position (See ab	oove) Injured?	YES	NO
5.	Seat Position (See ab	oove) Injured?	YES	NO
6.	Seat Position (See ab	oove) Injured?	YES	NO

Additional notes/comments:

Comp Fx T12-L1 12 Dley thigh lac Lapbett banises of SW

ISTH-35W Bridge Collapse Interview Questionnaire	
Date of Interview: 8807 Time: 12 00	
Interviewer: RON K.	
DRIVER	
Driver's License Number: State:	
Full Name Julie GRAVES DOB:	
Full Address Ht 5'3' wt. 130165	
Telephone Home: Work: Fignore	
Compliance with DL restrictions: Glasses, etc YES NO NA	
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right	
Rear Seat Left Center Right Bus occupants see diagram	
Ejected: YES NO	
Safety Equipment used: Belts: LAP SHOULDER BOTH W/A	
Safety Equipment used: Belts: LAP SHOULDER BOTH N/A Transported to Hospital What Ambulance Service: Walk-in Hospital HCMC	
Nature of Injury (Circle):	

(A)

Incapacitating injury - broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.

- В Non-incapacitating injury - Cuts, bruises, scrapes
- \mathbf{C} Complaint of injury with no obvious injury visible

Please explain where you were on the bridge -(direction of travel [NB SB], which lane,

refer to bridge diagram): close to end of the bridge.

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

. 1
it
£
`
`

Make Plate:	Model Owner:	Year	Color		
Insurance Company:		_Policy Number	: <u> </u>		
Who else was in the vehicle val.	•	NA (Name (See above)	· •	e, DOB YES	-
2.	Seat Position	(See above)	Injured?	YES	NO
3.	Seat Position	(See above)	Injured?	YES	NO
4.	Seat Position	(See above)	Injured?	YES	NO
5.	Seat Position	(See above)	Injured?	YÈS	NO
6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:

Compression T-12 L1 Fx's, Avulsion & Triceps', Sep LAC & Forenem, & Ankle Fx, & Foot Fx, & Bytoe Fx, Deep Lacs & leg (Knee, Shin) & eye Blacks Blue NO Concussion

Starwell. I pushed myself up and asked how the Kids ARE. Kimasked me to help turn off bus. I couldn't walk much due to my injuries. Kim told Me not towalk. Jeremy helped me off bus. Jimmy Hanson sat w/me on street and help came for me. Guy from RED Cross.

Monica Segura & ADMI Chaperone's

Michele Kloudg

SASha Bouye (Boowie)

Angi Haney Haeny



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-9-07

1130 Time:

Interviewer:

RON K

DRIVER

Driver's License Number:

State:

Full Name Argela HAENY

DOB:

Full Address

Cell:

Telephone

Home:

Work:

NO YES

NA

Seat Position:

Front Seat

Compliance with DL restrictions: Glasses, etc

Driver

Center

Right

Middle Seat Rear Seat

Left Left Center Center Right Right

Bus occupants see diagram

5th or 6th Row behind driver

Ejected:

YES / NO

Safety Equipment used:

Belts:

LAP SHOULDER BOTH

Transported to Hospital What Ambulance Service: YES

Walk-in

Hospital HCMC

Nature of Injury (Circle):

Α Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.

Non-incapacitating injury - Cuts, bruises, scrapes В

Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

5-6 Rous behind DR in Aisle.
RICATROO, ZACH ROBLE DE

Boys AMAR, De Luis, Feysal
Across
Ayline behind me.

What other vehicles or people were they doing? Scm? Loep behnd	to tef- Semi	t - A.	head o	FI	xs, •	a blac
What did you see, feel, hear, a sensation is described – mo	vement left to right, i	forward an	d back, up or	down et	tc.)	
staying games.	looking@	River	- Ife	e1 t	17 d	rop.
anded once, -	then fel	1 ags	AIN PE	me	mber	moun
olaying games. anded once, s vehicle:	(4) = (B)	All	'thek	ad S	3 CRI	Mny.
What vehicle were you in?					,	
Make Plate:	Model Owner:	Year	Color			
Insurance Company:	Polic	y Number:			·	
Who else was in the vehicle	with you? NA	(Name,	address, phon	e, DOB	3)	
1.	Seat Position (See a	bove)	Injured?	YES	NO	
2.	Seat Position (See a	bove)	Injured?	YES	NO	
3.	Seat Position (See a	lbove)	Injured?	YES	NO	
4.	Seat Position (See a	lbove)	Injured?	YES	NO	

Additional notes/comments:

5.

6.

BACK PAIN. Chin bruised bit lip

Injured?

Injured?

YES

YES

NO

NO

Seat Position (See above)

Seat Position (See above)

my coworkers of Kids got off bus. I then saw that bridge was gone. We got off bus. I then bridge to street.



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-4-07 Time:	1 30
Interviewer: Ron K	•
DRIVER	
Driver's License Number:	State:
Full Name James Hanson	DOB:
Full Address	
HT5"W1. 213103	
Telephone Home:	Cell:
Compliance with DL restrictions: Glasses, etc	YES NO NA
Seat Position: Front Seat Driver Middle Seat Left	Center Right Center Right
Rear Seat Left Bus occupants see diagram	Center Right
Ejected: YES NO	
Safety Equipment used: Belts: LAP	SHOULDER BOTH NA
Transported to Hospital YES NO Walk-What Ambulance Service:	SHOULDER BOTH NA in Hospital HCMC TE', R
	en bones, hospitalized, severe cuts

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

C

going SB over looks just past River

Non-incapacitating injury - Cuts, bruises, scrapes

Complaint of injury with no obvious injury visible

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Semi next to us on (B/ACK SUV behind us,

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if

sei two one	a sensation is described - mo mi honked his h times after p I was throw VEHICLE: forwa	vement left to right, 102N PASSI 12+ one I who to Rig und.	ing or	sent b	down ended to Ack	us dro, then n I was	pping ext beaning
	What vehicle were you in? Make	Model	Year	Color			
	Plate: Insurance Company:	Owner:	cv Numbe	r:			
	Who else was in the vehicle		(Name	e, address, phon	ne, DOE YES		
	2.	Seat Position (See	above)	Injured?	YES	NO	
	3.	Seat Position (See	above)	Injured?	YES	NO	
	4.	Seat Position (See	above)	Injured?	YES	NO	
	5	Seat Position (See	above)	Injured?	YĖS	NO	
	6	Seat Position (See	ahove)	Injured?	VEC	NO	

Additional notes/comments:

Chest contusion upper (), upper back center contusion, Chin contusion, broke a couple teeth (3-4)
Bit tonque, slight concussion

I was confused, helped jenny up since I was on top of her. Everyone got off bus I went back on to help bus driver off. I felt bus shift. I helpe shut off the bus while she Applied PARKING brake. I got off and went to sipewalk. I helped Julie while she sat on sipewalk.

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-11-07

Time: 335

Interviewer:

Ronk

DRIVER

Driver's License Number:

State:

Full Address

Full Name Da MARIS MontoyA



Telephone

Hom

Cell:

Compliance with DL restrictions: Glasses, etc

YES NO

NA

Seat Position:

Front Seat Middle Seat Driver Left

Center Center Right

Rear Seat

Left

Center

Right Right

Bus occupants see diagram

Ejected:

YES

Safety Equipment used:

Belts:

LAP SHOULDER BOTH

Transported to Hospital What Ambulance Service:

YES

NO

Walk-in

Hospital North Men. TER

Nature of Injury (Circle):

Incapacitating injury – broken bones, hospitalized, severe cuts

An inability to perform a task they could do before injury.

 \mathbf{B} Non-incapacitating injury - Cuts, bruises, scrapes

Complaint of injury with no obvious injury visible

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?


Then	What did you see, feel, hear, a a sensation is described – more than the bus fell VEHICLE: Off the What vehicle were you in?	vement left to	right, forward ar	nd back, up or d	own etc	2.)
	Make Plate:	Model Owner:	Year	Color		
	Insurance Company:		Policy Number	:		
	Who else was in the vehicle val.	with you? Seat Position	•	address, phone Injured?	-	NO
	2.	Seat Position	(See above)	Injured?	YES	NO
-	3.	Seat Position	(See above)	Injured?	YES	NO
	4.	Seat Position	(See above)	Injured?	YES	NO
	5.	Seat Position	(See above)	Injured?	YĖS	NO
	6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:

SORE BACK



Date Of Interview: 8-10-07
Interviewer: <u>Sgt. Jo-l Sandbeng-MPD. 3rd Pet</u> Kid's Full Name: <u>Sagal Ali Roble</u> <u>Ht: 5'0</u> Wt: 105
Kid's Full Name: Sagal Ali Roble Ht: 5'0 Wt: 105
Floral & Whah NUR
Address: 5100. Lyndele AVS. MPCS
Contact Phone #:_
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name: Abbott Northwest run Hospital
Admitted, T&R, N/A: Not admitted
What type of injuries did you get? Some Neck- Right Foot hunts - Sagal wint to The TDK. ON 8-10-07 to get Some Shots. AT This Time She had The TDK. Check here injuries From The acceptant
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
Ji HING NEXT YO & LITTLE NISS, I PACT
hus Start to bounce up and down (Small bounces)
T The Filt The hus drop like The Vower Tower" at
Vallen Fail F Fill on the Floor OF The bus, We all Froze
Scared. I lould See dost and smoke
- It was next that was next to the bus, that
C The back door or the man are the top
Contess out of the back. Jone prople harped us out
The bos, we went to the Rud (Ross building and Received halps



Date Of Interview: 8.10-07
Interviewer: Det Churboneau HCSO 11
Kid's Full Name: Saiku M. Kanneh Ht: 52" Wt: 119
Parent/Guardian Name: ROSE C, Gbadamassi -
Address:
Contact Ph
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: How? Ambulance POV POV Transported to Hospital: No x not that day No x not that day
Hospital Name: Childrens Hospital 8-2-07
Admitted, T&R, N/A: Just went for check-up
What type of injuries did you get? Pain in upper back & Neck
Gave Bain meds.
also Followed up with family
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and
CAMI
I was sleeping woke up belause the pridse
Dumping. Then they stopped the bus and
Jornan hilo me aut. Iden they were
helped off the Bridge and brought do
Red cross.

(A-30)

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview:	3.8-07	Time:	1035		
Interviewer: Po	nK				
DRIVER					
Driver's License Nur			State:		
Full Name Jere	my Herr	andez	DOB:		
Full Address	·				
5'11	141 /4	63			
Telephone Home	:	Work:	Cell:		
Compliance with DL	restrictions: G	lasses, etc	YES NO	NA	
Seat Position:	Front Seat Middle Seat Rear Seat	Driver Left Left	Center Center	Right Right	
Bus occupant	s see diagram	Len	Center	Right	
Ejected: YES	NO				
Safety Equipment us	ed: Belts:	LAP	SHOULDER	ВОТН	NA
Transported to Hospi What Ambulance Ser		NO Walk-	in Hosp	ital_ <i>Abb</i>	oth
Nature of Injury (Cir A	Incapacitating	g injury – broke ability to perfor	, ,	•	
(B)	Non-incapaci	tating injury -	Cuts, bruises	, scrapes	

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

PARALLEL TO DAM HDG 5/B

Complaint of injury with no obvious injury visible

C

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Female in truck (SUV) to back left of bus. MINIVAN in front of her

ioen. Ifel	What did you see, feel, hear, a a sensation is described - more of the solver of the bridge of VEHICLE: over NU	and smell relativement left to Just to Just to Property	ive to the crash? right, forward an woke u Theory enfect notsure	Please ask fond back, up or dep. A ser	or speci lown et wi b ban do	ifics if c.) nonked his cy like Aco Non, Tures
	What vehicle were you in?	Schoo	d bus.			
	Make Plate:	Model Owner:	d bus, Year	Color		
	Insurance Company:		_Policy Number	:		
	Who else was in the vehicle val.	vith you? Seat Position	•		e, DOB YES	-
	2.	Seat Position	(See above)	Injured?	YES	NO
	3.	Seat Position	(See above)	Injured?	YES	NO
	4.	Seat Position	(See above)	Injured?	YES	NO
	5.	Seat Position	(See above)	Injured?	YĖS	NO
	6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:

HIP PAIN, LAC lower lip (statches)
MIDDLE BACK VERY SORE 138NECK SORE

some Kids ontop of Scats. Then it dropped/fell again scemed to drop again maybe us hit somethy. Lots of dust couldn't see Anything Dust settled, Kids screaming we're gonna Die.
Bus stanted Lolling backwards. Bus stopped
against eurb. I told then all to get out I
went & opened the back dook, jumped out, standles
saw we were close to grown. I started grabbing them of harding them down to grown The bridge Still seemed to be shaking. I looked back sow Kids anddled around. Is Am this guy w/ blooky pose and we started harding Kids down thon PAN back to helpwore Kids down from bus Someone sand dulie was hurt, myselfall another boy helped carry Julie out of bus, we harded her down to street. Jimmy holped. Kinmy out of lous.

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-8-07

Time:

Interviewer:

Ronk

DRIVER

Driver's License Number:

State:

Full Name Jenny Xion G

DOB:



Full Address

HT 48" WT 100 165.

Telephone

Home:

Work:

Cell:

Compliance with DL restrictions: Glasses, etc

YES NO

Seat Position:

Front Seat

Driver

Center

Right

Middle Seat Rear Seat

Left Left Center Center Right Right

Bus occupants see diagram

Ejected:

YES (NO

Safety Equipment used:

Belts:

SHOULDER BOTH N/A LAP

Transported to Hospital What Ambulance Service:

Walk-in

Hospital North Mem MED CTR

Nature of Injury (Circle):

A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.

В Non-incapacitating injury - Cuts, bruises, scrapes

C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Semi truck to be bus.

freef Immy	what did you see, feel, hear, a sensation is described - mo ver bridge, I middling then hit got off. I inhall VEHICLE: headed walking As What vehicle were you in?			•	_	
	Make Plate:	Model Owner:	Year	Color		
	Insurance Company:	Po	olicy Number:			
	Who else was in the vehicle val.	with you? N Seat Position (Se	•		, DOB YES	
	2.	Seat Position (Se	ee above)	Injured?	YES	NO
	3.	Seat Position (Se	ee above)	Injured?	YES	NO
	4.	Seat Position (S	ee above)	Injured?	YES	NO
	5.	Seat Position (S	ee above)	Injured?	YĖS	NO
	6	Seat Position (S	aa ahoya)	Injured?	VES	NO

Additional notes/comments:
Lower back compression FX L? Knees SORE
ABRASION (1) Ankle.

141

I Didn't notice Anything until we stated free falling. I only felt the I hat when we hat the ground.

Barcia 8.10.07 Date Of Interview: Charboneny 4150 Kid's Full Name: Joaquin Fences Garcia Ht: 5'8 Wt:/38 Parent/Guardian Namo: FloF. Vener Reo Von Garrig Address: Contact Phone #: Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows. After Osash Transported to Hospital: Y____ Ambulance Hospital Name: Childrens Hosp. 8-2-07 next day Admitted, T&R, N/A: back + Neck Pain Nicoled What type of injuries did you get? went Chisopractor on 8-8-07 Spine + neek problems Still going for Treatment. What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and Remember hitting a bumb then everyone went Nep, Then it stopped and started saw) again a couple times. Remeber Semi honking at us and noticed bridge going down, when landed it was quite with alet of dust in air once dust settled down Jecemy Jump over Seats Kick Cooler out of the way opined the door

Then he was helping tolds get out when I get out to when I get out to went to look for my brother and sister

and I was frying to calm
the Kids down that were ensing.
Then I remember my sister fainting
and going to the Hospital, and nobody
was helping her she hit her head
and needed water. Then a biter
cume and gave me water I
dumped it on her to wake her
up. Then eventually brought to
Red Cross




Date Of Interview: 8-10-07
Interviewer: Det. Charboneau 4050
Kid's Full Name: Randi Lynn Leonard: UNK Wt: UNK
Parent/Guardian Name: Linka beannd
Address: 2535 /87H Ave So
Contact Phone #:_
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name:
Admitted,T&R, N/A:
What type of injuries did you get? No injuries


What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)

Playing Concentration with Friend and talking about Duildings. Then I them by Falling and then Smoke.


Just head Kids screaming while falling and after. Gat off bus with People helping Jeremy and sasha then other people helpid off bridge.

Then remeber secins Fire and black smake after getins off the bus.





Date Of Interview: 8-10-07	<u> </u>		
Interviewer: Ron Kaminski			
Kid's Full Name: 8/5A Segura	Ht:	5	Wt:_//O
Parent/Guardian Name: MARIA Flores		DOB	
Address:			
Contact Phone #:	DAMISH only		
Seating position (Show ous seating chart): Ask who they were seated next to and around them and put t	hem in chart as well	as using	arrows.
Transported to Hospital: Y How? Ambulance	No POV	Wen	+ thursday
Hospital Name:			
Admitted T&R, N/A:		_	
What type of injuries did you get? upper should with. Knees confused.	den/aeck·	STRA	1 N ,
What do you remember from the accident? (Interviewer: If p saw) driving bus then went down I then to the P then the whole bridge went down. I drops. I turned around to see who fell out of his seat	in a little"? a buck filled to like to the text of th	etlas 3 di	ent forward I the Fferent
ACROSS was SAMIRA, JOES I MAY have been in 4th	pow		





Date Of Interview: 8-10-07
Interviewer: Ron K
Kid's Full Name: CERISTIAN MANETINEZ Ht: 45" Wt: 70
Parent/Guardian Name: ROSA CoferRas
Address:
Contact Phone #:_
Seating position (Snow sub seating chart). Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name: HCMC
Admitted T&R N/A:
What type of injuries did you get? Blackeye. DKaee & butt sore.
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) crossing bridge. And it All fell. Jeremy too Kouh coolers and opened the door. Don't Tremenber much everyone was screaming
my sister marriella 970 scratches not treated.



Date Of Interview: 8-10-07 Interviewer: Kon K		
Interviewer: KON K		
Kid's Full Name: Michele Klouda	Ht:5 4	_ Wt:_ 120
Parent/Guardian Name:		
Address:		
Contact Phone #:	_	
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in cha	rt as well as usin	g arrows.
Transported to Hospital: How? Ask who they were seated next to and around them and put them in characteristic and around them are put them		
Hospital Name: HCMC Admitted T&R N/A:		
What type of injuries did you get? Lumban & Cell Strain	,	
What do you remember from the accident? (Interviewer: If possible ask saw) I remember flyny up out of my 5 2-3 times not sure howmany. Window saw we were learning. girls as streeted moving off by	I then I gradb	100Ked out



Date Of Interview: 67001
Interviewer: Kon K
Kid's Full Name: EIFE60 Vences Ht: 58 Wt: 150
Parent/Guardian Name:
Address:
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No POV LATER
Hospital Name: Childrens
Admitted,T&R N/A:
What type of injuries did you get? BRUISED \$050, Thoracic Strain.
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) I closed my eyes felt like a speed bump. Theard semi beep. I could feel myself dropping. Diana was next to me holding me. Then Smoke all over Everyone panicang. Jeremy opened dook I pushed Diana i your nephen out. I helped Veremy get kids out of bus. The semi stacks on fire. I have shaperentalating. She was towards

My Sister was hyperventilating. She was towards back ANDA Vences.



Date Of Interview: Of Torrow	_
Interviewer:	
Kid's Full Name: Jonathan Angeles Sanchez Ht:_ Parent/Guardian Name: Jobs ta Francusco	Wt:
Parent/Guardian Name: Jobi ta Francisco	
Address:	
Contact Phone #:	
Seating position (Show bus seating chart). Ask who they were seated next to and around them and put them in chart as wel	l as using arrows.
Transported to Hospital: Y No How? Ambulance_ POV	-
Hospital Name: North Point	
Admitted_T&R N/A:	_
What type of injuries did you get?	<i>;</i>
What type of injuries did you get?	- ;

What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)

I don! + Know what happed I just renewber

the bus on the SIPE.



Date Of Interview: 8-10-07
Interviewer: Sst. Tool Sandborg MDD 3rd Pet
Kills F. W. Soman Roble (Fey So LHt: 4'0 Wt: 50 (45) Perconduction rame. Ali & Francisco Ubah Nur (Somalian)
Address:
Contact Phone #:
Seating position (She Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name:
Admitted,T&R, N/A:
What type of injuries did you get?
Scratch on Forehead
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
Fey Sal was almost Sleeping in his Seaf
1 = Maril & fook place Fores (C)

betore the accident took place, Fey Sal (Soloman) WAS Sitting in the middle of the Seat between 2 other Kids. Frysol Suddenly hearda" Bary-Bary-Barg" end Then The bus Then dropped and Fell Over alittle bit. Fry Sal Sat on the hos Floor arTex The accident. "I Thought it was kind Othis Fun"

Foysal is his Real Firest name, but he also goes by Soloman

(A-30)

Date Of Interview:
Interviewer: Detective Thinly 17468
Kidle Full Marrier / EV Tour KEV INF Ht: Wt: 115
Parent/Guardian NamemSARA NAULA OUALLAA-Nauta
Address:
Addiess
Contact Photogram 1997 1997 1997 1997 1997 1997 1997 199
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No No No How? Ambulance POV> Father
Hospital Name: Mals Childrens - 8/2/07
Admitted, T&R, N/A: Soce Chart - Hit seak
Dit Tongue in front of
What type of injuries did you get? The series of the serie


What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and


Bungy then "crash")
Remained he seat

saw)

8-10-07

8-10-07 Date Of Interview: Kid's Full Name: > CARINACA Parent/Guardian Name(M) ROCIO CALDERONE Address: Transported to Hospital: How? HCMC Hospital Name: Admitted, T&R, N/A: Jaken to Haggetel new dog by Father Ceasar Calderone Hunt Ribs, Duck What type of injuries did you get? What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and oing burneys! saw)







Date Of Interview: 8/10/07
nterviewer: Defective Brian McKague HCS
nterviewer: <u>Defective Brian McKague</u> #CSO Guadalupe Kid's Full Name: <u>Monica</u> S egura Segura 5'4" Wt: 140
Parent/Guardian Name: Macia Flores
Address:
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y es No No How? Ambulance NO POV X - ay and on 8/4 Hospital Name: Absorption
Hospital Name: Absort
Admitted,T&R, N/A:
What type of injuries did you get? Bruised thest some internal bleeding but how stopped R. Knee pain (has brace on K. Knee) Back pain - upper
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) bumper to bumper ! ked at Cell just before 6:05 m 1st felt like someone ran into bus (semi truck) chropped Stopped then chropped again. after dropped 2 ml time dust cleared & could see sen; truck: rear door opened by Juneary helped all kids off. 5th from last off felt bus move + last 5 ran off. didn't Know bridge fell until she got off



Date Of Interview: 08/10/07
Interviewer: Detective Brian McKagne HCSO
Interviewer: Detective Brian McKagne HCSO Kid's Full Name: Zack Roble Aile Ht: ~60" Wt: 60-70 M
Parent/Guardian Name: Mother - Ob a
Address: <u>\$</u>
Contact Phone
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name:/ A
Admitted,T&R, N/A: // A
What type of injuries did you get? Bruise on L. cheek
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) felt bus fall and tip right. Smelled Smoke from truck on fire
sister Aisla Roble Aile also on 645



Date Of Interview: 08/10/07
Interviewer: Detective Brian McKague HCSO
Interviewer: Defective Brian McKague HCSO Kid's Full Name: Ronal Migeal Agnaiza Ht: UNK Wt: UNK Parent/Guardian Name: Florintina Seabre Address:
Parent/Guardian Name: Florintina Seabre
Address:
Contact Pho
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: How? Ambulance POV X - no flor drove after getting home
Admitted,T&R, N/A: T & R
What type of injuries did you get? bump above Left ear - 'hit with rock" bit tounge
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) felt bus "jump" Saw smake after getting off






Date Of Interview: Offo to 1
Interviewer: Ann Raymer
Kid's Full Name: Diana Segura Ht: Wt:
Parent/Guardian Name: Maria Flores, Salvador Segura
Address:
Contact F
Seating position (Show bus seating chart). Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name:
Admitted,T&R, N/A:
What type of injuries did you get?
bruise on knee
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
fult like speed bump-felt groing down, saw smoke.
silent, - didn't hear any moises prior to the fall



Date Of Interview: 8/10/07
Interviewer: Ann Raymer
Kid's Full Name: Jazmin angeles Ht: Wt:
Parent/Guardian Name: Jobita Gorge 15 TSmael Galvan
Address:
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y_X No How? Ambulance POV
Hospital Name: North Point , aug 9
Admitted,T&R, N/A:
What type of injuries did you get?
back + ribs + foot - just had pain get x-roup but showed no breaks
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and
saw)
heard a moise + bus started to fall, lifted of their seats
bus helt like it was Midwa





Date Of Interview: 8/10/07
Interviewer: Ann Roymer
Kid's Full Name: Samantha Com Calderon Wt:
Parent/Guardian Name: Cesac Calderon
Address:_
Contact Pl
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y_X No No POV POV
Hospital Name: North Memorial - Weds - aug 1 st
Admitted,T&R, N/A:
What type of injuries did you get?
back ribs, cut on chin pain
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) Hying of the seato. Ing lump + turned to the side,
Open of the same, so of composition to the bude,
Doundo like mutal being thrown on the floor - what she heard as they felt like a roller coaster were yalling



Date Of Interview: 8-10-07
Interviewer: DETECTIVE PALALA HOSO - 6 475 OLD
Kid's Full Name: FERNANDA ARAUTO CALDERON Wt: Wt:
Parent/Guardian Name: AJGELICA CALNERON
Address:
Contact Ph
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows. SITTIME ON DRIVERS SIDE AISLE SEAT — CADEM (MALE) WI MIDDLE / SASHA (FEMLE) WEXT TO BLACK TO LOER THAN ME BLACK TO LOER THAN ME THAN ME How? Ambulance X POV
Hospital Name: HCMC
Admitted, T&R, N/A: ADMITTED - IN FOR TWO DAYS
What type of injuries did you get? SOAR BOTTOM "I WAS BLEEDING BETWEED MY LEGS"
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
SWEING SONGS AND PLAYING GAMES SITING FORWARD IN SEAT
BUS MOVED UP AND DOWN FOUR TIMES WHEN BUS STOPPED
I was on THE FLOOR IN THE AISLE ON BUTT EVERYONE
GOT UP - JEREMY KICKED THE BACK DOOR OPEN

SOMEONE HELPED ME OUT THE BUS THEN MY BROTHER


CARRIED ME

Date Of Interview: 8-13-07
Interviewer: DETECTIVE PALAMA HCSS ANTONY DOB - 15 4PS OLD
Kid's Full Name: IVAN ANTIONY LUNA-CALDERUN Ht: 5-9 Wt: 145
Parent/Guardian Name: Aubecica Caussol
Address
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name: HCMC - NEXT by IN AM
Admitted, T&R, N/A: ADMITTED 1-2 Hours AT HOSPITAL
What type of injuries did you get? SOAR BUTT SOAR BUDY
BRUISING - STILL SOAR MUSCLE'S HURT

What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)

DRIVING LESS THAN NORMAN SPEED, SEMI TRUCK NEXT
TO US ON MIDDLE OF BRIDGE, SEMI HONKED AND PASSED US
DON'T KNOW WHY HE HONKED, WE DROVE FOR ABOUT IN H
SECONDS MORE, HEARD A LOWD BOOM THEN I CONLOW HEAR
ANYTHING FOR ABOUT 3 MORE SECONDS, THEN FELT LIKE
I WAS FLOATING, WENT UP AND DOWN H TIMES, SAW A
LOT OF DIRT COMING IN WINDOWS, SAW ROCKS FLYING,
HIT THE SIDE OF THE BRIDGE BOWNIESD THREE TIMES
UP AND DOWN FOURTH BOWNICE HTT CONCRETE SIDE THEN
BUS WAS AT AN ANCLE - CRANITY WAS PULLING US BOWN I SCAT

-8X8X-



* ALE INFO From IVAN CALDERON *




Date Of Interview: 8/10/07
Interviewer: Cynthia M Mc Grath (Fisi)
Kid's Full Name: Jeisy Jojana: Aguaiza Ht: 513" Wt:
Parent/Guardian Name: Florentina Sibri
Address:
Contact Phone #:_
Seating position (Show bus seating chart): $Row 10 - window$ Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Walked Ambulance POV
Hospital Name: Children's Hospital on Chicago Ave.
Admitted, T&R, N/A: X-rayed and contacted her next day of told she had a fractured vortebrae. Has back brace.
What type of injuries did you get?
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) Jeisy was askep to heard frailer honking - everyone looked her, next thing she knew the bus was falling. Saw, dust, heard noises from buses (banging) hitting things thick; didn't smell anything Shert after bus stopped falling the Jeremy opened door the students got off the bus. Got off bridge
Silent after bus stopped falling to their Jeromy opened door to the students got off the bus. Got off bridge by people helping to then went and sat on grass. Were told to so to the Red Cross.




Date Of Interview: 8/10/2007
Interviewer: SA Cynthia M ME Grath (FBI) Kid's Full Name: Aisha Roble Ali Roble Doesn't hum! Wt:
Kid's Full Name: Aisha Roble Ali Roble 1808: Doesn't hum! Wt:
Parent/Guardian Nam
Address:
Contact Phone #
Seating position (Show bus seating chart): See Row 2 - window Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No howsp. How? Ambulance POV Aunt took her/on 8/10/07
Hospital Name: Children's hospital near a closed gas station
Admitted, T&R, N/A: N/A - checked up - school.
What type of injuries did you get? None.
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) Was sleeping and was awakened by kids screaming. Next thing she knew peop staff member, Julie Grace, was bleeding. Then Jeverny kicked out the Coolers, they fell into the water and then he kicked open the back door. After getting off the bus went to the Red Cross.

169



Date Of Interview: 8/10/2007
nterviewer: St. CHOYLES D GETAL MOL
Kid's Full Name: Kym/ Henlary Warkins LOB Ht: #5'5" Wt: 115
Parent/Guardian Name: Part Kay Warking
Address:
Contact Phone #:_
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name:
Admitted, T&R, N/A: AMED HEATH PORTHERS PLUISE LINE 8/3/07
What type of injuries did you get? BAD HEAD ACHE 8/1/07-8/3/07 SORE HECK NULSE RECOMMEND ICE PACK FOR "MILD WIMPLASH")
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) - I CORETE IN LETTLE OF BUS STACKED UNTED DE ENCH OFFICE UN RIGHTSIDE OF PATTINEZ - FELT A BIG POTHOLE, SAT DOWN, - FELT D BIGHT SIDT INTO ASLE BUT SIPPORTED SELF UN STAT TO PREVENT FINLING - LUST T DEBLIS CAME INTO AIR OF BUS. - SAW NINA SCUMPED TO LETT IN STAT. - TILTING CAME TO BACK OF BUS AND CATALTA REAL DOOK. TEQUIPMENT PEOLOGICAL OUT BACK. RYAN HEAPTH TELETH. - MIN OTHERS (3.4) GET OFF BLIDGE.
THOUGHT WAS AN ACCIDENT UNITED SAW BRIDGE WINLE OUTSIDE BUS. - HAS TO FIT LEAST BECAUSE DOCK BLOCKED BY CEMENT GENDERS



SGT CD GREEN MPA.

(A-30)

Date Of Interview:
nterviewer: St. Computs J. CREEN Mp.A.
(id's Full Name: MOHAMES ALI ROBLE DOS THE 53 Wt: 124
Parent/Guardian Name: ALI FARHA
Address:
Contact Phone #:
Seating position (Seatled next to and around them and put them in chart as well as using arrows.
Transported to Hospital: How? Ambulance //=5 POV
Hospital Name: HTTHEDIN COUNTY MEDICALLENTER
Admitted, T&R, N/A: HAMITED ROY TESTS POST ACIDENT TESTS POST ACIDENT CASS
What type of injuries did you get?
Bump un FUREHEAD ONTA LEATTYE
For SUPPULA INJULTA/SOLE SORE MUSCLES
SOFE TIUSCLES
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
BETCHE ACCIDENT HETEL SOUND DESCRIBED AS METAL BENDING/SQUEEKING. HEAR
SAN A DELIVER PASS ON LETT SIDE OF BUS AND CLASH INFAUNT STRATED ON FIRE- ALIVER COULD NOT BET OUT
SAN A LEGIVER I PASS ON LETT SIDE OF BUS
DRIVER Could HOT BET OUT
RIAGE AVENT DELLE FAST " ALANGE SEE FALL




Date Of Interview: 8/10/2007
nterviewer: D. COLLINS (NTSB)
(id's Full Name: EICARDO RAMER 12-AVELLEZ Ht: ULF Wt: UNK
Parent/Guardian Name: MARIA + JOSE ALMEREZ-AQUEAR
Address: UNENGWA
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name:
Admitted,T&R, N/A:
What type of injuries did you get?
BUISE, C) ARM UNPERSIDE
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) Trailer to left, pished bus over to left.
then bridge Fell.

(4-5)
Date Of Interview: 8/10/2007 Interviewer: D. Collins (W15B)
nterviewer: D. Collins (WTSB)
(id's Full Name: <u>AMAR ELGHORAB</u> Ht: <u>52"</u> Wt: <u>82 /6</u>
Parent/Guardian Name: EMAN AST
Address:
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Fransported to Hospital: Y No How? Ambulance POV
Hospital Name:A
Admitted, rain, rva.
What type of injuries did you get?
BACK, LEFTSIDE SPINE
DRX2
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) Went to AMR DAVID, CAMERON Noise life over a bump Remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) PAVID, CAMERON Remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
Moise like over a bump
Jereing Saved everybooky - pushed coolers out of way
all out back-main door was squished
Down to side walk until truck fire -
Staff fold to run:




Date Of Interview:
nterviewer: DCCKLINS CINTSIS)
Kid's Full Name: ANA BUENCES Ht: 5'2" Wt:
Parent/Guardian Name: ELFEGO VENCEST REYNA BARCIA
Address: Description
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name: ABBOT
Admitted,T&R, N/A:
What type of injuries did you get? went to churoproctor - Scelling 3x week
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw). Was fold fainted zafter off bus Alexis under scat after
Jeremy Kicked Rear door open-out, he food can't remember crash






Date Of Interview: 8 10 07
Interviewer: SA Brian Blanch
Kid's Full Name: Amy Sebrina Newlet Carrillo Ht: wt:
Parent/Guardian Name: Clemente Naula, Margarita Carillo
Address:
Contact Phone #:_
Seating position (Snow ous seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: How? Ambulance No
Hospital Name: HCMC
Admitted(T&F, N/A:
What type of injuries did you get?
Low to mid been sprein
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw)
Playing games with friends, felt bumps, Smelled smore. Once feeling bumps, felt bus felling. Thought I was going
to fall into the water.



Date Of Interview: 8 10 07
Interviewer: SA Brian Blanch
Kid's Full Name: Canzan Harris Mattson Ht: 4'3" Wt: 59
Parent/Guardian Name: Erika Taylor - Tyrone Mattson
Address:
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name: Childrens Hospital
Admitted,T&R, N/A:
What type of injuries did you get? Scretches on neck, Mees benged up, Oorgh.
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) We started falling, and when we landed, dust dame into the bis. When we fell, we want upwards. People on bus scared and crying, People said we were going to die. It will take me awhile to not over this.
When we fell, we want upwards. People on bus scared and crying, people said we were going to die. It will take me awhile to get over this




Date Of Interview: 8 10 07
Interviewer: SA Brian Blanch
Kid's Full Name: Creole Ava Taylor Ht: 311" Wt: 55
Parent/Guardian Name: Erika Taylor / Tyrone Mattson
Address:
Contact Phone #:_
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name: Children's Hospital
Admitted,T&R, N/A: T&R
What type of injuries did you get?
Prin in legs
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) We started to fall, then we landed, then there was
ZIOT PERST. SEW that part of the prige was created
during time of accident



(A-30)

Date Of Interview: 8//0/07	<u> </u>			
nterviewer: DETECTIVE	JOHN SEERY :	\$395 HCSO		
Kid's Full Name: MAIARU -	JUBNITA LEO	HORI) Ht:	407	_ Wt: 75-80 10
Kid's Full Name: MARNO -	NDA KAN LE	UNARI)		
Address:				
Contact Phone #:_				
Seating position (Show bus s Ask who they were seated ne		nd put them in chart as we	ell as usin	g arrows.
Transported to Hospital: How?	Y Ambulance	No POV	_	
Hospital Name:				
Admitted,T&R, N/A:				
What type of injuries did you	get?		7	
	NONE			

What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) Driptinh Off To Sleep, worke up when Heard of ISIL CRASH. FELT like Bus was FALLING, 1715 AND STOPPED. SAW PEUPLE BLEEDING BAD FALLIAN CUT OF SEAT. JERBANG CIRBRED JIHR SAIT AND STOPPED OF SEAT. JERBANG CIRBRED JIHR SAIT AND STOPPED ILFTING KIDS ONT OF THE BUS. GOT OFF BUS AND WENT TO LEASEN BUS.



(A-30)

ate Of Interview:
iterviewer: DETECTIVE JOHN SEERY #395 HCSO
id's Full Name: OLIVIA JAYNE REYNOLDS Ht: 400 Wt: 78/BS
arent/Guarrian Name: VICTORIA LINDHUM
ddress:
contact Phone #:_
eating position (Show bus seating chart): sk who they were seated next to and around them and put them in chart as well as using arrows.
ransported to Hospital: How? Ambulance POV POV
Hospital Name: Nonth M Emoning L
Admitted, T&R, N/A: T+R
Vhat type of injuries did you get? Hunt CHEST + NECK (WHU/ISSH), BOTH MINOR.
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) DNINNU- AND THE BUS STANTED TO SITAKE AND TITEN THE BUS STANTED TO FALL, ONCE BUS STOPED FALL, NE (STNAIGHT DOWN) IT STANTED TO ROLL FORWARD. DUST AND

RUIKS, DEBRIS, WATER (MIST) LAME THOUGHT WINDOWS.

JEREMY SEARCH KICKED OPEN REAR EMERIENY DOOR.

STARTED HANDING KIDS TO BIKERS THAT STOPPED TO

1481P. BIKERS (DICYCLE) CAMPE From 131 KB TRAIL ON BEAUE?




Date Of Interview:	07			
nterviewer: DETECTIVE	L JOHN SERRY	#395	Hesu	
Aid's Frankland PAN BU DOR Parent/Guardian Name:	g maria Hae N/A	ery.	Ht: SOY	Wt: <u> / (()</u>
Address:				
Contact Phone #:				
Seating position (Show bus Ask who they were seated n	next to and around them a	and put them in o	chart as well as usir	ng arrows.
How?	Ambulance X	POV		
Admitted,T&R, N/A:_	T+R		.	
What type of injuries did yo	u get? Sone BA	ck bmd c	HEST	

What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and BOS WAS DRIVING HEROND SEMI HONK, OBSBRURD saw) SAME SEM, POSS BUS. BUS WANT UN AND THBN DOWN, DUBS NOT REMISER FALLING DUNN. CAME TO A STOP. OBSERVED CONCRETE POILING TOID BURRAUNE TO GRT OFF THE BUS, AMERICA HRIVED EVERY ONE CIOUN DOWN AND TO GET OF THE BALL BUIT. DID NOT KNOW THE BRIDGE FELL WINTIL SIDE WAS WK IS AND LOUKED BACK.




Date Of Interview: Quant 10, 2007
nterviewer: Tom Hendrickson #2960 MPD
(id's Full Name: BeTsy Calle Nayla Ht: 4'0 Wt: 70
Parent/Guardian Name: Sara 9180rs old
Address:
Contact Phone #
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No No POV_Paint took her to hospital
Hospital Name: Dolsnit Know
Admitted,T&R, N/A:
What type of injuries did you get? Shoulder injury
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) The bus was driving along. The bridge separated and we went Boom, Boom we were falling and after the bus landed, my older cousin and fernang helped me get off the bus.



Imahni Taylor Henderson

Date Of Interview: 8-10-2007
nterviewer: Jon Hendrickson #2960 MPLS. MIRPD
(id's Full Name: Imahni Henderson Ht: 514 Wt: 119
Parent/Guardian Name: Erka Taylor - TYRONE MATTSON
Addressi
Contact Phone #
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No No How? Ambulance POV Mom Drove legitory Hospital Name: Childrens_Male
Admitted, T&R, N/A: Examined and released
What type of injuries did you get? no injury at time of accident - now being treated
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and saw) Children returning from swimming trip. Driving on the road the felt that the his had hit a big Bump. She then felt as they were folling. It seemed that we were fall forever "I The his hit another has big himp. There was a Cloud of dust, Jeremen opened the emergency door and said we got out we left the lus and I couldn't believe the bridge feel.



· Tyrone Matson Tr.



Date Of Interview: 8/10/07
interviewer: 5A Dearl Chypell FF
Kid's Full Name: Tyrone Taylor-levet Matson JR. Ht: 59.5" Wt: 84#
Parent/Guardian Name: Tyrone Matsun
Address:
Contact Phone #:
Seating position (Show bus seating chart): Ask who they were seated next to and around them and put them in chart as well as using arrows.
Transported to Hospital: Y No How? Ambulance POV
Hospital Name: HCMC
Admitted, T&R, N/A: Telegraph.
What type of injuries did you get? Shoulder, neck, - Back side, Sligh, Bruising.
Still has some Slight poin on Top 12 right should. Burps on head.
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and

saw)

Playing of cameron his burns, Then flying indir, hit head on citing. All on shoulder in viste, when of bus supped moving, everyone was aviet. Telemonto got up and kicked me back down upon. Then everyone got out the back of bas Kim + Julie were stillon bus. Jimmy houses got Kinny + Tulie off lass Kinny Was passidout. Felt Should pop when exiting lass. Penentus all The rows on The brige and in the mater. Was mad that the bright fell. everyone was crying 192nd asking to use well phones. very Territyad.



ate Of Interview: 6/16/07	
terviewer: 5A Dean Chappelle Dean Chappelle	
terviewer:	_
arent/Guardian Name: Tyline Mattson Ericka Taylor	
ddress:	
ontact Phone #:	
eating position (Show bus seating chart): sk who they were seated next to and around them and put them in chart as well as using arrows.	
ransported to Hospital: Y No How? Ambulance POV	
Hospital Name: Children's Hospital, MPLS	
Admitted,T&R, N/A: TeR	
Scratch on right love by. Scratch on right foot. Bruise on right foot. legs were having.	
What do you remember from the accident? (Interviewer: If possible ask them what they felt, smelled and	
telt 7 bumps. 1 little, 1 big.	
everyone Execusing, aring. Trying reger our	
- Teremy Kicked The back down a helped him getout.	
- Say Semi- on fire. Police coming.	
Bus driver was STII on bus -	
that he put on his continuous	

Isaiah Matton Topical Taylor

- Creole

- Morres

- Morres Santiflas 5.54en g wros Sulamon -Jolean

ISTH-35W Bridge Collapse Interview Questionnaire

	Date of Interview: A - / 1 ime:
	Interviewer: Detection file of 14050
	DRIVER Wagner, Wilfred Joseph
	Driver's License Number:
	Full Name Hame DOB:
	Full Address
	Telephone Home: Work: Cell:
	Compliance with DL restrictions: Glasses, etc YES NO NA
	Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
	Ejected: YES (NO)
	Safety Equipment used: Belts: LAP SHOULDER BOTH
	Transported to Hospital YES NO Walk-in Hospital Hospital CMC
	Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
	B Non-incapacitating injury - Cuts, bruises, scrapes
	C Complaint of injury with no obvious injury visible
	Places avalain vibore von vore on the bridge (direction of turned DVD (CD1) which land
	Please explain where you were on the bridge (direction of travel [NB SB]) which lane, refer to bridge diagram):
6	ecame shakey. Then down
	193

	chool D	(L)	14	lids
What did you see, feel, hear, a sensation is described – mo				
		:		
VEHICLE:				
What vehicle were you in? Make futer WA Plate: Insurance Company:		Jak 7	C.e.	ital
Who else was in the vehicle 1.	with you? NA (Nat Seat Position (See above)	ne, address, phoi Injured?	ne, DOE YES	•
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
	· ·			

Additional notes/comments:

5.

6.

Seat Position (See above)

Seat Position (See above)

YĖS

YES

NO

NO

Injured?

Injured?





|--|

DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	32

RECORD OF INTERVIEW

Brian Sturgill

Interviewed August 10, 2007 by phone

Sgt. Steve Wagner of the Minneapolis PD conducted this interview after the interviewee called him back on his cell phone. The interviewee lives in San Diego, California.

Brian Sturgill



Mr. Brian Sturgill stated he was driving northbound in the right lane, going very slowly, in a silver 2007 Chevrolet Impala, which was a rental car. According to Mr. Sturgill, the first thing he felt was his car shaking. He saw the bridge break apart in front of him and felt like he was freefalling then stopped. According to Mr. Sturgill, he started to freefall again and ended up with the back end of his vehicle in the river and filling up with water. Mr. Sturgill stated that he initially couldn't open his door so he tried kicking out the windshield. He said that the car shifted and he then was able to open his door and climbed to the bridge.

According to Mr. Sturgill, he was told that he sustained some compressed disc in his back and was released.

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-10-07	Time:	600 PM	1
Interviewer: Sgt. Steve	Wagne	r	
Date of Interview: 8-10-07 Interviewer: Sgt. Steve DRIVER Bran Sturgell Driver's License Number:	Ü		
Driver's License Number:		State: CA	
Full Name Brian Sturgi	.[]	DOB:	
Full Address			
Telephone Home:	Work:	Cell:	
Compliance with DL restrictions: G	lasses, etc	YES NO	NA
Seat Position: Front Seat Middle Seat Rear Seat Bus occupants see diagram	Driver Left Left	Center Center Center	Right Right Right
Ejected: YES NO			
Safety Equipment used: Belts:	LAP	SHOULDE	REPOTH
Transported to Hospital What Ambulance Service: YES	NO Walk-	in Hosp	pital University Fairuleu
Nature of Injury (Circle): A Incapacitating An in	g injury – broke ability to perfo	en bones, <u>hos</u> rm a task they	could do before injury.
B Non-incapaci	itating injury -	Cuts bruise	es, scrapes

Please explain where you were on the bridge-(direction of travel [NB SB], which lane, refer to bridge diagram): I was driving NB in the right lane. Traffic was very slow. There was a Cadillac in the left lane next to me. I remember the car started to shake and at first I thought it was an earthquake. I don't remember hearing anything. I saw 196 the bridge break apart in front of my car. I don't remember any other cars in

Complaint of injury with no obvious injury visible

C

				_
Nave Struck the I was looking what other vehicles or people were they doing? Water There was a seat area sto going to go what distyou see, seel, hear, a sensation is described, me	started to free I started to free I started to free e rear of my of up and the book word around you? (Color, may be arting to fill will and smell relative to the crast overment left to right, forward out to but it would but it would but it would be able to open accounted on	ake, model, do A Pritty The water drown. 1. (Please ask and back, up or	ny Coscription Smol	ar was in the hought I was tried to kick
What vehicle were you in?	Rental			
Make (how) Plate Insurance Company:	Model Impala Year Owner: Policy Number		Silv	er
• • • • • • • • • • • • • • • • • • • •				•
Who else was in the vehicle 1.	with you? (Nam Seat Position (See above)			
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO .
5.	Seat Position (See above)	Injured?	YĖS	NO
	Seat Position (See above)	Injurad?	VEC	NO

Additional notes/comments:

I climbed onto the bridge and sow the Cadillac I had noticed before. The driver was bleeding from his head He was in the water. I grabbed a 2x4 and I was able to pull him toward me onto the bridge. A rescue boat took us to the shove and I was transported to the hospital in the back of a pick-up track.

They took x-rays and told me I didn't have any broken bones but there were discs that had been compressed. I was released from the ER. I have spoken to the Univer of the Cadillac since the incident. His name is Omar and he lives in Texas.

C



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-28-07 Time: 130
Interviewer: RONK
DRIVER
Driver's License Number: State:
Full Name OMAR AbuAbARA DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NA
Seat Position: Front Seat Oriver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital FAIRVIEW U of M What Ambulance Service:
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

Complaint of injury with no obvious injury visible

on a conference call, HDG M/B in FAR [] lane going ~ 30 mph

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

	· ·	· ·				
<u></u>	What did you see, feel, hear, a sensation is described—mo I femender Ke Dominos fell. Closed my VEHICLE: Isau bo What vehicle were you in?	and smell relative to the crassovement left to right, forward See my bridg I shell holy eyes screamed adge collapsing				ofmo 163, heard 4t.
	Make CACIIIa C	Model CTS Year Owner: Hertz	07 Color	Sil.	IUR	
:	Insurance Company:	Policy Number	er:	<u></u> .		
	Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)		, DOB) YES		
	2.	Seat Position (See above)	Injured?	YES	NO	
:	3.	Seat Position (See above)	Injured?	YES	NO	
	4.	Seat Position (See above)	Injured?	YES	NO	٠ · · · ·
	5.	Seat Position (See above)	Injured?	YĖS	NO	
•	6.	Seat Position (See above)	Injured?	YES	NO	

Additional notes/comments:

Bruised Bluey Pribs Oclavicle, hards out.

Bruised Bluey Pribs Oclavicle, hards out.

CAT SCARS X-RAYS 200 Numbress in feet. BACK

Fender in Hosp til SAT. Abnormal Lactic ADD count.

63"265"

until water Ko'D it. I thought I was deing. Water coming in. I broke window behind me. got out. I struggled getting seat belt of I somehow broke window. I get out, standing on I somehow broke window. I get out, standing on back of cak. I realized a fuel tanker close to me back of cak. I realized a fuel tanker close to me Light colon CAR near me, people left it in and yot out, It started smoking. I was Afraid it got out, It started smoking. I was Afraid it got out, I swam to way of gas from tanker leaking. I swam towards Brian who was on bridge got up on Bridge. I used his cell to call my DAD to let him know I was Alive.

the

Swam to book w/ Bein Sturgill, Andic got taken to shore i dropped off, walked around looking for Ambulance, City of Mina Platenek we ask him to help us He Refused not enough room. Iwas shocked He had a smill smile on his face I assed him out, canister of some short in his bed. I Asked how to take giels At least He said NO ROOM. Blood long straight hair. grig dude. Climbod up to street level another pla Stopped to helpus. We hopped inbadicanel we were taken to Hosp.

DAVE



B
ISTH-35W Bridge Collapse Interview Questionnaire
Date of Interview: $08/66/67$ Time: 1836
Interviewer: Détective Brian McKagne HCSO
DRIVER
Driver's License Numbe
Full Name Kelly whittlinger Kahle DOB:
Full Address
Telephone Home: NONE Work: Cell: 6
Compliance with DL restrictions: Glasses, etc YES NO N
Seat Position: Front Seat Oriver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES (NO)
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES (Walk-in Hospital Melhodist What Ambulance Service: Walk-in Hospital Melhodist
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge -(direction of travel [NB] SB], which lane, refer to bridge diagram):

Left Lane - center of bridge

South end of center span

were they doing? Silver 2 Sur's Side 2 worm What did you see, feel, hear a sensation is described - no road a hear ro	car behind in the car behind in the side a head one sor, I women in an	him I bill offer sh? (Please asl and back, up of offer offe	SyV s for spe or down of	man go alon vicle new cifics if	of on
What vehicle were you in?					
Make Staturn Plate:	Model L300 Year Owner: Yes	20=/ Colo	r <i>5,</i> 7/	ver	
	ican family Policy Numb	er:		_•	
Who else was in the vehicle 1. Kinberly Brown	e with you? NA (Nan Seat Position (See above) Front Right	ne, address, pho Injured?	one, DOI YES	B) Scrapes	
2.	Seat Position (See above)	Injured?	YES	NO	
3.	Seat Position (See above)	Injured?	YES	NO	
4.	Seat Position (See above)	Injured?	YES	NO	·
5.	Seat Position (See above)	Injured?	YĖS	NO	
6.	Seat Position (See above)	Injured?	YES	NO	

Additional notes/comments:

ISTH-35W Bridge Collapse Interview Questionnaire

17	2011 2011 2011 2011 por incorvion Questionnaire
	Date of Interview: 8-6-07 Time: 1810
	Interviewer: Detective Dan Kinty / HCXX
\$ 2	DRIVER Passinger: Kimberly Joo Donies
	Driver's License Number Stote In 1 Beaux
	Full Name DOB:
	Full Address
	Telephone Home: Work: Cell:
	Compliance with DL restrictions: Glasses, etc YES NO NA
	Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Response to the Center Right
	Rear Seat Left Center Right Bus occupants see diagram
	Ejected: YES NO
	Safety Equipment used: LAP SHOULDER BOTH
	Transported to Hospital YES NO Walk-in Hospital 10 P.M. What Ambulance Service:
	Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
	B Non-incapacitating injury - Cuts, bruises, scrapes
	C Complaint of injury with no obvious injury visible
e de	Please explain where you were on the bridge –(direction of travel NB SB], which lane, refer to bridge diagram):
Jogan	refer to bridge diagram): Length of the bridge diagram then bridge diagram then bridge diagram.

What other vehicles or people were they doing?	le were around you? (Color,			
a concation is described - me	and smell relative to the cra evement left to right, forward in Illy	l and back up of	r down e	tc)
VEHICLE: MM	MC3ZZ			
What vehicle were you in?			~1	
Make Atur Plate:	Model 230 Year Owner: Keely	Color	SI.	ger Kahl
Insurance Company:	Policy Num	ber:	·	<u>.</u>
Who else was in the vehicle 1.	with you? NA (Nat Seat Position (See above)	ne, address, pho Injured?	ne, DOF YES	•
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

5.

6.

Seat Position (See above)

Seat Position (See above)

Injured?

Injured?

YĖS

YES

NO

NO

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8/8/07 Time: 100
Interviewer: D.COLUNS NTSB C.GREEN MPD DRIVER
Driver's License Number:
Full Name KRISTIN DEANNH WEST DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA READ
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital CLINE ROCCOWIN
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes MILOCONCUSSION Compleiet a Sinital Ville Concustor Muscle ACHES
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing? FRONT: BLACK, POS COMPACT IN LANE

LL : SILVER OR WHITE 4-DR SEDAN FROM MEDGE FROM WASH

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

PACKED UP @ MERGE, SUST FREEING UP 3-4 REPAR IN STEM PATTERN

BLAKES IN FRONT, RUMBLE, ROCKING SIDE-TO-SIDE, UNCLEAR ON TIMES
WAS NEAL WORKERS, POFFS OF DUST ARROUND STARTED TO FALL - MOTION

FREING FOLWARD & TORIGHT, SPAN DEOPPED, HZO & CALLED HOSB 1805

VEHICLE: NOW IN LEFT LIN – NO MOVE FORWARD AFTER LANDING

BLITED THROUGH PASS IDE

What vehicle were you in?

Make CHEUT

Model TRAILALAZER

Year 2005 Color BLACK

Owner: WEST, FRISTIN

Insurance Company: American Franky Policy Number:

who else was in the vehicle		ne, address, pho	one, DOE	3)
1.	Seat Position (See above)	Injured?	YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YÈS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

12



HENNEPIN COUNTY SHERIFF'S OFFICE INVESTIGATIVE REPORT Case # 07-00-2714

This follow-up report is dictated by Detective Ralph Clark on 8/3/07. Mary Vawracz typing on 8/3/07 at 9:49 AM.

SYNOPSIS

This report pertains to a phone interview of KRISTIN DEANNA WEST on 8/3/07

1.	On 8/2/07, Kristin Deanna West,		
	MN, home phone	cell phone	reported to HENNEPIN
	COUNTY SHERIFF'S PATROL	DEPUTY FELBER that s	she was driving her black
	Chevy Trail Blazer, MN plate	northbound on	the 35W bridge when it
	collapsed.		

- 2. On 8/3/07, I, Detective Clark phoned West and conducted a phone interview. West provided the following information.
- 3. West was driving home on the 35W Mississippi bridge northbound in her black Chevy Trail Blazer, MN plate when the bridge collapsed. West's vehicle road the bridge down to the river then came to a rest. West was not injured, but shaken up. West exited the passenger side door of her vehicle and was transported to shore by boat. West was advised by officers at the scene to wait for an ambulance to transport her to the hospital, but got mixed up in the crowd and was escorted away from the scene. West was later picked up by her husband at 12th and University Avenue.
- 4. I gave West my contact numbers and advised her that a report would be written. West was thankful.

REC:mkv...027







					, , , , , , , , , , , , , , , , , , , ,
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	22


RECORD OF INTERVIEW

Suzanne M. Blundell

Interviewed August 7, 2007 at Ms. Blundell's residence

Present during the interview was Elizabeth C. Wunderlich, a passenger in Ms. Blundell's vehicle, Ms. Blundell's mother, NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD


Suzanne Blundell (5'2", 120 lbs.)



Ms. Blundell stated she and her passenger Elizabeth Wunderlich, were driving northbound in the left lane at the north end of the bridge in her silver 2003 Nissan Pathfinder. According to Ms. Blundell, the first thing she felt was the bridge shaking and swaying. Ms. Blundell said that she felt three distinct drops. According to Ms. Blundell, the last drop, her vehicle fell into the river and was showed with debris. Ms. Blundell stated they went out the driver's door and were picked up by a boat and taken to shore.

According to Ms. Blundell, she sustained only a sore neck and back.

Elizabeth Wunderlich Same address as above



According to Ms. Wunderlich, she first saw a wave of concrete coming at them. She said she felt the car drop down then drop down a second time. Ms. Wunderlich stated that they fell into the river and were showed with debris on the way down.

According to Ms. Wunderlich, she sustained only a sore neck and back.

B-5)

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: $8-7-07$ Time: 2^{85}
Interviewer: Row K
DRIVER
Driver's License Number:
Full Name Suzanne M. Blundell DOB:
Full Address HT 5'2" wT 120165
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES (NO)
Safety Equipment used: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital U of M Far RVI-ew What Ambulance Service:
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

We were NB in far Blane near U of M Exit in middle section in River. Wegotout called my nom, wonted. A boat come broughtus to shore. Ent's said to walk if ok and get a RIDE. We went to Hosp

were they doing? A black CAR SEDAM front of us, to left WES A b) ACK SUV What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) I felt shaking and a sway a bunch of Rocks Debris flew at my wndow Dropped to bottom in River we felt 3 distinct drops prior to hitting VEHICLE: hottom What vehicle were you in? Make NISSAN Model Pathfinderear 03 Color Silver Plate: Owner: Georginne Blundell Insurance Company: All State INS Policy Number: (Name, address, phone, DQB) Who else was in the vehicle with you? NA Seat Position (See above) Injured? Sizabeth Right front. 5"135 NO Seat Position (See above) Injured? YES Seat Position (See above) Injured? YES NO Seat Position (See above) Injured? YES NO YĖS NO 5. Seat Position (See above) Injured?

YES

Injured?

NO

What other vehicles or people were around you? (Color, make, model, description), what

Additional notes/comments:

6.

Neck! BACK PAIN CT SCAN ADMITTED UNTIL FRIDAY PM.

Seat Position (See above)

I SAW A WAVE of concrete coming @ us. CAR Shook. Jolted down, shook again jolted down again. Then we fell all the way down. All this debris came down on us. wouted got out drivers door. Wagot a RIDE of boat to shore



ISTH-35W Bridge Collapse Interview Questionnaire

Time: 1835 Date of Interview: Interviewer: DET. STEVE KRITZECK DRIVER Driver's License Number State: MN Full Name EMILY ANN PADEN DOB: Full Address Work: *MA* Telephone Cell: Home: NA CONTACTS Compliance with DL restrictions: Glasses, etc NO Seat Position: Front Seat Driver) Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram YES Ejected: Safety Equipment used: Belts: LAP SHOULDER BOTH Walk-in Transported to Hospital YES Hospital NORTH What Ambulance Service: Nature of Injury_(Circle):

Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. BROKEN BACK

В Non-incapacitating injury - Cuts, bruises, scrapes

C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram): B6 N. RIGHT LANE

What other vehicles or people were around you? (Color, make, model, description), what were they doing? No

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

SAN BRIDGE RISE UP IN FRONT OF HERE CAR BEGAN ROLLING BACKWARDS & THEN FELL

VEHICLE:

What vehicle were you in?

Make PONT. Model GRAND PAIX Year '04 Color BLACK Plate: Owner: SAME

Insurance Company: STATE FARM Policy Number: Who else was in the vehicle with you? (Name, address, phone, DOB) Seat Position (See above) Injured? YES NO 2. Seat Position (See above) Injured? YES NO YES 3. Seat Position (See above) Injured? NO YES NO Injured? 4. Seat Position (See above) Injured? YĖS NO 5. . Seat Position (See above) Seat Position (See above) Injured? YES NO 6.

Additional notes/comments:

NOTEC.








DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	17

RECORD OF INTERVIEW

David Ostrowski

Interviewed August 7, 2007 at Mr. Ostrowski's sister's residence Present during the interview was Mr. Ostrowski's sister, NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

David L. Ostrowski (5'9" 240 lbs.)



Mr. Ostrowski stated that he took several photos with his cell phone and agreed to send them to this investigator.

According to Mr. Ostrowski, he sustained a compression fracture to T-12 along with neck soreness.

Mr. Ostrowski stated that he normally wears his seat belt but was not wearing his lap and shoulder belt on this trip.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	23

RECORD OF INTERVIEW

Amy Lindholm

Interviewed August 7, 2007 at Ms. Lindholm's place of business.

Present during the interview was a friend of Ms. Lindholm's, NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Amy Lindholm (5'4" 180 lbs.)



Ms. Lindholm stated she was driving northbound in the far left lane in the center section of the bridge in her silver 2004 Saturn L200. According to Ms. Lindholm, she was on her cell phone when she first thing felt a rumbling then heard a boom and heard metal twisting and saw part of the bridge in front of her go down. According to Ms. Lindholm, after getting out of her vehicle (unknown how), she initially tried to help a person stuck in a car that was floating in the river but jumped off after it started shaking. Ms. Lindholm stated that she then helped two injured construction workers.

According to Ms. Lindholm, she sustained a bruised left knee, and her back and neck are still very sore. Ms. Lindholm stated that she was wearing her seatbelts.

Date of Interview: 8-7-0 (Time: // AM
Interviewer: Rook
DRIVER
Driver's License Number: IN CAR State: MN
Full Name Amy Lindholm DOB:
Full Address
Ht. 54" WT 180/bs.
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital Unity
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB], which lane,

I was NB in far Dlane, I was exphone felt bridge go down.

I climbedon car seemy this person couldn't get out I was supped course it was a haking. I climbed off onto bridge I saw a couple hunt construction in water lying helped clean their cuts. I trucks (construction) in water lying couldn't get out.

Resue boots took me to shore worth size

1	What other vehicles or people were they doing? CAN Home of we. Ether black CAR	e were around you? (Color, m + Really Rembersherry Engel E	ake, model, desc H. b/AC Orcteon	ription L), what CARIN Front of
	What did you see, feel, hear, a sensation is described—mo feel fumbling seemed like it vehicle: dust.	and smell relative to the crash vement left to right, forward a then boom head bridge twee commy	أمسم يسدد والممط المسا	- 4مما	
	What vehicle were you in?				
	Make Saturn Plate:	Model L200 Year of Owner: NAMEY LING	2004 Color 1holm.	Sil	vel
	Insurance Company: Proc	ressive. Policy Number	r:		
	Who else was in the vehicle 1.		e, address, phone	e, DOB YES	
	2.	Seat Position (See above)	Injured?	YES	NO
	3.	Seat Position (See above)	Injured?	YES	NO
	4.	Seat Position (See above)	Injured?	YES	NO .
	5.	Seat Position (See above)	Injured?	YĖS	NO
	6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

Bruised @ Knee, Neck & Back very sore painful TER

Date of Interview: 8-6-7	Time: 1800	
Interviewer: KRITZECK -HCSO		
DRIVER		·
Driver's License Number	State: MN	
Full Name KEVIN WILLIAM KOPELKI	E DOB:	
Full Address		· · · · · · · · · · · · · · · · · · ·
Telephone Home ork:	952-253-268 4 Cell:	
Compliance with DL restrictions: Glasses, e	etc YES NO	NA
Seat Position: Front Seat Driver Middle Seat Left Rear Seat Left Bus occupants see diagram	Center Center Center	Right Right Right
Ejected: YES NÔ		
Safety Equipment used: Belts:	LAP SHOULDER	ВОТН
Transported to Hospital YES NO What Ambulance Service:	Walk-in Hospi	ital
Nature of Injury (Circle): A Incapacitating injury - An inability to		italized, severe cuts could do before injury.
B Non-incapacitating in	jury - Cuts, bruises,	, scrapes
C Complaint of injury w	vith no obvious injury	visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram): \mathcal{N} – \mathcal{LEFT} \mathcal{LANE}

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

HE WAS BEHIND SHETLY ENGEBRETSEN'S BLK. MERGADES

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

CLOND OF DUST-LOND NOISE- SMOREN DROP STRAIGHT DOWN

Model GRAND MARK Year 92

Owner: SAME

Color

VEHICLE:

What vehicle were you in?

Make MERO

1 late	Owner. Shore			
Insurance Company: Amen	Family Policy Numb	er:	· ·	-•
Who else was in the vehicle	with you? (NA) (Nam	ie, address, pho	ne DOF	3)
1.	Seat Position (See above)		YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments: GoT out THROUGH DRIVER'S WINDOW

NOTEN

201907 Time: 1318 Date of Interview: Interviewer: SAMAHSNEII, FBI DRIVER Driver's License Number: State: MV Full Name Kevin William Kopelke DOB: Full Address Telephone Home: Work: Cell: Compliance with DL restrictions: Glasses, etc YES NO Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES /NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital YES (Walk-in Hospital What Ambulance Service:

Nature of Injury (Circle):

A Incapacitating injury – broken bones, hospitalized, severe cuts

An inability to perform a task they could do before injury.

B Non-incapacitating injury - Cuts, bruises, scrapes

C Complaint of injury with no obvious injury visible

Backpain, armpain, nedepain

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

NB - far left lane, north and of center span

Slow speeds, Kopelhe estimates less than 10 mph.

What other vehicles or people were around you? (Color, make, model, description), what were they doing? RUSL Now traffic, vehicles in front of back of and next to Hopelies, not sure what type.

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

gee back sheet-

VEHICLE:

What vehicle were you in?

Make Mercury Plate:	Model Grand Nargo Year Owner: Kevin Kopelke	1992 Color	Bloc	k-
Insurance Company	rafamily Policy Number	er:	<u>:</u>	_doesn't know.
Who else was in the vehicle		e, address, phor	ie, DOI	B)
1.	Seat Position (See above)	Injured?	YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

Interviewed by Dennis of NTSB

Blo

ISTH-35W Bridge Collapse Interview Questionnaire

D	Date of Interview:	8-23-0	7 Time:	0900	
Ir	nterviewer: Tom	Hendri	ckson		
Eric L	DRIVER C Wayn (Driver's License No un Name Uayn e H ull Address ,			State: MN DOB:	/
	elephone Ho	L restrictions: G	Work lasses, etc	/ Cell: YES NO	NA NA
Se	eat Position: Bus occupan	Front Seat Middle Seat Rear Seat ts see diagram	Driver Left Left	Center Center Center	Right Right Right
Sa Tr	jected: YES afety Equipment us ransported to Hosp That Ambulance Se	ital YES		SHOULDER n Hospit	
Na	ature of Injury (Ci A	Incapacitating An inal	pility to perform	n a task they co	alized, severe cuts ould do before injury.
Ple	•	you were on the	njury with no o	dom t	•

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VIDWIGHT.	· ***	lought breakfor Even the dient teel was already	him	. •
VEHICLE:		breakfo	٠٠٠ :	٠
What vehicle were you in?		Even the	me h	<u> </u>
Make For d Plate:	Model Year Owner:	war alread	July int	
Insurance Company:	Policy Numb	er:	·····	_•
Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)		ne, DOI YES	3) NO
1.	Scat Position (See above)	injureu:	1123	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
	(4 * 2 * 4 * 4 * 5)	-		
5	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

NOTEC.



Date of Interview: 8/9/0710:07 Time: Interviewer: DCOLLIE C.GREEN
N75B MPD DRIVER Driver's License Number: State: MN Full Name Sheraz DIN DOB: Full Address Telephone Home: , oia. 952 939 0701 Compliance with DL restrictions: Glasses, etc YES NA Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES Safety Equipment used: Belts: LAP SHOULDER BOTH Hospital FAIRFIEW USEM Transported to Hospital Walk-in What Ambulance Service: Nature of Injury (Circle): Incapacitating injury - broken bones, hospitalized, severe cuts HUMOUROUS An inability to perform a task they could do before injury. PODT Non-incapacitating injury - Cuts, bruises, scrapes \mathbf{B}

Please explain where you were on the bridge – (direction of travel [NB &B], which lane, OUTSIDE refer to bridge diagram):

Complaint of injury with no obvious injury visible

PIER 6

C

What other vehicles or people were around you? (Color, make, model, description), what were they doing? CW WALBNG ON BRIDEE TO TRAILER

a sensation is described my	and smell relative to the crassovement left to right, forward of Sey Smok) - SLAMMED BOAKES (STOPPED)
	up were going ste				_
What vehicle were you in?					
Make Toyota Plate:	Model CAMARY Year Owner: ANDREW	1999 co	olor TAI	J	
Insurance Company: 5 7A	1E FARMPolicy Numb	er:_			
Who else was in the vehicle 1. TINA NGUYEN		ne, address, p Injured?	YES	NO	NOAMB46 DEPLOYMEN
2.	Seat Position (See above)	Injured?	Poss Sul YES	NO	
3.	Seat Position (See above)	Injured?	YES	NO	
4.	Seat Position (See above)	Injured?	YES	NO	
5.	Seat Position (See above)	Injured?	YĖS	NO	·
6.	Seat Position (See above)	Injured?	YES	NO	

10

 $\overline{\alpha}$

NOTES.

SUMMARY OF WITNESS INTERVIEW CONCERNING THE I-35W BRIDGE COLLAPSE

INTERV	TEWEE: OB:
INTERV	IEWERS: Jennifer Morrison, NTSB Office of Highway Safety
DATE:	11-6-2007
LOCAT	ION: Email Correspondence
	r. Ebling was identified as a victim from the collapse through vehicle on of car ID # B18, a 2005 Red Ford Focus.
to be inte survivors contact in Ebling's	r. Ebling was severely injured as a result of the bridge collapse and was unable erviewed within the first few months after the collapse. Mr. Ebling attended a meeting on September 24, 2007 were he provided investigators with updated aformation and his email address. An email interview was then conducted at Mr. convenience and contained the following information; J.M. refers to questions estigator Jennifer Morrison and G.E. refers to answers from Mr. Garrett Ebling:
	here were on the bridge at the time of the collapse? Southbound, northbound, right ne, left lane, etc
	vas heading southbound on I-35W in the right lane and had made it roughly 1/3 of e way across.
J.M.: W	here you the driver or passenger? Where there any other passengers? If so, please t.
G.E.: I	vas the driver and sole person in the car.
J.M.: W	hat other vehicles were around you?

J.M.: What do you recall about the collapse? Did you hear or see anything as the bridge the collapsed?

G.E.: I had the radio on pretty loud so I don't recall any sounds. The bridge began to shake and I watched the first span fall - the cars just disappeared. Then I felt the bridge below me give way and started to nosedive.

J.M.: Did you see or hear any construction on the bridge?

G.E.: I do not recall.

B18

G.E.: I saw workers on the bridge. Because of the construction one lane was closed and vehicles were required to merge.

J.M.: What do you recall after the collapse? Physical surroundings, sounds, sights, emergency response, etc.

G.E.: Being critically injured, I do not recall anything though I was conscious. Doctors say it was a type of amnesia.

J.M.: Did you go to a hospital after the collapse? If so, which hospital, and how did you get there?

G.E.: Yes. I was taken by ambulance to Hennepin County Medical Center.

J.M.: Were you injured? If so, please describe your injuries.

G.E.: I had a compound fracture in my left foot, a hairline fracture in my right foot, two compound fractures in my left forearm, a severed abdominal wall and colon; a ruptured diaphragm and collapsed lung, an injured right eye, broken jaw in three places and broke every bone in my face, and several gashes and bruises.

New B19

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8 [17]	ime:
Interviewer: Wagner	
DRIVER	
Driver's License Nu	State: MN
Full Name Roman Koyrakh	DOB:
Full Address	Height: 6
	Weight: 155
Telephone Work:	СеЦ
Compliance with DL restrictions: Glasses, etc	YES NO NA
Seat Position: Front Seat Driver Middle Seat Left Rear Seat Left Bus occupants see diagram	Center Right Center Right Center Right
Ejected: YES NO	
Safety Equipment used: Belts: LAP	SHOULDER BOTH
Transported to Hospital YES NO Walk What Ambulance Service:	-in Hospital_NMMC
Nature of Injury (Circle):	
A Incapacitating injury – broke An inability to perfor	en bones, hospitalized, severe cuts m a task they could do before injury,
B Non-incapacitating injury -	
C Complaint of injury with no	obvious injury visible

Please explain where you were on the bridge —(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what -

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.)

VEHICLE:

Mak

What vehicle were you in?

Plate	Owner: Levyrakh	200 C	olor Oveen
Insurance Company:	Policy Nui	nbe r	
Who else was in the wehi	cle with you? (Na (Na Seat Position (See above)	aine, address, p Injured?	hone, DOB)
2.	Seat Position (See above)	Injured?	YEŞ NÖ
3.	Seat Position (See above)	Injurêd?	YES NO
4.	Seat Position (See above)	Injured?	YES NO
5	Seat Position (See above)	Injured?	YĖS NO

Seat Position (See above)

Injured?

I was driving northbound in the left lane approaching the north end of the bridge. I think there were a vehicles in front of me. The car felt like it jumped up a little. Then I saw a cloud of dust or smoke, Everything started to rumble and shift.

I closed my eyes and kept them shot. I felt the car failing nose first. It never stopped but I felt ithe car storking several objects on the way sown like maybe pieces of the failing bridge. I think my airbag deployed the first time I hit something.

I landed in the water I opened my eyes and there was water filling up the inside of the car. I realized I wasn't dead, I was under water and I was able to open my car. I grabbed onto a steel girder and pulled myself up and onto a piece of the bridge.

There was a silver SUV shead of my car and there was a woman inside who was hurt. I didn't want to move her and risk hurting her more. She was awake and and I told her there would be help coming soon. Then I thought I heard a woman screaming thom beneath where I was standing D. I went back into the water to look but I couldn't see any thing. I went back to where my car was and it was upside bon in the water water with the times showing. I did not remember the car being upside Boar when I got out.

I swam to the shore. I could feel y	Din in my
night leg. I was taken to the hospit	al won
Subulance They took yours and to	Id uso mer
- Subulante. They took x-rays and to right hip was badly bruised but the	Pic 1) and
Rodures	re merejno
	:
	e .
	Por land and an analysis of the second secon
	The bridge beautiful to prophy or supply or su
	/A 75000000000000000000000000000000000000
238	





1 1 2					
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	16

RECORD OF INTERVIEW

Wen-Yan King

Interviewed August 7, 2007 at Ms. Kings parents residence.

Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Wen-Yan King (5'4" 150 lbs.)



Ms. King stated she was driving northbound near the south end of the bridge in her tan 1994 Nissan Sentra. According to Ms. King, she felt the bridge rumble and saw the bridge come apart near her front bumper. Ms. King stated that she feels her car rotated or tumbled upside down coming to rest upside down on an angle atop a beam. She thought she crawled out the passenger side door or window and crawled down a beam to a pile of debris. She said from there she walked in shallow water to where ambulances and rescue vehicle's started pulling up.

According to Ms. King, she sustained avulsion lacerations to both hands and a chest bruise from her shoulder belt. She stated that her vehicle has an automatic shoulder belt and a manual lap belt, but was only wearing her shoulder belt.



- 1 -

FEDERAL BUREAU OF INVESTIGATION

Date of transcription 08/08/2007

SARA C. MILLER, date of birth

, was interviewed at her residence. After being advised as to the identity of the interviewing agent and the nature of the interview, MILLER provided the following information:

Attached are the I-35W Bridge Collapse Questionnaire and the written statement of SARA C. MILLER documenting her experience at the I-35W bridge collapse. As well, MILLER provided photographs of the final position of her vehicle (C1 - Red 74S Volvo,

Investi	gation on	08/0	7/2007	at	St.	Paul,	Minnesot	a		
File #	308H-M	IP-692	278					Date dictated	08/08/2007	
by	SA Joh	ın J.	Gainer							

August 8, 2007

On Wednesday August 1st 2007 I was traveling south bound on highway 35W. The traffic was stopped. I was on the north side of the bridge about 10 feet from the section that fell directly into the water, I watched the bridge sway with a deep rumble and then the car in front of me dropped and vanished before my eyes, I thought for a minute that I would be fine, I thought it was over for a very brief moment. I felt a rumble under me and heard the cement beneath me start to crunch. I gripped my steering wheel and braced myself for the worst. I felt the air under my glutes, and thighs which should have been on the seat but were not, I was in a free fall. I thought thank God I am wearing my seatbelt! Suddenly I heard a crash and realized it was my car smashing backwards into the car behind me. I saw the two young men in the white SUV beside me waving to me "Are you okay?" I unfastened my seatbelt grabbed my phone and dialed 911, as I climbed out of my car through my sunroof that I thankfully had open.

I looked around in disbelief and heard yelling and screaming everywhere. The young men got out of their car and we started opening car doors for trapped people and just helping in any way telling people to slow down their breathing to stay calm, and that help was on its way. Once the first team of fire fighters and police and EMT's showed up, they needed help carrying people on body boards and lifting them down over the wall we were up on. The motion of all the survivors who were there who like me were able bodied were all heroes, the spirit on that bridge was awesome.

I tried to get back to a man that I found trapped in his GMC Jimmy to see how they were doing but the authorities wouldn't allow it. I told several men there that I called his wife and that his name was Michael Weese. They said thanks maam but you gotta go now. I talked to that mans wife 4 days later and was disappointed to hear that he was a John Doe when they got him to HCMC, that not one of the people who was supposed to be an authority there working to get him out of his car trapped under a truck, cared enough to use his name. The flood of police, firefighters, EMT's was unreal, the voices barking out orders, the Ego's of those who just wanted to be in charge of something that no one could possibly be in charge of was like pouring vinegar on the fresh wounds we all just had. They were telling us we had to get off because it could collapse again. Well to be honest there was nowhere else for it to go and if that be the case they were putting a lot more weight on it with their equipment their quantity of people and their heavy egos. At this point it was a bit insulting how the authorities were treating the heroic survivors.

When I climbed down the ladder to the river level there was another lady officer freaking out yelling that the power lines are down, and handling the situation a little frantically ordering those crossing at her directed point in a single file and telling us to go up the hill and tell an officer our name. I understood her concern however her orders to the people who were just in a huge crash and who were just carrying bodies to safety, was a bit harsh and I think quite uncalled for. We all got the sea of ambulances and fire trucks and police cars and it was complete chaos. We all stood together for a moment and looked stunned upon each other. I wish I had the sense to ask the names of the others who were there with me however I didn't realize the scope of the event at that moment; I was in emotional and physical shock. As some of the emergency vehicles were leaving the scene the group of us got broken up. I asked several officers if there was anyone taking names of the survivors from the bridge? Each one of them turned me away. I sat on my duffel bag I salvaged from my car for a moment then the police started to blare their

sirens to get people out of the area. I started walking with the crowd I had no choice no one was there to help the surviving who were now stranded with out a vehicle. I was amazed at the lack of ownership and organization and the complete let down of the states police system. They all seemed more concern with taking their own pictures or talking with each other, or on their phones or wanting to order someone around that they lost all sense of humanity and the mood was very ugly. The 1st team of responders were great and very compassionate, but the rest were so much more concern with what they were getting out of the experience that they lost sight of those who needed help after their experience.

I finally walked to the top of the hill and the voice was yelling, "Go Left or Go Right just keep walking!!!" He just kept repeating. I was so lost I had no idea where I was, I kept trying but my cell phone network was busy, I couldn't get through to anyone. A bystander asked me if I was okay and I just asked him where I was and, what is the best way to find me if I get a hold of my husband, to tell him where I am. We walked to 4th street and he bought me a water at a little shop, I was a bit dehydrated from everything that just happened and the walk didn't help. I thanked him for his kindness and said that I see a police officer and that I'm sure he can help me. I was at the northwest corner of 4th and 10th a place I have never been before in my life. I will never forget it now. I approached the officer, and asked "Can anyone get me a ride or tell me where a good place to be is; I was just on the bridge." The officer was directing traffic he looked to be in his late 40's early 50's, Caucasian, taller, dark haired man and his squad car was from Roseville. That is all I remember I wish I would have thought to take his picture with my cell phone but I was so incredibly shocked at what came next I don't know what affected me more the bridge collapse or how he handled me. He screamed at me "GET ATTA HERE LADY THERE ARE PEOPLE DYING ON THAT BRIDGE!" then he leaned into me and pushes me back with his brut force like I was a threat to him. I couldn't believe he actually did that! I yelled back at him and said that I was one of those people that could have just died and that he should not push people for no reason, it's not right! I was so distraught, my heart was pounding I started shaking and I didn't know what else to do so I kept walking, I saw other officers down the road just standing around but at that time I was so damaged by the police and their loss of control and their raging egos that were crazed for a part of the action I lost all hope and faith in the protection of our not so fine MN police.

The officer that pushed me had an opportunity to actually do something good and right, which I thought was part of the job when you are a police officer for someone who genuinely needed help from that terrible bridge accident. However I appeared able bodied to him and was walking so I was of no earthly concern to him. I am so disucusted with the way the majority of the police on and surrounding the scene acted that day I only hope my experience can be heard and that some real training in humanity is in order for all police in this fine state of Minnesota. We are all equal humans no matter what authority one thinks they may have, it is a fallacy. We all breathe the same air, we all bleed the same way, we all live in the land of the living on this earth, or we leave our bodies behind to decompose the same way, and each human being deserves to be treated with humanity and respect just as much as we as individuals believe we deserve humanity and respect. Something needs to be done about the huge lack of respect and humanity that is so lost by those who believe to be an authority figure, and abuse that false sense of

242

power which creates chaos and fear when it is so unnecessary and needless in our world already in a state of chaos. It begins with you and me and it is the responsibility of anyone who believes themself to be a good human to make a change and be responsible for their own action and act kindly to others. That is a sense of humanity to rise up over the ego and do what you know is right and respectful to those around you. I am saddened by August 1st deeply by what I saw happened to those who fell with me, who were less fortunate than I. Yet I am so inspired by those who fell with me and rose up with me there, and took initiative and stayed clam and controlled who displayed a true sense of selfless concern and helped one another with no selfish agenda and showed true heroism.

I am ashamed of how it was handled by those who were supposed to be in charge and really be the heroes, and took the credit for it, those who call themselves authorities who actually made my experience a living hell. A great human once said; "We can do no great things, only small things with great love." The words of Mother Teresa should be thought of when we think of our accomplishments in this life.

Regretfully Yours,

Sara C. Miller

Car# C1 on 35W north side of the bridge.

These are my word of testament to any and all who care to read and will be kept from no one, by any means.

Date of Interview: $\hat{\mathcal{E}}/7/2007$ Time:	10:15
Interviewer: SA JOHN J. GAINER	
DRIVER	
Driver's License Number	State: MN
Full Name Sora CHRISTING MILLER I	DOB:
Full Address	
Telephone Home: Work:	Cell:
Compliance with DL restrictions: Glasses, etc	YES NO NA
Middle Seat Left (Center Right Center Right Center Right
Ejected: YES NO	
Safety Equipment used: Belts: YT LAP &	HOULDER BOTH
	Hospital Do pour Medical Chin VES - Doctor Check/Physi
Nature of Injury (Circle): A Incapacitating injury – broken In An inability to perform	DOCT - + ME OF OF OF OF ONLY
	-
An inability to perform B Non-incapacitating injury - C Could duag C Complaint of injury with no ob Muscle Shain in Lise An inability to perform B Non-incapacitating injury - C Could duag C Complaint of injury with no ob Muscle Shain in Lise An inability to perform B Non-incapacitating injury - C Could duag C Complaint of injury with no ob Muscle Shain in Lise An inability to perform B Non-incapacitating injury - C Could duag C Complaint of injury with no ob Muscle Shain in Lise An inability to perform Could duag C Complaint of injury with no ob Muscle Shain in Lise An inability to perform	vious injury visible — Scripe on left wish Fare — Sheld Bleaky kolo on of travel [NB SB], which lane,
Rect -	

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Great - Suellangest U Down Vehicle (may be hendle)
- in front -

What did you see, feel, h	near, and smell relative to the crash	? (Please ask for specifics if
a compation is descrit 1	. 1 0	t torne may for abcettics II
a sensation is described -	- movement left to right, forward a	nd back up or down ato
	and the state of t	and buck, up of down cit.

a sensation is described – movement left to right, forward and back, up or down etc.)	
- Set - a drap -	
- heavel - a combile timbell .	
VEHICLE: Screens In Sally - head - crash.	
VEHICLE: - Come in rest for crossle	
- Che is its of the Wash	
What vehicle were you in? - Saw white Sav Find	
Make Volvo Model 740 Tueso Year 1991 Color Red house	•
Plate: Owner: ARIC B. MILLER (17-2-	

Insurance Company: 🙏	TG Policy Numb	or.			A helped
Who else was in the vehic.	le with you? NA (Nam Seat Position (See above)	ne, address, ph Injured?) NO	out- mi people out judel
2.	Seat Position (See above)	Injured?	YES	ИО	DARK 4Dage
3.	Seat Position (See above)	Injured?	YES	ΝО	-30; -anphoe-
4.	Seat Position (See above)	Injured?	YES	ИО	- retricial material clepent.
5.	Seat Position (See above)	Injured?	YÈS	ΝО	(XLRIVA.


Injured?

YES NO

Additional notes/comments: Mrs Willer would like to whe who will have a complaint 245 young to of freeze who should have.

Seat Position (See above)

6.





Date of Interview: 47 Time: 1317
Interviewer: DCOLLINS / C, GREEN
DRIVER
Driver's License Number:
Full Name Bradley Robert DOB:
Full Address
Telephone Home: Work: Cell: 6
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH NO A/B
Transported to Hospital YES NO Walk-in Hospital St. John's What Ambulance Service:
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts
An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes MUSCLE WHIPLASH
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB] which lane, refer to bridge diagram):
GOING TO TWINS
601NG TO TWINS RTLANE (a) JOINT, Car in Front Fell 247
(a) JOINT, car intront tell

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Marcon Early 905 Cumrna Behind Black car (Picture in Paper)

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) Ripple; could hear cracks tilting in all direction FOUR SEC UNTIL his section Prop - 5A+ HICLE: 15+ DEOP, reversed, 2ND DEOP What vehicle were you in?

Make FOLD Model EXPLORER Year 1997 Color White Owner: KATHERINE PETER

Insurance Company: OWNERS I ASUS ance Policy Number:

Who else was in the vehicle	COMPERSON NA (Name	e, address, pho	ne, DQB)	
1. SETH DANIEL PETERS	Seat Position (See above)	Injured?	YES	NO
	FR RT		-5/	4me
2	eat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO

Additional notes/comments:



Date of Interview: $8/9/07$ Time: 1236
Interviewer: D COLLINS CNISS/C. GREEN CMPD)
DRIVER
Driver's License Number State: MN
Full Name DANIEUE KATHRYN DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH NO AIRBAG DERLE
Safety Equipment used: Belts: LAP SHOULDER BOTH NO AIRBAG DEPLE Transported to Hospital What Ambulance Service: POV
Nature of Injury (Cincle):
An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
COMP. Fracture LI TII/TIZ
Please explain where you were on the bridge –(direction of travel [NB SB] which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

SEE BACK

VEHICLE:

What vehicle were you in?

Make PONTIAC Plate:	Model GLAND FEET Year Owner: DANEUE	Zoco Color	DK	320E
Insurance Company:	N/A Policy Number		<u></u>	·
Who else was in the vehicle			ie, DOE	
1.	Seat Position (See above)	Injured?	YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

LADY, DK SUU, Straght UP, MEDICAL TRAINING?
LADY, DK SOU, STRAGOL OF, WELL
THEN MOON POOP
-coad lecad pre rollops
By White EXP
-ERICA?
(RAZO Ster TRIB 8/5)
-SPOKE TO DEPUTY PAUL LENZMEIER ANOFA CO. SHER.
- Arrived @ HOSPITAL @ 8:30 pm
- Arrived of 13th + Central
201 and Fire Truck
- moved to side + loft
- Moved to side - Walked UP hill & left - Walked UP hill & left
- Walker OF - SAW MIDDLE SECTION OF BRIDGE GO DOWN - SAW MIDDLE SECTION OF BRIDGE GO DOWN
- SAW MIDDLE SECTION OF BRIDGE GO - Next memory, Felt impact - Next memory, Felt impact - Gradded phone, called Figuree = 15 min Walt, then left made sevically (5+) - Gradded phone, called Figuree = made sevically (5+)
- Next memory, called Flancee mode severally (5) - Grabbed phone, called Flancee mode severally (6) - Grabbe
A Gentleman in Far RT car covidu & get out -101 -Civilians w/woden Step ladder over concrete wall -OVER EDGE, HILL OF SAND, WOOD ladder over concrete wall - Told to watch out for Fower line - Told to Watch out for Fower line - IN THIS AREA
-Civilians W/ Wood adder over concrete wall
- Told to watch out for power The FIRE TRUCK
- Told to watch out to 1 - Told to watch out to 1 - IN THIS AREA MOUNTED AT MOST 10-15
- SOU WAS HEAVY - HEAVIER THAN NORMING - DIVING
2 CTUL FOR WHICE I WILL TO WELL
and a commute of the
- RESULT COMMINE DESIGNATION - ERICA may belong to pontac UFDR - she was on ground by time backboards came out
- She was on ground by time occlesors com

NOTEO.





	*				***
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	14

David L. Brown

Interviewed August 5, 2007 at Mr. Brown's residence.

Present during the interview was Mr. Browns girlfriend, NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

David L. Brown (6'4" 205 lbs.)



Mr. Brown stated he was driving southbound in the far right lane on the northside of the river in his black 2001 Saab 9.3. According to Mr. Brown he felt and saw the bridge sway left to right, tilting more so to the left. He immediately saw a puff of smoke and he felt his vehicle drop down prior to his span tilting back causing him to roll rearwards. He said that as he came to a stop, a Ford Explorer that slid back into him struck him.

According to Mr. Brown, he sustained compression fractures to T-6 and L-1 along with some minor soft tissue bruises.

Telephone Interview

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-24-07 Time: 1442

Erica Christine Gwillim DOB: Erica Christine Gwillim Telephone Home: Work: Cell: Compliance with DL restrictions: Glasses, etc YES NO NA Seat Position: Front Seat Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital YES NO Walk-in Hospital Hospital What Ambulance Service: Abbott Northwester Nature of Injury (Circle): A Incapacitating injury - broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes Complaint of injury with no obvious injury visible Back A Tomack	ice
Telephone Home: Work: Cell: Compliance with DL restrictions: Glasses, etc YES NO NA Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital YES NO Walk-in Hospital What Ambulance Service: A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury – Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Back A Tomach	
Telephone Home: Work: Cell: Compliance with DL restrictions: Glasses, etc YES NO NA Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital YES NO Walk-in Hospital What Ambulance Service: A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes Complaint of injury with no obvious injury visible Back A Tomach	
Telephone Home: Work: Cell: Compliance with DL restrictions: Glasses, etc YES NO NA Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital YES NO Walk-in Hospital What Ambulance Service: A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Dack	
Compliance with DL restrictions: Glasses, etc YES NO NA Seat Position: Front Seat Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital What Ambulance Service: A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Back Tionach	
Seat Position: Front Seat Middle Seat Rear Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital What Ambulance Service: A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury – Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Back C Center Right Roar SHOULDER BOTH Transported to Hospital What Ambulance Service: Abbott NorTHWes Ter Cuts, bruises, scrapes	
Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram Ejected: YES NO Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital YES NO Walk-in Hospital What Ambulance Service: Abbott Northwester Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Back - Stomach	
Safety Equipment used: Belts: LAP SHOULDER BOTH Transported to Hospital YES NO Walk-in Hospital Hospital Hospital What Ambulance Service: Abbott Northwester W Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Back A Tomach	
Transported to Hospital YES NO Walk-in Hospital	
What Ambulance Service: Abbott Northwester Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Back + Stomach	
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury - Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible Back + Stomach	
C Complaint of injury with no obvious injury visible Back & Stomach	
Back & Stomach Pain	
JIOTHO, CH.	
Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram): Southbound as 35W (approx Span 9) talking on her cellphone. She felt without	-
of the bridge moving. She could see the Cars ahead of her moving and swaying	L

What other vehicles or people were around you? (Color, make, model, description), what were they doing? a whenour Suvwith a man in it

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

Swaying - Can't remember what direction

VEHICLE:

What vehicle were you in?

Make Plate: Insurance Company:	Model Owner: INS Cmec S Pol	Year Urance icy Number:	Color	
Who else was in the vehicle 1.	•	(Name, addre		B) NO
2. Other Person	Seat Position (See	above) Injure	d? YES	NO
3.	Seat Position (See	above) Injure	d? YES	NO
4.	Seat Position (See	above) Injured	i? YES	NO
5	Seat Position (See	above) Injured	1? YĖS	NO
6.	Seat Position (See	above) Injured	I? YES	NO

Additional notes/comments: She spoke with a Henn. Co. Deputy in the Hospital

MOTEC.

Date of Interview: 8/6/2007 Time: 1830
Interviewer: DCOLLINS/C. GREEN
DRIVER
Driver's License Number:
Full Address Told onen
Full Address
Telephone Home Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH NO A)B
Transported to Hospital YES No Walk-in Hospital What Ambulance Service:
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible NONE
Please explain where you were on the bridge (direction of travel [NB SB], which lane, refer to bridge diagram): SIB LOVGHLY 3 Deck SECHON, RODOL DUC
SUPOU C

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

4 Vehicle infront

What did you see, feel, hear, a sensation is described – mo all care fait felt deducted when covering the contraction of the co	and smell relative to the crash vement left to right, forward a SRD BD clust word starting to the crash when starting to the country to the crash to the country to the crash to	SABB, Star (Please ask and back, up or Aparel West, Parel West, Pa	for spec down e	SED sifics if tc.) Revenue
What vehicle were you in?			-	,
Make FoLD Plate:	Model EXPOR Year Owner: Him	2002 Color	MM	neral grey
Insurance Company: PRO	6 LESSIVE Policy Number	r		
Who else was in the vehicle val.	with you? NA (Name Seat Position (See above)	e, address, phor Injured?	ie, DOE YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5	Seat Position (See above)	Injured?	YĖS	NO
6	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

OF PLATE BSR841

259






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	13

Jesse Shelton

Interviewed August 4, 2007 at North Memorial Medical Center.

Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Jesse Shelton (5'4" 135lbs.)



Ms. Shelton stated that she was driving an 2001 Honda Civic LX. Ms. Shelton related that she was driving southbound in the far left lane planning to exit at 11th avenue when she felt a jolt and an upheaval and her vehicle started rolling backwards. Ms. Shelton does not remember anything after that point.

Ms. Shelton said she sustained a bruise across her waist from her seatbelt, and 4 compression fractures 2 to her thoracic spine and 2 to her lumbar spine, and a concussion.



Date of Interview: 8/8/2007 Time: 1500
Interviewer: COLLINS (NTSB)/GREEN (MPD)
DRIVER
Driver's License Number
Full Name LOIS ELIZABETH WELMAN DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc. YES NO NA
Soot Baris'
Middle Seet L. G. Center Right
Rear Seat Left Center Right Bus occupants see diagram Rear Seat Left Center Right
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH AIRBAG DEPLOYED
Transported to Hospital YES NO Walk-in Hospital KNIGHTED HOSP
What Ambulance Service: Poll
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts
An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes BACKACHE
C Complaint of injury with no obvious injury visible
compressed Fracture 8+9 vert.
Please explain where you were on the bridge –(direction of travel [NB] SB], which lane, refer to bridge diagram):
to oringe diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

LITTLE BLACK CAR, SINGLE REMALE OCCUPANT

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

OUTS (DE BRIDGE MOULUC IN-OUT THOUGHT WAS EARTHOUAKE

VEHICLE:

What vehicle were you in?

Make BUICK Plate:	Model RIVIERCE Year Owner: LOTS WELM	1992 Col	or Burg	gand
Insurance Company: H	,			
Who else was in the vehicle.	le with you? NA (Nan Seat Position (See above)	ne, address, ph Injured?	one, DOI YES	B) NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:

Turned officer couldn't get out left & Black truck w/ construction equip *
- rest with her. HE ned broken tog arm - EMS CAME, ASTED OF - Two college students helped her up incline - Went under from tracks - Walked to University - Lutheran Student Center - ZHR wait forande - ET LANE -PAST CONSTRUCTION - WAVE OR RIPPLE MOTION, STARTED WOUT BOTH AHEAD

THEN IT WAS ALL OUTE Siver car under truck- Male drivers of both vehicles ofay (Black truck broken arm) (Black - Black This in Front of BUK truck, over, car (LT LANE)

- LOTOF DUST NO HEARING, SMERIS

263

ñ

NOTES.

7

Date of interview: 9/14/07
Interviewed by Sgt. Steve Wagner-MPD
,

Vehicle: 1999 GMC Jim----

Insurance: AIG Policy#-----

No DL Restrictions

Not ejected/ lap and shoulder belt was used.

Transported to HCMC by ambulance.

Injuries: Suffered the following incapacitating injuries:

Shattered facial bones, 3 lower back fractured vertebrae, 2 fractured ribs, collapsed lung, fractured sternum, intracranial bleeding. He required surgery to fuse vertebra T10-L3.

Comments: Weese remembers he was northbound in the left lane of traffic approaching the north end of the bridge. He could not recall any vehicles near him. He remembered looking in his rear view mirror and seeing the center section of the bridge disappear and thinking he needed to quickly get off of the bridge. Then the section on which he was driving gave way and he went from driving straight ahead to falling head first to the river. He recalls nothing further about the event.





DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	9

Thomas Hughes

Interviewed August 4, 2007 at Fairview Medical Center at the University of Minnesota Campus. Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Thomas Hughes (5'8" 238lbs.)



Mr. Hughes stated that he was driving a 1990 Chevrolet ½ ton extended pick-up truck. According to Mr. Hughes, he was heading northbound in the left lane traveling approximately 20-30 m.p.h. He stated that he felt the bridge flex and then saw the pavement ripple. He said he experienced it again prior to his truck's back end falling back striking the concrete center divider prior to flipping end over end and landing on his wheels. Mr. Hughes stated that he unbuckle his seat belt and attempted to get out. He called out his windshield and was helped by a fireman off the bridge.

Mr. Hughes said he sustained an T-10 and T-11 compression fractures, a fractured left wrist, and a puncture laceration to his left armpit.






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGÉ
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	10

Karge James Olsen

Interviewed August 4, 2007 at Fairview Medical Center at the University of Minnesota Campus. Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD.

Karge James Olsen (5'10" 175 lbs)



Mr. Olsen stated he sustained fractures to his cervical and thoracic spine, right clavicle, and a concussion.



Date of Interview:		Time:			
Interviewer: Tom	Hendri	CKSON	# 2960	MPD	•
DRIVER TINA	Marie	Hickmo	an-AKA	Tina Marie	Chavi
Driver's License Nun		/ (-) (-)	Maden State: MA		
Full Name IINA Marie Full Address	Hickr	nan	DOB: 5510	9	
Telephone Home	:	Work:	Cell:		
Compliance with DL	restrictions: G	lasses, etc	YES NO	NA UNKNO	WN
Seat Position: Bus occupants	Front Seat Middle Seat Rear Seat see diagram	Driver Left Left	Center Center Center	Right Right Right	, WN
Ejected: YES	NO UN	KNOWA	<i>j</i>		
Safety Equipment use	ed: Belts:	LAP	SHOULDER	BOTH WNK	10 W N
Transported to Hospit What Ambulance Ser		NO Walk-	in Hospit	al	
Nature of Injury (Circ	Incapacitating	injury – broke	n bones, hospit	alized, severe cuts ould do before injury.	
В	Non-incapacit	ating injury -	Cuts, bruises,	scrapes	•
C	Complaint of	injury with no	obvious injury	visible	
Please explain where refer to bridge diagrar	•	e bridge –(direc	ction of travel	[NB SB], which lane	,

See attached Note

What other vehicles or people were around you? (Color, make, model, description), what were they doing? $\bigcup \mathcal{N} \mathcal{K}$

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

UNK

VEHICLE:

What vehicle were you in?	Tai	urus		-	
Make Ford	_Model	oor Year	2003 Color	Gr	V
Plate	Owner: Ti	Na Mari	e Chai	· S	,
Insurance Company: (InK	Policy Number		,	
					
Who else was in the vehicle 1.		NA (Name (See above)	e, address, phor Injured?	ie, DOI YES	3) NO
		(200 430 (0)	211) 01 0 0 .	120	21,0
2.	Seat Position	(See above)	Injured?	YES	NO
	Scat i Osmon	(See above)	injuieu:	1123	NO
3. UNV K	Cont Donition	(01)	T., t., 30	י מייני	NO
)	Seat Position	(See above)	Injured?	YES	NO
4		(C) 1)	T . 10	*****	270
4.	Seat Position	(See above)	Injured?	YES	NO
	- ·				
5.	Seat Position	(See above)	Injured?	YĚS	NO
6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:

NOTEO.

Tina Marie Chavis MN DL also PL Tina marie Hickman MN MN Taurus 4 Door FORD 8-6-2007 Lest mossage 6:00pm Lest message 7:33pm 805pm 8-7-2007

Receive Da Tolonhane Call &approx 1330h

Let message 0846 hrs

press, I explained to Mr. Fink that I had just checked HCMC and there was no Tina marie Chavis nor Tina marie Hiehman, He stated that her family had her incommunido



Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram): South Bound-See diagram

d copy


What other vehicles or people were around you? (Color, make, model, description), what were they doing? Two when we hicles ahead can remember

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

See Statement attack.

VEHICLE:		
What vehicle were yo	wallpaper. Samples, Fabri	carr Blinds
Make Dedq (TIRING LAC	or Blue 612,377-391
Insurance Company:	Travelers Policy Number	5 2ND AVE. NO. MAIS. MA
Who else was in the ve		one, DOB) YES NO
2. e/Se	Seat Position (See above) Injured?	YES NO
3.	Sant Danisia (G	ES NO
4.	s. laccidently	S NO
5.	se orginial	S NO
6.	Son	3 NO
	•	*

Additional notes/comments:
See attached Statem





Linda Paul's Account of the 35W Bridge Collapse on August 1, 2007

Linda was at the Hirshfield's Shop-At-Home offices in Roseville. She primarily works out of her home at 5215 Park Ave in South Minneapolis but was at Hirshfield's for the weekly "office day". She called her husband, Gene around 5:30pm to tell him that he would be leaving shortly. She was returning home to complete work on a file since she had met with a client that afternoon and promised that she would get back to them Wednesday evening with a quote.

She left the Shop-at-Home office around 5:40pm and took 35W southbound although it was clogged with rush-hour traffic. Due to work on the road and the bridge, traffic was stop-and-go. As she approached the 35W bridge she saw workers in the left hand lane. A short way ahead of her she saw an overhead sign buckling and racking. This reminded her of a film about the Tacoma Narrows Bridge collapse in Oregon and she thought the same thing might be happening. As the watched the southern section of the bridge collapsing she thought she was far enough back to avoid being in it. At that moment she looked down to the left and saw the expansion joints separating beneath her. The next few moments were unclear as the van began to fall. She felt like she was tumbling and as she descended, concrete and re-bar broke through the windows of the van. She was hit on the left side of her face with concrete chunks five or six inches in diameter. She used her arms to shield her eyes and head. Product samples, manuals, and work supplies used in her job were flying all about. The van came to a sudden stop and she found herself in a cloud of dust suspended at an angle from her seatbelt toward the center of the vehicle. She noticed her air bag had not deployed and this could explain her being tossed around during the fall.

As the cloud of debris dispersed she heard voices of people all around some talking on cell phones. She looked out the window which was facing up and she could see people standing on the broken edge of the bridge approach looking down at her. She began screaming for help and someone named Bernie stuck his head in the passenger window and asked how she was. She was concerned about the car bursting into flame because the engine was still running and she was unable to turn it off. He tried to cut the seat belt but she was able to unbuckle it before he succeeded. They shoved debris out of the way and he helped her slide out the passenger side window, feet first. He then helped her over to a sand bank a short ways away where she sat with another person named Luis. Bernie went off to help others but kept checking back to see how

Linda was doing.

Paramedics then began to arrive and each asked Linda how she was doing before they moved on to take care of the more seriously injured. After a while the paramedics were ready to move her and they locked-hands to form a seat to carry her down a steep embankment to another triage area. She sat there for a while and the paramedics asked if she was able to climb down a ladder to the area where the emergency vehicles were. She was unable to stand unsupported so they strapped her to a back board and a group of people lowered her down and she was placed in an ambulance with two other victims. She isn't sure if she slipped into unconsciousness during the trip to the hospital but can remember paramedics squeezing her hand and saying, "I'm here with you...etc."

Once she arrived at the HCMC emergency room, she remembers being asked questions by ER room personnel and them cutting her clothes off to put her in a hospital gown. Her memories became more jumbled as she "let go" and was probably going into shock

noter by officer Hendrichson #2960

he sign is the large green thewarder aign Washington are






DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	33

Mercedes M. Gordon

Interviewed August 11, 2007 at Fairview Medical Center at University of Minnesota campus. Present during the interview was Ms. Gordon's fiancée, NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Mercedes M. Gordon (5'8" 140 lbs.)



Ms. Gordon stated she was driving northbound in the left lane just past the center section of the bridge in her black 1998 Ford Escort. According to Ms. Lindholm, she was traveling around 20 m.p.h. The first thing she saw was what looked like the road was in a wave and then felt it sway left to right. According to Ms. Gordon, the look on the construction workers faces was one of panic. Ms. Gordon stated that the roadway pitched forward and she just held onto the steering wheel. According to Ms. Gordon, her legs were pinned by the doorsill and the dashboard and she needed to be extricated from her vehicle.

According to Ms. Gordon, she shattered both the tibia and fibula's on both legs, fractured her left ankle, and ruptured a disc in her spine at L-1. Ms. Gordon stated that she was wearing her seatbelts.



Date of Interview: 8-11-01 Time: 10	AM
Interviewer: Row K	
DRIVER	
Driver's License Number: State	m MN
Full Name MERCEDES Michele DOIL	3:
Full Address	
	HT 58" WT 140
Telephone Home: Work:	Cell:
Compliance with DL restrictions: Glasses, etc YES	S NO NA
Seat Position: Front Seat Driver Cent Middle Seat Left Cent Rear Seat Left Cent Bus occupants see diagram	ter Right
Ejected: YES (NO)	
	DULDER BOTH AB deployed
Transported to Hospital YES NO Walk-in What Ambulance Service:	Hospital U o f M
Nature of Injury (Circle): A Incapacitating injury – broken bor An inability to perform a t	nes, hospitalized, severe cuts ask they could do before injury.
B Non-incapacitating injury - Cut	s, bruises, scrapes
C Complaint of injury with no obvio	ous injury visible

I was N/B in @ lane just past middle SPAN. going ~ 20 mph pretty much bumper to bumper

Please explain where you were on the bridge -(direction of travel [NB SB], which lane,

refer to bridge diagram):

were they doing? tan a again of me. To driving prior to What did you see, feel, hear,	and smell relative to the crash	was CRU pone around	nched up and me whon specifics if
What vehicle were you in? Make FORD Plate:	Model Escort Year Owner:	98 Color 7.	3/ACK
Insurance Company: AI	Policy Number	er:	
Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)	e, address, phone, I Injured? YF	OOB) ES NO
2.	Seat Position (See above)	Injured? YI	ES NO
3.	Seat Position (See above)	Injured? YI	ES NO
4.	Seat Position (See above)	Injured? YI	ES NO
5.	Seat Position (See above)	Injured? Y	ÈS NO
6.	Seat Position (See above)	Injured? Y	ES NO

Additional notes/comments: Shatlered both keys (Fib, Tib) and @ Footfankle Ruptured L1 veet. 279 SW. Hit ad Realized I was still alive.

No one that me I didn't that many other vehicles.

LAnded on

My leys were pinned by door sill & Dashboard.

W/1 5 minutes people came stayed u/me

until rescue workers theto came. I had to

be extercated from my cor





	· · · · · · · · · · · · · · · · · · ·				
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	11

Ana Marie Sokolowski

Interviewed August 4, 2007 at Fairview Medical Center at the University of Minnesota Campus. Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD.

Ana Marie Sokolowski (5'3" 172 lbs)



Ms. Sokolowski stated that she wearing her seat belt in her 2000 Toyota Camry, heading northbound in the far left lane when she saw the pavement of the bridge look like a wave. She recalled the bridge. Ms. Solokowski stated that she ended up upside down and hanging by her seat belt. She said she unbuckle her seat belt and went to the biggest window where several people pulled her.

Ms. Solokowski said she sustained a couple lumbar fractures, a left shoulder injury and a sore right thigh.

Date of Inter-	view: (ع	Aug 200	7 Time			٠.
Interviewer:C	offi.	cer Ton	n Hendri	CKSAN #	2960 MPLS. 7	PN
DRIVER A	na	Marie	O' Nea		~ 16 C MILS. 1	رو , ا
D ' 1.x'	**			State: MN		
Full Name	arî e	O'neal		DOB:		
Full Address						
Telephone	Home		Work:	Cell:		
Compliance v	vith DL	restrictions: C	lasses, etc	YES NO	NA	
Seat Position:		Front Seat Middle Seat Rear Seat	Driver Left Left	Center Center Center	Right Right Right	
Bus oc	cupants	s see diagram				
Ejected:	YES	NO				
Safety Equipm	ient use	ed: Belts:	LAP	SHOULDER	ВОТН	
Transported to What Ambula			NO Walk-	in Hospit	al	
Nature of Injur	ry (Circ	le):				
	A	Incapacitating			alized, severe cuts ould do before injury.	
	В	Non-incapacit	ating injury -	Cuts, bruises,	scrapes	
	C	Complaint of i	njury with no	obvious injury v	visible	

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

Make 1090 FCA Plate	Model 4 D Owner:	R Year	2000 Color	BRI	· ·
Insurance Company:		_Policy Number	er:		_•
Who else was in the vehicle 1.		NA (Nam (See above)		ne, DOI YES	3) NO
2.	Seat Position	(See above)	Injured?	YES	NO
3.	Seat Position	(See above)	Injured?	YES	NO
4.	Seat Position	(See above)	Injured?	YES	NO
5	Seat Position	(See above)	Injured?	YĖS	NO
6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:

NOTEC.

Hawkins I discovered That and Sokolowshi WI, had a Brother by the name of Jim Sokolowshi in wise, I called him and he stated that and was his sister and that he had seen and Sat August 4, 2007. She was in HCMC. She had a brohen back and deep bone bruising.

8.8.07 1855
I Called HCMC and ana sokolowski
was a patient there I was transpered
to Station STN#1I spoke with her nurse. The nurse
stated that ana was asleep and
world pass on my telephone number
to Call me in the morning.

Talked to By Wagner

Ana Marie O'Neal C-18 -BRN MN ToyoTa Name Ana Marie O'Neal ADDRESS 8-6-2007 Left message 603pm Leftmessage 7:33 pm no ansever 8:05 pm 8-7-2007 Left message Left message 8:48 Am 8:12 pm Left message 8-8-2007 1830 hm







DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	12

Bradley Coulter

Interviewed August 4, 2007 at North Memorial Medical Center.

Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Bradley Coulter (5'9" 190lbs.)



Mr. Coulter stated that he was driving a Gold 2002 Honda Odyssey minivan. Mr. Coulter related that he was driving with his 18-year-old daughter in the right front seat, his 17-year-old daughter in the second row right seat and his 43-year-old wife in the second row left seat. Mr. Coulter stated that all four of them were wearing their seatbelts.

According to Mr. Coulter, he was driving slowly heading northbound near the east bank of the river, when the bridge started to wobble from side to side. He looked over to the side and saw all the bridge workers running. He said when the bridge collapsed his vehicle slid down forward hitting the front end and flipping on its roof. Mr. Coulter stated that they he and his two daughters were able to undue their seatbelts and crawl out. He did not recall which window they exited. Mr. Coulter stated that his wife was semi unconscious and after exiting called for others to help him get his wife out.

Mr. Coulter said he sustained two compressed fractures to his vertebrae in his lumbar and cervical regions. He added that both his daughters sustained vertebrae fractures while his wife was still in ICU at Hennepin County Medical Center.



Date of Interview: 8-29-07 Time:	1430
Interviewer: Sgt Wagner DRIVER Bradley Coulture	
DRIVER Bradley Conture	
Driver's License Number:	State:
Full Name Brandi Couture	DOB:
Full Address	
Telephone Home: Work:	Cell:
Compliance with DL restrictions: Glasses, etc	YES NO NA
Seat Position: Front Seat Driver Middle Seat Left Rear Seat Left	Center Right Center Right Center Right
Bus occupants see diagram	
Ejected: YES NO	
Safety Equipment used: Belts: LAP	SHOULDER BOTH
Transported to Hospital What Ambulance Service: Walk-	in Hospital <u>HCMC</u>
Nature of Injury (Circle): A Incapacitating injury – broke An inability to perfor	n bones, hospitalized, severe cuts m a task they could do before injury.
B Non-incapacitating injury -	Cuts, bruises, scrapes
C Complaint of injury with no	obvious injury visible
·	

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

Make Plate:		Model Owner:	Year	Color		
Insurance Company:_			_Policy Numbe	er:		_ *
Who else was in the v 1. Bradley			NA (Name (See above)		ne, DOI	B) NO
2. Paula	RL	Seat Position	(See above)	Injured?	YES	NO
3. Brianna	FR	Seat Position	(See above)	Injured?	YES	NO
4.		Seat Position	(See above)	Injured?	YES	NO
5		Seat Position	(See above)	Injured?	YĖS	NO
6.		Seat Position	(See above)	Injured?	YES	NO



Date of Interview: 8-7-07 Time: 1630
Interviewer: Set I. San Sheng Mars 1
Interviewer: Sgt. I. San Shring MP15 PT DRIVER Marcelo ORSaz-CRUZ
Driver's License Number: tate: MN
Full Name Marcelo CRdaz - CRUZ DOB:
Full Address
Telephone Home: Work: Cell: L (51-488-03C5) Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital Hemc What Ambulance Service: wint to hospital Me next day on his own
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
No Injulies
Please explain where you were on the bridge - direction of travel INR SRI which lane

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):


What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

Insura	Make Olymouth Plate Plate ance Company: 1	Model Var Owner: Mo	rcelo Policy I	Year Occionation	1995 Color 127 - CNV	B1.	, .
Who	else was in the vehicle	with you? Seat Position	NA (See abo	(Name	e, address, phor Injured?	ne, DOI YES	3) NO
2.	n	Seat Position	(See abo	ve)	Injured?	YES	NO
3.	None	Seat Position	(See abo	ve)	Injured?	YES	NO
4.	\	Seat Position	(See abov	ve)	Injured?	YES	NO
5.	·	Seat Position	(See abov	ve)	Injured?	YĖS	NO
6.		Seat Position	(See abov	/e)	Injured?	YES	NO



Interview with Marcelo Ordaz-Cruz (Male)

Mr. Ordaz-Cruz was driving a blue 1995 Plymouth van, MN license Mr. Ordaz-Cruz is paralyzed and restricted to a wheel chair as a result of being shot multiple times while living in North Carolina.

Mr. Ordaz-Cruz was the driver and only person in his van when the bridge collapsed. Mr. Ordaz-Cruz was driving in the South bound lane and ended up crashing his blue van into the center median on the North end of the bridge.

Mr. Ordaz-Cruz reports that when driving, the bridge "Started shaking up and down". Mr. Ordaz-Cruz says that he remembers seeing other vehicles in front of him before the bridge collapsed. Mr. Ordaz-Cruz reports that he did observe vehicles in front of him go over the end of the bridge, but he cannot recall the description of any of these vehicles. Mr. Ordaz-Cruz also reports seeing two bridge workers crawling on the ground to get away from the area of the bridge that did collapse.

Mr. Ordaz-Cruz was restricted to his van and waited for approx. four minutes until he was helped out of his van by unknown good Samaritans, including one police officer.

Mr. Ordaz-Cruz did go to HCMC on his own the next day because he had slight pain in his back as a result of this accident. Mr. Ordaz-Cruz reports that he is medical A'ok.

Mr. Ordaz-Cruz reports that while in his van, he could hear a female voice screaming for help. This screaming voice was coming from below where the bridge had collapsed. Mr. Ordaz-Cruz feels very bad that he could not help this female yelling for help.

Mr. Ordaz-Cruz states that she slammed on the brakes of his vehicle "Right away", but that things happened so quick that he does not remember everything that happened.

Mr. Ordaz-Cruz then called a friend of his who came and picked up Mr. Ordaz-Cruz and brought him home.

Cal

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-8-07 Time: 1430 has
Interviewer: Sst. Toch Sandberg MDD
DRIVER Daniel Joseph Cenmak
Driver's License Number: State:
Full Name Daniel Joseph Cennak Dollie
Driver's License Number: State: MN Full Name Daniel Joseph Cennak Full Address Dofficer Officer
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right
Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital What Ambulance Service:
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
C Complaint of injury with no obvious injury visible Muscle fightening in back Please explain where you were on the bridge – (direction of travel [NB SB], which lane,
Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or peop were they doing?	le were around you? (Color,		escriptio	n), what	
a sensation is described - m	and smell relative to the cra ovement left to right, forward	l and back, up o			
VEHICLE:					
What vehicle were you in?			·		
	Model Oxtera Year Dwner: Taniel (Policy Numb	,		en	
Who else was in the vehicle 1. Sandra Marie (ermak	with you? NA (Nan Seat Position (See above) Front Passengen Sea	ne, address, pho Injured?	ne, DOE YES (NO)	ole
2.	Seat Position (See above)	Injured?	YES	NO	
3.	Seat Position (See above)	Injured?	YES	NO	
4.	Seat Position (See above)	Injured?	YES	NO	
5	Seat Position (See above)	Injured?	YĖS	NO	

Additional notes/comments:

6.

Seat Position (See above)

Injured?

YES NO

Interview with Daniel Joseph Cermak-Retired St. Paul Police Officer

Mr. Cermak was driving a 2007 grey Nissan X-tera SUV, MN license Mr. Cermak had his wife in the vehicle as well. Sandra Marie Cermak was sitting in the front passenger seat of the vehicle.

Mr. Cermak was planning on attending the Mn Twins game as he was traveling in the South bound lane in the most Western lane while on the bridge. The vehicle driven by Mr. Cermak is currently parked on the North end of the bridge.

Mr. Cermak reports that before the bridge collapse, he was in a long line of traffic which Mr. Cermak describes as "Bumper to bumper". While driving his vehicle, Mr. Cermak described what he thought to be a "Bouncing" sensation on the bridge as if a large truck had passed by him. Mr. Cermak observed two construction workers to his left as they were working on the bridge. Mr. Cermak then heard a "Cracking" noise as he then observed a construction trailer sliding down the road. Mr. Cermak then realized that the bridge was falling as he tried to put the brakes on is vehicle, but the vehicle continued to roll towards the broken end of the bridge. Mr. Cermak began to yell at his wife that they were going to be going over the bridge in their vehicle. Mr. Cermak then heard a third "Crash" and then he saw a large amount of smoke and debris flying in the air. Mr. Cermak reports that his vehicle then came to a stop as he neared the edge of the bridge. Mr. Cermak yelled for his wife to get out of the car as he did the same. Mr. Cermak looked back towards his vehicle as he saw that the construction trailer was gone and had gone over the edge of the bridge. Mr. Cermak then helped other people off of the bridge as a small group of people headed over a median and towards the 4th St. exit.

Mr. Cermak added that while he saw the construction trailer going over the edge of the bridge, he thought he observed a third construction worker get run over by this trailer. Mr. Cermak could later see two construction workers helping an injured third construction worker to safety after the construction trailer had, perhaps, hit this third construction worker.

Mr. Cermak described the traffic in front of him as being "Bumper to bumper" and very busy. Mr. Cermak has seen photos of the bridge collapse and believes that there are numerous cars that are in the water as he could see a long string of vehicles in front of him before the bridge gave way. These vehicles that Mr. Cermak is describing are not seen in the photos after the devastation.

Mr. Cermak describes the Northbound traffic on the bridge as being "Bumper to bumper as well.

Mr. Cermak has muscle tightness in his back and his wife, Sandra Cermak also has muscle soreness in her back.

Mr. Cermak then called his daughter and had the daughter pick he and his wife up at Dinkeytown, near the Uof M.

(2)

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-9-07 Time: 1350 hrs.
Interviewer: Sgt. Tork Sandbrag-MPLS PD DRIVER Amanda To Hilshorst
DRIVER Amanda To Hil Shorst
Driver's License Number: State: MN
Full Name Amanda To H: L Shorst DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital What Ambulance Service: Socienies - Lower back
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
7 III materially to perform a task they could do octore injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

		Model matiba Year Owner: Amanda H			
Insura	ance Company: <u>5</u> 7	are Fax Policy Numb	oer: レルビ .		_·
Who	else was in the vehicle	e with you? NA (Nan Seat Position (See above)		ne, DOI YES	•
2.	N A	Seat Position (See above)	Injured?	YES	NO
3.	¢ V	Seat Position (See above)	Injured?	YES	NO
4.		Seat Position (See above)	Injured?	YES	NO
5.		Seat Position (See above)	Injured?	YĖS	NO
6.		Seat Position (See above)	Injured?	YES	NO

Interview with Amanda Jo Hilshorst on 8-9-07 at 1610 hours.

Ms. Hilshorst was driving a Chevy Malibu, MN license Ms. Hilshorst was driving her vehicle on the South bound lane of traffic, but was at the North end of the bridge when it collapsed.

Ms. Hilshorst stated that she observed "Wall to wall traffic" before the bridge collapsed. Ms. Hilshorst states that her vehicle was stopped in traffic when the bridge collapsed. Ms. Hilshorst could remember seeing a construction truck to her left as well as 5/6 construction workers. Ms. Hilshorst then felt "Like a wave or something..and then it bounced three or four times really hard (ground). Ms. Hilshorst, initially, thought this bouncing to be because of the work being done by the worker. Ms. Hilshorst said her vehicle then "Lunged" forward as she held on to her steering wheel.

Ms. Hilshorst then observed a red vehicle go over the edge of the bridge. Ms. Hilshorst remembers seeing the under carriage of this vehicle as it went over the end of the bridge. Ms. Hilshorst also remembers seeing a construction worker rolling down the now elevated street (on foot), but she does not remember if this construction worker went over the end of the bridge or not. Ms. Hilshorst could hear other construction workers yelling for the worker who had rolled down the street towards the end of the bridge.

Ms. Hilshorst then made her way off the bridge along with other bridge victims. Ms. Hilshorst then walked home. Ms. Hilshorst did not sustain any major injuries and reports only soreness in her lower back.



Date of Interview: 8-7-07 Time: 1530
Interviewer: Syt. I. Jan Shing MAD
DRIVER Stary Fregueson - only Preson in valide
Driver's License Number:
Full Name Stacy ELizabeth Stickney Fraguson
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital What Ambulance Service:
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
NO ITTURY
Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

Make Honda Plate	Model (AV Year Owner: Stacy Fing	12003 Cole	or Bla	CK
Insurance Company: 57	Tate Farm Policy Numl			
Who else was in the vehic 1.	le with you? NA (Nan Seat Position (See above)		one, DO YES	
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

Interview with Stacy Elizabeth Stickney Ferguson

Ms. Ferguson was driving a black colored 2003 Honda CRV, MN license . Ms. Ferguson was driving in the South bound lane and was stopped on the North end of the bridge. Ms. Ferguson did provide me with photos of the bridge site and further showed me where her vehicle is located in these photos. I have included these photos in the packet of Ms. Ferguson.

Ms. Ferguson was driving in the most east lane of the South bound lane going over the 35W bridge. While driving her vehicle in traffic, Ms. Ferguson reports that she observed the workers on the bridge walking towards the center of the bridge. Ms. Ferguson then felt a vibration on the bridge. Ms. Ferguson says this vibration began to "Rumble" and then she saw dust rising. Ms. Ferguson could then see the bridge workers running towards her and yelling that the bridge was collapsing.

Ms. Ferguson reports that her vehicle was "Rocking side by side". Ferguson says she looked to her left and could see a construction vehicle also "Rocking" back and forth. Ms. Ferguson eventually observed this construction vehicle (Possibly a dump truck) go over the broken off edge of the bridge. Ms. Ferguson described this truck as "An open end truck". Ms. Ferguson also reports watching one of the workers fall off the edge of the bridge. Ms. Ferguson says this bridge worker was on foot and not in any vehicle. Ms. Ferguson says that this worker could not grab onto anything to hold himself back from falling over the edge.

Ms. Ferguson says that she did not sustain any injuries from this devastation.

I asked Ms. Ferguson further about "Rocking" that she had described to me. Ms. Ferguson stated that her vehicle, as well as others, was rocking back and forth so hard that the vehicle tires were coming off of the cement pavement of the bridge.

Ms. Ferguson says that she had got out of her vehicle and crawled over the median to get into the North bound lane of the bridge. Ms. Ferguson then walked with a group of people onto the 4st exit off of 35W. Ms. Ferguson then began to talk to other people who appeared to be in shock.

Telephone	Interview	
-----------	-----------	--

C-25

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-24-2007 Time: 1000
Interviewer: Tom Hendrickson #2960 Minneapolis Police
Robert Bradley Carlson
Robert Bradley Carlson
HILL Addrogs
l'elephone Hon Worl Cell:
Compliance with De Touristions. Glasses, etc YES NO NA Canc-IPS
Seat Position: Front Seat Oriver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital What Ambulance Service:
Nature of Injury (Circle): No in Jurie S A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB], which lane,
refer to bridge diagram): Southbouned 35W for right, Stopanel go traffic top speed at times was 15 m. P.H.
He was stopped in trappic and he looked over and saw a Crane in the Construction
site. He observed the back tires were louncing of the ground
John Jound

What other vehicles or people were around you? (Color, make, model, description) what were they doing? In front of him was a light Colored Sodan

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) Saw the bonnes of a Construction Crane-See Report Observed a dark Colored Sav go into the water.

VEHICLE:

What vehicle were you in?

Make INFINIT Plate:	1,10001	2001 Color	Silver	INC
Insurance Company:	Will call b			
Who else was in the vehicle 1.	for insurance will info-1	ldress, pho jured?	ne, DOB) YES NO	
2.	Se	jured?	YES NO	•
3.	Seat Position (See above)	Injured?	YES NO	
4.	Seat Position (See above)	Injured?	YES NO	
5.	Seat Position (See above)	Injured?	YES NO	
6.	Seat Position (See above)	Injured?	YES NO	

MOTEC.

Date of Interview: 8/9/2007 Time: ZOOPM
Date of Interview: 8/9/2007 Time: Z'00 pm Interviewer: Patrick Michaels/Phillips Furskerburg
DRIVER
Driver's License Number:
Full Name John Jeffrey Mogosh DOB:
Full Address
Telephone Home Vork: 763, 367, 45/5Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital What Ambulance Service:
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge - (direction of travel [NB SB], which lane, refer to bridge diagram): Traveling SB, unsure in which SB lane, Believe, the was his vehicle was located on top of the support column backed between Span 9 and span 10. The part of the bridge That he was on remained level while the section in hem (south bound) and to the part (NB) collapsed.


What other vehicles or people were around you? (Color, make, model, description), what were they doing? Expedition behind (Cold) - directly behind

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.)

First heard very lound boom, left bridge swaying side to side, sour PCI workers named NB in closed loves on his side (SB loves), he trenfelt his cer (ell (not very for). After be fell be reduced the bridge had collepted VEHICLE:

What vehicle were you in?

Make BMW Plate: Insurance Company: United	Model 3301 Year Owner: Northern Wate Works Supply w	r 7 W Colo	or Silva	es Fergrisa
Who else was in the vehicle 1. \mathcal{N}	with you? NA (Nan Seat Position (See above)	ne, address, pho Injured?	one, DO YES	B) NO
2. NA	Seat Position (See above)	Injured?	YES	NO
3. MA	Seat Position (See above)	Injured?	YES	NO
4. MA	Seat Position (See above)	Injured?	YES	NO
5. M/A	Seat Position (See above)	Injured?	YĖS	NO
6. N/A	Seat Position (See above)	Injured?	YES	NO





Date of Interview: 8/9/07 Time: 1000 hrs
Interviewer: SA Philippe Furstenberg
DRIVER
Driver's License Number: N/A State:
Full Name Christine Olson DOB:
Full Addres
Telephone Home Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital ~/A
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible Non€
Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):
Southbound outside Love on no-th side of bridge, Car on 12-fout
Portion that did not collapse. Over law new University Are NF.

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Silver Ford SUV to left Silver Honde Civic to less of Front - Herelling 10-15 MPH Silver Sedan in Front hed vehicle behind felt back What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) Mrs. Olson was looking up the . She felt a movement much like an earthquare. The bridge in front collapsed. Her hisband yelled at her to get out of they both did. She attend chound on debris dust. Offers were getting on it their cors. They all sot clown vis the bridge it becar it them. Mrs. Olson was is a nurse of went to Red Coiss to help. What vehicle were you in? Make TAGUAR Model X5-6 Year 1993 Color Green Owner: OLSON, Brant Fedural Plate: Insurance Company: Austak Policy Number: Who else was in the vehicle with you? NA (Name, address, phone, DOB) Seat Position (See above) Injured? YES (OLSON (hosband) dover Xinteritweel at some time as driver. Seat Position (See above) Injured? YES NO 3. Seat Position (See above) Injured? YES NO 4. Seat Position (See above) Injured?

Additional notes/comments:

5. .

6.

Seat Position (See above)

Seat Position (See above)

YES

YĚS

YES


Injured?

Injured?

NO

NO

NO



NOTES.

Date of Interview: 8/9/07

Time: 1000 has

Interviewer: SA Philippe Furstenberg, DSS

DRIVER

Driver's License Number:

State: MN

Full Name Brent Edward Olson

DOB:

Full Address

Telephone

Home

Work:

Cell

Compliance with DL restrictions: Glasses, etc

YES NO

Seat Position:

Front Seat Middle Seat <u>Driver</u> Left

Center

Right

Rear Seat

Left

Center Center Right Right

Bus occupants see diagram

Ejected:

YES

Safety Equipment used:

LAP

SHOULDER BOTH

Transported to Hospital

What Ambulance Service:

YES

Belts:

Walk-in

Hospital

NONE

Nature of Injury (Circle):

Incapacitating injury - broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.

В Non-incapacitating injury - Cuts, bruises, scrapes

C Complaint of injury with no obvious injury visible DINE

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

Supposed outside lane on Morth side of bridge. Gr on 12 Foot portion that did not collapse. Over land near University St

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

| travelling to 15 miles per hour.

Silver Ford SUV to left of From Silver Hards Croic to left of From Silver Schen in Front.
Red return behind Fell back.

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

First Felt something. Passenger was looking up trues. Fine felt movement, like a slow out to passenger asked it this was an earth quake. At some time, drown saw the bridge in front collapse. It collapsed in sections from south to north definitely. The ear rose up thouna bit. Waited for theirs to go down, but it didn't Lookeed back thoused the back was gone as usell. He told wike to get out. They got out, got cell phone.

VEHICLE: (Contid on back)

What vehicle were you in?

Make JAGUAR Model XJ-6 Year 1997 Color Green Plate: Owner: Description of Brent Edward

Insurance Company: Alls take Policy Number:

Who else was in the vehicle with you? NA (Name, address, phone, DOB) Seat Position (See above) Injured? YES (NO 1. Christine Front passenger of Address & phone same as doner" Seat Position (See above) Injured? YES NO 1 & NOTE: PASSENGER interviewed at some time as other 3. Seat Position (See above) Injured? YES NO 4. Seat Position (See above) Injured? YES NO 5. YĖS Seat Position (See above) Injured? NO 6. Seat Position (See above) Injured? YES NO

Additional notes/comments:

-) They met a nurse who lived on the 13th floor of the Riverside Apts who saw the bridge colleger. She immediately called 317 911 - but they don't remember her name.

C28

ISTH-35W Bridge Collapse Interview Ouestionnaire


25 11 55 W Bridge Conapse Interview Questionnaire
Date of Interview: 8/7/2007 Time: 1727
Interviewer: Patrick Michaels / Phillipe Furstenburg
DRIVER
Driver's License Number
Full Name Matthew Mark Lundquist DOB:
Full Address
Telephone Home Work: 651 738 8788Cell
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right
Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES (NO)
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital Urgent love of Apple Welley, M. What Ambulance Service: Walk-in Hospital Urgent love of Apple Welley, M. 100 am Thursday
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Jagver directly to right, believed Jagver was green or blue—occupents ren away via 2nd street who talking to anyone. Silver Civic directly in front Ford F250 parked in northbound lane—construction vehicle What did you seel feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described—movement left to right, forward and back, up or down etc.) Felt shaking, then felt large Jolt, then another large jolt, after which he hit his head on the ceiling. Locked out and saw that all cars in front of him had disappeared. He then saw smake noting VEHICLE: his rehide and two construction nothers many bound. What vehicle were you in?						
Make Ford Plate:	Model Espedition Yearner: Matthew	12005 Col	or Ta	n/60ld		
Make Ford Model Expedition Year 2005 Color Tan/Gold Plate: Matthew Lundquist Insurance Company: Policy Number: Att Vallagum						
Who else was in the vehicl 1.		ne, address, ph	one, DC	DB)		
1.	Seat Position (See above)	Injured?		NO		
2.	Seat Position (See above)	Injured?	YES	NO		
3.	Seat Position (See above)	Injured?	YES	NO		
4.	Seat Position (See above)	Injured?	YES	NO		
5.	Seat Position (See above)	Injured?	YĖS	NO		
6.	Seat Position (See above)	Injured?	YES	NO		

NOTEC.







DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	20

RECORD OF INTERVIEW

Mohamed A. Mohamud

Interviewed August 6, 2007 over the phone

Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Mohamed A. Mohamud

Mr. Mohamud stated he was driving southbound in the right lane at the north end of the bridge in his silver 2004 Ford Freestyle. According to Mr. Mohamud, the first thing he heard was a noise like a tornado. He then observed two construction workers falling just prior to him falling and

landing above the train tracks. He said the bridge then collapsed behind him.

According to Mr. Mohamud, he sustained a lower back strain, a sprained left ankle, and was momentarily knocked unconscious.

(C-3/)

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 86.07 Time: 315	
Interviewer: Ron K	
DRIVER Mohamed Mohamud.	
Driver's License Number: License Number: MIN CLASS A	
Full Name DOB:	
Full Address	
Telephone Home: Work: Cell:	
Compliance with DL restrictions: Glasses, etc YES NO NA	
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram	
Ejected: YES NO	
Safety Equipment used: Belts: LAP SHOULDER BOTH NO NE WORK	J
Transported to Hospital YES NO Walk-in Hospital U of M What Ambulance Service: 1eft @ 4 AM	
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.	
B Non-incapacitating injury - Cuts, bruises, scrapes	
C Complaint of injury with no obvious injury visible	
Please explain where you were on the bridge –(direction of travel [NB SB], which lane,	

refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing? Ked CAR behind we

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) I heard noise like formed saw Z guys from construction falling, next I fell. We hit the VEHICLE: VEHICLE:							
What vehicle were you in?							
Make FREETY C Plate: UNK	Model FORD Year of Owner: SAME	64 Color	slva	e			
Insurance Company Ameur	can Family INS. Policy Numbe	r: IN CA	<u></u>	<i>:</i>			
Who else was in the vehicle 1.	with you? NA (Name Seat Position (See above)	e, address, phone Injured?	e, DOE YES	B) NO			
2.	Seat Position (See above)	Injured?	YES	NO			
3.	Seat Position (See above)	Injured?	YES	NO			
4.	Seat Position (See above)	Injured?	YES	NO			
5.	Seat Position (See above)	Injured?	YĖS	NO			
6.	Seat Position (See above)	Injured?	YES	NO			

Additional notes/comments:

DANKLE SPRAIN LOW BACK STRAIN K'O'S NOMENTARRY



	Date of Interview: 8-13-2007 Time: 1200 hrs
	Interviewer: Tom Hendrickson #2960 MDD
elis	SA Anne Hughes-manied/melissa Anne Hanson Manden Minnesota
	Tell Name Melissa Anne Hughes DOB:
	Telephone Home Work: Cell:
	Compliance with DL restrictions: Glasses, etc YES NO (NA)
	Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
-	Bus occupants see diagram
	Ejected: YES (VO)
	Safety Equipment used: Belts: LAP SHOULDER BOTH
	Transported to Hospital YES (NO) Walk-in Hospital What Ambulance Service:
	Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
,	B Non-incapacitating injury - Cuts, bruises, scrapes
	C Complaint of injury with no obvious injury visible neck-Back seeing her own dorlor
	Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram): Traveling fourth bound on 35W in the far right lane.
	Traveling South bound on 35W in the far right lane. Traveling very slowly approx 5 to 8 MPH. There was a white Van directly in front of her.
	She observed a Construction worker and trappic baracaider and various hoses that were of the
	, of the was freefalling to

What other vehicles or peop were they doing?	le were around you? (Color, 1) _ Minj Van Direc	nake, model, de	escription Long	on), what
Two Tone Chew to	Mini Van direr uck upside d	own on T	top c	of her weh
a concetion is described m	, and smell relative to the crassovement left to right, forward hearing the glavindows up an ed by a emplo	and hade un a	. dorrm	ata)
What vehicle were you in?			i	
Make Ford Plate	Model ESCORT Year Dwner: Melissa	997 color Hughes	Red	
Insurance Company: <u>STaT</u>	e Farm Policy Number	er:		
Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)	e, address, phor Injured?	ne, DOI YES	=
2. A	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	ЙО

NOTEO.

Date of Interview: 8/8/2007 Time:
Interviewer: 5A Sunshine Adams
DRIVER Melissa Anne Hughes
Driver's License Number
Full Name DOB:
Full Address
Telephone Home: Work: Cell: (551-494-1795) Compnance with DE restrictions: Glasses, etc (YES) NO NA Contacts Glasses
Composition: Glasses, etc YES) NO NA Contacts Glasses Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital What Ambulance Service:
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Nech, back, shoulder Sorc Please explain where you were on the bridge—(direction of travel [NB SB], which lane, refer to bridge diagram): See diagram
She content see the water where she

•						
What other vehicles or peowere they doing? Person Men please white min-Black picks. What did you see, feel, head a sensation is described - response.	use crash - w top. Just man vorge of meta	make, model, of who have started as the started as and back, up of the started as	lescription War atting k for specific down	on), what S coo Garr ecifics if etc.)	amin / Chi eir	DU.
Make Ood Plate	Model Escot Year Dwner:	1997. Colo	r Re	d		
Insurance Company:	te Farm Policy Numb	er:				
Who else was in the vehicle	VIN		DO	D)		
1.	e with you? (NA) (Nan Seat Position (See above)	ne, address, pho Injured?	yES	NO B)		
2.	Seat Position (See above)	Injured?	YES	NO		
3.	Seat Position (See above)	Injured?	YES	NO		
4.	Seat Position (See above)	Injured?	YES	NO	:	
5.	Seat Position (See above)	Injured?	YĖS	NO		
6.	Seat Position (See above)	Injured?	YES	NO		X

NOTEN

FEDERAL BUREAU OF INVESTIGATION

	Date of	transcription	08/08/2007
	MELISSA ANNE HUGHES, date of birth , tele was interviewed at her pl Corporate Graphics, 1170 Grey Fox Road, Arden H telephone (651) 494-1795. HUGHES was advised o the interviewing agent and the purpose of the i provided the following information:	phone ace of ills, M f the i	employment, innesota, dentities of
	HUGHES was driving her red 1997 Ford plate when the 35-W bridge collapsed. any passengers in her car that day. HUGHES has glasses when she drives. HUGHES was not ejected a pick-up truck landed on her car when the bridge remembers hearing the sound of the truck crashing does not remember any other sounds. The bridge the spot HUGHES was located. HUGHES heard a management of the saw the screaming man holding his back apain.	HUGHES to wea d from ge fell ng on h fell t n screa	did not have r contacts or her car, but . HUGHES er car, but wo times in ming nearby
	HUGHES spoke to a few individuals after Works employee helped her out of her car. A workname of Wong had just picked up her son from some spoke to a couple who were celebrating their and couple was headed to the Twins game to celebrate white mini-van nearby and a black pick-up truck see the drivers of these vehicles.	man wit ccer. niversa e. The	h the last HUGHES also ry. This re was a
	HUGHES was in the far right southbound train tracks near Span 10. When HUGHES was help she remembers going to the Minnesota Metal Work few other individuals.	ped out	of her car,
	HUGHES provided no further information	n.	
Investig	ation on 08/08/2007 at Arden Hills, Minnesota		
	308H-MP-69278 Date dictated	N/A	

SA Sunshine C. Adams bo

by



Date of Interview: 8/16/07 Time: 1020
Interviewer: D COLLINS / GREEN N73B MPD
DRIVER
Driver's License Numbe
Full Name Alon DAVID BAHLELEN DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH AIRBAGS NO DEF
Safety Equipment used: Belts: LAP SHOULDER BOTH AIRBAGS NO DEAT Transported to Hospital Walk-in Hospital FAIRVIEW USAM What Ambulance Service: POV
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible BRUISING, CUTS HAWDS KNEES
Please explain where you were on the bridge –(direction of travel [NB/SB], which lane,

	e were around you? (Color, ma	ake, model, desc	cription), what
	our - lacas amor	CAP	en.	
A DE DE	MERICAN MADE	CDT 4	U)	
	SLARGER WOMAN,	3015		
What did you see, feel, hear,	and smell relative to the crash	? (Please ask f	_	
CAW MIERREAD L	vement left to right, forward a N SIGNS COME DO	ل ن ن ن		
DUST BEHIND FAST-TIPPED	FORWARD, STR D	own (s	΃	BACF
VEHICLE:				
What vehicle were you in?	1000		٠	
Make GMC Plate	Model SIERPA 1500 Year Owner: ARON	Zoo Color	Blac	K
	l <i>C任SSNE</i> Policy Number			•
Who else was in the vehicle v	with you? NA (Name	, address, phone	e, DOB	5)
1.	Seat Position (See above)	Injured?	YES	NO
2.	Seat Position (See above)	Injured?	YES	NO
	,			
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
/				
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

MOTFO.

Lt Kim Lune 290-3950



Date of Interview: 8/7/07 Time: 3:3	30 pm
Interviewer: SA Sunshine Adams	
DRIVER TFO John D. Vogelpohl	
Driver's License Numbe State: 1	My
Full Name Adam Jarold NOC DOB:	·
Full Address	
Telephone Home: Work:	Cell:
Compliance with DL restrictions: Glasses, etc YES N	NO NA
Seat Position: Front Seat Driver Center Middle Seat Left Center Rear Seat Left Center Bus occupants see diagram	Right Passengur Right Right Was able to retrieve
Ejected: YES (NO)	DER (BOTH) Wed. Mrs
Safety Equipment used: Belts: LAP SHOULI	DER BOTH Wed. Mg
Transported to Hospital YES NO Walk-in H What Ambulance Service:	Iospital
Nature of Injury (Circle): A Incapacitating injury – broken bones, h An inability to perform a task th B Non-incapacitating injury - Cuts, bru	nospitalized, severe cuts hey could do before injury.
C Complaint of injury with no obvious in Back of speech stiff	•
Please explain where you were on the bridge -(direction of tra	avel [NB SB], which lane, - South bourd

What other vehicles or people were around you? (Color, make, model, description), we were they doing?	
one of the following.	red 4-de
Even minuan to bot & 7 Cas.	s in his
What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics	if
a sensation is described movement left to right, forward and back, up or down etc.) Whomat ton Arc Exit Dign want estraight down Extensive Couple hilping Enic	Sharp no
Somali man in front w/ newer van	Startling
VEHICLE: One in work truck long noise	V
Diant tan too tan. Shook him 'What vehicle were you in?	"mside"
Make Jeen Model CMD Year 2006 Color Silver Plate: Owner: Jacqueline Hill	
Insurance Company: Progressive Policy Number: in glove box	
Who else was in the vehicle with you? NA (Name, address, phone, DOB) 1. Seat Position (See above) Injured? YES NO Gir Paulsen driving	
2. Seat Position (See above) Injured? YES NO	•
3. Seat Position (See above) Injured? YES NO	
4. Seat Position (See above) Injured? YES NO	
5. Seat Position (See above) Injured? YES NO	
6. Seat Position (See above) Injured? YES NO	
Adam saw Eric Leave the Car, then must have fallen. Nothing above vehicle	Eric
must have fallen.	
Nothing above vehicle	
Additional notes/comments:	

MOTER.

FEDERAL BUREAU OF INVESTIGATION

	Date of transcription 08/08/200	7
ADAM JAROLD MOR date of h	hirth	
was interviewed at his rental East, Minneapolis, Minnesota. NOE we the interviewing agents and the purpovided the following information:	was advised of the identities	of
NOE was in the front passed Jeep Commando, license plate The Jeep belongs to PAULSEN's girlfinot ejected from the vehicle at the his seatbelt fastened. At approximate evening, an officer assitance NOE with important items from the Jeep.	riend, JACQUELINE HILL. NOE w time of the collapse and had ately 8:45 pm, Wednesday	N.
NOE was not transported to of neck and back stiffness. NOE was Minneapolis, Minnesota. NOE was bel bridge, near the train tracks, befor collapse, NOE was able to get out of passenger side door.	hind or near Span 10 on the 35 re it collapsed. After the	
NOE remembers seeing a bla over onto a red smaller 4-door near mini-van to his left. There was a w PAULSEN, but no one was inside the t seven cars in NOE's general area.	work truck next to NOE and	L
NOE heard a sharp loud noi and saw the Washington Avenue Exit s noise was so loud it "shook [NOE] in couple assisting PAULSEN. A Somali a newer van.	nside." There was an elderly	ng
NOE provided no further in	nformation.	
vestigation on 08/07/2007 at Minneapolis, M		_
BA Sunshine C. Adams (A)	Date dictated N/A	

338

TFO John D. Vogelpohl

	Date of Interview: $8/7/2007$ Time: $2'.10 pm$
	Interviewer: 5A Sunshine Adams DRIVER TFO John D. Vogelpohl
	Driver's License Number: State: MN
٠	Full Name Eric James Paulsen DOB:
	Full Address
	Telephone Home: Work: Cell: Hourglass Drycleaners Compliance with DL restrictions: Glasses, etc YES NO (NA) Firearms Centificate
	Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
	Backend of Collapse
	Ejected: YES NO Trained freman (Cert.)—got Dut of vehicle Safety Equipment used: Belts: LAP SHOULDER BOTH Put cur in park
	Transported to Hospital YES NO Walk-in Hospital HCMC but couldn't What Ambulance Service: What Ambulance Service: Walk-in Hospital HCMC but couldn't more kneck but couldn't
	Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
ماد	ash (probably) Can't more kned (B) Non-incapacitating injury - Cuts, bruises, scrapes
	C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing? a 300 m - luxury vehicle 2 trucks. flipped over
Not sure where trucks were

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described – movement left to right, forward and back, up or down etc.)

The whole bridge waived - made eye contact W/ construction worker.

VEHICLE:

What vehicle were you in?

Make TGGO	Model CMD Year	Colo	r Silve	ور	
Plate	Owner: Jacqueline	Hill	DOP		
Insurance Company: Pro	ressive Policy Number	r: In gla	ve Bi	×	Friend
Who else was in the vehicle	with you? NA (Name Seat Position (See above)	e, address, pho	one, DOI	3) Ada	m NOE
1.	Seat Position (See above)				
Passenge	r Seat	L	of s	we	
2.	Seat Position (See above)	Injured?	YES	NO	
					Holams =
3.	Seat Position (See above)	Injured?	YES	NO	
4.	Seat Position (See above)	Injured?	YES	NO	•
5	Seat Position (See above)	Injured?	YĖS	NO	
		-			
6.	Seat Position (See above)	Injured?	YES	NO	

NOTFO

C36

• '.	Date of Interview: $8/10/2007$ Time: $3:00pm$
٠	Interviewer: Sunshine Adams
	DRIVER
	Driver's License Number: State: mN
٠	Full Name Angela Wong DOB:
	Full Address
	Telephone Home: Work: N/A Cell: N/A
	Compliance with DL restrictions: Glasses, etc YES (NO) NA
	Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
	Ejected: YES NO
	Safety Equipment used: Belts: LAP SHOULDER BOTH
· .	Transported to Hospital YES NO Walk-in Hospital What Ambulance Service:
	Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
•	B Non-incapacitating injury - Cuts, bruises, scrapes on ann, leg, eye C Complaint of injury with no obvious injury visible
	Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):
Bej	refer to bridge diagram): See diagram. wird/Near train tracks

The couple's can was intact. Red car of lady w/ baby Car fell on top of the red car. What other vehicles or people were around you? (Color, make, model, description), what were they doing? Iruck absorbed - pilver in cola - She exchanged #S W him. One guy helped then get her son's tennis bog (FBI ognit) One man had an injured his antle (Somali). One lady W baby pictures. What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if who grashed her purse. a sensation is described - movement left to right, forward and back, up or down etc.) Falling forward when bridge conapsed - could see through Could per small debus falling. morning often etrything was done She heard a man VEHICLE: No other morses reca

What vehicle were you in?

	Make TOYOTA Plate:	Model SIE Year Owner: Chuch Ta		5ilv		soud on
Insur	ance Company: Stat	te Farm Policy Num	bei		pide	ped on (Rt side)
Who 1.	else was in the vehicle $5m$	with you? NA (Nat Seat Position (See above)	me, address, phor Injured? (Not plant He plant	TES	INO L	o france
2.		Seat Position (See above)	Injured?	YES	NO	
3.		Seat Position (See above)	Injured?	YES	NO	
4.		Seat Position (See above)	Injured?	YES	NO	*
5.		Seat Position (See above)	Injured?	YĖS	NO	
6.		Seat Position (See above)	Injured?	YES	NO	Ť

NOTEC

FEDERAL BUREAU OF INVESTIGATION

		•			
				Date of transcription	08/13/2007
identitie:	IAI WEE AN interviewed s of the int	at her resterviewing a	is, Minneso idence. Wo gent and th	ota, telepho DNG was advi ne purpose o	sed of the
Wong's hus passenger into Minne tracks be could see	sband, CHUEN seat, comin eapolis, Min fore Span 10 out her fro ner song wer	TANG. Wonding from the management with the bridge on the bridge on the bridge on windshie.	g was with north side NG was behi dge. As th ld, the dek	her son in of the brid ind or near ne bridge cooris falling	lge to get the train llapsed, she
not trans	eye and on ported to th WONG went on	her arm. We hospital.	ONG was re WONG's so	Latively unh on was also	es on her leg armed and was not seriously after the
An FBI age car after spoke with time. The on top of	ne shock. Went helped Went the collaps	ONG and her e. A Somal: o had pictur the baby wa r. A middle	ith the own son retrical man had a see of her as driving	ner of the seve a tennis an injured a new baby wi a red car.	ilver truck. bag from the nkle. WONG th her at the A car fell
downward, windshield in pain.	as she saw	ers falling, debris fall: not hear an	ing below h	er through	falling the front man moaning
	WONG provid	ed no furthe	er informat	ion.	
		· · · · · · · · · · · · · · · · · · ·	·		
Investigation on 087	/13/2007 at	Minneapolis	s, Minnesot	a	
File # 308H-MP-69	9278		Date	dictated N/A	



- 1 -

FEDERAL BUREAU OF INVESTIGATION

		Date of transcription	08/07/2007
1	JUSTIN MICHAEL PROBST ("PROBST") residing at Minnesota, telephone number MN dirver's license at his residence. At the time of this inte CYNTHIA AND JOHN PROBST were not home. Afte identity of the interviewing Agent and the PROBST provided the following information:	cellular tele , was rview, PROBS er being adv	ephone number interviewed I's parents ised of the
	PROBST was traveling southbound, the center span, on the Interstate 35W brieferons was driving his mother's vehicle, a bearing Minnesota license plate . Al friend DERRIK COLE ("COLE"). Bloomington, MN, telephone Trecalled seeing at time of the collapse was behind him in the inside lane.	dge when it of brown 1996; so in the vel	collapsed. Saturn SL1, nicle was his cle PROBST
	PROBST felt the bridge "sway", thand then the bridge fell. PROBST does not impact. PROBST then recalled seeing concrevehicle fire. PROBST and COLE then exited doors and were assisted back onto the bridge worker with a pole. Approximately 20-25 mixtaken by a fire department boat to the nor Mississippi River.	remember the te dust and s the vehicle t ge by a const nutes later t	fall or the smoke from a through the truction they were
	PROBST advised that he still had headaches but did not sustain any injuries hospital, however, his parents did take his CARE CLINIC on Lyndale Avenue in Bloomingte examined, no injuries reported.	. PROBST did m to the FAII	not go the RVIEW URGENT
Investig	gation on 08/07/2007 at Bloomington, Minneso	ta	
File #		e dictated	
by	SA Robert J. E. Blackmore:rjeb		

Date of Interview: 8/1/07 Time: 1200Fm	
Interviewer: SA Robert J. E. Blackmore	
DRIVER	_
DRIVER Driver's License Number: 17113 > 1 State: WW Cythia Probability of Dan Pobs	r O
Full Name Justin Michael Probot DOB:	1
Full Address	
Telephone Work: Cell:	
Compliance with DL restrictions: Glasses, etc YES NO NA	
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right	
Bus occupants see diagram	
Ejected: YES NO	
Safety Equipment used: Belts: LAP SHOULDER BOTH	
Transported to Hospital YES NO Walk-in Hospital Fair on Lyndole What Ambulance Service: Hospital Fair on Lyndole Boomington, MN	-
Nature of Injury (Circle):	
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.	
B Non-incapacitating injury - Cuts, bruises, scrapes	
C Complaint of injury with no obvious injury visible Sore neck Xrays regarding has headacles	
Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):	

What other vehicles or people were around you? (Color, make, model, description), what were they doing? white truck behind him

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.)

SB 35W @ Star Crawl pass sway bridge nearly then feell

doesn't remember fall/impact saw dust to make from semiexited through we hick doors, Construction worker whole assisted back to bridge. On bridge 20-25 min then back to Show (north side) by boot FD

VEHICLE:

What vehicle were you in?

Make Saturn Model SLI Year 1996 Color Wown
Plate: Owner: Cynthia Probot

Insurance Company: Proce 1755; M. Insurance Number:

Who else was in the vehicle of the left of	with you? NA (Name Seat Position (See above)	e, address, phon Injured?	e, DOF YES	NO NO
2.	Seat Position (See above)	Injured?	YES	NO
3.	Seat Position (See above)	Injured?	YES	NO
4.	Seat Position (See above)	Injured?	YES	NO
5.	Seat Position (See above)	Injured?	YĖS	NO
6.	Seat Position (See above)	Injured?	YES	NO

NOTEC

Date of Interview: 8/7/67 Time: (515
Interviewer:	
DRIVER	mother
Driver's License Number	te: MN Theresa Cole
Full Name Derrik Robert Cde DC	DB:
Full Address	
Telephone Home: Work:	Cell:
Compliance with DL restrictions: Glasses, etc YE	S NO NA
Seat Position: Front Seat Driver Cen Middle Seat Left Cen Rear Seat Left Cen Bus occupants see diagram	nter Right
Ejected: YES (NO)	
	OULDER BOTH Urgent care - Next Hospital Fair View Order
What Ambulance Service:	Hospital Lyndak, Black
Nature of Injury (Circle): A Incapacitating injury – broken bo An inability to perform a	· · ·
B Non-incapacitating injury - Cut	s, bruises, scrapes
C Complaint of injury with no obvious of the contents of the c	
Please explain where you were on the bridge -(direction refer to bridge diagram): B-mper to Bungeer by	

What other vehicles or people were around you? (Color, make, model, description), what were they doing? white track boking

•	ar, and smell relative to the cra	•	•	s if
	movement left to right, forwar	· -	,	
tett rumbling	, felt drop like rolle	er Coaster,	don't r	emenber
Climber the	Lodor, exited swar worker helped w/ broa	nto bridg	e piece in	river
VEHICLE: Saw (odic front by	Me un m	inch 1	
What vehicle were you in?	oad in Front byo Jetta in ortsile law partially in water	re hangin	g on gr	adrail
Make	Model Yea			
Plate:	Owner:			
Insurance Company:	Policy Num	ber:	•	
Who else was in the vehicle	le with you? NA (Nai	ne, address, ph	one, DOB)	
1.	Seat Position (See above)	Injured?	YES NO)
2.	Seat Position (See above)	Injured?	YES NO	· •
	(,		·	
2	Cook Donision (Cook house)	I	MEG NO	
3.	Seat Position (See above)	Injured?	YES NO	
4.	Seat Position (See above)	Injured?	YES NO	· ·
				٠
5.	Seat Position (See above)	Injured?	YĖS NO)
	,	-		
6	Seat Position (See above)	Injured?	VES NO	•

FEDERAL BUREAU OF INVESTIGATION

				Date of transcription	08/07/2007
DI residing at				date of birth	
was COLE's r	mother THER being advi	residenc RESA COLE, Ised of th	e. Also p cellular e identit	present during telephone nurely of the inte	mber Leading
helonging to	o PROBST's E was seate	mother, a ed in the	1996 Sat front pas	N PROBST in a curn, MN licen ssenger's seat	se plate
lane of 35W road buckle as a roller the water.	when COLE up in from coaster ty COLE and PI doors and	felt rumb nt of him ype feelin ROBST were then swam	ling and prior to g. COLE of able to the h	g southbound i then dropped. dropping. COL does not remem exit the vehioridge where ter with a brook	COLE saw the E described i ber impacting cle through hey were
was sore from	om the vehi owever, his CLINIC at	icle's sea s parents 98th and	t belts. took him Lyndale,	ad stiffness i COLE did not to the FAIRVI Bloomington,	go to the EW OXBORO
estigation on08/0	7/2007 at	Bloomingt	on, Minn	esota	
# 308H-MP-692	78			Date dictated	
SA Robert J	. E. Blackı	more:rjeb-	A PA		








DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	8

RECORD OF INTERVIEW

Lindsey Peterson

Interviewed August 4, 2007 at Fairview Medical Center at the University of Minnesota Campus. Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Lindsey Peterson (5'6" 190lbs.)



Ms. Peterson stated that she was driving a 2000 Volkswagon Passat. According to Ms. Peterson, she was heading southbound in the left lane when she heard a snapping sound and saw the bridge in front of her collapse. She recalled then falling down into the river. Ms. Peterson stated that she unbuckle her seat belt and initially felt like she was thrashing around and drowning while trying to get out of her vehicle. She did not recall how she escaped her vehicle but surfaced where a construction worker helped her out.

Ms. Peterson said she sustained an L1 burst fracture of her spine, facial abrasions from her air bag deploying, and abrasions to her right hand and right knee.







DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	15


RECORD OF INTERVIEW

Alicia Babitz

Interviewed August 7, 2007 at Ms. Babitz's residence.

Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Alicia Babitz (5'3" 130 lbs.)



Ms. Babitz stated she was driving southbound in the far right lane on the middle span of the bridge in her black 1998 Nissan Maxima (VIN Babitz, she felt the bridge come out from under her and simultaneously saw the bridge come apart in front of hers. She said she closed her eyes and the next thing she remembers is feeling the water filling into her vehicle. She doesn't recall how she released her seatbelt but did so and went out one of the windows (unknown which one). She said she swam to the bridge, crawled up on top and waited for help.

According to Ms. Babitz, she sustained a fractured sacral, concussion and numerous scrapes to her extremities in addition to seatbelt bruises to her chest and hips.

Date of Interview: 8/8 Time: 1420
Interviewer: COLLINS / 6 REEN NTSB MPD
DRIVER MPD
Driver's License Number: State: CA
Full Address
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital DAT AFTER - DOCTOR
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury. B Non-incapacitating injury – Cuts, bruises, scrapes C Complaint of injury with no obvious injury visible.
C Complaint of injury with no obvious injury visible 5 WALL WUSCLE TEARS
Please explain where you were on the bridge – (direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing? WEAR JEREMY - WAT DIV OR EXPLORER, WAS IN FRONT BY

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.)

BRIDGE SHAKING - FELT LIKE EARTH QUATE, WHT TRUCK SLID. TO LEFT, SHEIN LFT LN, FOR SPLIT SECOND COULD SEE OTHER

SIDE OF BRIDGE NEXT THING, CAR IN 1720, ROLLED DOWN WINDOW SWAM TO PART OF BRIDGE NOT UN DERWATER.

VEHICLE:

What vehicle were you in?

Make INFINITY Model 635	Year 2005 Color SILVER
Plate: Owner: C. Y.	(SHEWAS BWNEE)

Insurance Company STATE	FARM	Policy Number	r:		
Who else was in the vehicle val.	with you? Seat Position		, address, phon Injured?		B) NO
2.	Seat Position	(See above)	Injured?	YES	NO
3.	Seat Position	(See above)	Injured?	YES	NO
4.	Seat Position ((See above)	Injured?	YES	NO
5	Seat Position ((See above)	Injured?	YĖS	NO
6.	Seat Position ((See above)	Injured?	YES	NO

Additional notes/comments:

VIN

SPÄN 3

NOTEC.

 γ_{p+1}

ISTH-35W Bridge Collapse Interview Questionnaire
Date of Interview: 8/1/07 Time: 930 AM
Interviewer: SA Robart J.E. Blackmore
DRIVER Jerenz State Schutte
Driver's License Number
Full Name Jereny Scott Schutte DOB:
Full Address
Telephone Home: Work: Cell: (65)-784-9666
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: NO Belts: LAP SHOULDER BOTH regat surgery
Transported to Hospital YES NO Walk-in Hospital Fairuien Regents in What Ambulance Service: What Ambulance Service: Hospital Fairuien Regents in Burnsville, MN
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible brome on head had stickes checked from band brades
Please explain where you were on the bridge –(direction of travel [NB SB], which lane,
refer to bridge diagram): South bound Sie diagram

verelvich					:
phone offer france could Bel	Front Lyona Guys Swa	In Ginity	piss.e r world	ed to Stree	
a sensation is described Febt like couple Sh phone of time Saw section of with diplow Heard rumbling WEHICLE:	-movement left to right, forward ockwaves, big speed but deck sisk up when began road broke trank laws of at beginning, herste	and back, up	or down e	etc.) w/b	room-
got booknown Make Chewale parker xysminutes Plate:	Model 2599 Year Owner: Carroll Dis		or whi	01,0101000	AVE IN 5250/
Who else was in the veh	icle with you? NA (Nam Seat Position (See above)	ne, address, ph Injured?		B) NO	
2.	Seat Position (See above)	Injured?	YES	NO	
3.	Seat Position (See above)	Injured?	YES	NO	
4.	Seat Position (See above)	Injured?	YES	NO	
5. .	Seat Position (See above)	Injured?	YĖS	NO	
6.	Seat Position (See above)	Injured?	YES	NO	

NOTFO.

in the 200-300 steel pieces in truck 3-4 ft. Long 4 in wide 2 10-12 pls/each galvanited Steel - in back of pick up

- packaged to each strapped together Loser in Yellow box 2 boxes of galvanited anchor bolts N 5 packs concrete form ties (Solid Steel) 2 black cases w/ rebar tying gons

FEDERAL BUREAU OF INVESTIGATION

				Date of transcription	08/07/2007
	JEREMY S	COTT SCHUTTE	("SCHUTTE"),	residing at	
	was DISTRIBUTING, 7540 651-784-0606. Afte interviewing Agent provided the follow	r being advis and the natu	Lino Lakes, sed of the icare of the in	e of employme MN, telephor dentity of th	ne number ne
	SCHUTTE of the center collapsed. SCHUTTE Chevrolet 2500 pic VIN prior to the bridgwas occupied by two SCHUTTE. Behind SC	was driving kup truck bea SCHUTTE e collapse. (o(2) young bo	e Interstate his work veh aring Iowa li recalled two one vehicle, oys was immed	35W bridge which a whith the second plate of t	when it te 2003 and ear him just be a Saturn, cont of
	SCHUTTE feeling he was tra- observed a section fall. SCHUTTE drop the water the road SCHUTTE exited the construction emplo	of the deck ped straight broke and hi vehicle on h	oig speed bun rise up as h down into th is vehicle we nis own and w	mps. SCHUTTE his vehicle be ne water. Upo ent into the was assisted	then began to began hitting water. by a PCI
	SCHUTTE Burnsville, MN. SC that the purpose f and clean stitches	or his hospit	sustain any cal visit was	y injuries am s to have a c	nd stated doctor check
	SCHUTTE 300 pieces of galv in length, 4 inche strapped together two(2) boxes of ga solid steel concre laser equipment, a	s wide, weigh in groups of lvanized anch te form ties,	that are eaching 10-12 point 10. The vehicle and a yellow ca	ch approximatounds. These icle also cord 5 strapped ase containing	cely 3-4 feet pieces are ntained packages of ng a piece of
	The fema call her fiancé. T	le in the Int he fiancé cal	finity used S Lled back ide	SCHUTTE's celentifying him	ll phone to mself as
Investig	ation on 08/07/2007	at Lino Lake	es, Minnesota	a .	
File #	308Н-МР-69278		Date	e dictated	
by	SA Robert J. E. Bl	ackmore:rjeb	265 B		

FD-302a (Rev. 10-6-95)

308H-MP-69278

Continuation of FD-302 of JEREMY SCOTT SCHUTTE ,On 08/07/2007 ,Page 2

JASON JENNINGS, telephone cellular and that he was looking for KATHERINE YANKELEVISH.



Minneapolis Police Department Family Violence Unit



From the desk of Lt. Kim Lund 612-673-3676

NTSB

Date: 8-27-07

To:

Subject: Phone interview of 35W bridge victim

Crystal Manning

Home-Cell- 7

On 8-28-07 at approximately 1445 hours, I spoke by phone to a party that identified herself as the above, CRYSTAL MANNING.

Manning told me that she was driving her Grand Cherokee southbound on 35W at the time of the collapse of the bridge. She stated that she was in the lane closest to the river and had just gotten onto the bridge when she heard a loud crack and bang and stated that it felt like she was on a wave. She then felt a side to side jolt and went down head first. Manning believed that they hit the bridge on the passenger side of the vehicle, as the tires blew out, the vehicle then bounced and flipped into the water upside down. She then remembers her passenger, MICHAEL STONER trying to free her from the seatbelt. The front windshield broke out and she was able to open the drivers side door of her vehicle and exit into the water.

Manning states that both she and STONER had seat belts on, but does not recall airbags deploying, she believed that a white car was in front of her and that she was going approximately 45 MPH in MN

Manning suffered a fractured T-11 and a badly bruised arm Stoner suffered from lacerations to the hand, arms and legs and possibly whiplash, both were transported to hospitals.

I did not speak to Stoner, as he is currently incarcerated at Washburn Cty Jail pending court on child abuse charges, she last spoke to him on 8-3-07.

Manning stated that the bus and the Taystee truck both passed her earlier on 35W.

ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-4-07 Time: //A. M
Interviewer: Detection Danfieldy / HC
DRIVER They Thanh 12h
Full Name DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital Hospital Hospital Transported to Hospital YES NO Walk-in Hospital Hospit
Nature of Injury (Circle):
An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

Atopped in Dungen to i traffic Haw Heard Mundle Haw I Heard Mundle

	what other vehicles or people were around you? (Color, make, model, description), what
	were they doing?
	hashed model fort
	into rem. Cont swem
12	eled selfing to share
	What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if
	a sensation is described – movement left to right, forward and back, up or down etc.)

VEHICLE:

What vehicle were you in?

Make Mayda Insurance Company:	Model A Owner:	V Year Loane Policy Number	80 Color 7. Ro- 1:	b	J.
Who else was in the vehicle		NA (Name (See above)		e, DOE YES	
2.	Seat Position	(See above)	Injured?	YES	NO
3.	Seat Position	(See above)	Injured?	YES	NO
4.	Seat Position	(See above)	Injured?	YES	NO
5.	Seat Position	(See above)	Injured?	YĖS	NO
6.	Seat Position	(See above)	Injured?	YES	NO

Additional notes/comments:





- 4 "					
					<u> </u>
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	31

RECORD OF INTERVIEW

Abdi Sahal

Interviewed August 10, 2007 at his residence Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Abdi Sahal (5'9", 126 lbs)



Mr. Sahal stated he was driving southbound in the left lane, just north of the middle span, going 5 m.p.h. in his navy blue 1992 Toyota Camry. According to Mr. Sahal, the first thing he saw was the bridge ahead of him drop a little then drop a lot ending up in the river. Mr. Sahal stated that the span he was on angled downward. According to Mr. Sahal, his whole car went underwater. Mr. Sahal stated that he undid his seatbelt and went out the driver window to the surface. He said when he surfaced, he saw another girl swimming and a guy with a bloody face in a red car that couldn't get out.

According to Mr. Sahal, he sustained a neck injury, a rib injury and a lung contusion.



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview:

8-10-07

Time: 10 15

Interviewer:

Bonk

DRIVER

Driver's License Number: 5 400 -029 -080 \$770

State: MIN.

Full Name

Abdi SAhAl

DOB:



H+5'9" wt. 126/65

Telephone

Home:

Work:

Cell

Compliance with DL restrictions: Glasses, etc

YES

NO

Seat Position:

Front Seat

Driver

Center

Right

Middle Seat Rear Seat

Left Left Center Center Right Right

Bus occupants see diagram

Ejected:

YES / NO

Safety Equipment used:

Belts:

SHOULDER BOTH LAP

Transported to Hospital

Walk-in

Hospital HCMC ADMITTED.

What Ambulance Service:

Nature of Injury (Circle):

Incapacitating injury - broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.

Non-incapacitating injury - Cuts, bruises, scrapes В

C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

I was in @lane going S/B, worth of middle SPAN. gong Smph

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

Don + Remembel

l so K	What did you see, feel, hear, a sensation is described—mo Bunger to Dun Led forward. SA I Know I'm VEHICLE: What vehicle were you in? Make Toyota Plate		`	-	
	Make Toyota Plate	Model Year Owner:	90 Color A	JA V -	7
	Insurance Company: Amel	Famly FAS. Policy Numb	er:		
	Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)	e, address, phone, Injured? Y		NO)
	2.	Seat Position (See above)	Injured? Y	ÆS	NO
·	3.	Seat Position (See above)	Injured? Y	ÆS	NO
	4.	Seat Position (See above)	Injured? Y	ÆS	NO .
	5	Seat Position (See above)	Injured?	YĖS	NO
	6.	Seat Position (See above)	Injured?	YES	NO

Additional notes/comments:
NECK Injury, Ribinjury, pulmonary Contusion

undied seal belt.

- My whole car nent under the water. I went out Driver window. I got to surface saw another girl swimning. A RED can behind me the driver's face swimning. A RED can behind me the driver's face was bloody couldn't get out. Police off. told soneone was bloody couldn't get out. Police off. told soneone else on RADIO to get a Kinife out of his CAR. I swam else on RADIO to get a Kinife out of his CAR. I swam to bridge. Z guys helped me up. Idon't Know if quy in Red car got out.




ISTH-35W Bridge Collapse Interview Questionnaire
Date of Interview: 8/9/07 Time: 1526
Interviewer: D. COLLINS NISB/CELEN MPD
DRIVER
Driver's License Number: F376-021-040816 State: NN
Full Name DIJANA ANDIC DOB:
Full Address
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital FAIRVIEW OF M
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge – (direction of travel [NB which lane, Green to bridge diagram):
DTLU
et Li

What other vehicles or people were around you? (Color, make, model, description), what were they doing? NO INFA

What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) TRAFFIC-SAYS LOOKED SMP PEINING INTO UV !! HITSOMETHING -THINKS OTHER SIAL SAW CONSTRUCTION " RIPPLE ET FECT AIRBAG DEPLOYED impact on nead, body VEHICLE: What vehicle were you in? Make NISSAN Model ULTIMA Year 1999 Color STLVER Plate: Owner: DIJANA ANDIC Insurance Company: Americaa fanda Policy Number: Insurance Who else was in the vehicle with you? **NA** (Name, address, phone, DOB) Seat Position (See above) Injured? YES NO 2. Seat Position (See above) Injured? YES NO 3. Seat Position (See above) Injured? YES NO 4. Seat Position (See above) Injured? YES NO 5. . Seat Position (See above) Injured? YĖS NO 6. Seat Position (See above) Injured? YES NO

Additional notes/comments:



NOTES.







DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	28

RECORD OF INTERVIEW

Sheila Bennet-Kilander

Interviewed August 9, 2007 at Red Cross Center
Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Sheila Bennet-Kilander (5'5" 120 lbs.)



Ms. Bennet-Kilander stated she was driving northbound, going about 30 m.p.h. in the right lane at the north end of the bridge in her pewter 2006 Acura TL. According to Ms. Bennet-Kilander, she remembered hearing a loud "bad" strange sound come from behind her. She immediately thought something bad happened at the construction site. All of the sudden she said the road was breaking up in front of her. Ms. Bennet-Kilander stated that there was a huge upheaval of pavement and then she started falling. According to Ms. Bennet-Kilander, after stopping, she stepped on the gas but then pulled over and stopped after the guy in front of her did so. She said that she was able to drive her vehicle off the bridge.

According to Ms. Bennet-Kilander, she sustained a stiff neck and back along with a headache.



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8- (Time:
Interviewer: Kon
DRIVER
Driver's License Number: State: MIN.
Full Name Shiela Bennett Kilander DOB:
Full Address
Ht. 55" WT 12016
Telephone Home: Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat <u>Oriver</u> Center Right Middle Seat Left Center Right
Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: Belts: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital UNI+Y
Nature of Injury (Circle):
A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible
Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):
N/B. IN Blane very close to university
I was going 30. I was told I was last carto
refer to bridge diagram): N/B. IN B / Ane very close to University Twas going 30. I was told I was last car to get over no, cars Afterme.

What other vehicles or people were around you? (Color, make, model, description), what were they doing? I don't recall

st bad the co	What did you see, feel, hear, a sensation is described - mo Theard a loud happened in con nakete ROAD wa VEHICLE: up h	and smell relative to the crash overment left to right, forward a sound; a sound; a breaking up eaval of pavene them an impact	and back, up or of Strange. I come f infronta nt. I th	downetc.) I thought something me fore. Then a hundred hought heat buck	hi gi
	Make Acura Plate:	Model TL Year of Owner: Bruce Kill	2006 Color Anden	Pewter	
- :		e FARM Policy Number			
	Who else was in the vehicle 1.	with you? NA (Nam Seat Position (See above)	e, address, phon Injured?	ne, DOB) YES NO	
	2.	Seat Position (See above)	Injured?	YES NO	
·	3.	Seat Position (See above)	Injured?	YES NO	
	4.	Seat Position (See above)	Injured?	YES NO	
	5.	Seat Position (See above)	Injured?	YĖS NO	
	6.	Seat Position (See above)	Injured?	YES NO	


Additional notes/comments:

51. FF NECK i back Headache

I thought I was about to Die. Then the fallow stopped. I stepped on the gas, I saw the car in front of me pull over i stop. I pulled over in front of him. I was standing by my care, the guy that was infront of me told my the bondge collapsed.

I was Able to drive away,







		**			
DATE OF COLLISION	TIME (2400)	INVESTIGATOR-IN-CHARGE	GROUP CHAIRPERSON	CASE NUMBER	PAGE
08/01/07	1801	G. Van Etten	R. Kaminski	HWY-07-MH-024	1

RECORD OF INTERVIEW

Justin Mishler (E2)

Interviewed August 7, 2007 at Mr. Mishler's residence Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Justin Mishler (5'11", 200 lbs.)



Mr. Mishler stated he was driving northbound in the left lane at the north end of the bridge in his purple 1999 Saturn SL2. According to Mr. Mishler the first thing he felt was the bridge shaking and rumbling. Mr. Mishler said that his vehicle dropped once then dropped again. According to Mr. Mishler, his vehicle stalled and he was able to restart it and drive it off the north end of the bridge. Mr. Mishler stated that he drove a few blocks away and parked his car because he could feel that the suspension wasn't right.

According to Mr. Mishler, he sustained a compression fracture to his spine at T-12.



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-7-87 Time: 300						
Interviewer: RONK						
DRIVER						
Driver's License Number: State: MIN						
Full Name Justin Mishler DOB:						
Full Address 4						
Ht 5'11" WT. 200165						
Telephone Home: Work: Cell:						
Compliance with DL restrictions: Glasses, etc YES NO NA						
Seat Position: Front Seat Driver Center Right Middle Seat Left Center Right Rear Seat Left Center Right						
Bus occupants see diagram						
Ejected: YES NO						
Safety Equipment used: Belts: LAP SHOULDER BOTH						
Transported to Hospital YES NO Walk-in Hospital Unity						
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.						
B Non-incapacitating injury - Cuts, bruises, scrapes						

Please explain where you were on the bridge -(direction of travel [NB SB], which lane, refer to bridge diagram):

 \mathbf{C}

Iwas N/B in () lane when bridge started shaking & Rumbling. I drove over som. Above train. Tracks. Stretzed sinking then a larger drop stop CAR stalled. I restorated & drove off bridge.

Complaint of injury with no obvious injury visible

were they doing? Isaw when it star Don't pemem What did you see, feel, hear,	e were around you? (Color, many construction uted Rumbling ber any cars and smell relative to the crash evement left to right, forward a	workers aroun ? (Please ask 1	Sor spec	Junning Since I sifies if	drovi off Bridge
VEHICLE:					
What vehicle were you in?					
Make Saturn Plate:	Model 522 Year Owner: Tom Family Mutual Policy Number	99 Color	Pu	rple.	
Insurance Company: Amer	Policy Numbe	r:			
Who else was in the vehicle 1.		e, address, phon Injured?	e, DOE		
2.	Seat Position (See above)	Injured?	YES	NO	
3.	Seat Position (See above)	Injured?	YES	NO	
4.	Seat Position (See above)	Injured?	YES	NO	
5.	Seat Position (See above)	Injured?	YĖS	NO	

Additional notes/comments:

6.

Compression FX T-12

TER

Injured?

YES NO

Seat Position (See above)



-1- C C FEDERAL BUREAU OF INVESTIGATION

Date of transcription 08/08/2007

Michele Marie McLane, DOB:

was interviewed at her place of employment

GMAC RFC, One Meridian Crossing, Richfield, MN. McLane was

interviewed regarding her experience during the collapse of the 35w

bridge. McLane provided the following information:

McLane was driving home from work on August 1, 2007 and was crossing the 35W bridge in Minneapolis when it collapsed. McLane was driving her 2002 silver Saturn L200 in the center northbound lane on the bridge. Her Minnesota license plate is She was driving across the bridge like normal when she heard a big boom sound. The sound was louder than fireworks and it lasted for a few seconds. It sounded as if something very heavy fell on something else very heavy. McLane looked out her driver side window and noticed approximately ten construction workers standing in a group. There was one man who looked like he was in charge of the other workers. This man appeared concerned and was looking south. McLane then looked south and saw something similar to a roll-off dumpster that had just fallen. McLane attributed th loud boom to the sound of the dumpster-like object falling. dumpster object was also similar to the box of a dump truck. McLane turned her focus forward when the bridge started moving like a boat on water. The main construction man was trying to keep his balance. McLane thought that there may have been an earthquake. McLane further described the movement of the bridge as smooth and rippling in every direction, McLane saw the bridge, itself, waving like water. The movement was similar to when you are docking a boat, and shortly after you shut off the engine, a wave comes back toward the boat and moves the boat in many directions at the same time.

After the waving, there was a millisecond when everything seemed OK. Then the second wave came. The bridge movement was violent and terrifying. The movements were not smooth, but were jerking. McLane may have experienced on sharp jerk which made her move down and to the right. McLane's personal items were falling out of compartments in the car. This movement did not last long, it was shorter than the first wave and it was horrifying. McLane noticed that her car had come to be at a little more than a 45 degree upward incline. McLane feared she would go into the

Investigation on	08/08/2007	at	Richfield, MN			
File # 308H-	MP-69278		É	Date dictated	08/08/2007	
by SA Ru	th E. Hovey					

This document contains neither recommendations nor conclusions of the FBI. It is the property of the FBI and is loaned to your agency; it and its contents are not to be distributed outside your agency.

308F-MP-69278

200 200 - 5	<u>Michele Marie</u>	McLane	, On <u>08/08/2007</u>	, Page <u>2</u>	
Continuation of FD-302 of	HILCHOIC HAR				

water and that it was too far to fall, she asked God to get her out and floored her gas pedal. McLane drove up the incline, over the rest of the bridge and past University Avenue. She pulled over to the right side of the road and started crying. She initially rolled down her window, but there was a lot of cement dust coming rolled down her window, but there was a lot of cement dust coming in her car, so she closed it. She tried to cal 911 but did not get in her car, so she closed it. She tried to cal 911 but did not get through. She called her husband and her father. McLane saw some cracking of cement, but does not recall where she saw it.

McLane saw a tan/goldish color car ahead of her when she was driving off the bridge. This car had a female driver. McLane could not recall anything else about the driver's appearance. McLane noticed this car shortly after she floored her gas pedal. McLane was going fast and ended up behind this car, which was not McLane was going fast and ended up behind this car, which was not going very fast, so McLane passed it in the right lane. McLane going very fast, so McLane passed it is the right lane. McLane looked in her rearview mirror was she was going to pass this car looked in her rearview mirror was no one behind her. She did notice a and noticed that there was no one behind her. She did notice a blue car on her far right side. This car turned onto University Avenue. McLane could not describe this vehicle or the driver any further.

When McLane first entered the bridge area she noticed a car in front of her with a bumper sticker that said, "Pro-child Pro-life." McLane recalled nothing else about this vehicle. When McLane crossed the bridge, traffic was lighter at the end, she recalls that she did not worry about other cars hitting her car while the bridge was waving or when it was jerking.

McLane described the construction worker as a white male, fit, in his mid-forties, with dark hair, wearing a hard hat and possibly something white. McLane thinks he had his sunglasses on top of his helmet. He was wearing a safety vest. he appeared very concerned as he looked south.

McLane later noticed that her car had a small dent and some minor scratches on the rear passenger side bumper. McLane did not see this damage prior to the bridge falling down. McLane took her car to the Saturn dealer and they found no additional damage. McLane is not currently planning to repair the bumper damage.

McLane provided a written statement that she wrote on 08/02/2007, so that her recollection was fresh. The statement is attached to this report. McLane also forwarded email messages which may help identify people to be interviewed. One person is Dan Schueller, who wrote an email telling his story of helping people

FD-302a (Rev. 10-6-95)

308F-MP-69278

Continuation of FD-302 of <u>Michele Marie McLane</u>	On <u>08/08/2007</u> , Page <u>3</u>
of the bridge. He was riding his bike ho collapsed. Schueller's email address is attached.	ome when the bridge s: nail that McLane sent are
McLane also marked her location supplied. the added the location of the the dumpster-like container.	on on the bridge diagram e construction workers and

August 2nd 4:00pm

RE: Personal Statement of 35 Bridge Collapse

Below is an account of my experience during the 35 bridge collapse on August 1, 2007. This statement was also given to Deputies J Alderink and Joseph Burk of the Anoka County Sheriff department the evening of the event. One of the deputies verified times I made calls on my cell phone and to whom. The Deputies talked to their commander who indicated I should call the Minneapolis police and give this statement. I called and spoke to Nancy at who indicated she would pass the information on and someone would get back to me. At the time of this statement no one has called; however, it is completely understandable considering the circumstances.

Per my cell phone record, I called my husband (Shawn) at 5:28pm to relay a story. After our call I left my place of employment at the corner or 35W and 494 and headed North.

I was driving across the 35W bridge in the left lane closest to the median and I heard a load "Boom." There were about 10 construction workers in the Southbound lane. I noticed one worker had a "What is going on" look on his face and was looking behind me. I looked over my left shoulder and saw a yellow box (possibly similar to a roll-off dumpster but maybe larger) that had just fallen. I am confident it had just fallen as the direction of the sound was consistent with where the dumpster was and there was dust coming up from around the bottom of dumpster. I did not see what the dumpster had fallen from as I turned back to check traffic a head of me.

After that, the bridge started to move. There were two waves of movement. The first wave wasn't too bad but the second wave was terrifying. After the second wave I found myself at what I thought was a 45-degree angle. I realized that I might be going into the water and yelled out "God get me out of here". I gunned it. I got over the crest. When I made it over the crest there was another car in my lane that was driving forward, but I wanted to get off the bridge faster and checked my rear view mirror to change lanes. There was only one blue car to my far right side. I moved lanes so that I was now in the right lane. I drove to flat land and parked my car. I did not see any other cars come behind me.

At 6:05pm I attempted to call 911 but only dialed 91. I placed another call to 911 and dialed correctly, but the line was busy. I then called my husband at 6:06pm. I calmed down enough to drive off the freeway to the Taco Bell near Stinson Blvd. At 6:36pm I called my Dad who recommend we write down the events while they are fresh in my mind and his finance' took notes.

I then called Shawn at 6:58pm and could not get through. I tried again at 6:58pm and we decided that I would calm down and drive home, as traffic was too bad in the area for him to come get me. I tried calling Shawn again several times but not get through.

I exited 35W at the City of Wyoming exit. I saw two Anoka County Deputies at the McDonalds. I met them at the door as they were leaving. I asked if we could please go back inside and asked if I could give them a statement. They took my driver's license information, home number and my work number in addition to the statement. We then went back to our cars. I sat in my car for sometime after the statement, as I was upset again. In the mean time the deputies had called their supervisor who indicated that I should call the Minneapolis Police department and make a

statement to them, as they would probably be heading up the investigation. After the deputy told me that information, then left the McDonalds parking and headed for home.

When I got home I had several calls to return. One included concern over a co-workers parents that she had not heard from. We live close by to her parents so we drove over to their house to see if they were home. We then returned home and I returned more calls. After I had a chance to re-group and learn that my co-workers family had checked in I called the Minneapolis Police department. They directed me to 612-673-3000 and I spoke to Nancy. Nancy indicated that she would get my contact information to the correct individual and someone would call me back.

Michele McLane

Work: 952-979-4165

Please do not call our home. We run a business from our home and I do not receive timely personal messages from that number.


8/8/07 12:30pm

Update

On Sunday August 5th I noticed damage to the back of my car. The damage consists of a dent, some scratches and pitting that was not there prior to this event. I do not intend to turn in a claim or fix the car at this time. I took the car to the Saturn dealership yesterday 8/7/07 at the recommendation of a co-worker. They checked the underbody of the car and no damage was found.



Interview #6



Mrs. Lach called the toll-free number established by the Board following the collapse of the I-35W bridge in Minneapolis and was identified as a potential victim. She was interviewed at her home on August 7, 2007 at 1900 hours. The interview was conducted by NTSB Senior Investigator Dennis Collins. Also present was her husband, Jeremy Lach.

Mrs. Lach stated she was northbound in the left lane on the I-35W bridge on August 1, 2007 at approximately 1810 hours. She described her location as just north of what she termed the "ski jump", referring to a section of the bridge resting at approximately a 45-degree angle. She further stated she had called her sister via cell phone at 1802 hours and was over the water at that time. She stated she was moving at a maximum speed of 5 MPH. She recalled being in-line with a group of construction workers using jackhammers; she had to turn to look out the driver's door window to see them. As she was looking at the workers, one of them started running northbound along the bridge. She described him as a young man with a thick, dark beard. According to Mrs. Lach, he went at most 10 feet, turned around, and gave a shrug. Mrs. Lach described the shrug and the expression on the worker's face as "Do you blame me?"

According to Mrs. Lach, as the worker did this, the bridge swayed, like a snake. At this, all the workers began to run. The bridge dropped a couple of feet, enough to start Mrs. Lach's car rolling backwards. The bridge deck dropped again, a drop Mrs. Lach described as "crumbly". After this drop, the front tire of the car in front of Mrs. Lach was over the edge of the collapsing bridge deck, placing Mrs. Lach one car length from the break. She stated this car was a blue Saturn; a light-colored SUV was in the right lane, occupied by a lone male.

Mrs. Lach stated she accelerated, "flooring" her car, passed between the cars in front of her, and passed over the break. She specifically recalls driving up an incline. The Saturn accelerated as well, remaining slightly in front of her. As she passed over the break, the bridge behind her continued to collapse. She continued northbound, passing under the 4th Street bridge and pulling to the left before the pedestrian walk. The blue Saturn from the bridge stopped under the pedestrian bridge, then pulled away. She stated she got out of her car and tried to call 911, but was unable to find her phone. She managed to convince a woman traveling southbound to call 911 (southbound traffic has stopped by this time). Mrs. Lach did speak to a 911 operator, but was not asked for any contact information.

¹ Refer to photo documentation of the scene; Mrs. Lach's position would be near the blue van with the wheelchair lift, on the opposite side of the highway.

Mrs. Lach recalled what she described as a lot of concrete dust in the air. She noticed the smoke from a fire was blowing to the north. She stated the first emergency responder she saw arrive from the north was a State Trooper. Emergency personnel began slowly arriving; Mrs. Lach flagged down another Trooper. When she indicated she did not need an ambulance, she was told to stay where she was. She recalled another responder, an older gentleman in a white SUV/Bronco marked "State Reconstruction". After waiting approximately 90 minutes, she called a friend in law enforcement. She was advised by her friend to remain where she was unless she needed medical attention; in that case, she was to provide her contact information to someone prior to leaving. She stated she gave her card to a MnDOT worker, then drove herself to Unity Hospital in Fridley. Mrs. Lach stated she was distraught, and could only drive at about 40 MPH at first, then managing to keep up with traffic as necessary. She recalled passing a southbound roadblock in Rosedale, halfway to the hospital in Fridley. She also recalled seeing lines of emergency vehicles making their way to the bridge. She stated it began raining, with lightning, as she neared the hospital.

At the hospital, she encountered the driver of the Saturn; she believes his name was Justin Mischer (spelling unclear) and she thinks he gave an interview to ABC News. A third person, a woman, also claimed to have been on the bridge at approximately the same place as Mrs. Lach. This unidentified woman took the exit right after the bridge and may have been the last northbound vehicle to successfully cross the bridge. When asked about any injuries, Mrs. Lach stated she had a possible hairline fracture of the right arm.

When asked to clarify her description of the movement of the bridge, Mrs. Lach described it as serpentine, believing that it first went to the right, then the left. She added that she thinks all the traffic around her shifted to the right in the early stage of the collapse.

When asked to provide additional information about her vehicle, she stated she was driving a 2003 silver Nissan Altima, Minnesota license plate was equipped with lap/shoulder belts and airbags. Mrs. Lach was wearing her seatbelt at the time of the collapse and was not ejected from her vehicle. The airbags in her car did not deploy. She was the sole occupant of her car.

When asked, she stated she traveled over the bridge twice daily, five days a week. She also stated she was concerned about the construction on the bridge, but she was not concerned about a collapse; rather, she was concerned about damage to the cars using the bridge.

Her insurance company is State Farm, Policy number



NATE OF COLLISION TIME (2400) INV 8/01/2007 1805 CST

investigator-in-charge
G. Van Etten

INVESTIGATOR

D. Collins

CASE NUMBER
HWY-07-MH-024

PAGE

SUMMARY OF WITNESS INTERVIEW CONCERNING THE I-35W BRIDGE COLLAPSE

INTERVIEWEE:

Dave Schamhorst ____

INTERVIEWER:

Dennis J. Collins, NTSB - Office of Highway Safety

DATE:

9-12-2007

LOCATION:

Via Telephone

On August 1, 2007, the interviewee was northbound in the left lane of I-35W, on the bridge over the Mississippi River in Minneapolis, Minnesota. Mr. Scharnhost was the sole occupant of a 2000 Dodge Intrepid, license plate MN

According to Mr. Scharnhost, as he was approaching the north end of the bridge span, he heard what he described as a "noise" behind him. He stated he looked to the left and saw a construction worker standing by some construction equipment and what he termed an "outhouse". Mr. Scharnhost stated it appeared as if the construction worked flew into the air; however, looking back on the events, Mr. Scharnhost believes that the section of bridge that he was on had dropped, rather than the construction worker and equipment moving upward. According to Mr. Scharnhost, the back end (behind him) of the section of the bridge he was on went down and he accelerated forward and off that section.

A car Mr. Scharnhost believes was behind him, also in the left lane, accelerated off the bridge and stopped as well. Mr. Scharnhost describes this car as a black Acura with a female driver; although he did speak with this woman, he does not know her name. He was able to recall that the black Acura had sustained some sort of damage, including a broken rear view mirror.

Mr. Scharnhost went back towards the collapsed bridge and met a number of construction workers coming off the span. Realizing he couldn't help, Mr. Scharnhost drove away, traveling with the black Acura to a nearby hospital where the driver was met by her husband. Mr. Scharnhost stated he was not injured and his vehicle did not sustain any damage. When asked, he stated the trip across the bridge was normal with nothing out of the ordinary until the noise. He was able to refer to a picture of the collapsed span and confirm he was on the section that came to rest on the train.

E6

SUMMARY OF WITNESS INTERVIEW CONCERNING THE I-35W BRIDGE COLLAPSE

INTERVIEWEE: Charles E. Hoffman, Jr. (Chuck)



INTERVIEWER: Invest

Investigator Dennis Collins, NTSB Office of Highway Safety

DATE:

10-17-2007

LOCATION:

Via telephone

Mr. Hoffman called the toll-free number established by the Board following the collapse of the I-35W bridge in Minneapolis and was identified as having been on the bridge at the time of the collapse.

According to Mr. Hoffman, he was southbound in the right lane of I-35W, heading towards Minneapolis, on August 1, 2007. As he approached the south end of the bridge, he felt his car drop two separate times. He looked in his rearview mirror and saw the north end of the bridge collapse; he could not see the middle of the span. Looking forward again, he observed the deck of the bridge "undulating". He accelerated, crossing the two remaining sections of the span, and took the first exit (Washington Avenue). Mr. Hoffman stated he was the last car to clear the span in the southbound direction. He also stated his vehicle is the one visible driving away from the bridge on the MnDOT traffic camera video. Mr. Hoffman parked by the University of Minnesota. He did not witness any portion of the Fire, EMS, or police response.

When asked, Mr. Hoffman stated he did not see, hear, or feel anything out of the ordinary prior to the two separate drops mentioned above. He did recall looking at the construction activities and thinking it might have been quitting time, as a number of the workers seemed to be heading towards their vehicles. He stated he used the bridge two or three times a week and had never observed anything out of the ordinary prior to August 1st.

Mr. Hoffman's car is a dark green 1999 Subaru Forester. Mr. Hoffman was the sole occupant of the vehicle. Neither Mr. Hoffman nor his vehicle sustained any damage as a result of the collapse. He could not recall his vehicle's license plate number from memory during the interview.

NTSB RAYBURN INTERVIEWS CONSTRUCTION WORKERS ON BRIDGE



Time and Date 1:45 pm 8/6/07 PCI Headquarters

Mr. Weston is a construction Superintendent. He has been with PCI for 27 years and is experienced in all areas of bridge repaving work. He said it was a normal day maybe a little hot in the afternoon. He went to work about 6 am and planned to work until midnight or 1am. When the collapse occurred he was about 800 feet north of the staging area walking south. He said he felt unusual movement, saw dust flying, and yelled for the men to run. He described the movement as an excessive undulating type movement. He indicated it all happened in a second or two. He was running the other way when the deck fell. He thought he made maybe 10 steps when he was knocked down.

When questioned e answered that no state inspector had ever given him instructions or advice about where to stack materials or stage equipment on a bridge when preparing to pour an overlay. He indicated longer pours might even take another load of sand and rock. He said Steve Klug did the calculations for how much material was needed.

He went on to say that the three factors that limited your staging area were the traffic control, the length of your planned pour, and the repairs that had already been made. Mr. Weston said he thought the south end of the bridge gave away first because all the dust came from the south end.

NTSB RAYBURN INTERVIEWS CONSTRUCTION WORKERS ON BRIDGE



Interview of Roger Lombard

Mr. Lombard is 42 and has been employed at PCI since April 2007. He was working with the overlaying crew on the day of the collapse. He was near the Bidwell paver located at the end of the planned 530-foot pour area setting up a catwalk when he heard a loud noise. Next he heard Steve Weston yell "Run." Then he felt the deck trembling. His next memory was picking himself up from the deck. He said he saw dust before he turned to run. It looked like the dust came from the northbound side of the south end of the bridge. After the collapse he helped people get to safety.

Earlier in the day he had patched some holes on a different job on University. In the past he has worked on the "Snooper Truck", framing holes underneath the deck. He said he never noticed anything unusual underneath the bridge. He had no knowledge of any accidents or anything that could have damaged the bridge prior to the collapse.



ISTH-35W Bridge Collapse Interview Questionnaire


Date of Interview: 8/7/2007 Time: 1400 Interviewer: Patrick Michaels DRIVER FAMILIANE Forthburg Truck
Driver's License Number:
Full Name Roger Allen Lombord DOB:
Full Address
Telephone Home Work: Cell:
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Driver Center Right Working construction Middle Seat Left Center Right in Southward loves Rear Seat Left Center Right Bus occupants see diagram
Ejected: YES NO NA
Safety Equipment used: Belts: LAP SHOULDER BOTH NA
Transported to Hospital YES NO Walk-in Hospital Foley Medical Center What Ambulance Service: Walk-in EMT = 51/10
Nature of Injury (Circle): A Incapacitating injury – broken bones, hospitalized, severe cuts An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes

Please explain where you were on the bridge - (direction of travel [NB SB], which lane, refer to bridge diagram): Working (outruction (reported) on North and of bridge over railroad facks in closed South borned lane

Complaint of injury with no obvious injury visible

What other vehicles or people were around you? (Color, make, model, description), what George Youell were they doing? Steve Westin - Forman ben LNU What did you see, feel, hear, and smell relative to the crash? (Please ask for specifics if a sensation is described - movement left to right, forward and back, up or down etc.) Heard loud body, felt the bridge pumbling like an earthquake beneath his feet.
No snaying just rumbling, saw smake rising from south end of bridge. He then
heard his foremen Steve Westin yell I'ven, the bridge is collapsing." He turned North and ran toward university Ave. As he ran north bridge collapsed kereath VEHICLE: him a 45° angle and he fell performed. What vehicle were you in? NA Model 350 Super Cob Year 2002 Color Blue Owner: Roger Allen Lombord Make Fund Policy Number: Unknown (any liability insurance; no Insurance Company:_ (Name, address, phone, DQB) Who else was in the vehicle with you? NA Seat Position (See above) YES NO Injured? 1. Steve Wester * on bridge, not con knee light Foremen for PCI Injured? Seat Position (See above) 2. Jean LNU # on bodge, not car Torn Relator (of boken Ankle 3. Hector LNU Injured? Broken Arm Seat Position (See above) -> Still in hospital - unknown beation Bone prohiding 4. LUS LNO Injured? (YES) NO Seat Position (See above) Ston bridge, not cor Benkpain 5. George Povell Injured? NO Seat Position (See above) then brigge, not car ab infort Injured? YES Seat Position (See above) 6.

ESTE PCI - Progressive Contractors Incorporated
Corporated April
Connectic Worked 395 pot was on scene



NOTEC.



Interview Summary of Steve Klug 9 a.m. 8/7/07 Counsel Present Kevin Gulden Present

in rehide

Steve Klug is 41 years old and has been with PCI for 21 years. He is a job Foreman. He had been working on this project for 3 weeks and came to work about 5:30 a.m. on the day of the collapse. He said he expected to work until about midnight or 1 a.m. He stated that he and Gary Gulden ordered the materials for this overlay. He said he had 4 end dumps of sand and 4 end dumps of rock with 3 cement tankers; one on-site and two off-site. When asked had the MNDOT or any State inspector ever gave him guidance on where to stage materials, he stated, " On the last northbound pour he asked inspector Harvey Unruh was it okay to stage on the bridge?" He said Mr. Unruh's reply was, " What are you asking me for, sure it's okay. no problem." Mr. Klug said he asked to make sure because he didn't want to have to move the load. He indicated this was the second pour in July. He went on to say that no inspector had ever given him any guidance on how to stage materials on bridge decks, and that it was common to have to place materials on the decks. Mr. Klug advised the truck driver's where to place the materials. He said the sand loads came first and then the rock loads. The trucks came on the deck one at a time because they didn't want them traveling over a freshly sand blasted area and their were patch repairs on the other end that limited space.

Next he and Terry Holleman traveled to get another water truck. He was northbound between the abutment and pier# 5 in the traffic lane with the general public when the collapse occurred. He said he got out of the truck and then the truck slid down the pavement and fell.

He indicated this was pour number 8 in the overlay sequence. He and Kevin Gulden then provided diagrams and they both provided the following sequence.

June 28^{th} – Ken Dobel and his crew staged on the ramp and poured a sliver to widen the road.

July 2nd – Staged on university ramp and poured a 473-foot by 26-foot-wide overlay

July 6^{th} – Two crews met and poured in both directions. They pour a 750-foot overlay in the outside southbound lanes from just north of pier 8 in span9 southbound to pier 6 at the end of span 7. The other crew poured southbound from pier 6 to the abutment over a 720-foot-long area.

On the southbound abutment pour the staging area was off the bridge. On the southbound pour near pier 8 span 6 staging was similar to the weights and overall dimensions of the staging area on the day the bridge collapsed except that any additional three loads of sand and rock were stored of the bridge for the extra long overlay pour. Next, the 4th overlay on July 19th was staged off the bridge.

July $23^{rd} - 5^{th}$ overlay was a planned pour from expansion joint 5 northbound lanes near the mid-point of span 8 just north of pier 8 to the expansion joint1 at the end of span 7 or 589 feet of overlay. The staging area for this pour was about 183 feet long. It extended from expansion joint 5 through one half of span 8 and about 50 feet of span 9. The staging area had three 24-ton loads of rock and three 24-ton loads of sand. An additional load of rock and sand was stored on the ramp to avoid extra clean-up in the am.

July 25 – The 7th overlay pour was staged on the ramp.



Interview Summary of Paul Holtz

Mr. Holtz is a 27 year-old concrete finisher that has been employed with PCI for 5 years. He was with Wayne Khron and Luis Del Rio when the collapse occurred. He first became aware of a problem when the bridge shook like a truck going by. Then he saw dust and heard someone yell "RUN." He began running and then the surface collapsed and he fell down. He received minor cuts and scrapes. Mr. Holtz began working on this bridge about 10 days before the collapse. He never heard of or noticed any accidents or observed any unusual damage.



Mark Hagland Interview Summary

Mr. Haglund is 48 years old and has 27 years with PCI. He is a cement finisher/Foreman. He came to work about 7 a.m. and expected to work to about midnight. He had worked on the bridge for about three weeks, and was on the north end of the bridge when the collapse occurred. He said he felt excessive movement. Then the movement became worse so he turned around to walk the other way because he felt like something was not right. About that time he heard Steve Weston yell for everyone to run. He made a few steps and then heard a loud roar. He also saw dust before turning to run. Next he was face down on the deck. Then he tried to locate members of his work crew, and helped some motorists escape to areas of safety.



Matt Hoheisel Interview Summary

Mr. Hoheisel is a 24-year-old concrete finisher/laborer with 1 ½ years on the job with PCI. He cam to work about 10 a.m. and expected to work to midnight or 1 a.m. He remembered he ate lunch in the staging area and began walking back to the pour area. He was walking toward the north end in the southbound lanes. He said he saw Steve Weston, then he saw dust and hear Steve yell to run. He felt the bridge deck throw him into the air. Then he came down and injured his left arm. He remembered being in the area of the boom truck and blue minivan. After the accident he tried to find his co-workers and gave statement to the police.



Jeff Ringate Interview Summary

Mr. Ringate is a 30-year-old construction worker with 5 years on the job at PCI. Normally he installs expansion joints, but on this job he was helping the overlay crew. He had worked on this project for 2 ½ - 3 weeks. He cam to work on 8/1/07 about 10 a.m. and expected to work until the paving job was finished about midnight or 1 a.m. He was located on a Mustang buggy. He was moving the buggy out of an MNDOT inspectors' way. He believed he was facing south. He felt the bridge shake like a truck going by and then felt it falling. He looked up and could see that he was falling. He could see the south end still in the air. Then he landed and fell in the river. He was lying partially on the concrete and partially in the river when he came to. Next he pulled Josh out of the water and then helped a couple of other people. He said his back was injured. He evacuated the area by boat. The four in that area were Roger, Jolly, he and Jeff.



George Powell Interview Summary

Mr. Powell is a 58-year-old worker that has been with PCI since 1981. He operates a jackhammer and removes expansion joints. He has worked on this bridge since June. He went to work about 6 a.m. and was scheduled to work until 1 a.m. George was with a state inspector in the southbound lanes on the north end abutment. He had done 6 or 7 type one patches. He became aware of the accident when he was walking up from the south end of the bridge. He heard a boom and saw the bridge coming at him like a domino falling. George was with Gene Weidendorf. He said his section dropped out from underneath him. He was on the last span by the boom truck; the boom truck was behind him and Gene. He said he ended up on the slanted down pavement that was on top of the railroad cars. He received injuries to his right shoulder and arm.

He said he never noticed any accidents or unusual damage on the bridge. Some of his work that day included consisted of jackhammering some curb somewhere south of the staging area. He went on to say that the rubble from Type one repairs is stacked on the deck and then removed with a skidsteer. He says he thinks the inspector located the location of his patches.



Roger Burma Interview Summary

Mr. Burma is a 47 year-old worker that has been with PCI for 4 years. He works with the mixer truck getting material ready for the overlay. He had worked on this project since June when it began. Roger was between the mixer and the cement truck when the collapse occurred. He said he felt a roll on the deck pavement and then it fell. He said a lady in a blue scrub came out of a car to help Bob the inspector. He was rescued by boat. He says he remembers being with Bob, Jolly,Roger, Jeff, and Josh.



WITNESS INTERVIEW

Date:

August 7, 2007

Location:

PCI Construction Company

Name:

Wayne Krohn

Age:

56

Phone #

Job Title:

Cell#

Cement Finishing Foreman

Employed by PCI:

36 years 10 days

On the Job: Schedule:

Noon to midnight

Summary of Interview

He said he normally works with a set crew, but because of construction at other site he was working with only part of this crew. He supervises the operation of the "Bidwell" which is a concrete leveling machine. He began work about 1:30 pm and took a break about 5:00 pm. He left the site and had lunch under the 4th st. bridge in a closed lane on 35W near the north side of the bridge.

He was walking back to the site, near where the bridge crosses over the rail line. He saw a large cloud of dust to the south end of the bridge. The cloud covered the whole bridge. He heard a sound "like a train coming at you"; like thunder. It got louder as it got closer.

A fellow worker, Steve Westin yelled "run". He took only a few steps and felt the bridge give way under him. He fell down and suffered minor injuries on his knees, right arm, and chin.

He indicated he did not feel anything unusual prior to the bridge collapse, nor was there anything unusual about the loading on the bridge.

End of interview.



WITNESS INTERVIEW

Date:

August 7, 2007

Location:

PCI Construction Company

Name:

Josh Weidendorf

Age:

21

Phone #

Job Title:

Laborer

Employed by PCI:

Part-time from 1977 – 93 and full-time since May 2007 3 weeks

On the Job: Schedule:

10:00 am to midnight

Summary of Interview

He said his work hours vary; some times he starts at 6:00 am and sometimes at 10:00 am. This job he started at 10:00 am. His job was shoveling, sandblasting and other manual labor tasks. He was patching holes in the concrete at this site. He took a break about 5:15 pm -5:30 pm and went with Jeff Ringate to the Taco Bell at the north end of the bridge where he had parked his black Chevrolet Breeta on the side of the bridge. He returned about 5:45 pm. He took on of the diesel "buggies" southbound on the bridge back to the work site. About 10 minutes later he felt a 'shaking of the roadway" [a vibration]. He felt the bridge slide to the west. He heard a lady screaming in the car next to him. The next thing he remembers is that he was in the water.

He suffered a broken kneecap and some abrasions on his legs.

He said that up to that time he had noticed no unusual activity on the bridge and did not think the construction material was load any differently than before.


End of interview.



RECORD OF INTERVIEW

Gene L Weidendorf, Construction worker on bridge Interviewed on the phone August 11, 2007

Gene L. Weidendorf



Mr. Weidendorf stated that he was working on the deck machine and the first thing he noticed was a dull "pop" noise to the south of his position. He turned and saw what he described as the bridge deck looking like a wave. Mr. Weidendorf continued, saying that a section of bridge on the south end rose up and he could see the vehicle's rise up along with it. According to Mr. Weidendorf, he started running towards the north end because he knew the bridge was going to collapse. As he was running he said the pavement underneath him dropped and he ended up on the section of bridge atop the train tracks. As he stood up a Bidwell trailer struck him and from that point rescue workers carried him off the bridge.

Mr. Weidendorf said he sustained a fractured right ankle, a fractured and dislocated left collarbone and shoulder, stitches to his nose and lip, along with numerous spots of road rash.



ISTH-35W Bridge Collapse Interview Questionnaire

Date of Interview: 8-11-07 Time: 1140
Interviewer: Ron K
DRIVER WKL
Driver's License Number: Construction WKK State: Full Name GEne Weidendorf DOB:
Full Name GEne Weidendorf DOB:
Full Address
Telephone Home: Work: Cell: 2
Compliance with DL restrictions: Glasses, etc YES NO NA
Seat Position: Front Seat Town Center Right Middle Seat Left Center Right Rear Seat Left Center Right
Bus occupants see diagram
Ejected: YES NO
Safety Equipment used: LAP SHOULDER BOTH
Transported to Hospital YES NO Walk-in Hospital HCMC TREATED HOSP What Ambulance Service: West to Combaidage Hosp
Nature of Injury (Circle): An inability to perform a task they could do before injury.
B Non-incapacitating injury - Cuts, bruises, scrapes
C Complaint of injury with no obvious injury visible

Please explain where you were on the bridge –(direction of travel [NB SB], which lane, refer to bridge diagram):

What other vehicles or people were around you? (Color, make, model, description), what were they doing?

a sensation is described— SORKMY OF DEC TO SOUTH OF U WUS IKE A U VEHICLE: end What vehicle were you in	movement left to right, for K MAChine, 1 secured up. =	orward and back, to the look from of Could	up or down et	dul pop noise onder deck e on south eniches RISP well
Make Plate:	Model Owner:	Year	Color	
Insurance Company:	Policy	Number:		•
Who else was in the vehical.	cle with you? NA Seat Position (See ab	(Name, address ove) Injured	-	NO
2.	Seat Position (See ab	oove) Injured	? YES	NO
3.	Seat Position (See ab	oove) Injured	? YES	NO
4.	Seat Position (See ab	oove) Injured	? YES	NO
5.	Seat Position (See at	oove) Injured	? YĖS	NO
6.	Seat Position (See at	pove) Injured	? YES	NO

Additional notes/comments:

BANKIE FX, D collarbone shouldber dislocated Stitches to NOSCE upper lip sore Alloven ROADRASH back & DARM

I stanted rummy to worth end All tho sudden nothing under neath me. the fell near train teacks. I stood up then a bidwell trailer hit me. I went back down, someone grabbed me took me off bridge.

I wortched the bridge collapse from the south not the North.



WITNESS INTERVIEW

Date:

August 7, 2007

Location:

PCI Construction Company

Name:

Luis Del Real

Age:

24

Phone #

Job Title:

Laborer

Employed by PCI:

Part-time from 1977 – 93 and full-time since May 2007

On the Job:

2 weeks

Schedule:

10:00 am to midnight

Summary of Interview

He said he was working on another bridge till about 4:30 pm when he came to work on the 35W bridge. At 5:00 pm the entire crew took a break until 6:00 pm. He was several other workers were walking north from the south end back from their break when he heard a "bang" or "crash". He saw dust near the center of the area of the bridge. The "cracking" sound was getting closer. He turned to run but fell down. The center span fell down. His uncle, Hector Bustes-Peralta was walking in front of him, fell down with the bridge.

He did not feel any movement prior to the "cracking" sound.


He did not know of any thing unusual about how the bridge was loaded or how they were going about their business.

End of interview.

Hector Bustos-Peralta P15

Due to the severity of injury this victim was not interviewed at the time that this report was completed.

Mr. Bustos-Peralta was in an induced coma and then transported to a long term care facility for rehabilitation. It is believed that he is recovering and will be able communicate at a later date.




RECORD OF INTERVIEW

Robert John Rucker, Minnesota DOT Bridge Inspector

Interviewed August 4, 2007 at Hennepin County Medical Center. Present during the interview was NTSB Investigator Ron Kaminski and Sgt. Steve Wagner with the Minneapolis PD

Robert John Rucker (6'2" 210lbs.)



Mr. Rucker stated that he heading southbound in his work truck (Black Ford F250, A27) and had pulled over and was setting up his equipment. Mr. Rucker stated he was walking north between a cement mixer and tanker when he felt the bridge lurch and drop slightly. Mr. Rucker said he started running away further north from his precarious position between the two large trucks because he knew the bridge was going to fall and he didn't want to be next to the large trucks. According to Mr. Rucker, he didn't take but a few steps before the entire span fell down. He said he ended up under the tanker truck near the wheels. Mr. Rucker stated that two PCI construction workers helped pull him out and he crawled further away from the large trucks.

Mr. Rucker said he sustained 5 fractured ribs to his left side, a left elbow injury with ligament damage, a torn triceps muscle to his left arm, pneumothorax to his lung (unknown which side), and road rash to his extremities.