



Photo 1 – Accident Site Overview



Photo 2 – Wreckage diagram



Photo 3 – Cabin & Main Rotor



Photo 4 – Main Rotor & Attached Blades



Photo 5 – Aft Fuselage & Engine



Photo 6 – Engine intake showing compressor blade tips bent opposite to the direction of rotation.



Photo 7 – Tail boom



Photo 8 – Tail rotor drive with rotor blades attached to tail rotor hub.