



**SURVIVAL AND VEHICLE FACTUAL REPORT
ATTACHMENT**

Witness Photographs

Coral Gables, FL

HWY21FH011

(4 pages)



Photograph 1: Photo from Jorge Perez. This photograph is a view looking at the rear of the Tesla on fire next to the tree. The photograph is taken looking in the northeast direction. This photo was estimated to have been taken 30 seconds after the crash.



Photograph 2: Photo A from Celina Olmos. This photograph is a view of the fire from a residence behind a hedge and gate east of the crash. The photograph shows flames rising above the gate. The time of the photograph was not determined.



Photograph 3: Photo B from Celina Olmos. This photograph is a somewhat closer view of the fire from a residence behind a hedge and gate east of the crash. The photograph shows flames rising above the hedge and fire surrounding the tree. The time of the photograph was not determined.



Photograph 4: Photo from Gus Rodrigo. This photograph is a view looking at the rear of the Tesla on fire next to the tree. The photograph is taken looking in the southwest direction. This photo was estimated to have been taken at 8:56 p.m.