



Photo 1 – Building Damage - Courtesy of FAA (Federal Aviation Administration)



Photo 2 – Fuselage damage - Courtesy of FAA



Photo 3 – Tail rotor damage – (Courtesy of FAA)