



**Photo 1 – N1013J, a Rockwell 112, at the David Wayne Hooks Memorial Airport (DWH), after recovery (FAA photo)**



**Photo 2 – Left wing and aileron damage (FAA photo)**



**Photo 3 – Right wing and spar damage (FAA photo)**