



Photo 1 – N441CX, pre-accident photo



Photo 2 – Cabin area, right side



Photo 3 – Cabin area, left side, airstair and door



Photo 4 – Forward cabin, cockpit



Photo 5 – Instrument panel



Photo 6 – Left wing



Photo 7 – Inverted right wing



Photo 8 – Main spar



Photo 9 – Horizontal stabilizers, less elevators



Photo 10 – Separated elevator



Photo 11 – Vertical stabilizer



Photo 12 – Right engine, propeller



Photo 13 – Left engine, propeller