## Aircraft Documents - Digital Photo Description Sheet Insured: Smokn' Haute Aircraft: N25TX File #: 3416398

| N25TX                    | is Assigned Ideral Working Day at Midnight   |  |               |                |  |
|--------------------------|--|--|---------------|----------------|--|
|                          |  |  |               |                |  |
| Data Updated each Fed    | leral Working Day at Midnight  |  |               |                |  |
| A                        |  |  |               |                |  |
|                          |  |  |               |                |  |
| <b>**</b>                | ISI or   |  |               |                |  |
| Aircraft                 | Description  |  |               |                |  |
| 0304369                  | Status   | V  | alid          |                |  |
| ABBOTT WILLIAM ARTHUR JR | Certificate Issue Date   |  | 10/01/2018    |                |  |
| RANS S-7S COURIER        | Expiration Date  |  | 10/31/2021    |                |  |
| Fixed Wing Single-Engine | Type Engine  | R  | Reciprocating |                |  |
| None                     | Dealer   |  |               | No             |  |
| None                     | Mode S Code (base 8 / oct)   |  | 50453344      |                |  |
| 2005                     | Mode S Code (base 16 / he  | ex) A  | A256E4        |                |  |
| Individual               | Fractional Owner   |  |               |                |  |
| RANS INC                 | Kit Model  | S  | S-7 COURIER   |                |  |
| Regist                   | ered Owner   |  |               |                |  |
| ABBOTT MARYANN L         |  |  |               |                |  |
|                          |  |  |               |                |  |
|                          |  |  |               |                |  |
| HONDO                    |  | State  |               | TEXAS          |  |
| MEDINA                   |  | Zip Code   |               | 78861-6804     |  |
| UNITED STATES            |  |  |               |                |  |
| Airw                     | orthiness  |  |               |                |  |
| ROTAX                    | Classification   | E:   | Experimental  |                |  |
| SEE BOMBADIER            | Category   | A  | Amateur Built |                |  |
| 10/11/2005               | Exception Code   | N  | 0             |                |  |
|                          | 3034399 303439 30340000000000 | ABBOTT WILLIAM ARTHUR JR  Certificate Issue Date Expiration Date Expiration Date Expiration Date Expiration Date Type Engine None Dealer None Mode S Code (base 8 / oc Individual Fractional Owner RANS INC KIT Model  Registered Owner ABBOTT MARYANN L  HONDO MEDINA UNITED STATES  Airworthiness ROTAX Classification Classification SEE BOMBADIER Category |               | Status   Valid |  |

| Picture No: |  |
|-------------|--|
|             |  |

**Description:** Airworthiness and registration from FAA website.
Original documents destroyed in aircraft.

| RANS AIRCRAFT MAINTENANCE LOG                       |
|---|
| N_25TX  |
| MODEL NUMBER S75 MODEL NAME COURIER                 |
| SERIAL NUMBER 0304369 DATE OF MANUFACTURE OCT. 2005 |
| ENGINE TYPE ROTAX 9125 ULHORSEPOWER 100             |
| REGISTERED OWNER William Arthur Abbott, Jr.         |
| STREET & NO.  |
| CITY, STATE, ZIP Hondo, Texas, 78861-6804           |
|   |

Picture No: 2

**Description: Builder of** 

Aircraft

## Aircraft Documents - Digital Photo Description Sheet Insured: Smokn' Haute Aircraft: N25TX File #: 3416398

| INSPECTION AND MAINTENANCE RECORD  |    |
|--|----|
| DATE TACH. INSPECTION OR MAINTENANCE PERFORMED                                   |    |
| 248 Iss. 6 Inspected this arrest fengin per of                                   | 79 |
| Cap may 2024. Persurmed an ops of  | 14 |
| #1 = 80/80 Gite & ail Serviced with 30th mobil 1                                 |    |
| #3= 79/50 Replaced all engine of hoses. Replaced 41 to 15 Park pluss.            | 1  |
| Carbonetors overhanted by South  |    |
| Carbureturs, test ran of adjusted belon<br>Re-torqued prop botts. I certify that | ٠. |
| and it has been found to be in a condition for sof                               | سن |
| Flight agentions. John H. Langston   |    |

| Picture No: | 3 |
|-------------|---|
|             |   |

**Description:** Airframe annual inspection 11/8/18 at tach time

188.6.

| INSPECTION AND MAINTENANCE RECORD   |
|---|
| DATE TACH. INSPECTION OR MAINTENANCE PERFORMED  12/21/18 190.2 CHRINGED O' 18 FILTER - 294 LITS, Aeroshell  12/21/18 190.2 Reflected BATTERY - Oddessey PC 680  2/11/19 203.6 Darkelled VGS - Lity flesser (STOLSPEES)  |
| 2/23/19 205.5 Sustalled MATCO wheels, dising brakes Part & MHEGBI.75 6" Wheel & broke A3C axles MHESE spaces kit Denne Aero Closic & So-6 Ties This 19 205.5 Sustalled Whichound Propellie Model #  |
| 3/18/19 217.5 Reinstalled Costs Mnew goshets to lines (monifold)  3/18/19 217.5 Reinstalled Costs Mnew goshets to lines (monifold)  18/18/19 217.5 Refaced air pump primure spring ball and  threshold plus with part nor. 84083 857230  as per 8/18 9/12-04/142-R2 |

Picture No: 4

**Description:** Airframe maintenance log. Log shows new propeller installed

2/23/19