

Photo 1 – Accident airplane with tire marks (Courtesy of Airport Ops)




Photo 2 – Accident airplane, right side (Courtesy of Airport Ops)




Photo 3 – Wing damage (Courtesy of Airport Ops)