

[DCA22MA193]

**WRECKAGE LAYOUT PHOTOS - GENERAL**



**Photograph 1 - Fuselage View from Front Right**



**Photograph 2 - Fuselage View from Front Left**





**Photograph 3 - Aft Fuselage View from Right**



**Photograph 4 - Horizontal Stabilizer - Center Lower Panel (Internal)**



**Photograph 5 - Trim Actuator Upper Mount (with Actuator Top Eye end and Bearing Assembly Attached)**