



Photo 1 – View oil under where airplane started.



Photo 2 – View of oil trail as airplane taxied for departure.



Photo 3 – View of accident site.



Photo 4 – View of accident site and damaged trees.



Photo 5 – View of engine at accident site.