



VEHICLE FACTORS ATTACHMENT

2014 Freightliner Maintenance and Daily Inspection Documents

Pala Mesa, California

HWY20FH003

(50 pages)

Type	Vehicle Name	Trailer	Author	Signed At	Duration	Mechanic/ Mechanic I Defects	Status	Vehicle De Trailer Defect Details
Pre-trip	6857			Nov 23, 9:34 AM	16s	-	Safe	
Post-trip	6857			Nov 23, 7:18 PM	19s	-	Safe	
Pre-trip	6857			Nov 24, 9:47 AM	17s	-	Safe	
Post-trip	6857			Nov 24, 8:20 PM	22s	-	Safe	
Pre-trip	6857			Nov 25, 9:41 AM	29s	-	Safe	
Post-trip	6857			Nov 25, 9:16 PM	31s	-	Safe	
Pre-trip	6857			Nov 26, 6:07 AM	9s	-	Safe	
Pre-trip	6857			Nov 26, 3:41 PM	9s	-	Safe	
Post-trip	6857			Nov 26, 9:21 PM	8s	-	Safe	
Pre-trip	6857			Nov 27, 8:46 AM	6s	-	Safe	
Post-trip	6857			Nov 27, 1:36 PM	5s	-	Safe	
Pre-trip	6857			Nov 27, 1:39 PM	11s	-	Safe	
Unspecified	6857			Nov 27, 9:38 PM	17s		TRUE	Resolved
Pre-trip	6857			Nov 28, 5:40 AM	16s	-	Safe	
Post-trip	6857			Nov 28, 3:37 PM	11s	-	Safe	
Pre-trip	6857			Nov 28, 3:38 PM	20s	-	Safe	
Post-trip	6857			Nov 28, 8:08 PM	8s	-	Safe	
Pre-trip	6857			Nov 29, 8:25 AM	8s	-	Safe	
Post-trip	6857			Nov 29, 12:56 PM	7s	-	Safe	
Pre-trip	6857			Nov 29, 1:02 PM	10s	-	Safe	
Post-trip	6857			Nov 29, 9:55 PM	9s	-	Safe	
Pre-trip	6857			Nov 30, 7:46 AM	17s	-	Safe	
Post-trip	6857			Nov 30, 7:00 PM	25s	-	Safe	
Pre-trip	6857			Dec 1, 7:42 AM	29s	-	Safe	
Post-trip	6857			Dec 1, 6:31 PM	27s	-	Safe	
Pre-trip	6857			Dec 2, 7:44 AM	18s	-	Safe	
Post-trip	6857			Dec 2, 7:09 PM	30s	-	Safe	
Pre-trip	6857			Dec 3, 5:46 AM	13s	-	Safe	
Post-trip	6857			Dec 3, 6:41 AM	11s	-	Safe	
Pre-trip	6857			Dec 3, 9:33 AM	15s	-	Safe	
Post-trip	6857			Dec 3, 9:25 PM	17s	-	Safe	
Pre-trip	6857			Dec 4, 5:47 AM	22s	-	Safe	
Post-trip	6857			Dec 4, 3:01 PM	11s	-	Safe	
Pre-trip	6857			Dec 4, 3:42 PM	8s	-	Safe	
Post-trip	6857			Dec 4, 8:33 PM	7s	-	Safe	
Pre-trip	6857			Dec 5, 8:30 AM	8s	-	Safe	
Post-trip	6857			Dec 5, 12:55 PM	6s	-	Safe	

Type	Vehicle Na Trailer	Author	Signed At	Duration	Mechanic/ Mechanic Defects	Status	Vehicle Defect Details	Trailer Defect Details
Unspecifie	6857		Jan 23, 7:33 AM	24s		Safe	Unset - air leak at driver seat.	
Unspecifie	6857		Jan 23, 7:10 PM	58s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 23, 7:11 PM	21s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 24, 9:47 AM	10s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 24, 9:36 PM	20s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 25, 9:57 AM	19s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 25, 8:44 PM	30s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 26, 5:45 AM	8s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 26, 3:41 PM	8s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 26, 7:57 PM	9s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 27, 8:23 AM	7s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 27, 1:02 PM	7s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 27, 1:08 PM	20s		Safe	Unset - air leak at driver seat.	
Unspecifie	6857		Jan 27, 10:00 PM	11s		TRUE Resolved	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 28, 5:45 AM	13s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 28, 2:28 PM	8s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 29, 5:39 AM	12s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 29, 3:17 PM	9s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 30, 9:18 AM	29s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 30, 10:04 AM	13s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 30, 8:27 PM	17s		Safe	Unset - air leak at driver seat.	
Pre-trip	6857		Jan 31, 7:50 AM	10s		Safe	Unset - air leak at driver seat.	
Post-trip	6857		Jan 31, 8:00 PM	1m 20s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 1, 9:38 AM	20s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 1, 8:55 PM	19s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 2, 5:54 AM	7s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 3, 5:34 AM	9s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 3, 2:36 PM	11s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 3, 3:42 PM	8s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 3, 8:33 PM	13s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 4, 8:26 AM	8s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 4, 9:18 PM	8s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 6, 12:19 PM	8s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 6, 4:37 PM	12s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 7, 5:44 AM	11s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 7, 10:26 AM	12s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 7, 12:26 PM	6s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 7, 5:34 PM	12s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 8, 7:57 AM	10s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 8, 5:39 PM	10s		Safe	Unset - Front right headlight burned out.	
Pre-trip	6857		Feb 9, 7:44 AM	11s		Safe	Unset - Front right headlight burned out.	
Post-trip	6857		Feb 9, 6:48 PM	12s		Safe	Unset - Front right headlight burned out.	

Pre-trip	6857	[REDACTED]	Feb 10, 12:41 PM	14s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Post-trip	6857	[REDACTED]	Feb 10, 9:55 PM	10s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Pre-trip	6857	[REDACTED]	Feb 11, 7:33 AM	7s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Post-trip	6857	[REDACTED]	Feb 11, 12:13 PM	11s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Pre-trip	6857	[REDACTED]	Feb 13, 12:18 PM	9s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Post-trip	6857	[REDACTED]	Feb 13, 5:06 PM	5s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Pre-trip	6857	[REDACTED]	Feb 13, 5:56 PM	8s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Post-trip	6857	[REDACTED]	Feb 13, 10:17 PM	7s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Pre-trip	6857	[REDACTED]	Feb 14, 8:20 AM	10s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Post-trip	6857	[REDACTED]	Feb 14, 1:03 PM	7s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Pre-trip	6857	[REDACTED]	Feb 15, 7:21 AM	12s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Post-trip	6857	[REDACTED]	Feb 15, 6:43 PM	30s	[REDACTED]	Safe	Unset - Front right headlight burned out.
Pre-trip	6857	[REDACTED]	Feb 16, 10:02 AM	13s	-	Safe	
Post-trip	6857	[REDACTED]	Feb 16, 8:19 PM	12s	-	Safe	
Pre-trip	6857	[REDACTED]	Feb 17, 9:38 AM	8s	-	Safe	
Post-trip	6857	[REDACTED]	Feb 17, 8:44 PM	7s	-	Safe	
Pre-trip	6857	[REDACTED]	Feb 18, 12:41 PM	37s	-	Safe	
Post-trip	6857	[REDACTED]	Feb 18, 10:16 PM	47s	-	Safe	
Pre-trip	6857	[REDACTED]	Feb 19, 7:52 AM	9s	-	Safe	
Post-trip	6857	[REDACTED]	Feb 19, 4:31 PM	11s	-	Safe	
Post-trip	6857	[REDACTED]	Feb 19, 4:33 PM	17s	-	Safe	
Pre-trip	6857	[REDACTED]	Feb 20, 9:37 AM	9s	-	Safe	
Post-trip	6857	[REDACTED]	Feb 20, 8:53 PM	8s	-	Safe	
Pre-trip	6857	[REDACTED]	Feb 21, 9:33 AM	11s	-	Safe	
Post-trip	6857	[REDACTED]	Feb 21, 9:35 PM	25s	-	Safe	
Pre-trip	6857	[REDACTED]	Feb 22, 7:33 AM	8s	-	Safe	

Type	Vehicle Na Trailer	Author	Signed At	Duration	Mechanic/ Mechanic I Defects	Status	Vehicle De Trailer Defect Details
Pre-trip	6857		Dec 23, 12 9s	-		Safe	
Post-trip	6857		Dec 23, 11 9s	-		Safe	
Pre-trip	6857		Dec 24, 8:28s	-		Safe	
Post-trip	6857		Dec 24, 8:212s	-		Safe	
Pre-trip	6857		Dec 25, 10 7s	-		Safe	
Post-trip	6857		Dec 25, 8:08s	-		Safe	
Pre-trip	6857		Dec 26, 8:28s	-		Safe	
Post-trip	6857		Dec 26, 1:39s	-		Safe	
Pre-trip	6857		Dec 30, 9:46s	-		Safe	
Pre-trip	6857		Jan 2, 7:54 6s	-		Safe	
Pre-trip	6857		Jan 3, 12:4 11s	-		Safe	
Post-trip	6857		Jan 3, 10:2 14s	-		Safe	
Pre-trip	6857		Jan 4, 12:2 11s	-		Safe	
Post-trip	6857		Jan 4, 10:1 22s	-		Safe	
Pre-trip	6857		Jan 5, 9:29 11s	-		Safe	
Post-trip	6857		Jan 5, 7:18 25s	-		Safe	
Pre-trip	6857		Jan 6, 9:40 13s	-		Safe	
Post-trip	6857		Jan 6, 9:34 28s	-		Safe	
Pre-trip	6857		Jan 7, 7:43 11s	-		Safe	
Post-trip	6857		Jan 7, 6:32 16s	-		Safe	
Pre-trip	6857		Jan 8, 7:37 14s	-		Safe	
Post-trip	6857		Jan 8, 6:35 18s	-		Safe	
Pre-trip	6857		Jan 9, 7:38 13s	-		Safe	
Post-trip	6857		Jan 9, 6:48 11s	-		Safe	
Pre-trip	6857		Jan 10, 7:3 13s	-		Safe	
Post-trip	6857		Jan 10, 7:1 10s	-		Safe	
Pre-trip	6857		Jan 11, 10: 14s	-		Safe	
Post-trip	6857		Jan 11, 8:5 22s	-		Safe	
Pre-trip	6857		Jan 12, 5:5 8s	-		Safe	
Pre-trip	6857		Jan 13, 7:5 1m 10s	-		Safe	Unset - air leak at driver seat.
Post-trip	6857		Jan 13, 7:0 12s	-		Safe	Unset - air leak at driver seat.
Pre-trip	6857		Jan 14, 5:4 16s	-		Safe	Unset - air leak at driver seat.
Post-trip	6857		Jan 14, 9:0 9s	-		Safe	Unset - air leak at driver seat.

Pre-trip	6857	[REDACTED]	Jan 16, 12: 8s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 16, 5:0 13s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 16, 6:2 7s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 16, 10: 8s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 17, 12: 8s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 17, 5:3 6s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 17, 6:1 7s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 17, 10: 9s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 18, 12: 14s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 18, 10: 10s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 19, 12: 7s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 19, 4:3 7s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 19, 6:2 6s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 19, 10: 8s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 20, 12: 7s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 20, 10: 8s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 21, 8:3 11s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 21, 9:0 7s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 22, 8:2 19s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 22, 12: 11s	[REDACTED]	Safe	Unset - air leak at driver seat.
Pre-trip	6857	[REDACTED]	Jan 22, 12: 9s	[REDACTED]	Safe	Unset - air leak at driver seat.
Post-trip	6857	[REDACTED]	Jan 22, 9:4 10s	[REDACTED]	Safe	Unset - air leak at driver seat.

BUS MAINTENANCE & SAFETY INSPECTION

INSPECCION Y MANTENIMIENTO DEL AUTOBUS

*Inspection of these items required by 34505 CVC

* Inspeccion de estas cosas es el requisito por la ley 34505 CVC

VEHICLE NO. NUM. VEHICULO <i>6857</i>	LICENSE NO. NUM. LICENCIA <i>EP01900</i>	MILEAGE MILLAGE <i>189927</i>
MAKE MARCA <i>Freightliner</i>	MODEL MODELO <i>BUS</i>	YEAR AÑO <i>08/2013</i>
INTERIOR AND EXTERIOR / INTERIOR Y EXTERIOR		
1. Fire extinguishers, warning reflectors, first aid kit <i>Extinguidores, reflectores triangulares (luces muertas), primeros auxilios</i>		OK DEF ✓
2. Instruments, secure seats, clean interior, driver's seat and belt <i>Marcadores, los asientos asegurados, interior limpio, asiento y cinturon de seguridad del chofer</i>		✓
3. Windshield, w/wipers, windows, mirrors, floor condition <i>Vidrio, limpia brisas, rajaduras del vidrios, espejos, condicion del piso</i>		✓
4. Lights, interior, exterior, signals, warning, switches and wiring <i>Luces - interior, de afuera, direccionales, indicadores, lineas electricas</i>		✓
5. Warning devices - horn, oil, temperature, lift, door(s) <i>Señales de emergencia - claxon, aceite, temperatura, elevador, puerta(s)</i>		✓
6. Heaters, defrosters, cooling and vent systems <i>Calenton, descongelador (estan calientes?), sistema de enfriamiento y ventilas</i>		✓
7. Door operations, sensitive edges, timing, padding, handrails, safety panels <i>Operacion de las puertas, borde sensibles, tiempo, relleno, soportes del mano, paneles de seguridad</i>		✓
8. Exterior condition, paint, identification <i>Condicion de afuera, pintura, identificacion</i>		✓
ENGINE AND ELECTRIC / MOTOR Y ELECTRICO		
9. Generator / alternator, starter, brushes, wiring - mounting <i>Generador / alternador, arrancador, escobillas, lineas electricas - monturas</i>		OK DEF ✓
10. Batteries, water, terminals, cables <i>Baterias - agua, terminales, cables</i>		✓
11. Radiator, water hoses, water pump - securement, leaks <i>Radiador, mangueras de agua, bomba de agua - asegurar, fugas</i>		✓
12. Compressor(s), fan, waterpump, acc. - belts - condition and adjustment <i>Compressor(s), abanico, bomba de agua, bandas - condicion y ajuste</i>		* * ✓
13. Clutch adjustments - freeplay <i>Ajuste del embrague - juego libre</i>		N/A
14. Throttle, linkage, fuel system leaks, air filter <i>Acelerador, conecciones, fugas de combustibles, filtro de aire</i>		✓
15. Manifolds, gaskets - securement, leaks <i>Manifold y empaques - asegurar, fugas</i>		✓
16. Engine mounts, oil leaks <i>Monturas del motor, fugas de aceite</i>		✓
REMARKS/COMENTARIOS		
** eEMERGENCY EXIT WINDOWS SALIDAS DE EMERGENCIA		

INSPECTOR/
INSPECTOR (FIRMA)
CHP108A-ES

DATE/
FECHA COMPLETA *02/10/2020*

REVISED 03-03-98

*1. Repair on Engine oil oil filters change 6. Repair Coded Hose Protect Leg
2. Repair on Engine Air Filter Cleaner 7. Repair Exhaust Pipe Bracket
3. Repair on All Springs Levels check 8. Repair on All Tires Air Pressure check
4. Repair Drive seat Air Seat hose replace 9. Repair on All Brakes Adjustments
5. Repair all batteries hoses connections replace 10. Repair on Bus engine valve and
and lubricant on all wires protect*

BRAKES / FRENOS	OK	DEF
17. Hydraulic fluid level, leaks, hoses and tubing - secured, protected <i>Nivel de fluidos hidraulicos, fugas, mangueras y tubos - asegurados, proteccion</i>	* ✓	
18. Air governor adjustment - minimum 85, maximum 130 <i>Ajustes del pulmon (governador del compresor) - minimo 85 - maximo 130</i>	* ✓	
19. Air leaks, unapplied, 1 minute 3 pounds maximum <i>Fugas de aire, sin aplicar, uno minuto 3 libras maximo</i>	* ✓	
20. Air leaks, applied, 1 minute 3 pounds maximum <i>Fugas de aire, frenos aplicados, uno minuto 3 libras maximo</i>	* ✓	
21. Drain number 1 air reservoir - test check valve(s) - low air warning operates <i>Drenar el tanque mojado -chece las valvula(s) de uno sentido, señal de baja presion se opera</i>	* ✓	
22. All tanks secure, drains operable, drain tanks <i>Monturas de todos los tanques, purgadores operables, drene tanques</i>	* ✓	
23. Vacuum loss - 3" per min., 15" minimum vac. - low vacuum warning - tanks secure <i>Fugas de succion - 3 pulgadas por minuto, 15 pulgadas vacio minimo - señal de baja vacio - tanques asegurados</i>	* ✓	
24. Brakes, lining, drums and adjustment - near cam over, pedal height on hydraulic <i>Frenos - balatas, tambores y ajuste - cerca del centro de gabilan, alta del pedal - frenos hidraulicos</i>	* ✓	
25. Parking brake - condition and adjustment <i>Freno de estacionamiento - condicion y ajuste</i>	* ✓	
26. Emergency stopping system - labeled and operable <i>Sistema de Alto de emergencia - marcado y operable</i>	* ✓	
27. Release after loss of service air. Anti skid if equipped <i>Soltar de frenos despues de perder aire de servicio. equipado contra derrapes</i>	* ✓	
CHASSIS / CHASSIS	OK	DEF
28. Wheels, tires, lug nuts - cracks, secured - tread - inflation <i>Rines, llantas, tuercas - rajadas, seguridad, banda rodante, presion de aire</i>	* ✓	
29. Wheel seals, leaks - hyd. brake system leaks <i>Retenes de las ruedas y fugas - fugas de la systema hidraulico</i>	✓	
30. Check steering gear mounting - free lash, oil level <i>Revisar sinfin del volante y monturas - juego libre, nivele de aceite</i>	* ✓	
31. Steering arms, drag links, tie rods <i>Brazos de direccion y barras de acoplamiento, terminales</i>	* ✓	
32. Check frame, crossmembers, cracks, etc. <i>Revisar el chasis, travesaños, rajaduras, etc.</i>	* ✓	
33. Springs, shackles, and "U"bolts, king pins, shock absorbers <i>Muelles, gemelos y pernos de "U", king pins, amortiguadores</i>	✓	
34. Transmission, differential, mounting and seals, drive shaft, "U"joints, guard <i>Transmision, diferencial, monturas y retenes, flechas y crucetas, protectores de las flechas</i>	✓	
35. Exhaust - condition, leaks, mounting <i>Escape - condicion, fugas, montura</i>	✓	
36. Fuel tanks, lines, pumps - condition, mounts, leaks <i>Tanque de combustibles, mangueras, bomba, condicion, soportes, fugas</i>	✓	
37. Body underside and firewall, airtight and clean <i>Por de bajo de la cabina y pared de fuego, aire sellado y limpio</i>	* ✓	
REMARKS / COMENTARIOS		
<div style="display: flex; justify-content: space-between; align-items: flex-end;"> <div style="width: 45%;"> <p>INSPECTOR/ INSPECTOR(FIRMA)</p> <div style="background-color: black; width: 200px; height: 40px; margin-top: 5px;"></div> <p>CHP108A-ES</p> </div> <div style="width: 45%; text-align: right;"> <p>DATE/ FECHA COMPLETA</p> <p>02/10/2020</p> <p>REVISED 03-03-98</p> </div> </div>		

BUS MAINTENANCE & SAFETY INSPECTION

INSPECCION Y MANTENIMIENTO DEL AUTOBUS

*Inspection of these items required by 34505 CVC

* Inspeccion de estas cosas es el requisito por la ley 34505 CVC

VEHICLE NO. NUM. VEHICULO 6857	LICENSE NO. NUM. LICENCIA EPO1900	MILEAGE MILLAGE 177145
MAKE MARCA Freshliner	MODEL MODELO BUS	YEAR AÑO 08/2013
INTERIOR AND EXTERIOR / INTERIOR Y EXTERIOR		
1. Fire extinguishers, warning reflectors, first aid kit <i>Extinguidores, reflectores triangulares (luces muertas), primeros auxilios</i>		OK DEF <input checked="" type="checkbox"/> <input type="checkbox"/>
2. Instruments, secure seats, clean interior, driver's seat and belt <i>Marcadores, los asientos asegurados, interior limpio, asiento y cinturon de seguridad del chofer</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
3. Windshield, w/wipers, windows, mirrors, floor condition <i>Vidrio, limpia brisas, rajaduras del vidrios, espejos, condicion del piso</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
4. Lights, interior, exterior, signals, warning, switches and wiring <i>Luces - interior, de afuera, direccionales, indicadores, lineas electricas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
5. Warning devices - horn, oil, temperature, lift, door(s) <i>Señales de emergencia - claxon, aceite, temperatura, elevador, puerta(s)</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
6. Heaters, defrosters, cooling and vent systems <i>Calenton, descongelador (estan calientes?), sistema de enfriamiento y ventilas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
7. Door operations, sensitive edges, timing, padding, handrails, safety panels <i>Operacion de las puertas, borde sensibles, tiempo, relleno, soportes del mano, paneles de seguridad</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
8. Exterior condition, paint, identification <i>Condicion de afuera, pintura, identificacion</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
ENGINE AND ELECTRIC / MOTOR Y ELECTRICO		
9. Generator / alternator, starter, brushes, wiring - mounting <i>Generador / alternador, arrancador, escobillas, lineas electricas - monturas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
10. Batteries, water, terminals, cables <i>Baterias - agua, terminales, cables</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
11. Radiator, water hoses, water pump - securement, leaks <i>Radiador, mangueras de agua, bomba de agua - asegurar, fugas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
12. Compressor(s), fan, waterpump, acc. - belts - condition and adjustment <i>Compressor(s), abanico, bomba de agua, bandas - condicion y ajuste</i>		* <input checked="" type="checkbox"/> * <input checked="" type="checkbox"/>
13. Clutch adjustments - freeplay <i>Ajuste del embrague - juego libre</i>		N/A
14. Throttle, linkage, fuel system leaks, air filter <i>Acelerador, conexiones, fugas de combustibles, filtro de aire</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
15. Manifolds, gaskets - securement, leaks <i>Manifold y empaques - asegurar, fugas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
16. Engine mounts, oil leaks <i>Monturas del motor, fugas de aceite</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
REMARKS/COMENTARIOS		
** eEMERGENCY EXIT WINDOWS SALIDAS DE EMERGENCIA		<input checked="" type="checkbox"/> <input type="checkbox"/>

INSPECTOR/
INSPECTOR (FIRMA)
CHP108A-ES

DATE/
FECHA COMPLETA **12/27/2019**
REVISED 03-03-98

1. Repair on Engine Oil or Filters Change, 6. Repair on All Axle Brakes
2. Repair on Engine Air Filter Clean, adjustment.
3. Repair on All Tires Levels Check. 7. Repair Rear Drive Axle Y side
4. Repair Batteries Posts Terminals Check mounting TOW Used Gires.
5. Repair Lubricant. 8. Repair All Tires Air Pressure Check
9. Repair on bus Dispercional
5. Repair Rear Drive Axle Replaces New Brakes and Repairs.

BRAKES / FRENOS	OK	DEF
17. Hydraulic fluid level, leaks, hoses and tubing - secured, protected <i>Nivel de fluidos hidraulicos, fugas, mangueras y tubos - asegurados, proteccion</i>	* ✓	
18. Air governor adjustment - minimum 85, maximum 130 <i>Ajustes del pulmon (governador del compresor) - minimo 85 - maximo 130</i>	* ✓	
19. Air leaks, unapplied, 1 minute 3 pounds maximum <i>Fugas de aire, sin aplicar, uno minuto 3 libras maximo</i>	* ✓	
20. Air leaks, applied, 1 minute 3 pounds maximum <i>Fugas de aire, frenos aplicados, uno minuto 3 libras maximo</i>	* ✓	
21. Drain number 1 air reservoir - test check valve(s) - low air warning operates <i>Drenar el tanque mojado -chece las valvula(s) de uno sentido, señal de baja presion se opera</i>	* ✓	
22. All tanks secure, drains operable, drain tanks <i>Monturas de todos los tanques, purgadores operables, drene tanques</i>	* ✓	
23. Vacuum loss - 3" per min., 15" minimum vac. - low vacuum warning - tanks secure <i>Fugas de succion - 3 pulgadas por minuto, 15 pulgadas vacio minimo - señal de baja vacio - tanques asegurados</i>	* ✓	
24. Brakes, lining, drums and adjustment - near cam over, pedal height on hydraulic <i>Frenos - balatas, tambores y ajuste - cerca del centro de gabilan, alta del pedal - frenos hidraulicos</i>	* ✓	
25. Parking brake - condition and adjustment <i>Freno de estacionamiento - condicion y ajuste</i>	* ✓	
26. Emergency stopping system - labeled and operable <i>Sistema de Alto de emergencia - marcado y operable</i>	* ✓	
27. Release after loss of service air. Anti skid if equipped <i>Soltar de frenos despues de perder aire de servicio, equipado contra derrapes</i>	* ✓	
CHASSIS / CHASSIS	OK	DEF
28. Wheels, tires, lug nuts - cracks, secured - tread - inflation <i>Rines, llantas, tuercas - rajadas, seguridad, banda rodante, presion de aire</i>	* ✓	
29. Wheel seals, leaks - hyd. brake system leaks <i>Retenes de las ruedas y fugas - fugas de la systema hidraulico</i>	✓	
30. Check steering gear mounting - free lash, oil level <i>Revisar sinfin del volante y monturas - juego libre, nivele de aceite</i>	* ✓	
31. Steering arms, drag links, tie rods <i>Brazos de direccion y barras de acoplamiento, terminales</i>	* ✓	
32. Check frame, crossmembers, cracks, etc. <i>Revisar el chasis, travesaños, rajaduras, etc.</i>	* ✓	
33. Springs, shackles, and "U"bolts, king pins, shock absorbers <i>Muelles, gemelos y pernos de "U", king pins, amortiguadores</i>	✓	
34. Transmission, differential, mounting and seals, drive shaft, "U"joints, guard <i>Transmision, diferencial, monturas y retenes, flechas y crucetas, protectores de las flechas</i>	✓	
35. Exhaust - condition, leaks, mounting <i>Escape - condicion, fugas, montura</i>	✓	
36. Fuel tanks, lines, pumps - condition, mounts, leaks <i>Tanque de combustibles, mangueras, bomba, condicion, soportes, fugas</i>	✓	
37. Body underside and firewall, airtight and clean <i>Por de bajo de la cabina y pared de fuego, aire sellado y limpio</i>	* ✓	
REMARKS / COMENTARIOS		
<div style="display: flex; justify-content: space-between; align-items: flex-end;"> <div style="width: 45%;"> <p>INSPECTOR/ INSPECTOR(FIRMA)</p> <div style="background-color: black; width: 150px; height: 80px; margin-left: 100px;"></div> <p>CHP108A-ES</p> </div> <div style="width: 45%; text-align: right;"> <p>DATE/ FECHA COMPLETA</p> <p>12/22/2019</p> <p>REVISED 03-03-98</p> </div> </div>		

BUS MAINTENANCE & SAFETY INSPECTION


INSPECCION Y MANTENIMIENTO DEL AUTOBUS

*Inspection of these items required by 34505 CVC

* Inspeccion de estas cosas es el requisito por la ley 34505 CVC

VEHICLE NO. NUM. VEHICULO	6857	LICENSE NO. NUM. LICENCIA	EPO1900	MILEAGE MILLAGE	161019	
MAKE MARCA	Freightliner	MODEL MODELO	BUS	YEAR AÑO	08/2013	
INTERIOR AND EXTERIOR / INTERIOR Y EXTERIOR					OK	DEF
1. Fire extinguishers, warning reflectors, first aid kit <i>Extintidores, reflectores triangulares (luces muertas), primeros auxilios</i>					✓	
2. Instruments, secure seats, clean interior, driver's seat and belt <i>Marcadores, los asientos asegurados, interior limpio, asiento y cinturon de seguridad del chofer</i>					✓	
3. Windshield, w/wipers, windows, mirrors, floor condition <i>Vidrio, limpia brisas, rajaduras del vidrios, espejos, condicion del piso</i>					✓	
4. Lights, interior, exterior, signals, warning, switches and wiring <i>Luces - interior, de afuera, direccionales, indicadores, lineas electricas</i>					✓	
5. Warning devices - horn, oil, temperature, lift, door(s) <i>Señales de emergencia - claxon, aceite, temperatura, elevador, puerta(s)</i>					✓	
6. Heaters, defrosters, cooling and vent systems <i>Calenton, descongelador (estan calientes?), sistema de enfriamiento y ventilas</i>					✓	
7. Door operations, sensitive edges, timing, padding, handrails, safety panels <i>Operacion de las puertas, borde sensibles, tiempo, relleno, soportes del mano, paneles de seguridad</i>					✓	
8. Exterior condition, paint, identification <i>Condicion de afuera, pintura, identificacion</i>					✓	
ENGINE AND ELECTRIC / MOTOR Y ELECTRICO					OK	DEF
9. Generator / alternator, starter, brushes, wiring - mounting <i>Generador / alternador, arrancador, escobillas, lineas electricas - monturas</i>					✓	
10. Batteries, water, terminals, cables <i>Baterias - agua, terminales, cables</i>					✓	
11. Radiator, water hoses, water pump - securement, leaks <i>Radiador, mangueras de agua, bomba de agua - asegurar, fugas</i>					✓	
12. Compressor(s), fan, waterpump, acc. - belts - condition and adjustment <i>Compressor(s), abanico, bomba de agua, bandas - condicion y ajuste</i>					*	✓
13. Clutch adjustments - freeplay <i>Ajuste del embrague - juego libre</i>					N/A	
14. Throttle, linkage, fuel system leaks, air filter <i>Acelerador, conecciones, fugas de combustibles, filtro de aire</i>					✓	
15. Manifolds, gaskets - securement, leaks <i>Manifold y empaques - asegurar, fugas</i>					✓	
16. Engine mounts, oil leaks <i>Monturas del motor, fugas de aceite</i>					✓	
REMARKS/COMENTARIOS						
** eEMERGENCY EXIT WINDOWS SALIDAS DE EMERGENCIA					✓	

INSPECTOR/
INSPECTOR (FIRMA)
CHP108A-ES



DATE/
FECHA COMPLETA 11/13/2019

REVISED 03-03-98

1. Repair Rear Drive Axle Side
and place two used tires mounting
2. Repair old tires Air Pressure Check.
3. Repair the front axle Adjustment.
4. Repair the Engine oil and Filters Change
5. Repair the Engine Air Filter Clean.

6. Repair Engine Computer Diagnostic Code
Fault: VGT Actuator Driver Circuit: SPN 641
7. Repair Inspection or Repairs.

BRAKES / FRENOS	OK	DEF
17. Hydraulic fluid level, leaks, hoses and tubing - secured, protected <i>Nivel de fluidos hidraulicos, fugas, mangueras y tubos - asegurados, proteccion</i>	* ✓	
18. Air governor adjustment - minimum 85, maximum 130 <i>Ajustes del pulmon (governador del compresor) - minimo 85 - maximo 130</i>	* ✓	
19. Air leaks, unapplied, 1 minute 3 pounds maximum <i>Fugas de aire, sin aplicar, uno minuto 3 libras maximo</i>	* ✓	
20. Air leaks, applied, 1 minute 3 pounds maximum <i>Fugas de aire, frenos aplicados, uno minuto 3 libras maximo</i>	* ✓	
21. Drain number 1 air reservoir - test check valve(s) - low air warning operates <i>Drenar el tanque mojado -chece las valvula(s) de uno sentido, señal de baja presion se opera</i>	* ✓	
22. All tanks secure, drains operable, drain tanks <i>Monturas de todos los tanques, purgadores operables, drene tanques</i>	* ✓	
23. Vacuum loss - 3" per min., 15" minimum vac. - low vacuum warning - tanks secure <i>Fugas de succion - 3 pulgadas por minuto, 15 pulgadas vacio minimo - señal de baja vacio - tanques asegurados</i>	* ✓	
24. Brakes, lining, drums and adjustment - near cam over, pedal height on hydraulic <i>Frenos - balatas, tambores y ajuste - cerca del centro de gabilan, alta del pedal - frenos hidraulicos</i>	* ✓	
25. Parking brake - condition and adjustment <i>Freno de estacionamiento - condicion y ajuste</i>	* ✓	
26. Emergency stopping system - labeled and operable <i>Sistema de Alto de emergencia - marcado y operable</i>	* ✓	
27. Release after loss of service air. Anti skid if equipped <i>Soltar de frenos despues de perder aire de servicio. equipado contra derrapes</i>	* ✓	
CHASSIS / CHASSIS	OK	DEF
28. Wheels, tires, lug nuts - cracks, secured - tread - inflation <i>Rines, llantas, tuercas - rajadas, seguridad, banda rodante, presion de aire</i>	* ✓	
29. Wheel seals, leaks - hyd. brake system leaks <i>Retenes de las ruedas y fugas - fugas de la systema hidraulico</i>	✓	
30. Check steering gear mounting - free lash, oil level <i>Revisar sinfin del volante y monturas - juego libre, nivele de aceite</i>	* ✓	
31. Steering arms, drag links, tie rods <i>Brazos de direccion y barras de acoplamiento, terminales</i>	* ✓	
32. Check frame, crossmembers, cracks, etc. <i>Revisar el chasis, travesaños, rajaduras, etc.</i>	* ✓	
33. Springs, shackles, and "U"bolts, king pins, shock absorbers <i>Muelles, gemelos y pernos de "U", king pins, amortiguadores</i>	✓	
34. Transmission, differential, mounting and seals, drive shaft, "U"joints, guard <i>Transmision, diferencial, monturas y retenes, flechas y crucetas, protectores de las flechas</i>	✓	
35. Exhaust - condition, leaks, mounting <i>Escape - condicion, fugas, montura</i>	✓	
36. Fuel tanks, lines, pumps - condition, mounts, leaks <i>Tanque de combustibles, mangueras, bomba, condicion, soportes, fugas</i>	✓	
37. Body underside and firewall, airtight and clean <i>Por de bajo de la cabina y pared de fuego, aire sellado y limpio</i>	* ✓	
REMARKS / COMENTARIOS		
24, Rear Drive Axle BRAKES IS ^{10/10} Needs Service Need to Replace		
INSPECTOR/ INSPECTOR(FIRMA)	DATE/ FECHA COMPLETA 11/13/2019	
CHP108A-ES	REVISED 03-03-98	

BUS MAINTENANCE & SAFETY INSPECTION


INSPECCION Y MANTENIMIENTO DEL AUTOBUS

*Inspection of these items required by 34505 CVC

* Inspeccion de estas cosas es el requisito por la ley 34505 CVC

VEHICLE NO. NUM. VEHICULO 6857	LICENSE NO. NUM. LICENCIA	MILEAGE MILLAGE 145304
MAKE MARCA Freightliner	MODEL MODELO BUS	YEAR AÑO 08/2013
INTERIOR AND EXTERIOR / INTERIOR Y EXTERIOR		
1. Fire extinguishers, warning reflectors, first aid kit <i>Extinguidores, reflectores triangulares (luces muertas), primeros auxilios</i>	OK	DEF
2. Instruments, secure seats, clean interior, driver's seat and belt <i>Marcadores, los asientos asegurados, interior limpio, asiento y cinturón de seguridad del chofer</i>	✓	
3. Windshield, w/wipers, windows, mirrors, floor condition <i>Vidrio, limpia brisas, rajaduras del vidrios, espejos, condicion del piso</i>	✓	
4. Lights, interior, exterior, signals, warning, switches and wiring <i>Luces - interior, de afuera, direccionales, indicadores, lineas electricas</i>	✓	
5. Warning devices - horn, oil, temperature, lift, door(s) <i>Señales de emergencia - claxon, aceite, temperatura, elevador, puerta(s)</i>	✓	
6. Heaters, defrosters, cooling and vent systems <i>Calenton, descongelador (estan calientes?), sistema de enfriamiento y ventilas</i>	✓	
7. Door operations, sensitive edges, timing, padding, handrails, safety panels <i>Operacion de las puertas, borde sensibles, tiempo, relleno, soportes del mano, paneles de seguridad</i>	✓	
8. Exterior condition, paint, identification <i>Condicion de afuera, pintura, identificacion</i>	✓	
ENGINE AND ELECTRIC / MOTOR Y ELECTRICO		
9. Generator / alternator, starter, brushes, wiring - mounting <i>Generador / alternador, arrancador, escobillas, lineas electricas - monturas</i>	✓	
10. Batteries, water, terminals, cables <i>Baterias - agua, terminales, cables</i>	✓	
11. Radiator, water hoses, water pump - securement, leaks <i>Radiador, mangueras de agua, bomba de agua - asegurar, fugas</i>	✓	
12. Compressor(s), fan, waterpump, acc. - belts - condition and adjustment <i>Compressor(s), abanico, bomba de agua, bandas - condicion y ajuste</i>	*	✓
13. Clutch adjustments - freeplay <i>Ajuste del embrague - juego libre</i>	w/10	
14. Throttle, linkage, fuel system leaks, air filter <i>Acelerador, conecciones, fugas de combustibles, filtro de aire</i>	✓	
15. Manifolds, gaskets - securement, leaks <i>Manifold y empaques - asegurar, fugas</i>	✓	
16. Engine mounts, oil leaks <i>Monturas del motor, fugas de aceite</i>	✓	
REMARKS/COMENTARIOS		
** eEMERGENCY EXIT WINDOWS SALIDAS DE EMERGENCIA	✓	

INSPECTOR/
INSPECTOR (FIRMA
CHP108A-ES



DATE/
FECHA COMPLETA

109/30/2013

1. Repair on Radiator New Speed Sensor.
2. Repair on Engine Coolant Pressure sensor.
3. Repair on Engine Compore Code Active Reset.
4. Repair on Engine Oil Fluid Levels Check
4. Repair on Inspection on Repairs.

BRAKES / FRENOS		OK	DEF
17. Hydraulic fluid level, leaks, hoses and tubing - secured, protected <i>Nivel de fluidos hidraulicos, fugas, mangueras y tubos - asegurados, proteccion</i>	* *	✓	
18. Air governor adjustment - minimum 85, maximum 130 <i>Ajustes del pulmon (governador del compresor) - minimo 85 - maximo 130</i>	* *	✓	
19. Air leaks, unapplied, 1 minute 3 pounds maximum <i>Fugas de aire, sin aplicar, uno minuto 3 libras maximo</i>	* *	✓	
20. Air leaks, applied, 1 minute 3 pounds maximum <i>Fugas de aire, frenos aplicados, uno minuto 3 libras maximo</i>	* *	✓	
21. Drain number 1 air reservoir - test check valve(s) - low air warning operates <i>Drenar el tanque mojado -chece las valvula(s) de uno sentido, señal de baja presion se opera</i>	* *	✓	
22. All tanks secure, drains operable, drain tanks <i>Monturas de todos los tanques, purgadores operables, drene tanques</i>	* *	✓	
23. Vacuum loss - 3" per min., 15" minimum vac. - low vacuum warning - tanks secure <i>Fugas de succion - 3 pulgadas por minuto, 15 pulgadas vacio minimo - señal de baja vacio - tanques asegurados</i>	* *	✓	
24. Brakes, lining, drums and adjustment - near cam over, pedal height on hydraulic <i>Frenos - balatas, tambores y ajuste - cerca del centro de gabilan, alta del pedal - frenos hidraulicos</i>	* *	✓	
25. Parking brake - condition and adjustment <i>Freno de estacionamiento - condicion y ajuste</i>	* *	✓	
26. Emergency stopping system - labeled and operable <i>Sistema de Alto de emergencia - marcado y operable</i>	* *	✓	
27. Release after loss of service air. Anti skid if equipped <i>Soltar de frenos despues de perder aire de servicio, equipado contra derrapes</i>	* *	✓	
CHASSIS / CHASSIS		OK	DEF
28. Wheels, tires, lug nuts - cracks, secured - tread - inflation <i>Rines, llantas, tuercas - rajadas, seguridad, banda rodante, presion de aire</i>	* *	✓	
29. Wheel seals, leaks - hyd. brake system leaks <i>Retenes de las ruedas y fugas - fugas de la systema hidraulico</i>		✓	
30. Check steering gear mounting - free lash, oil level <i>Revisar sinfin del volante y monturas - juego libre, nivele de aceite</i>	* *	✓	
31. Steering arms, drag links, tie rods <i>Brazos de direccion y barras de acoplamiento, terminales</i>	* *	✓	
32. Check frame, crossmembers, cracks, etc. <i>Revisar el chasis, travesaños, rajaduras, etc.</i>	* *	✓	
33. Springs, shackles, and "U"bolts, king pins, shock absorbers <i>Muelles, gemelos y pernos de "U", king pins, amortiguadores</i>		✓	
34. Transmission, differential, mounting and seals, drive shaft, "U"joints, guard <i>Transmision, diferencial, monturas y retenes, flechas y crucetas, protectores de las flechas</i>		✓	
35. Exhaust - condition, leaks, mounting <i>Escape - condicion, fugas, montura</i>		✓	
36. Fuel tanks, lines, pumps - condition, mounts, leaks <i>Tanque de combustibles, mangueras, bomba, condicion, soportes, fugas</i>		✓	
37. Body underside and firewall, airtight and clean <i>Por de bajo de la cabina y pared de fuego, aire sellado y limpio</i>	* *	✓	
REMARKS / COMENTARIOS			
<div style="display: flex; justify-content: space-between; align-items: flex-end;"> <div style="width: 45%;"> <p>INSPECTOR/ INSPECTOR(FIRMA)</p> <p>CHP108A-ES</p> </div> <div style="width: 45%; text-align: right;"> <p>DATE/ FECHA COMPLETA</p> <p>09/30/2019</p> <p>REVISED 03-03-98</p> </div> </div>			


BUS MAINTENANCE & SAFETY INSPECTION

INSPECCION Y MANTENIMIENTO DEL AUTOBUS

*Inspection of these items required by 34505 CVC
 *Inspeccion de estas cosas es el requisito por la ley 34505 CVC

VEHICLE NO. NUM. VEHICULO <i>6857</i>	LICENSE NO. NUM. LICENCIA <i>W 047c</i>	MILEAGE MILLAGE <i>135056</i>
MAKE MARCA <i>Freightliner</i>	MODEL MODELO <i>BUS</i>	YEAR AÑO <i>08/2013</i>
INTERIOR AND EXTERIOR / INTERIOR Y EXTERIOR		
1. Fire extinguishers, warning reflectors, first aid kit <i>Extinguidores, reflectores triangulares (luces muertas), primeros auxilios</i>		OK DEF <input checked="" type="checkbox"/> <input type="checkbox"/>
2. Instruments, secure seats, clean interior, driver's seat and belt <i>Marcadores, los asientos asegurados, interior limpio, asiento y cinturon de seguridad del chofer</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
3. Windshield, w/wipers, windows, mirrors, floor condition <i>Vidrio, limpia brisas, rajaduras del vidrios, espejos, condicion del piso</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
4. Lights, interior, exterior, signals, warning, switches and wiring <i>Luces - interior, de afuera, direccionales, indicadores, lineas electricas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
5. Warning devices - horn, oil, temperature, lift, door(s) <i>Señales de emergencia - claxon, aceite, temperatura, elevador, puerta(s)</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
6. Heaters, defrosters, cooling and vent systems <i>Calenton, descongelador (estan calientes?), sistema de enfriamiento y ventilas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
7. Door operations, sensitive edges, timing, padding, handrails, safety panels <i>Operacion de las puertas, borde sensibles, tiempo, relleno, soportes del mano, paneles de seguridad</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
8. Exterior condition, paint, identification <i>Condicion de afuera, pintura, identificacion</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
ENGINE AND ELECTRIC / MOTOR Y ELECTRICO		
9. Generator / alternator, starter, brushes, wiring - mounting <i>Generador / alternador, arrancador, escobillas, lineas electricas - monturas</i>		OK DEF <input checked="" type="checkbox"/> <input type="checkbox"/>
10. Batteries, water, terminals, cables <i>Baterias - agua, terminales, cables</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
11. Radiator, water hoses, water pump - securement, leaks <i>Radiador, mangueras de agua, bomba de agua - asegurar, fugas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
12. Compressor(s), fan, waterpump, acc. - belts - condition and adjustment <i>Compressor(s), abanico, bomba de agua, bandas - condicion y ajuste</i>	*	<input checked="" type="checkbox"/> <input type="checkbox"/>
13. Clutch adjustments - freeplay <i>Ajuste del embrague - juego libre</i>		<input type="checkbox"/> <input checked="" type="checkbox"/>
14. Throttle, linkage, fuel system leaks, air filter <i>Acelerador, conexiones, fugas de combustibles, filtro de aire</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
15. Manifolds, gaskets - securement, leaks <i>Manifold y empaques - asegurar, fugas</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
16. Engine mounts, oil leaks <i>Monturas del motor, fugas de aceite</i>		<input checked="" type="checkbox"/> <input type="checkbox"/>
REMARKS/COMENTARIOS		
** eEMERGENCY EXIT WINDOWS SALIDAS DE EMERGENCIA		<input checked="" type="checkbox"/> <input type="checkbox"/>

INSPECTOR/
INSPECTOR (FIRMA)
CHP108A-ES



DATE/
FECHA COMPLETA *08/20/2019*

REVISED 03-03-98

*1. Repair Engine oil and filter
 2. Repair Engine Coolant Reservoir
 and New Coolant on Base on Clamps
 3. Repair Air Ride Control Adjustment
 4. Repair on Installation New G.P.S System
 5. Repair All Other Air Pressure check
 6. Repair Electric door Compartment
 7. Repair A/C system Recharge Freon
 8. Repair on Front Suspension and
 U-Joints Lubrication
 9. Repair on Inspection on Repairs*

BRAKES / FRENOS		OK	DEF
17. Hydraulic fluid level, leaks, hoses and tubing - secured, protected <i>Nivel de fluidos hidraulicos, fugas, mangueras y tubos - asegurados, proteccion</i>	* *	✓	
18. Air governor adjustment - minimum 85, maximum 130 <i>Ajustes del pulmon (governador del compresor) - minimo 85 - maximo 130</i>	* *	✓	
19. Air leaks, unapplied, 1 minute 3 pounds maximum <i>Fugas de aire, sin aplicar, uno minuto 3 libras maximo</i>	* *	✓	
20. Air leaks, applied, 1 minute 3 pounds maximum <i>Fugas de aire, frenos aplicados, uno minuto 3 libras maximo</i>	* *	✓	
21. Drain number 1 air reservoir - test check valve(s) - low air warning operates <i>Drenar el tanque mojado -chece las valvula(s) de uno sentido, señal de baja presion se opera</i>	* *	✓	
22. All tanks secure, drains operable, drain tanks <i>Monturas de todos los tanques, purgadores operables, drene tanques</i>	* *	✓	
23. Vacuum loss - 3" per min., 15" minimum vac. - low vacuum warning - tanks secure <i>Fugas de succion - 3 pulgadas por minuto, 15 pulgadas vacio minimo - señal de baja vacio - tanques asegurados</i>	* *	✓	
24. Brakes, lining, drums and adjustment - near cam over, pedal height on hydraulic <i>Frenos - balatas, tambores y ajuste - cerca del centro de gavilan, alta del pedal - frenos hidraulicos</i>	* *	✓	
25. Parking brake - condition and adjustment <i>Freno de estacionamiento - condicion y ajuste</i>	* *	✓	
26. Emergency stopping system - labeled and operable <i>Sistema de Alto de emergencia - marcado y operable</i>	* *	✓	
27. Release after loss of service air. Anti skid if equipped <i>Soltar de frenos despues de perder aire de servicio, equipado contra derrapes</i>	* *	✓	
CHASSIS / CHASSIS		OK	DEF
28. Wheels, tires, lug nuts - cracks, secured - tread - inflation <i>Rines, llantas, tuercas - rajadas, seguridad, banda rodante, presion de aire</i>	* *	✓	
29. Wheel seals, leaks - hyd. brake system leaks <i>Retenes de las ruedas y fugas - fugas de la sistema hidraulico</i>	* *	✓	
30. Check steering gear mounting - free lash, oil level <i>Revisar sinfin del volante y monturas - juego libre, nivele de aceite</i>	* *	✓	
31. Steering arms, drag links, tie rods <i>Brazos de direccion y barras de acoplamiento, terminales</i>	* *	✓	
32. Check frame, crossmembers, cracks, etc. <i>Revisar el chasis, travesaños, rajaduras, etc.</i>	* *	✓	
33. Springs, shackles, and "U"bolts, king pins, shock absorbers <i>Muelles, gemelos y pernos de "U", king pins, amortiguadores</i>	* *	✓	
34. Transmission, differential, mounting and seals, drive shaft, "U"joints, guard <i>Transmision, diferencial, monturas y retenes, flechas y crucetas, protectores de las flechas</i>	* *	✓	
35. Exhaust - condition, leaks, mounting <i>Escape - condicion, fugas, montura</i>	* *	✓	
36. Fuel tanks, lines, pumps - condition, mounts, leaks <i>Tanque de combustibles, mangueras, bomba, condicion, soportes, fugas</i>	* *	✓	
37. Body underside and firewall, airtight and clean <i>Por de bajo de la cabina y pared de fuego, aire sellado y limpio</i>	* *	✓	
REMARKS / COMENTARIOS			
INSPECTOR/ INSPECTOR(FIRMA CHP108A-ES		DATE/ FECHA COMPLETA 08/20/2019 REVISED 03-03-98	

Semana Laborales

08/10/2019

Sabado # 3284 - 08/10/2019 - Millas - # 787070
Repair, Road Service on El Monte California spot
Inspectional BUS No Power. and Repair on Insulation
Used Baterie and Repair Drive to El Monte yural.

Lunes # 3284 - 08/12/2019 - Millas - # 787070
Repair on Rember Alternator and sent to Repair
and Repair on Insulation new Alternator on belts.
and Repair Alternator Vests charged - 13.70 Vests.
and Repair on Engine All Fluids Levels check.

Lunes # 6857 - 08/12/2019 - Millas - # 133852
Repair on Bfs Inspectional on A/C Compressor and
Oreop System on Repair on A/C Oreop Recharge
and Repair, Inspectional Interior on Exterior and A/C
Focus Motors on Engine All Fluids Levels check.

Lunes # 5910 - 08/12/2019 - Millas - # 422969
Repair on BUS Inspectional. on Repair eye Radiator and
Inted Cooler Rember on Engine Parts Rember.

Martes # 3284 - 08/13/2019 - Millas - # 787421
Repair on Inspectional BUS Air Leak on Repair
and Air Drier Hose Pass. on Repair Engine on Fluids

Martes # 5910 - 08/13/2019 - Millas - # 422969
Repair on Engine Parts Rember on Turbo on Oil Hoses
and Repair Engine Cooler Hose Rember and Repair
on Engine oil Cooler Parts Rember on Repair
on Oil Parts Rember Clener. on Repair Turbo to
Inspectional on Repair on Repair on Sent Radiator
Inspectional on Repair on Dealer order All
Parts.

Mercedes # 5910 — 08/14/2019 — Mallas — 422969

Repair on Installation New Radiator on Engine Fan Support on Repair on Assembly. All Parts Replaces and Repair on Replaces New oil Cooler Gaskets and O-rings on New Cooler Pipes and Repair EHG Cooler Hose on Gaskets New Replaces and Clamps on Repair Engine oil Drain on Filters.

Jeeps # 5910 — 08/15/2019 — Mallas — 422969

Repair on Installation New Turbo on the Parts Replaces on Assembly and Repair on Engine New Oil on Filters New Replaces on Repair All Sided Cooler Hose Assembly on All Wires on Cooler Hose Protected on Inspection No Leaks

Jeeps # 3284 — 08/19/2019 — Mallas — 787743

Repair Road Service on Corana Car on Inspection Bts No Power on Repair on Installation Used Alternator on Repair Inspection Alternator parts changed and Alternator changed. 13.84 Volts on Repair Bts Drive on 21 minute Car on yards

Jeeps # 3284 — 08/16/2019 — Mallas — 787471

Repair on Installation New Air Dryer and Inspection. Air Leaks on Repair on Engine All Fluids Levels Check

Jeeps # 5910 — 08/17/2019 — Mallas — 422969

Repair Bts Inspection on Engine Leak oil on Coolers System on Repair Bts Inspection on Over Air Pressure

Jeeps # 5330 — 08/16/2019 — Mallas — 835973

Repair Engine Water Leaks on Replaces Used Cooler Hoses and Clamps on Repair Engine All Fluids Levels Check

Semana Laborales

08/18/2019

Domingo # 5910 - 08/18/2019 - Millas # 423293
Repair Road Service on Baldwin Post Ca. Inspectioanal
A/C Compressor belt on Repair on belt Number.

Domingo # 5330 - 08/18/2019 - Millas # 836610
Repair on Bus Inspectioanal No starter on Repair and
Bus # 5797 - Number used starter on Repair and
Installation Bus 5330 - Used starter on Repair and
Inspectioanal Bateries on attenuators volts, charger. and
Repair, Installation New Side Head Light. on Repair,
Inspectioanal All Lights on Engine All Fluids Levels -

Lunes # 3284 - 08/19/2019 - Millas # 789396
Repair on Bus Inspectioanal Front Tires on Repair and
Number Side Tires on Sent to Repair on Tires is not
Good on Repair on Replaces new Tires on Air Pressure
check on Repair on Engine All Fluids Levels check.

Martes # 3284 - 08/20/2019 - Millas # 789700
Repair on Inspectioanal All System on Compressor Wires
Connectors on A/C Compressor belts on Electric Wires.

Martes # 5910 - 08/20/2019 - Millas # 424167
Repair on Replaces new Engine belt on A/C Compressor
New, belt Replaces and All Pulley Bearings, Inspectioanal
and Repair Engine All Fluids Levels check.

Martes # 6857 - 08/20/2019 - Millas # 735056
Repair on Engine oil on Filters new Replaces and
Repair Engine Cooler Reservoir New Replaces and
New Cooler on Hose on Clamps Replaces and Repair
All Axle Brakes Adjustment. and Repair All
Tires Air Pressure check.

Mercedes # 6857 - 08/21/2019 - # 135056

Repair on Suspension All axle oil level and
Repair on Installation New G.P.S System and
Reprogramming on Repair Electric Door Components
and Repair A/C Compressor Freon Recharge System.

Juventus # 6857 - 08/22/2019 - # 135056

Repair on Assembly All Parts Recharge on Repair and
Inspection on Fluids on All Connectors.

Juventus # 6857 - 08/22/2019 - # 135056

Repair on yard, Clean on Organize on Parts
and Used Parts on Repair Pie up New Tires.

Mercedes # 748 - 08/23/2019 - # 170278

Repair on Engine oil on Filters, Changes, and
Repair Engine Air Filter Clean. and Repair and
Replace New G.P.S System on Reprogramming and
Repair Side Mirror Bracket bolts Adjustment and
Repair All Tires Air Pressure check. on Repairing
on Engine on Brake Clean. on Repair on Suspension.

Senora Taboales

09/2/2019

Lunes # 3404 - 09/2/2019 - Millas # 296259
Repair on All Engine Filters Levels, check and
Repair on Fuel Jet Filter Level and Repair Bus Inspection.

Lunes # 7043 - 09/2/2019 - Millas - # 276457
Repair on Installation New License Resment and
Engine All Filters Level check.

Martes # 748 - 09/3/2019 - Millas - # 1705754
Repair on Installation New Power, outlet Socket
and Replaces new wires on Electric Connectors and
Repair on Engine All Filters Levels check.

Martes # 7043 - 09/3/2019 - Millas - # 277048
Repair on Engine oil on Filters changed and
Repair on Engine oil Leaks and Repair and
Inspection Bus Air Leaks.

Miércoles # 7043 - 09/4/2019 - Millas - # 277048
Repair on Installation New Engine Air Filter and
Bateries Posts Terminals Clamps. and Repair and
Repair Bong Aple Replaces, New Chambers and
Repair on Bus Air System check on No Air Leaks
and Inspection All Tires Air Pressure check on All Lights

Miércoles # 748 - 09/4/2019 - Millas - # 1706074
Repair on Inspection oil Leak on Repair on Flanaber
Hydraulic Brake Booter Assembly and sent To
Repair and Repair All Hydraulic Hose Clener.
on System oil Flashing. and Repair and Engine
oil on Filters changed, on Engine Air Filter Clamps. and
Repair on Bus Inspection on Repairs.

Jueves # 5330 — 09/5/2019 — Millas # 842241
Repair Rear Side Replaces Used Reverse Light
on Stop Light Repair on Repair on All Engine
Fluids Level Check on Repair on Inspectional
All Tires Air Pressure Check.

Jueves # 748 — 09/5/2019 — Millas # 1706074
Repair on Installation Hydraulic Brake Booster
and Repair on Assembly All Parts Reamber and
Repair on All Fluids, Levels check and Repair
Interior Floor and Clones on Repair All Tires
Air Pressure check and on Engine Fluids Levels

Viernes # 6857 — 09/6/2019 — Millas # 137738
Repair on Engine Code Compute Reset and
Repair on Reprogramming speed and Repair
on Engine All Fluids Levels check. on Repair
and DEF Fluid Level Replaces.

Sabado # 3284 — 09/7/2019 — Millas # 794979
Repair on Inspectional Rear Side Vent. Bracket
on Repair on Reamber All Glass and Make
Constant Glass Vent Windend Repair and
Vent Glass Window Check.

Semana Laborales

Lunes # 5910 - 09/9/2019 - Millas - # 429079
Repair on Inspectional Engine belt and Repair
and Replaces Engine Support Fan on Sent to Dealer
to Warranty and Repair on Installed New Fan
Support on Repair Engine Clones and Repair
Front Side Fender Bracket Support Welding Plate

Lune # 6857 - 09/9/2019 - Millas - # 138754
Repair on Inspectional Engine All Fluids Levels check
and Repair on the Vehicle Temporarily Repair Installation
on Repair Rear Side Bumper Corner Bolt Replaces

Martes # 5330 - 09/10/2019 - Millas - # 844206
Repair on Inspectional BUS All Tires on Repair
Rear Tray Axle Side Mounting Spare Tire on
Repair All Tires Air Pressure check on Repair
Engine All Fluids Levels check.

Martes # 5910 - 09/10/2019 - Millas - # 429079
Repair on Assembly Engine Support Fan belts
on All Pulleys on Repair on Assembly All Engine
New belts on Repair on Engine All Fluids Levels
check on Repair on Installed New Power Socket
on Electric Fuse Wire New Replaces.

Miercoles # 7043 - 09/11/2019 - Millas - # 279776
Repair on Inspectional All Tires on Repair on
Front Axle Mounting 2 New Tires and
Repair Rear Tray Axle Mounting 2 Used Tires
on Repair on All Tires Air Pressure check.
and Repair on Engine All Fluids Levels check
on Repair on Inspectional Interior Air Ventilation
Fans Motors and Ventilation Air Filters Clones.

925940

926174

Mercedes # 5330 - 09/11/2019 - Dallas-844850
Repair on Inspection All Tires on Spare Tires
~~925800~~ blew Side Mounting Tires.

Jueves - # 5330 - 09/12/2019 - Dallas # 844850
Repair on Bus Inspection on Repair on Rear
Tire Axle Replaces New Tires on All Tires
Air Pressure Check on Repair on Engine New oil
on Filters changes. on Repair Rear Tire Axle
Yoke New Labor Replaces on All Axle Brakes
Inspected.

Viernes # 5330 - 09/13/2019 - Dallas-844850
Repair on Spare Tire Mounting on Repair and
Engine All Fluids Level Check on Repair
on Bus Inspection on the right Inspection

Viernes Honda - 09/13/2019 - Dallas.
Repair on All Compressor New Replaces and
Dress and Repair All Vacuum System and
All Power Steering System and Repair
on Inspection Electric Short.

09/16/2019

Semana Laborales

Lunes # 5330 - 09/16/2019 - Milas - # 845470

Repair on Inspectional BUS to starter and repair on inspectional All fuses on Relays on check on repair and repair inspectional Engine All Fluids levels check on repair on Inspectional All tires on Tyres.

Lunes # Honda - 09/16/2019 - Milas - #

Repair on Desmounting front Cluster and Number All Control on Inspectional wires and connectors on All switches Fault.

Martes # 3284 - 09/17/2019 - Milas - # 796524

Repair on Inspectional Air leaks on Valve System on 10 leaks on repair on Inspectional Air Warning Sensors on 15 or. and repair on Air Tanks Water Purge System on repair on Inspectional Engine All Fluids.

Martes # 3404 - 09/17/2019 - Milas - # 301104

Repair on Engine oil on Filters changed and Engine Air Filter Clones on repair Rear 1/2 side Spare Tire Door Lockers Bracket and repair Entrance Passengers Door Cylinder Air Adjustment and repair Rear 1/2 side Air Bay, New Replaces and Replaces New Air Hose, and Fittings on repair All Tires Air Pressure check on repair on BUS Inspectional on repair Front Head lights Interior Clones on Tyres Adjustment.

Miércoles # 748 - 09/18/2019 - Milas - # 1709784

Repair steering wheel shaft U.Joint New Replaces and repair on Lubricant Joints on repair on Engine oil on Filters changed and Inspectional All Fluids levels check on repair All Tires Air Pressure check and repair on BUS Inspectional.

Jueves # 748 - 09/19/2019 - Dallas - # 1709784
Repair on Assembly New Air Hose and
Repair Air Hose Protection Brackets and Repair
BUS Drive To Springs Shop To Repair Springs.

Jueves # 6857 - 09/19/2019 - Dallas - # 141687
Repair on Front Axle Mounting New Tires Replaces
on Seat To Baulance Tires and Repair Rear Drive
Axle Yside Mounting Used Tires on Repair on All
Tires Air Pressure check. and Repair on Engine
All Fluids Levels check.

Viernes # yard - 09/20/2019 - Dallas - # 000000
Repair on yard Lines on All Parts Used Organize
and Repair Fernando, Seats on one bolts and
Repair Welding Seats.

Viernes # 748 - 09/20/2019 - Dallas - # 1709789
Repair on Pick up BUS Springs Shop on Drive To
yard on Repair on Suspension. All Axle and
Replaces New Springs on Shaefles on Supports on
15 on.

09/23/2019

Semana Laborales

Lunes # 3284 - 09/23/2019 - Millas - # 797992

Repair on Inspectional A/C System on Repair on A/C Compressor Freon Fluid checked and Repairing A/C Filters Clean on A/C Ventilation Fans Motors

Lunes # 748 - 09/23/2019 - Millas - # 1710421

Repair on Inspectional A/C System on Repair and Reamber A/C Compressor Pulley Failure on Repair and Installation Used Pulleys on A/C Compressor belt

Lunes # 6857 - 09/23/2019 - Millas - # 143278

Repair on Inspectional All Lights on Repair on Replaces New Head Light Side and Repair on Engine Compose Diagnostic Code Active on No Codes Actives and Repair on Compose Reset on Repair on Engine All Fluids Levels checked

Lunes # 7043 - 09/23/2019 - Millas - # 283276

Repair on Bus Inspectional on Repair on Reamber Parking Brake Handle Valve and Repair on New Handle Valve Replaces on Handle Adjustment. on Repair on Engine All Fluids Levels checked. on Inspectional All Tires Air Pressure

Martes # 3284 - 09/24/2019 - Millas - # 798315

Repair on Engine oil on Filters changed and Repair Engine Fans Hydraulic Box Pressure Transfer. New O-rings Replaces on New oil on Repair on Inspectional Bus and All Fluids Levels checked. and Repair on Hydraulic Pump on All Hose Pressure and Repair on Inspectional All Tires Air Pressure checked. on Repair Rear Drive Axle Brakes Adjustments

Mercedes # 6857 - 09/24/2019 - Dallas - # 143601
Repair Entree Door Glass and Repair Engine Computer
Diagnosing Code Active and Repair Engine Computer
Code Reset on Engine All Fluids Levels Check.

Mercedes # 3284 - 09/25/2019 - Dallas - # 798315
Repair Front Axle Side Replaces New Air bag
Height Control Valve on New Air Getting Hoses Push
Replaces and Repair All Tires Air Pressure Check
and Repair on Rear Drive Axle Inspection Air bags
on Repair Adjustments on Repair on Bus Inspection.

Juventus # 6857 - 09/26/2019 - Dallas - # 143916
Repair on Engine Computer Diagnosing Code Active
on Repair on Inspection Sensor on Wires Connectors
on Computer Code Reset on Engine All Fluids Levels

Juventus # 3284 - 09/26/2019 - Dallas - # 798936
Repair on Engine Computer Diagnosing Code Active and
Repair Tyrod Pressure Sensor New Replaces and Repair Engine
Casefilter New Replaces and Engine All Fluids Levels Check.

Mercedes # 3284 - 09/27/2019 - Dallas - # 798945
Repair on Engine Code Active on Repair and Inspection
Air Pressure Sensor on Repair on Engine Crankcase Filter
Pressure New Replaces on sensor and Repair on checked
All The Tubes on breather Pressure and Repair on
Parts Cleaners on Repair on Computer Code Reset.

09/30/2019

Semana Laborales

Lunes # 5330 - 09/30/2019 - Millas - # 850028

Repair on Vehicle Rear Right Side Long Axle Tire and Repair on Installation Spare Tire Mounting and Repair on Inspection All Tires on Air Pressure check and Repair on Bus Inspection on Repair and Engine All Fluids Levels check.

Lunes # 6857 - 09/30/2019 - Millas - # 145304

Repair on Replaces New Turbo Speed Sensor and Repair Intake Cooler Pressure Sensor on Repair Engine Computer Code Active on Code Reset on Repair Engine oil on Filter change on Engine All Fluids Levels check and Repair on Bus Inspection on Repairs.

Martes # 3284 - 10/1/2019 - Millas - # 799912

Repair on Inspection Engine Computer Diagnostic Code Active on Engine Injectors # 1 on 6 Cylinder Fault and Repair on Reamber Injectors on all Parts Reamber on Clines on Repair on Reamber Gaskets on Covers on bolts Clines.

Miercoles # 3284 - 10/2/2019 - Millas - # 799912

Repair on Engine Assembly 2 New Injectors and Replaces New Valve Cover Gaskets on Repair Valve Adjustment on Repair Intake Cooler Housing New Gasket Replaces on Assembly on Engine Parts Reamber and Engine Computer Code Reset and Repair on Inspection Engine All Fluids Levels check on Repair Engine Computer Injector Pressure Testing on Injector is off on Repair Cylinder Head Pressure Testing on Fault. Cylinder # 1 on Engine smoking

Jueves # 748 - 10/3/2019 - Millas # 1712182

Repair on Installation New A/C Compressor and
Repair on A/C Compressor New belt. Replaces and
Repair A/C Freon System Recharge and Repair
on Inspectional A/C Ventilation and Repair Engine
Compare Diagnostic Code Active and Engine Code
Active. Fault: Injection Actuation Pressure System Fault

Viernes # 748 - 10/4/2019 - Millas # 1712182

Repair on Installation New Hydraulic Injection Pressure
Pump and Repair on Engine New oil and Filter, change
on Repair on Engine on Fluids Levels check and
Repair Air Lines Air Pressure check and Repair
on Assembly New gear Box on oil Fluid Levels
on Repair on Inspectional Front Suspension.

Sabado # 3404 - 10/5/2019 - Millas # 306690

Repair Engine oil and Filters change on Inspectional
Engine, All Fluids Levels check. on Repair and
Installation Two Front Tires on Repair All
Tires Air Pressure check. on Repair on Inspectional
BUS on the light on Interior check.

10/6/2019

Semana Laborales

Domingo # 6857 - 10/6/2019 - Milas - # 147627
Repair on Road Service on Corona Caf. and Inspeccional
Bus Engine Code Active on Repair on Computer
Diagnostic Code Active OEM Code: 553 - SPV: 197
on Repair on Inspeccional All Fluids on Fault Water in
Fuel Indicator on OEM Code: 418 - SPV: 97 and
Repair on Engine Code Reset.

Lunes # 748 - 10/7/2019 - Milas - # 1712706
Repair on Inspeccional Engine Computer Diagnostic Code
and Repair on Inspeccional Injector Pressure System
on All Injector Fault Pressure on Cylinder Mixture Pressure.
and Repair on Remove All Injector on sent to warranty and
Repair on Assembly all New Injectors on Repair and
Engine and per Filter New Replaces on Engine Computer
Code Reset. on Inspeccional All Engine Connector and
Repair on Engine on Frame Clones. and Repair on All Tires
Pressure check and Repair on Bus Inspeccional on Repairs

Martes # 5330 - 10/8/2019 - Milas - # 853046
Repair on Inspeccional A/C System and Repair on A/C
High Pressure Tube Welding Repair on Repair Freon
System Recharge on A/C System and Repair on Inspeccional
Interior A/C Ventilation Fans Motors and Repair and
A/C Ventilation Filters Clones and Repair on Engine
All Fluids Levels check and Repair Engine on Frame
Clones and Repair All Tires Pressure check on Right.

Martes # 6857 - 10/8/2019 - Milas - # 147627
Repair on All sensor order Pick up Dealer and Oxycanite
for next day to go to work on Corona Caf. to
Repair Bus. on change Fuel Diesel Filters.

Thercoles # 6857 - 10/9/2019 - Milas - # 147643
Repair Road Service on Corona Cal. on Inspected
Bus on Repair Fuel Filters New Replaces and
Repair on All Fuel Lines Cleaner on Fuel Tank
on Fuel Separator Filter Housing Cleaner on Sensors
and Repair Injector Rail Pressure Tubers and
Repair on Replaces New Fuel Pressure Sensor and
Repair Computer Engine Code Reset and Repair
Engine Force Regeneration on is Complete.

Dyeres # 5330 - 10/10/2019 - Milas - # 853347
Repair on A/C Compressor New Belts Replaces and
Repair Alternator New Belts on Repair Engine
Fill in oil Tube used Replaces on New Gaslet
and Repair A/C Condensator Four Fans Motors
New Replaces and Repair Bus Interior A/C Ventilation
Fans New Motors Replaces on A/C Filters Cleaner.
and Repair on Inspected on Engine All Fluids Level Check

Viermes # 748 - 10/11/2019 - Milas - # 1713726
Repair on Engine Computer Diagnostic Code Active and
Engine Code Active Fault SPD: 91 - Accelerator Pedal
Position on Repair Engine Computer Code Reset
on Part Order on Repair on Engine All Fluids Level Check

Viermes # 6857 - 10/11/2019 - Milas - # 147643
Repair on Road Service on Corona Cal. on Replaces
New Fuel Diesel Pressure Rail Sensor and
Repair Fuel Diesel Purge System on Repair and
Engine All Fluids Level Check and Repair on
Bus Drive To Fl Motor To word and
Repair on Inspected on Fuel Air Pressure and
Engine Computer Code on No Code Present.

10/21/2019

Semana Laborales

Lunes # 5330 - 10/21/2019 - Milas - # 856997

Repair on Inspectional Bus on Repair Rear A/C Compressor Air Leaks on Repair on Replaces Air Valve Used Assembly on All Air Fittings and Repair on Inspectional Engine All Fluids Levels Check.

Lunes # 3284 - 10/21/2019 - Milas - # 799914

Repair on Inspectional All Injector on Turbo Sent to Repair on 2 Injector is not Good on 1 Sent to Warranty on Turbo charger is not Good on All Parts Sent to Repair

Lunes # 748 - 10/21/2019 - Milas - # 1716026

Repair on Road Service on Corona, Cal. on Pick up The bus on Drive bus to El Monte, Cal. on road on Repair on Assembly Used Tigotte Replal Position Sensor on Repair Engine Compure Code Resef. on Repair on Inspectional bus on Engine All Fluids Levels Check.

Martes # 5330 - 10/22/2019 - Milas - # 857317

Repair on Rear Yside Tail Light Wires open on Repair Wires Connector New Wires on Connector Replaces.

Martes # 7043 - 10/22/2019 - Milas - # 293114

Repair on bus Inspectional on Repair Rear Drive Axle Replaces New Brakes on Used Brakes Sensors and Repair Inspectional All Tires on Air Pressure Check. and Repair on Inspectional All Brakes and Repair and Engine All Fluids Levels Check. on Repair and Inspectional All Lights operation on Interior All Seating

Miercoles # 5330 - 10/23/2019 - Milas - # 857630

Repair Interior Compartment Bayage Trunks on Doors Air Valve Used Replaces. on Inspectional No Leaks and Air Valve Handle Used Adjustment.

Sabado # 748 - 10/26/2019 - Millas - # 1717206
Repair on Front Axle mounting Two New Tires on Seat To Balance and Repair
Rear Drive Axle mounting Two Used Tires on All Tires Air Pressure check and
Repair on Engine All Fluids levels check.

Mercedes # 3404 - 10/23/2019 - Millas - # 313075
Repair on bus Inspection on Rear Drive Axle side
oil leak on Repair on Remove All Parts, and
Repair on Inspection All Bearings on Cleaner and
Repair Axle on housing and Repair on Replaces New
BRACKES on New Wheel and Seal on All Springs New.

Mercedes # 5797 - 10/23/2019 - Millas - # 000000
Repair on Remove A/C Compressor and All Pressure
Hose on Wires Pressure Sensors and Repair to sent El Paso TX

Jueves # 3404 - 10/24/2019 - Millas - # 313075
Repair on Assemble All Parts Remove on Rear Axle
and Repair on Inspection Differential Fluid level oil
on Repair on Inspection Engine All Fluids levels Check
and All Brakes Adjustment on Repair on Inspection Bus.

Jueves # 305 Megrol Van - 10/24/2019 - Millas - # 243017
Repair on Assemble All Passengers Seats on Repair interior Clave
and Repair Inspection All lights on Engine All Fluids levels
check on All Tires Air Pressure check on A/C System and
Ventilation Interior on Inspection steps.

Viernes # 6857 - 10/25/2019 - Millas - # 153543
Repair on Engine Computer Diagnostic Code Active and
Repair on Fuel Diesel Filters New Replaces on Water Separator
Filter housing Cleaner on Repair Cleaner Sensors on Repair Engine
All Fluids levels check on Repair All Brakes Axle Brakes
Adjustment. and Inspection All Tires Air Pressure check.

Viernes # 3284 - 10/25/2019 - Millas - # 799914
Repair on To Assemble All Injector on Assemble All
Booster Valve on Assemble Valve rods and
Repair on Adjustment.

11/11/2019

Semana Laborates

Lunes # 748 - 11/11/2019 - Millas - \$ 1721395

Repair on Engine Code Active and Repair Fuel Pressure Sensor wires Connector and Repair Front Side Head Light New Replaces on Repair Rear Side Emergency Lacquer Bracket on Repair All Tires Air Pressure check on Repair All Drive Shafts and U-Joints Lubricant. on Repair Front Suspension Lubricant. on Repair Engine oil and Filters change on Repair Engine Air Filter Cleaner on Repair steering Gear box oil leak on Replaces New pricing on Repair Side Mirror Glass and Inspection & Repairs

Martes # 5910 - 11/12/2019 - Millas - \$ 451280

Repair Front Axle Mounting Two New Tires on Sent To Balance on Repair Front Axle Alignment on Repair All Tires Air Pressure check and Repair on Engine oil and Filters change on Air Filter Cleaner on Repair All Fluids Levels check. and Repair on Rear Drive axle Side Reassemble All Parts.

Miercoles # 5910 - 11/13/2019 - Millas - \$ 451280

Repair Rear Drive Axle Side on Assemble New wheel oil Seal on New Bearings on New Brakes and Repair Differential oil Level on Repair All Axle Brakes Adjustment on Repair on Bus Inspection & Repairs

Miercoles # 748 - 11/13/2019 - Millas - \$ 1722035

Repair on Replaces Pedal Sensor New and Repair on Engine Code Reset.

Miércoles # 6857 - 11/13/2019 - Millas # 161019
Repair on Rear Drive Axle Side Replaces Two
Used Tires Mounting on Repair All Tires Air
Pressure check on Repair All Axles Brakes Adjustment.

Jueves # 6857 - 11/14/2019 - Millas - # 161019
Repair on Engine oil on Filters change and
Repair on Engine Air Filter Clean on Repair
All Fluids levels check on Repair on Engine
Compute Diagnostic Code Active on Engine Code
Fault: VGT Actuator Drive Circuit, Code SPN: 641
on Repair on Engine sensor on wires connector and
check and Repair on Inspectional bus on Repairs,

Jueves # 3284 - 11/14/2019 - Millas - # 799914
Repair on Installation Compute on Repair All
Injector Testing and Fuel Leak on Exhaust system

Jueves # 5910 - 11/14/2019 - Millas - # 451902
Repair on Installation New Alternator on Repair
on Volts check on Repair on Inspectional All Batteries

Viernes # 3284 - 11/15/2019 - Millas - # 799914
Repair on Remove Engine Parts on Repair on Remove
All Injectors on Seal to Testing on Repair All
Parts Remove Clean.

Viernes # Heura Fernando Car - 11/15/2019 - Millas
Repair Engine oil on Filter change and Transmis
oil change on Inspectional All Fluids levels.

Viernes # 6857 - 11/15/2019 - Millas - # 161019
Repair on Inspectional bus accident on Repair Front
Side Hub Plug on Repair oil level Fill. Check

11/18/2019

Senara Laborales

Wines # 5330 - 11/18/2019 - Millas - #

Repair on Inspectonal A/C System on High Pressure Tube Leak and Low Head Valve Leak and Repair on Recharge A/C Green System on Repair on Engine All Fluids Levels check on Repair on Inspectonal Bus on All Tires on Tyghts check.

Wines # 7538 - 11/18/2019 - Millas - # 007946

Repair on Instalation used Bateries and All wires and Repair Engine Fuel Diesel Purge All System on Repair on Engine Starter and Repair Rear A/C Compressor Air Valve Used Replaces on Repair on Engine All Fluids Levels check. and Repair on All Tires Air Pressure check.

Wines # yard - 11/18/2019 -

Repair on All Used Tires sent To Industry Tires Shop To Recycle and Repair yard Clever.

Wines # 3284 - 11/18/2019 - Millas - # 799914

Repair on Air Dryer Replaces New Air Dryer Cartridge and New Air Purge Valve on All Orings on All Air Fitting Hose Assamble.

Wates # 7114 - 11/19/2019 - Millas - # 032469

Repair on Inspectonal Used Bateries on Bateries no Charge on Repair on Remobe All Bateries and sent To Recharge.

Wates # 3284 - 11/19/2019 - Millas - # 799914

Repair on Replaces New Tube ~~to~~ Fuel Drain and New Washers Sealing on All Parts Remobe Clever and Repair on Assamble.

Martes # Bases - 11/19/2019 - Millas

Repair on Road Service on Inspectional Bases on Notious Bus Sales on Norwalk CA. on Inspectional Bus Test Drive

Miercoles # 3284 - 11/20/2019 - Millas - # 799914

Repair on Assamble All Injectors on New Orings on Repair on Assamble Tube Drain Injectors.

Miercoles # 6857 - 11/20/2019 - Millas - # 163971

Repair on Inspectional Engine Compare Diagnostic Engine Code Active and Fault: Exhaust Gas Pressure Sensor on Repair on Replaces Used sensor and Fault: Turbo VGT Actuator Drive Circuit on Repair Engine Codes Compare Reset. and Repair on Regeneration is Active operating.

Jueves # 3284 - 11/21/2019 - Millas - # 799914

Repair on Assamble All Poches on All Sensors wires on Engine All Parts Assamble on Engine Starter. and Sent to Dealer to Inspectional on Repragraming All Injectors

Jueves # 6857 - 11/21/2019 - Millas - # 163971

Repair on Instalation New Pressure Sensor Fault. and Repair on Remube Turbo on sent to Repair Actuator. on Repair on Engine Remube All Parts on Hores

Viernes # 7538 - 11/22/2019 - Millas - # 007946

Repair on Bus Drive to Baldwin Park on Parking on yard on Repair on Remube All Bateries.

Viernes # 7114 - 11/22/2019 - Millas - # 032469

Repair on Instalation New Bateries on Repair on Bus Drive to El Monte Ca on yard to Repair. on Inspectional

Viernes # 6857 - 11/22/2019 - Dallas - # 165971

Repair on Instalations New Turbo Actuators on Turbo Clener
Interior on Repair on Assamble All Coolen Hoses
on oil Pressure Hoses on All wires Conector and
Repair Engine oil in Filter New Replaces and
Repair on Engine New Coolen Replaces and Repair
on Regeneration Couple and Repair on Inspeccional
Engine All Fluids Levels check on Engine NO Codes

12/23/2019

Semana Laborales

Lunes # 5330 - 12/23/2019 - Dallas # 877851

Repair Engine Fans new belts Replaces and
Repair on A/C Compressor New belt, and Repair
New Air Valve Replaces on Repair on Inspectional
Engine All Fluids Levels Check.

Lunes # 3284 - 12/23/2019 - Dallas - # 802574

Repair on Inspectional Engine All Fluids levels
check, on Repair on Inspectional Interior lights
and Inspectional A/C System.

Lunes # 5910 - 12/23/2019 - Dallas - # 467128

Repair on Engine oil on Filter changes and
Repair on Engine Air Filter Cleaner on Repair
All Fluids levels check, and Repair horn
New Wire Connector New Replaces and
Repair on TO Assemble All parts Reconnect
on Repair on Engine Remove Intake Cooler
Hose and Repair on Install parts.

Martes # 5330 - 12/24/2019 - Dallas - # 878175

Repair on TO Assemble New A/C Compressor belt.
on Repair on Assemble new Alternator belt. Replaces
Repair on Engine All belts Adjustments, and
Repair on Engine All Fluids Levels Check.

Martes # 7114 - 12/24/2019 - Dallas - # 033749

Repair Front Side Signal Warning Light New Replaces
and Repair Rear Side Stop Light New Replaces
on Repair on Inspectional on Lights operate and
Repair on Inspectional on Engine on Fluids
Levels Check.

Mercedes # 5910 - 12/24/2019 - Millis - # 467128
Repair on to Assemble Intake Cooler Hoses and
Air Filter Tubes on Repair on Engine Cooler
on Water Leak Repair Hose Clamp and
Repair Rear Drive Axle 4 Tires New Mounting
and Repair on All Tires Air Pressure, check and
Repair on All Axle Brakes Adjustment and
Repair on Inspection BUS on Repair.

Mercedes # 3284 - 12/25/2019 - Millis - # 802931
Repair on Road Service on Etelute Car, on Inspection
Bus No starter on Repair on All States on Fuses check
and one solenoid make Wires by Pass,

Juventus # 5910 - 12/26/2019 - Millis - # 467128
Repair on Assemble New Air Valve Presprotect Central
Valve New Replaces on Repair Inspection Air Leaks on No
Air Leak and Repair Rear Stop Lights Switch New Air Valve

Juventus # 6857 - 12/26/2019 - Millis - # 177145
Repair on Engine oil on Filters changed on Engine Air
Filter Clean on Repair on All Fluids Levels Check.

Viernes # 3284 - 12/27/2019 - Millis - # 803254
Repair on Inspection BUS No starter on No Power
on Repair on Replaces New Solenoid on Repair on
Inspection Alternator Volts Check on 15 ohm and
Repair Battery Posts Terminals Clean on Inspection
and Repair on to Engine All Fluids Levels check

12/27/2019

Semona Laborales

Viernes # 6857 - 12/27/2019 - Dallas - # 177145
Repair on Bateres Posts Terminals check on Lubricant
on Repair Rear Drive Axle New Brakes Replaces on
Repair on All Axle Brakes Adjustment. and
Repair Rear Drive Axle 1/2 side mounting Two
Used Tires on All Tires Air Pressure check.
and Repair on Bus Inspectional on Repairs

Viernes # 5330 - 12/27/2019 - Dallas - #
Repair on Rear 1/2 side Toy Axle mounting used
Tire on Repair on All Tires Air Pressure check.
and Repair to Inspectional Engine All Fluids
Levels check on Repair Interior Lights.

12/30/2019

Senador Labores

Lunes # 5330 - 12/30/2019 - Millas # 880144

Repair on A/C Tube Welding Repair on Assemble
New Tube Clamp Brackets and Repair on A/C
Freon Recharge System and Repair on
Engine oil Fluids Levels check. and
Repair A/C System Ventilation Fans motor interior
check on A/C Condenser Fans Motor check.

Lunes # 3284 - 12/30/2019 - Millas - # 804564

Repair Front Side Head Light New Replaces
and Repair on Inspectional All Lights operant.
and Repair on Engine oil Fluids Levels check.

Lunes # 7114 - 12/30/2019 - Millas - # 035028

Repair on starter Fuse New Replaces and Inspectional
All Relay check. and Repair on Engine oil Fluids Levels,

Jueves # 7114 - 01/2/2020 - Millas - # 039350

Repair on Inspectional Rear Tail Lights No operant.
and Repair on Replaces Lights and Repair and
Replaces Used Relay and Repair on Engine oil Fluids

Jueves # 3404 - 01/2/2020 - Millas - # 336980

Repair on Engine Computer Codes Active
on SPN: 4364 - FMI: 18 on SPN: 111 - FMI and
Repair on Inspectional sensor on wires connectors
and Repair on Engine Computer Codes reset.
and Repair on Oil Engine All Fluids Levels
check.

Jueves # Aurora Fernando - 01/2/2020

Repair Front Side Mirror Used Replaces and
Repair and Parts to Assemble

Semana Laborales

01/2/2020

Jueves # 5910 - 01/2/2020 - Milles - # 469742

Repair on Engine Computer Codes Active Exhaust Gas Recirculation Temperature and VGT Actuator Drive Circuit Motor on Repair to Code Reset on Repair on Computer Regeneration to provide on All Code Clear out on Repair on Engine All Fluids Levels Check

Viernes # 6857 - 01/3/2020 - Milles - # 177795

Repair to Assemble Two Used Tires Rear Drive Axle Side on Repair All Tires Air Pressure Check and Repair Rear Drive Axle Brakes Adjustment. and Engine All Fluids Levels Check

Viernes # Bases 01/3/2020 - Milles - #

Repair on install New stickers on Registration

Viernes # 3284 - 01/3/2020 - Milles - # 805913

Repair on Inspection A/C System on Freon Level and Repair on Inspection All Fuses on Relays on Wires Connectors and Repair on A/C Condenser Fans Motors on Faults and Repair Front Bumper Brackets Adjustment on Inspection Frame Cracks on No damages on All Lights Inspection on Tires on Brakes and Repair on Inspection Engine All Fluids

02/13/2020

Semana Laborales

Lunes # 5330 - 02/13/2020 - Millas - #

Repair on Remove Engine Parts on Repair on Remove
All Fluids Drain on Repair on Remove Turbo
on All Hoses on Repair on Remove Exhaust
Manifold on Repair on Remove All Covers

Martes # 5330 - 02/14/2020 - Millas - #

Repair on Remove Engine Head on All Parts
and Cleaners on Sent To Repair on Repair on
Parts Remove Brackets on All Parts Cleaner.

Martes # 6857 - 02/14/2020 - Millas - # 188585

Repair on Front Head Light Side and New
Light Replaces on Repair on Inspection of
Light Check on Inspection Engine All Fluids Levels

Miercoles # 3284 - 02/15/2020 - Millas - # 816463

Repair Rear Baggage Compartment Plate New
Bolts Replaces on Repair on Engine All Fluids Levels

Miercoles # 3404 - 02/15/2020 - Millas - # 346637

Repair Front Side Mirror Bracket on Repair Front
Covers on Mirror Bracket Adjustment. and Repair
Engine on All Fluids Levels Check.

Miercoles # 5910 - 02/15/2020 - Millas - # 480203

Repair on Engine New oil on Filters changed
and Repair Engine Air Filter Cleaner and
Repair on Engine All Fluids Levels Check
and Repair on Engine belts Adjustment.
on All Bolts Belts Check.

Jueves # 5910 - 02/6/2020 - Millas # 480528
Repair Exhaust Pipe New Clamp Replaces
and Repair on All Tires Air Pressure check
on All Tires Inspection and Repair Front
Head Lights New Replaces on Repair.
Oil Inspection on Repairs

Jueves # 5330 - 02/6/2020 - Millas - #
Repair on Go Assemble Engine Used Parts
and Cam Follower Assemblies on Installation on
The Side Clearance on must be adjusted.

Viernes # 7114 - 02/7/2020 - Millas - # 046637
Repair on Go Replaces Used Air Compressor
belt on All belts Adjustment on Repair
on Engine All Fluids Levels check.

Viernes # Accera Fernando Car - 02/7/2020
Repair on Go starter Position Plate Adjustment
and Repair Rear Ayle struts New Assemblies
on Repair on All Tires Air Pressure check and
Engine All Fluids Levels check.

Semana Trabados

02/10/2020

Lunes # 7114 - 02/10/2020 - Millos - # 047261
Repair on Inspectional Engine All belts and
Replaces New Alternators Tensioner belts
on All belts Adjustment and Repair
Inspectional Engine All Fluids Levels checked.
and Repair on to Install New Permits.

Lunes # 6857 - 02/10/2020 - Millos - # 189927
Repair on Engine oil on Filters changed and
Repair on Engine Air Filter Cleaner and
Repair on Engine oil Fluids Levels checked
on Repair Drive Seat Air Year Hose new Replaces
and Repair on Batteries Posts Terminals Cleaner
and Lubricant on All Wipes, Protected and
Repair Coolen Hose Protected and Repair
Exhaust Pipe Bracket Welding Repair and
Repair on All Tires Air Pressure checked and to
Repair on All Brakes Axles Adjustment. and
Repair on Bus Inspectional and Repairs

Martes # 5330 - 02/11/2020 - Millos - #
Repair on to Assembly New Engine Head
on new Gasket. on all bolts Head Cleaner and
Install All bolts on Torque All bolts.

Miercoles # 5330 - 02/12/2020 - Millos - #
Repair on Engine Head bolts on to Redo torque all
and Repair on to Assemble Engine Covers on
Install on to Install New Gaskets and
Repair on to Assemble Engine Coolen Hoses and
Brackets on Exhaust Manifold Install on
New Gaskets on all bolts Torque.

Jueves # 7114 - 02/13/2020 - Millas # 048219
Repair on Engine oil on Filters changed and
Repair on Engine Air Filter cleaner and
Repair on Batteries Posts Terminals. Cleaner
on Lubricant

Viernes # 7114 - 02/14/2020 - Millas # 048542
Repair Rear Drive Axle New Brakes on Used
Brakes Sensors Suspend and Repair Rear Axle
Dry Axle Air bag Fitting New Replaces
and Repair Air Line and Repair All Tires
Air Pressure check and Repair on BGS
Inspection on Repairs