



VEHICLE FACTORS ATTACHMENT

Maintenance Records

Highland, IL

HWY23MH015

(42 pages)

Work Order Cost Detail

Work Order: 1135128 **Unit No:** GLI 86245 **2014 PRVST X3-45**

WO Status: Closed	WO Location: XKY	Alt Unit No:
Date Opened: 04/12/2023 04:36:45	WO Reason: UNSCHEDULED / BRKDW	Serial No: 2PCG33495EC735508
Date Complete: 04/12/2023 04:38:34	Meter 1 - M: 1,170,040	License No: K000932
Date Closed: 04/18/2023 10:24:16	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Work Order Notes:

(KCH) Location changed on 4/12/2023 2:36:49 AM from XTX to XKY by KENNY.HESTER.

Repair Job: 16-174-011 - ROAD CALL OUTWARD OPENING BUS ENTRY DOOR COMPONENTS

Total Job Cost:	365.00
------------------------	---------------

Job Location: STATE OF KY	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: BREAKDOWN	Warranty Violation: None	

<u>Vendor Name</u>	<u>Invoice No.</u>	<u>Labor</u>	<u>Parts</u>	<u>Misc</u>	<u>Tax</u>	<u>Total Cost</u>
1197259 - Keith Woods DBA All Day 4305		\$365.00	\$0.00	\$0.00	\$0.00	365.00
Total Charges						365.00

Repair Notes:

(KCH) LUD - 4/12
 entrance door button was pushed out of place on side of dash repair
 (MI) The warranty is cancelled byon4/18/2023 8:24:09 AM

Contact:	Total Labor Hours: 0.00	Total Labor Cost: 0.00
Notify Date:	Job Count: 1	Total Material Cost: 0.00
Picked Up By:	Hours Opened: 0.0	Total Commercial Cost: 365.00
Pick Up Date:		Total Work Order Cost: 365.00

Work Order Cost Detail

Work Order: 1135611 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: CHM	Alt Unit No:
Date Opened: 04/13/2023 17:16:47	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 04/13/2023 19:57:14	Meter 1 - M: 1,170,710	License No: K000932
Date Closed: 04/13/2023 19:57:18	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 9.99
--	-----------------------------

Job Location: CHICAGO GARAGE	Labor Hours: 0.20	Labor Cost: 9.99
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Notes:
(DANIF) please see checklist history

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 271.76
---	-------------------------------

Job Location: CHICAGO GARAGE	Labor Hours: 0.17	Labor Cost: 8.31
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	88.00	2.99	263.45
			Total Charges	263.45

Repair Notes:
(DANIF) checked and topped off fluids

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost: 11.08
---	------------------------------

Job Location: CHICAGO GARAGE	Labor Hours: 0.22	Labor Cost: 11.08
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Notes:
(DANIF) ferried bus through lane

Contact:	Total Labor Hours: 0.59	Total Labor Cost: 29.38
Notify Date:	Job Count: 3	Total Material Cost: 263.45
Picked Up By:	Hours Opened: 2.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 292.83

Work Order Cost Detail

Work Order: 1135956 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: ATM	Alt Unit No:
Date Opened: 04/14/2023 23:28:49	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 04/15/2023 05:24:46	Meter 1 - M: 1,171,186	License No: K000932
Date Closed: 04/15/2023 05:24:46	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY	Total Job Cost:	19.86
---	------------------------	--------------

Job Location: ATLANTA GARAGE	Labor Hours: 0.40	Labor Cost: 19.86
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Notes:
(400559) done

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost:	125.51
---	------------------------	---------------

Job Location: ATLANTA GARAGE	Labor Hours: 0.17	Labor Cost: 8.49
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	35.00	2.73	95.39
UG	Urea - Gallons	7.00	3.09	21.63
Total Charges				117.02

Repair Notes:
(JIC) done

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost:	0.00
---	------------------------	-------------

Job Location: ATLANTA GARAGE	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost:	0.00
--	------------------------	-------------

Job Location: ATLANTA GARAGE	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Contact:	Total Labor Hours: 0.57	Total Labor Cost: 28.35
Notify Date:	Job Count: 4	Total Material Cost: 117.02
Picked Up By:	Hours Opened: 6.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 145.37

Work Order Cost Detail

Work Order: 1136769 **Unit No:** GLI 86245 **2014 PRVST X3-45**

WO Status: Closed	WO Location: ATM	Alt Unit No:
Date Opened: 04/17/2023 21:43:04	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 04/18/2023 05:13:50	Meter 1 - M: 1,172,184	License No: K000932
Date Closed: 04/18/2023 05:13:53	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY	Total Job Cost: 43.03
--	------------------------------

Job Location: ATLANTA GARAGE	Labor Hours: 0.86	Labor Cost: 43.03
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Notes:
(400559) done

Repair Job: 17-999-999 - ADD FLUIDS TOTAL VEHICLE ASSEMBLY	Total Job Cost: 191.80
---	-------------------------------

Job Location: ATLANTA GARAGE	Labor Hours: 0.10	Labor Cost: 5.13
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	64.00	2.68	171.22
UG	Urea - Gallons	5.00	3.09	15.45
Total Charges				186.67

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 25.19
---	------------------------------

Job Location: ATLANTA GARAGE	Labor Hours: 0.50	Labor Cost: 25.19
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Contact:	Total Labor Hours: 1.47	Total Labor Cost: 73.35
Notify Date:	Job Count: 3	Total Material Cost: 186.67
Picked Up By:	Hours Opened: 8.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 260.02

Work Order Cost Detail

Work Order: 1136972 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: ATM	Alt Unit No:
Date Opened: 04/18/2023 13:41:30	WO Reason: SCHEDULED / PM	Serial No: 2PCG33495EC735508
Date Complete: 04/18/2023 20:57:59	Meter 1 - M: 1,172,570	License No: K000932
Date Closed: 04/18/2023 20:58:26	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY	Total Job Cost: 59.28
Job Location: ATLANTA GARAGE	Labor Hours: 1.19 Labor Cost: 59.28
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: 02-174-000 - CLEAN BUS BODY	Total Job Cost: 0.13
Job Location: ATLANTA GARAGE	Labor Hours: 0.00 Labor Cost: 0.13
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 212.09
Job Location: ATLANTA GARAGE	Labor Hours: 0.18 Labor Cost: 9.01
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	76.00	2.67	203.08
Total Charges				203.08

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost: 82.35
Job Location: ATLANTA GARAGE	Labor Hours: 1.65 Labor Cost: 82.35
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 2.79
Job Location: ATLANTA GARAGE	Labor Hours: 0.06 Labor Cost: 2.79
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: 06-174-000 - INSPECT BUS BODY	Total Job Cost: 0.00
Job Location: ATLANTA GARAGE	Labor Hours: 0.00 Labor Cost: 0.00
Repair Reason: DRIVER REPORT	Warranty Violation: None

Repair Notes:

(U0000539) old body damage as rec
(U0000539) ok for service

Contact:	Total Labor Hours: 3.07	Total Labor Cost: 153.56
Notify Date:	Job Count: 6	Total Material Cost: 203.08
Picked Up By:	Hours Opened: 7.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 356.64

Work Order Cost Detail

Work Order: 1137402 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: ATM	Alt Unit No:
Date Opened: 04/19/2023 21:12:55	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 04/20/2023 01:35:16	Meter 1 - M: 1,173,768	License No: K000932
Date Closed: 04/20/2023 01:35:33	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY		Total Job Cost: 27.96
Job Location: ATLANTA GARAGE	Labor Hours: 0.56	Labor Cost: 27.96
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID		Total Job Cost: 261.52
Job Location: ATLANTA GARAGE	Labor Hours: 0.21	Labor Cost: 10.28
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	86.00	2.65	228.00
UG	Urea - Gallons	7.52	3.09	23.24
Total Charges				251.24

Repair Notes:
(400089) All fluids are at an optimal level.

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY		Total Job Cost: 15.64
Job Location: ATLANTA GARAGE	Labor Hours: 0.31	Labor Cost: 15.64
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Notes:
(400089) Coach has passed service lane inspection.

Repair Job: 06-174-000 - INSPECT BUS BODY		Total Job Cost: 10.08
Job Location: ATLANTA GARAGE	Labor Hours: 0.20	Labor Cost: 10.08
Repair Reason: DRIVER REPORT	Warranty Violation: None	

Repair Notes:
(400089) steering wheel have to be replaced, to old, have to much damage and it is unsanitary
(400089) Problem noted, coach still good for service.

Contact:	Total Labor Hours: 1.28	Total Labor Cost: 63.96
Notify Date:	Job Count: 4	Total Material Cost: 251.24
Picked Up By:	Hours Opened: 4.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 315.20

Work Order Cost Detail

Work Order: 1137587 **Unit No:** GLI 86245 **2014 PRVST X3-45**

WO Status: Closed	WO Location: MIM	Alt Unit No:
Date Opened: 04/20/2023 13:26:26	WO Reason: SCHEDULED / PM	Serial No: 2PCG33495EC735508
Date Complete: 04/21/2023 11:15:30	Meter 1 - M: 1,174,215	License No: K000932
Date Closed: 04/21/2023 11:15:30	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-174-000 - CLEAN BUS BODY		Total Job Cost: 19.50
Job Location: MIAMI GARAGE	Labor Hours: 0.39	Labor Cost: 19.50
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY		Total Job Cost: 40.15
Job Location: MIAMI GARAGE	Labor Hours: 0.80	Labor Cost: 40.15
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID		Total Job Cost: 100.51
Job Location: MIAMI GARAGE	Labor Hours: 0.11	Labor Cost: 5.61
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	30.00	2.96	88.72
UG	Urea - Gallons	2.00	3.09	6.18
Total Charges				94.90

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY		Total Job Cost: 1.17
Job Location: MIAMI GARAGE	Labor Hours: 0.02	Labor Cost: 1.17
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY		Total Job Cost: 7.83
Job Location: MIAMI GARAGE	Labor Hours: 0.16	Labor Cost: 7.83
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Contact:	Total Labor Hours: 1.49	Total Labor Cost: 74.26
Notify Date:	Job Count: 5	Total Material Cost: 94.90
Picked Up By:	Hours Opened: 22.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 169.17

Work Order Cost Detail

Work Order: 1138890 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: HOU	Alt Unit No:
Date Opened: 04/25/2023 10:23:03	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 04/25/2023 13:17:31	Meter 1 - M: 1,174,459	License No: K000932
Date Closed: 04/25/2023 13:17:36	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY	Total Job Cost: 41.53
---	------------------------------

Job Location: HOUSTON TERM/SI	Labor Hours: 0.83	Labor Cost: 41.53
Repair Reason: PREVENTIVE MAINT	Warranty Violation: None	

Repair Notes:
(AHL) clean out Restroom and interior mop etc dump and fill

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 6.75
--	-----------------------------

Job Location: HOUSTON TERM/SI	Labor Hours: 0.14	Labor Cost: 6.75
Repair Reason: PREVENTIVE MAINT	Warranty Violation: None	

Repair Notes:
(AHL) done

Repair Job: 06-174-022 - INSPECT BUS SEAT COMPONENTS	Total Job Cost: 14.89
--	------------------------------

Job Location: HOUSTON TERM/SI	Labor Hours: 0.30	Labor Cost: 14.89
Repair Reason: PREVENTIVE MAINT	Warranty Violation: None	

Repair Notes:
(AHL) inspect sea/components and amenities ok for Service

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost: 6.53
---	-----------------------------

Job Location: HOUSTON TERM/SI	Labor Hours: 0.13	Labor Cost: 6.53
Repair Reason: PREVENTIVE MAINT	Warranty Violation: None	

Repair Notes:
(AHL) done

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 171.29
---	-------------------------------

Job Location: HOUSTON TERM/SI	Labor Hours: 0.17	Labor Cost: 8.54
Repair Reason: PREVENTIVE MAINT	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	65.00	2.50	162.75
Total Charges				162.75

Repair Notes:
(AHL) done

Work Order Cost Detail

Contact:	Total Labor Hours:	1.56	Total Labor Cost:	78.24
Notify Date:	Job Count:	5	Total Material Cost:	162.75
Picked Up By:	Hours Opened:	3.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	240.99

Work Order Cost Detail

Work Order: 1138926 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: XTX	Alt Unit No:
Date Opened: 04/25/2023 12:27:18	WO Reason: SCHEDULED / PM	Serial No: 2PCG33495EC735508
Date Complete: 04/25/2023 21:55:25	Meter 1 - M: 1,174,459	License No: K000932
Date Closed: 05/02/2023 15:16:44	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 16-017-001 - ROAD CALL TIRE - PNEUMATIC

Total Job Cost:	300.13
------------------------	---------------

Job Location: STATE OF TX	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: DRIVER REPORT	Warranty Violation: None	

<u>Vendor Name</u>	<u>Invoice No.</u>	<u>Labor</u>	<u>Parts</u>	<u>Misc</u>	<u>Tax</u>	<u>Total Cost</u>
298421 - MICHELIN NORTH AMER	DA0054686695	\$299.50	\$0.00	\$0.00	\$0.63	300.13
Total Charges						300.13

Repair Notes:

(RIO) 04/25 Houston, TX
 Tire change
 (MI) The warranty is cancelled byon5/2/2023 1:16:20 PM

Contact:	Total Labor Hours:	0.00	Total Labor Cost:	0.00
Notify Date:	Job Count:	1	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	9.0	Total Commercial Cost:	300.13
Pick Up Date:			Total Work Order Cost:	300.13

Work Order Cost Detail

Work Order: 1139063 Unit No: GLI 86245 2014 PRVST X3-45

WO Status:	Closed	WO Location:	DLC	Alt Unit No:	
Date Opened:	04/25/2023 21:55:37	WO Reason:	SERVICE LANE	Serial No:	2PCG33495EC735508
Date Complete:	04/25/2023 22:32:09	Meter 1 - M:	1,174,459	License No:	K000932
Date Closed:	04/25/2023 22:32:16	Meter 2 - N:	0	Tech Spec:	14PVTX3-45VB
Using Dept:	MAINTUS - Greyhound US			Maint. Class:	20

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID

Total Job Cost:	2.42
-----------------	------

Job Location:	DALLAS GARAGE	Labor Hours:	0.05	Labor Cost:	2.42
Repair Reason:	INSPECT, ROUTINE	Warranty Violation:	None		

Repair Notes:

(AD) done

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY

Total Job Cost:	1.11
-----------------	------

Job Location:	DALLAS GARAGE	Labor Hours:	0.02	Labor Cost:	1.11
Repair Reason:	INSPECT, ROUTINE	Warranty Violation:	None		

Repair Notes:

(AD) done

Contact:	Total Labor Hours:	0.07	Total Labor Cost:	3.53
Notify Date:	Job Count:	2	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	1.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	3.53

Work Order Cost Detail

Work Order: 1139536 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: DLC	Alt Unit No:
Date Opened: 04/27/2023 13:14:04	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 04/27/2023 14:20:45	Meter 1 - M: 1,174,459	License No: K000932
Date Closed: 04/27/2023 14:20:48	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY Total Job Cost: 6.19

Job Location: DALLAS GARAGE	Labor Hours: 0.12	Labor Cost: 6.19
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID Total Job Cost: 8.50

Job Location: DALLAS GARAGE	Labor Hours: 0.17	Labor Cost: 8.50
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY Total Job Cost: 29.00

Job Location: DALLAS GARAGE	Labor Hours: 0.58	Labor Cost: 29.00
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Job: QC-999-999 - QUALITY CHK TOTAL VEHICLE ASSEMBLY Total Job Cost: 5.90

Job Location: DALLAS GARAGE	Labor Hours: 0.12	Labor Cost: 5.90
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Contact:	Total Labor Hours:	0.99	Total Labor Cost:	49.60
Notify Date:	Job Count:	4	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	1.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	49.60

Work Order Cost Detail

Work Order: 1139989 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed WO Location: ORL Alt Unit No:
Date Opened: 04/29/2023 05:06:32 WO Reason: UNSCHEDULED / BRKDW Serial No: 2PCG33495EC735508
Date Complete: 04/29/2023 06:34:04 Meter 1 - M: 1,174,459 License No: K000932
Date Closed: 04/29/2023 06:34:11 Meter 2 - N: 0 Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US Maint. Class: 20

Repair Job: 06-002-037 - INSPECT SEATS

Total Job Cost: 11.25

Job Location: ORLANDO TERM/SI Labor Hours: 0.23 Labor Cost: 11.25
Repair Reason: DRIVER REPORT Warranty Violation: None

Repair Notes:

(CARL) wheel chair door seats doesn't lock in to place
(CARL) locked seats in place

Repair Job: DV-013-000 - DVIR BRAKE SYSTEM

Total Job Cost: 32.42

Job Location: ORLANDO TERM/SI Labor Hours: 0.65 Labor Cost: 32.42
Repair Reason: DRIVER REPORT Warranty Violation: None

Repair Notes:

(CARL) Failed VEHICLE INSPECTION REPORT test, 04/29/2023 00:45:00 Test Results: Recorded Value - N - SERVICE BRAKES - DOT* - <I>BUILD AIR PRESSURE AND PERFORM AIR PRESSURE DROP TEST. CHECK SERVICE BRAKES. DOES AIR SYSTEM AND SERVICE BRAKES PASS INSPECTION? Notes - air pressure needs to be checked takes long to build.also when you apply service brakes it drops to 100 psi. rejected.
(CARL) Checked air psi no faults with air psi at this time.

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY

Total Job Cost: 7.17

Job Location: ORLANDO TERM/SI Labor Hours: 0.14 Labor Cost: 7.17
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(CARL) completed

Contact: Total Labor Hours: 1.02 Total Labor Cost: 50.83
Notify Date: Job Count: 3 Total Material Cost: 0.00
Picked Up By: Hours Opened: 1.0 Total Commercial Cost: 0.00
Pick Up Date: Total Work Order Cost: 50.83

Work Order Cost Detail

Work Order: 1140555 Unit No: GLI 86245 2014 PRVST X3-45

WO Status:	Closed	WO Location:	TAL	Alt Unit No:	
Date Opened:	05/01/2023 09:30:32	WO Reason:	SCHEDULED / PM	Serial No:	2PCG33495EC735508
Date Complete:	05/01/2023 09:54:52	Meter 1 - M:	1,174,459	License No:	K000932
Date Closed:	05/01/2023 09:54:58	Meter 2 - N:	0	Tech Spec:	14PVTX3-45VB
Using Dept:	MAINTUS - Greyhound US			Maint. Class:	20

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY

Total Job Cost: 19.25

Job Location: TALLAHASSEE -SI/AGENCY

Labor Hours: 0.39 Labor Cost: 19.25

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Repair Notes:

(U0000506) PERFORMED EXPRESS CHECK.CHECKED ALL FLUIDS. OIL,POWER STEERING AND COOLANT ARE ALL AT SERVICEABLE LEVELS.. COOLANT IS VISIBLE IN THE SITE GLASS. CHECKED WEEP HOLE ON WATER PUMP AND IT IS DRY. CHECKED WASHER FLUID AND IT WAS LOW.FILLED WASHER FLUID TO FULL LEVEL. CHECKED WIPER WASHERS AND THEY ARE WORKING. CHECKED OVER BELTS AND THEY ARE OKAY. CHECKED LIGHTS AND THEY ARE WORKING.

Contact:	Total Labor Hours:	0.39	Total Labor Cost:	19.25
Notify Date:	Job Count:	1	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	0.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	19.25

Work Order Cost Detail

Work Order: 1140763 **Unit No:** GLI 86245 **2014 PRVST X3-45**

WO Status: Closed	WO Location: ATM	Alt Unit No:
Date Opened: 05/02/2023 00:08:35	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/02/2023 04:57:44	Meter 1 - M: 1,174,459	License No: K000932
Date Closed: 05/02/2023 04:57:45	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY	Total Job Cost: 21.67
Job Location: ATLANTA GARAGE	Labor Hours: 0.43 Labor Cost: 21.67
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 273.79
Job Location: ATLANTA GARAGE	Labor Hours: 0.50 Labor Cost: 24.97
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	91.00	2.43	221.01
UG	Urea - Gallons	9.00	3.09	27.81
Total Charges				248.82

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost: 6.31
Job Location: ATLANTA GARAGE	Labor Hours: 0.13 Labor Cost: 6.31
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 3.01
Job Location: ATLANTA GARAGE	Labor Hours: 0.06 Labor Cost: 3.01
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Contact:	Total Labor Hours: 1.12	Total Labor Cost: 55.96
Notify Date:	Job Count: 4	Total Material Cost: 248.82
Picked Up By:	Hours Opened: 4.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 304.78

Work Order Cost Detail

Work Order: 1142725 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: DLC	Alt Unit No:
Date Opened: 05/08/2023 18:43:37	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/08/2023 22:10:53	Meter 1 - M: 1,183,941	License No: K000932
Date Closed: 05/08/2023 22:10:54	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 06-174-000 - INSPECT BUS BODY	Total Job Cost: 6.29
---	-----------------------------

Job Location: DALLAS GARAGE	Labor Hours: 0.13	Labor Cost: 6.29
Repair Reason: DRIVER REPORT	Warranty Violation: None	

Repair Notes:
(U0000635) old body damage

Repair Job: 09-036-010 - TROUBLESHOOT PROX-M / Electronic Logging Devic (ELD)	Total Job Cost: 6.81
---	-----------------------------

Job Location: DALLAS GARAGE	Labor Hours: 0.14	Labor Cost: 6.81
Repair Reason: DRIVER REPORT	Warranty Violation: None	

Repair Notes:
(U0000635) I was told by Marseille in mrd to switch the adapter box from white to black because the throttle would not deactivate. Abilene tx
(U0000635) had no issues connecting with tablets

Repair Job: 09-034-003 - TROUBLESHOOT SIGNAL, PARKING, & BACKUP LAMPS	Total Job Cost: 76.91
---	------------------------------

Job Location: DALLAS GARAGE	Labor Hours: 0.14	Labor Cost: 6.94
Repair Reason: DRIVER REPORT	Warranty Violation: Part Failure	

<u>Parts</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
930364	LAMP 60 LED FRT FLASHER	1.00	69.97	69.97
Total Charges				69.97

Repair Notes:
(U0000635) front signal light not working correctly
(D@H) The warranty is cancelled byon5/8/2023 5:40:51 PM
(U0000635) replace light

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 219.89
---	-------------------------------

Job Location: DALLAS GARAGE	Labor Hours: 0.15	Labor Cost: 7.40
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	80.00	2.54	203.22
UG	Urea - Gallons	3.00	3.09	9.27
Total Charges				212.49

Repair Notes:
(AD) Done

Work Order Cost Detail

Work Order: 1142725 Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY **Total Job Cost: 7.56**

Job Location: DALLAS GARAGE Labor Hours: 0.15 Labor Cost: 7.56
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:
(AD) Done

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY **Total Job Cost: 8.53**

Job Location: DALLAS GARAGE Labor Hours: 0.17 Labor Cost: 8.53
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:
(AD) Done

Contact:	Total Labor Hours:	0.87	Total Labor Cost:	43.53
Notify Date:	Job Count:	6	Total Material Cost:	282.46
Picked Up By:	Hours Opened:	4.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	325.98

Work Order Cost Detail

Work Order: 1142851 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: SNT	Alt Unit No:
Date Opened: 05/09/2023 07:29:16	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/09/2023 08:36:20	Meter 1 - M: 1,184,257	License No: K000932
Date Closed: 05/09/2023 08:36:47	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY	Total Job Cost: 40.06
Job Location: SAN ANTONIO TERM/SI	Labor Hours: 0.80 Labor Cost: 40.06
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 95.13
Job Location: SAN ANTONIO TERM/SI	Labor Hours: 0.10 Labor Cost: 4.78
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	38.00	2.38	90.35
Total Charges				90.35

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 8.79
Job Location: SAN ANTONIO TERM/SI	Labor Hours: 0.18 Labor Cost: 8.79
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost: 0.54
Job Location: SAN ANTONIO TERM/SI	Labor Hours: 0.01 Labor Cost: 0.54
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Contact:	Total Labor Hours: 1.08	Total Labor Cost: 54.17
Notify Date:	Job Count: 4	Total Material Cost: 90.35
Picked Up By:	Hours Opened: 1.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 144.51

Work Order Cost Detail

Work Order: 1143339 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: SNT	Alt Unit No:
Date Opened: 05/10/2023 20:00:46	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/10/2023 20:08:17	Meter 1 - M: 1,185,820	License No: K000932
Date Closed: 05/11/2023 06:48:00	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 191.76
Job Location: SAN ANTONIO TERM/SI	Labor Hours: 0.11 Labor Cost: 5.61
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	77.00	2.42	186.15
			Total Charges	186.15

Contact:	Total Labor Hours:	0.11	Total Labor Cost:	5.61
Notify Date:	Job Count:	1	Total Material Cost:	186.15
Picked Up By:	Hours Opened:	0.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	191.76

Work Order Cost Detail

Work Order: 1143597 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: SNT	Alt Unit No:
Date Opened: 05/11/2023 15:55:06	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/11/2023 16:02:38	Meter 1 - M: 1,186,175	License No: K000932
Date Closed: 05/13/2023 11:14:31	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID

Total Job Cost:	136.15
-----------------	--------

Job Location: SAN ANTONIO TERM/SI	Labor Hours: 0.11	Labor Cost: 5.60
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	54.00	2.42	130.55
			Total Charges	130.55

Contact:	Total Labor Hours: 0.11	Total Labor Cost: 5.60
Notify Date:	Job Count: 1	Total Material Cost: 130.55
Picked Up By:	Hours Opened: 1.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 136.14

Work Order Cost Detail

Work Order: 1144248 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed WO Location: AMM Alt Unit No:
Date Opened: 05/14/2023 01:05:33 WO Reason: SERVICE LANE Serial No: 2PCG33495EC735508
Date Complete: 05/14/2023 07:19:10 Meter 1 - M: 1,187,205 License No: K000932
Date Closed: 05/15/2023 08:14:03 Meter 2 - N: 0 Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US Maint. Class: 20

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY

Total Job Cost: 106.15

Job Location: AMARILLO GARAGE Labor Hours: 2.12 Labor Cost: 106.15
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(JGH) cleaned, fueled, checked fluids, visual on belts, pulleys, and hoses

Repair Job: 06-174-022 - INSPECT BUS SEAT COMPONENTS

Total Job Cost: 16.61

Job Location: AMARILLO GARAGE Labor Hours: 0.33 Labor Cost: 16.61
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(JGH) all seats in poor condition

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY

Total Job Cost: 9.57

Job Location: AMARILLO GARAGE Labor Hours: 0.19 Labor Cost: 9.57
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(JGH) express check completed no issues found

Contact: Total Labor Hours: 2.65 Total Labor Cost: 132.33
Notify Date: Job Count: 3 Total Material Cost: 0.00
Picked Up By: Hours Opened: 6.0 Total Commercial Cost: 0.00
Pick Up Date: Total Work Order Cost: 132.33

Work Order Cost Detail

Work Order: 1144407 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: DLC	Alt Unit No:
Date Opened: 05/14/2023 17:40:34	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/14/2023 21:58:35	Meter 1 - M: 1,187,662	License No: K000932
Date Closed: 05/14/2023 21:58:37	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 176.88
---	-------------------------------

Job Location: DALLAS GARAGE	Labor Hours: 0.07	Labor Cost: 3.74
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	64.00	2.56	163.87
UG	Urea - Gallons	3.00	3.09	9.27
Total Charges				173.14

Repair Notes:
(AD) done

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost: 5.71
---	-----------------------------

Job Location: DALLAS GARAGE	Labor Hours: 0.11	Labor Cost: 5.71
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None	

Repair Notes:
(AD) done

Contact:	Total Labor Hours: 0.19	Total Labor Cost: 9.44
Notify Date:	Job Count: 2	Total Material Cost: 173.14
Picked Up By:	Hours Opened: 4.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 182.59

Work Order Cost Detail

Work Order: 1145082 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: ATM	Alt Unit No:
Date Opened: 05/17/2023 02:37:37	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/18/2023 06:21:52	Meter 1 - M: 1,189,407	License No: K000932
Date Closed: 05/18/2023 06:21:55	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 06-174-000 - INSPECT BUS BODY	Total Job Cost: 6.35
Job Location: ATLANTA GARAGE	Labor Hours: 0.13 Labor Cost: 6.35
Repair Reason: DRIVER REPORT	Warranty Violation: None

Repair Notes:
 (U0000623) The mirror inside the restroom is loose
 (U0000623) part not in stock

Repair Job: DV-034-002 - DVIR LAMPS - TAIL, STOP, TURN & LICENSE, REAR	Total Job Cost: 4.42
Job Location: ATLANTA GARAGE	Labor Hours: 0.09 Labor Cost: 4.42
Repair Reason: DRIVER REPORT	Warranty Violation: None

Repair Notes:
 (U0000623) Failed VEHICLE INSPECTION REPORT test, 05/16/2023 23:55:00 Test Results: Recorded Value - N - TURN SIGNALS AND HEADLAMPS - DOT* - <->CHECK TURN SIGNALS, 4 WAYS, TAIL LIGHTS, HEADLIGHTS, AND BACK UP LIGHTS. ARE ALL SIGNAL, HEADLIGHT, AND BACKUP LIGHTS WORKING PROPERLY? Notes - left low beam needs to be replaced and low beams need to be realigned rejected.
 (U0000623) light are functioning properly

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY	Total Job Cost: 32.28
Job Location: ATLANTA GARAGE	Labor Hours: 0.65 Labor Cost: 32.28
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 280.28
Job Location: ATLANTA GARAGE	Labor Hours: 0.08 Labor Cost: 4.08
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	117.00	2.36	276.20
			Total Charges	276.20

Repair Notes:
 (U0000623) fluids are at optimal levels

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 7.39
Job Location: ATLANTA GARAGE	Labor Hours: 0.15 Labor Cost: 7.39
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Notes:
 (U0000623) check was completed

Work Order Cost Detail

Work Order: 1145082 Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: 03-017-201 - REPLACE PART DRIVE AXLE LEFT OUTER TIRE **Total Job Cost: 133.31**

Job Location: ATLANTA GARAGE Labor Hours: 2.67 Labor Cost: 133.31
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(400557) replaced both drive brakes. and adjusted brakes 4x. reinstalled new wheel guards and completed first and secondly torque. third torque needed.

Repair Job: 06-013-000 - INSPECT BRAKE SYSTEM **Total Job Cost: 60.47**

Job Location: ATLANTA GARAGE Labor Hours: 1.21 Labor Cost: 60.47
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(MIA) INSPECT TAG AND STEER BRAKES
(PTG) COMPLETED FRONT AND TAG BRAKE IN
(PTG) COMPLETED FRONT AND TAG BRAKE INSPECTION, JACKED BUS UP IN FRONT , PUT ON STANDS , REMOVED BOTH FRONT WHEELS , NOTICED FRONT BRAKES ARE WORN AND ROTORS ARE CRACKED , NEED REPLACING

REMOVED RIGHT TAG TO INSPECT TAG BRAKES , NOTICED TAG BRAKES ARE GOOD, BUT RIGHT TAG WHEEL HAS CHUNK OF TREADS MISSING , NEED CHANGING , NOTIFIED SUPERVISOR OF INSPECTION RESULTS .

Repair Job: 09-013-000 - TROUBLESHOOT BRAKE SYSTEM **Total Job Cost: 52.24**

Job Location: ATLANTA GARAGE Labor Hours: 1.04 Labor Cost: 52.24
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(MIA) INSPECT TAG AND STEER BRAKES
(U0000605) Need front brake pads and rotors.job done

Repair Job: 03-013-201 - REPLACE PART DRIVE AXLE LEFT DISC BRAKES **Total Job Cost: 137.72**

Job Location: ATLANTA GARAGE Labor Hours: 2.75 Labor Cost: 137.72
Repair Reason: ROUTINE REPAIR Warranty Violation: None

Repair Notes:

(PTG) COMPLETED REPLACING THE FRONT LEFT BRAKE ASSEMBLY . REPLACED : ROTOR , BRAKE PADS , AND HUB FLANGE BOLTS, TORQUE FLANGE BOLTS TO SPEC. , WITH BLUE LOCK-TITE APPLIED TO THREADS ON EACH BOLT.
COMPLETED 1ST AND 2ND TORQUE ON FRONT LEFT WHEEL . FRONT LEFT WILL NEED 3RD TORQUE AT NEXT SHOP STOP

Repair Job: 03-013-132 - REPLACE PART STEER AXLE RIGHT BRAKE CHAME **Total Job Cost: 97.29**

Job Location: ATLANTA GARAGE Labor Hours: 1.95 Labor Cost: 97.29
Repair Reason: ROUTINE REPAIR Warranty Violation: None

Repair Notes:

(U0000605) Removed front right steer tire.Replaced and reassembled right rotor and torqued flange with new bolts.Replaced right front brake pads.Reinstalled right steer tire and torqued.job completed

Work Order Cost Detail

Work Order: 1145082

Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: 24-013-000 - REPAIR BRAKE SYSTEM

Total Job Cost: 793.44

Job Location: ATLANTA GARAGE

Labor Hours: 0.54 Labor Cost: 26.86

Repair Reason: PREVENTIVE MAINT

Warranty Violation: None

Parts	Description	Quantity	Unit Price	Total Cost
610072	PADS-BRAKE SERVICE KIT	1.00	173.97	173.97
196544	GUARD-WHEEL,STUD MOUNT	5.00	3.75	18.75
611955	SCREW CAP HEXF M14-1.5X7	28.00	6.11	171.08
611359	ROTOR-BRAKE	2.00	201.39	402.78
Total Charges				766.58

Repair Job: 03-018-302 - REPLACE PART TAG AXLE RIGHT WHEEL END COMPONENTS

Total Job Cost: 55.13

Job Location: ATLANTA GARAGE

Labor Hours: 1.10 Labor Cost: 55.13

Repair Reason: ROUTINE REPAIR

Warranty Violation: None

Repair Notes:

(U0000605) SOP 106 .reason is chuck of tire tread missing.job completed.

Repair Job: 09-016-001 - TROUBLESHOOT INDEPENDENT FRONT SUSPENSIC

Total Job Cost: 67.93

Job Location: ATLANTA GARAGE

Labor Hours: 1.36 Labor Cost: 67.93

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Repair Notes:

(PTG) WHILE DRIVING BUS IN FIGURE 8 IN PARKING LOT , I NOTICED A CONSISTANT LOUD THUMPING SOUND COMING FROM UNDERNEATH THE FRONT OF THE BUS .

(PTG) FRONT SUSPENSION NEED MORE TROUBLESHOOTING .

(400557) Bus not done. needs inspection.

Repair Job: 03-017-001 - REPLACE PART TIRE - PNEUMATIC

Total Job Cost: 138.47

Job Location: ATLANTA GARAGE

Labor Hours: 0.00 Labor Cost: 0.00

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Parts	Description	Quantity	Unit Price	Total Cost
15814103	RETREAD MNT 10K 2-SD PSH	1.00	138.47	138.47
Total Charges				138.47

Repair Notes:

(MIA) replace right tag tire

Repair Job: 06-016-000 - INSPECT SUSPENSION SYSTEM

Total Job Cost: 83.36

Job Location: ATLANTA GARAGE

Labor Hours: 1.67 Labor Cost: 83.36

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Repair Notes:

(U0000605) Inspected front suspension.Check kingpins they are good.Tighten four nuts on steering damper.Need father investigation.

Work Order Cost Detail

Work Order: 1145082 Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: 18-999-999 - ROAD TEST TOTAL VEHICLE ASSEMBLY

Total Job Cost: 124.96

Job Location: ATLANTA GARAGE

Labor Hours: 2.50 Labor Cost: 124.96

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Repair Notes:

(400089) Coach drives smooth, good for service.

Contact:	Total Labor Hours:	17.88	Total Labor Cost:	893.78
Notify Date:	Job Count:	16	Total Material Cost:	1,181.25
Picked Up By:	Hours Opened:	28.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	2,075.03

Work Order Cost Detail

Work Order: 1145595 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: DLC	Alt Unit No:
Date Opened: 05/18/2023 22:39:58	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 05/19/2023 03:13:08	Meter 1 - M: 1,190,343	License No: K000932
Date Closed: 05/19/2023 03:15:03	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 24-002-010 - REPAIR MIRRORS	Total Job Cost: 7.39
Job Location: DALLAS GARAGE	Labor Hours: 0.15 Labor Cost: 7.39
Repair Reason: DRIVER REPORT	Warranty Violation: None

Repair Notes:
 (U0000634) left reverse lens is missing
 (U0000634) verify please
 (U0000611) Removed and replaced left rear back up light

Repair Job: 17-044-001 - ADD FLUIDS TANK - FUEL, LIQUID	Total Job Cost: 346.89
Job Location: DALLAS GARAGE	Labor Hours: 0.08 Labor Cost: 4.21
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

<u>Products</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
DG	Diesel Fuel - GAL	128.00	2.58	330.32
UG	Urea - Gallons	4.00	3.09	12.36
Total Charges				342.68

Repair Job: 37-999-999 - FERRY VEH TOTAL VEHICLE ASSEMBLY	Total Job Cost: 12.94
Job Location: DALLAS GARAGE	Labor Hours: 0.26 Labor Cost: 12.94
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY	Total Job Cost: 2.71
Job Location: DALLAS GARAGE	Labor Hours: 0.05 Labor Cost: 2.71
Repair Reason: INSPECT, ROUTINE	Warranty Violation: None

Contact:	Total Labor Hours: 0.55	Total Labor Cost: 27.25
Notify Date:	Job Count: 4	Total Material Cost: 342.68
Picked Up By:	Hours Opened: 5.0	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 369.93

Work Order Cost Detail

Work Order: 1145845 Unit No: GLI 86245 2014 PRVST X3-45

WO Status:	Completed	WO Location:	XKS	Alt Unit No:	
Date Opened:	05/19/2023 16:48:48	WO Reason:	SCHEDULED / PM	Serial No:	2PCG33495EC735508
Date Complete:	05/19/2023 21:52:55	Meter 1 - M:	1,190,709	License No:	K000932
Date Closed:		Meter 2 - N:	0	Tech Spec:	14PVTX3-45VB
Using Dept:	MAINTUS - Greyhound US			Maint. Class:	20

Work Order Notes:

(MARCEL) Location changed on 5/19/2023 3:10:12 PM from XCO to XKS by MARCEL.MARTIN.

Repair Job: 20-002-035 - TOWING WINDSHIELD WIPER & WASHER

Total Job Cost:	0.00
-----------------	------

Job Location:	STATE OF CO	Labor Hours:	0.00	Labor Cost:	0.00
Repair Reason:	BREAKDOWN	Warranty Violation:	None		

Repair Notes:

(MARCEL) @ Wichita, KS, windshield wipers stop working towed to Bruckners, Wichita, KS. 5/19/2023 MRD MTM

Contact:	Total Labor Hours:	0.00	Total Labor Cost:	0.00
Notify Date:	Job Count:	1	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	5.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	0.00

Work Order Cost Detail

Work Order: 1146530	Unit No: GLI 86245	2014 PRVST X3-45
----------------------------	---------------------------	-------------------------

WO Status: Closed	WO Location: XKS	Alt Unit No:
Date Opened: 05/19/2023 10:00:00	WO Reason: SCHEDULED / PM	Serial No: 2PCG33495EC735508
Date Complete: 06/05/2023 14:58:40	Meter 1 - M: 1,190,709	License No: K000932
Date Closed: 06/09/2023 15:01:00	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Work Order Cost Detail

Work Order: 1146530 Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: 06-045-000 - INSPECT POWER PLANT

Total Job Cost:	2,385.18
------------------------	-----------------

Job Location: STATE OF KS

Labor Hours: 0.00 Labor Cost: 0.00

Repair Reason: DRIVER REPORT

Warranty Violation: None

Vendor Name	Invoice No.	Labor	Parts	Misc	Tax	Total Cost
S924628SHRLA - Bruckners Shreve	RA600056501	\$1,837.00	\$64.10	\$250.00	\$234.08	2,385.18
Total Charges						2,385.18

Repair Notes:

(DENIS) engine faults dw/mrd
 (MI) The warranty is cancelled byon6/9/2023 12:50:29 PM
 (MI) JOB #3 100 SERVICE - GENERAL REPAIR
 COMPLAINT CHECK WIPER OPERATION -
 CAUSE
 REMOVED THE PANEL EXPOSING THE WINDSHIELD WIPER MOTOR. TURNED THE WIPERS ON, HEARD THE RELAY KICK ON AND THE MOTOR IS BUZZING BUT THE WIPERS ARE NOT MOVING. CHECKED THE VOLTAGE AT THE CONNECTOR, IT HAS POWER AND GROUND. THEN USED MY POWER PROBE TO DIRECTLY SEND POWER TO THE WIPER MOTOR AND IT KEPT BUZZING. THE WINDSHIELD WIPER MOTOR IS FAULTY AND NEEDS TO BE REPLACED
 (MI) JOB #4 ASSIST DEFAULT ASSIST JOB
 COMPLAINT CHECK CAUSE OF MIL LIGHT BEING ON -
 CAUSE
 PULLED THE CODES AND THEY WERE ALL INACTIVE. THEY WERE ACTIVE YESTERDAY AND THEY WERE ALL DUE TO OUTPUT LOW OR LOW CURRENT. TESTED THE BATTERIES AND 2 OF THE 4 FAILED. ALL 4 BATTERIES WILL NEED TO BE REPLACED. ALSO FOUND 12 RELAYS BY THE BATTERIES ARE CORRODED AND NEED TO BE COMPLETELY REMOVED AND CLEANED. AFTER REPLACING THE BATTERIES CHECKED THE CODES AGAIN AND THEY WERE ALL INACTIVE. CLEARED THE CODES
 (MI) JOB #6 100 SERVICE - GENERAL REPAIR
 COMPLAINT CHECK ALL FLUIDS -
 CAUSE
 CORRECTION POWER STEERING FLUID AT ADD LINE ALL OTHER FLUIDS ARE AT CORRECT LEVEL
 (MI) JOB #7 269 SERVICE - PRESSURE CHECK COOLING SYSTEM FOR LEAKS VISUAL INSPECTION OF THE ENTIRE COMPLAINT PRESSURE CHECK COOLING SYSTEM FOR LEAKS VISUAL INSPECTION OF THE ENTIRE COOLING SYSTEM -
 CAUSE
 CORRECTION FOUND 3 COOLANT LEAKS.
 (MI) JOB #8 100 SERVICE - GENERAL REPAIR
 COMPLAINT REPLACE WIPER MOTOR -
 CAUSE
 REMOVED THE OLD WINDSHIELD WIPER MOTOR AND INSTALLED THE NEW ONE. BEFORE PUTTING ALL THE INTERIOR BACK TOGETHER TESTED THE WIPERS TO MAKE SURE THEY WORK AND THEY WORK IN ALL SPEEDS. PUT ALL THE INTERIOR BACK TOGETHER. REPAIR COMPLETE
 (MI) JOB #11 526 SERVICE - REPLACE AIR DRYER DESSICANT CARTRIDGE.
 COMPLAINT REPLACE AIR DRYER DESICCANT CARTRIDGE -
 CAUSE
 INSTALLED THE AIR DRYER CARTRIDGE. LET THE TRUCK BUILD AIR AND SPRAYED IT DOWN WITH SOAPY WATER TO SEE IF IT HAD ANY LEAKS. NO LEAKS & IT PURGED AS IT SHOULD. REPAIR COMPLETE
 (MI) JOB #12 701 SERVICE - CHECK & REPAIR LIGHTS
 COMPLAINT REPAIR LIGHTS -
 CAUSE
 INSTALLED THE LIGHT ABOVE THE DOOR, ONCE THE LIGHT WAS INSTALLED I TURNED THE LIGHTS ON AND ONE OF THE FRONT CLEARANCE LIGHT WENT OUT. IT NEEDS TO BE REPLACED.GOT THE NEW MARKER LIGHT, REMOVED THE OLD ONE AND INSTALLED THE NEW ONE WE RECEIVED IN. REPAIR COMPLETE

Work Order Cost Detail

Work Order: 1146530 Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: 06-013-000 - INSPECT BRAKE SYSTEM

Total Job Cost:	350.00
-----------------	--------

Job Location: STATE OF KS

Labor Hours: 0.00 Labor Cost: 0.00

Repair Reason: DRIVER REPORT

Warranty Violation: None

Vendor Name	Invoice No.	Labor	Parts	Misc	Tax	Total Cost
S924628SHRLA - Bruckners Shreve	RA600056501	\$350.00	\$0.00	\$0.00	\$0.00	350.00
Total Charges						350.00

Repair Notes:

(DENIS) air leaks dw/mrd
 (MI) The warranty is cancelled byon6/9/2023 12:50:39 PM
 (MI) JOB #5 520 SERVICE - CHECK AIR SYSTEM OPERATION
 COMPLAINT CHECK AIR SYSTEM OPERATION - CAUSE
 THE AIR SYSTEM IS OPERATING AS IT SHOULD. RELEASED THE BRAKES AND BLED THE AIR DOWN AND THEY SET AROUND 35-40PSI. TURNED THE BUS ON AND IT AIRED UP WITHIN SPEC. THE AIR SYSTEM IS PERFECTLY FINE. DID FIND THE AIR DRYER CARTRIDGE NEEDS REPLACED

Repair Job: 06-053-999 - INSPECT VEHICLE FLUIDS, LUBRICANTS, GASES, & PARTICUL

Total Job Cost:	0.00
-----------------	------

Job Location: STATE OF KS

Labor Hours: 0.00 Labor Cost: 0.00

Repair Reason: PM REPAIR

Warranty Violation: None

Vendor Name	Invoice No.	Labor	Parts	Misc	Tax	Total Cost
S924628SHRLA - Bruckners Shreve	RA600056501	\$0.00	\$0.00	\$0.00	\$0.00	0.00
Total Charges						0.00

Repair Notes:

(DENIS) Failed MN-96 DISC test, Work Order: 749534 Job: IE-999-999 Test Results: Recorded Value - N - 1.7.6 - OIL, FUEL, AND COOLANT LEAKS. Notes - oil leak rear of engine and at pinion seal rejected. Failed MN96 DISC PPREVOST test, Work Order: 792375 Job: IC-999-999 Test Results: Recorded Value - N - 1.7.6 - OIL, FUEL, AND COOLANT LEAKS - OIL, FUEL, AND COOLANT LEAKS. Notes - oil filter leaking oil rejected. Work request canceled by JMP at 1/30/2020 9:21 AMFailed MN96 DISC PPREVOST test, Work Order: 932868 Job: IC-999-999 Test Results: Recorded Value - N - 1.7.6 - OIL, FUEL, AND COOLANT LEAKS - OIL, FUEL, AND COOLANT LEAKS. Notes - cam shaft cover at back of engine leaking oil rejected.
 (MI) The warranty is cancelled byon6/9/2023 12:50:50 PM

Repair Job: 03-032-001 - REPLACE PART BATTERY & CABLES

Total Job Cost:	619.97
-----------------	--------

Job Location: STATE OF KS

Labor Hours: 0.00 Labor Cost: 0.00

Repair Reason: DRIVER REPORT

Warranty Violation: None

Vendor Name	Invoice No.	Labor	Parts	Misc	Tax	Total Cost
S924628SHRLA - Bruckners Shreve	RA600056501	\$350.00	\$269.97	\$0.00	\$0.00	619.97
Total Charges						619.97

Repair Notes:

(DENIS) replace batteries dw/mrd
 (MI) The warranty is cancelled byon6/9/2023 12:58:53 PM

Contact:	Total Labor Hours:	0.00	Total Labor Cost:	0.00
Notify Date:	Job Count:	4	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	412.0	Total Commercial Cost:	3,355.15
Pick Up Date:			Total Work Order Cost:	3,355.15

Work Order Cost Detail

Work Order: 1151608 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: KCD	Alt Unit No:
Date Opened: 06/08/2023 06:32:25	WO Reason: SERVICE LANE	Serial No: 2PCG33495EC735508
Date Complete: 06/08/2023 14:35:06	Meter 1 - M: 1,190,709	License No: K000932
Date Closed: 06/08/2023 14:35:12	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 09-002-035 - TROUBLESHOOT WINDSHIELD WIPER & WASHER **Total Job Cost: 350.87**

Job Location: KANSAS CITY -SI/AGENCY Labor Hours: 1.05 Labor Cost: 52.44
 Repair Reason: DRIVER REPORT Warranty Violation: Part Failure

Parts	Description	Quantity	Unit Price	Total Cost
300445	CRANK ARM 45.8	1.00	58.74	58.74
800380	MOTOR, W/S WASHER	1.00	239.69	239.69
Total Charges				298.43

Repair Notes:

(CLL) wiper stop backwards. over right mirror.
 (CLL) checked wiper malfunction - parts ordered

Repair Job: CK-001-000 - CHECK HVAC SYSTEM **Total Job Cost: 61.06**

Job Location: KANSAS CITY -SI/AGENCY Labor Hours: 1.22 Labor Cost: 61.06
 Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(CLL) checked hvac/serviced - operational

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY **Total Job Cost: 33.50**

Job Location: KANSAS CITY -SI/AGENCY Labor Hours: 0.67 Labor Cost: 33.50
 Repair Reason: PREVENTIVE MAINT Warranty Violation: None

Repair Job: 24-152-000 - REPAIR ONBOARD LAVATORY **Total Job Cost: 13.43**

Job Location: KANSAS CITY -SI/AGENCY Labor Hours: 0.27 Labor Cost: 13.43
 Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(CLL) repaired toilet

Repair Job: 24-024-000 - REPAIR DRIVE SHAFTS **Total Job Cost: 48.32**

Job Location: KANSAS CITY -SI/AGENCY Labor Hours: 0.97 Labor Cost: 48.32
 Repair Reason: DRIVER REPORT Warranty Violation: None

Repair Notes:

(CLL) knocking beneath driver. An squeaking noise underneath.
 (CLL) checked front end - reported findings w/pics to CHM/MRD

Work Order Cost Detail

Contact:	Total Labor Hours:	4.18	Total Labor Cost:	208.75
Notify Date:	Job Count:	5	Total Material Cost:	298.43
Picked Up By:	Hours Opened:	8.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	507.18

Work Order Cost Detail

Work Order: 1153479 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: XKS	Alt Unit No:
Date Opened: 06/14/2023 10:00:52	WO Reason: SCHEDULED / PM	Serial No: 2PCG33495EC735508
Date Complete: 06/14/2023 10:03:59	Meter 1 - M: 1,190,709	License No: K000932
Date Closed: 06/21/2023 10:15:53	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 20-015-000 - TOWING STEERING SYSTEM

Total Job Cost:	600.00
-----------------	--------

Job Location: STATE OF KS	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: DRIVER REPORT	Warranty Violation: None	

Vendor Name	Invoice No.	Labor	Parts	Misc	Tax	Total Cost
847332 - SANTA FE TOW SERVICE	29380	\$600.00	\$0.00	\$0.00	\$0.00	600.00
Total Charges						600.00

Repair Notes:

(KBR) Steering complaint
 (MI) Tow From 1101 Troost Ave, Kansas City, MO 64106, USA (1101 Troost Avenue)
 Tow To 4001 N Randolph Rd, Kansas City, MO 64161
 (MI) The warranty is cancelled byon6/21/2023 8:15:42 AM

Contact:	Total Labor Hours:	0.00	Total Labor Cost:	0.00
Notify Date:	Job Count:	1	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	0.0	Total Commercial Cost:	600.00
Pick Up Date:			Total Work Order Cost:	600.00

Work Order Cost Detail

Work Order: 1153481 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed	WO Location: XKS	Alt Unit No:
Date Opened: 06/14/2023 10:04:11	WO Reason: SCHEDULED / PM	Serial No: 2PCG33495EC735508
Date Complete: 06/29/2023 13:11:23	Meter 1 - M: 1,190,709	License No: K000932
Date Closed: 07/10/2023 12:46:27	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 06-015-000 - INSPECT STEERING SYSTEM	Total Job Cost: 3,825.59
--	---------------------------------

Job Location: STATE OF KS	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: DRIVER REPORT	Warranty Violation: None	

<u>Vendor Name</u>	<u>Invoice No.</u>	<u>Labor</u>	<u>Parts</u>	<u>Misc</u>	<u>Tax</u>	<u>Total Cost</u>
S924628MO - Nextran Kansas City	17441	\$3,420.00	\$0.00	\$80.64	\$324.95	3,825.59
Total Charges						3,825.59

Repair Notes:

(KBR) Steering complaints
 (MI) 1215959 COULD HEAR POPPING SOMETIMES WHILE TURNING OR GOING OVER BUMPS. FOUND PLAY IN STEERING GEAR
 (MI) The warranty is cancelled byon7/10/2023 10:38:22 AM

Repair Job: 03-015-000 - REPLACE PART STEERING SYSTEM	Total Job Cost: 284.71
---	-------------------------------

Job Location: STATE OF KS	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: DRIVER REPORT	Warranty Violation: None	

<u>Vendor Name</u>	<u>Invoice No.</u>	<u>Labor</u>	<u>Parts</u>	<u>Misc</u>	<u>Tax</u>	<u>Total Cost</u>
S924628MO - Nextran Kansas City	17441	\$125.00	\$0.00	\$159.71	\$0.00	284.71
Total Charges						284.71

Repair Notes:

(KBR) Replace:
 Drag link
 Tie Rod ASM
 Pitman Arm
 Steering gear box
 (MI) The warranty is cancelled byon7/10/2023 10:40:42 AM

Repair Job: 03-016-000 - REPLACE PART SUSPENSION SYSTEM	Total Job Cost: 3,076.96
---	---------------------------------

Job Location: STATE OF KS	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: DRIVER REPORT	Warranty Violation: None	

<u>Vendor Name</u>	<u>Invoice No.</u>	<u>Labor</u>	<u>Parts</u>	<u>Misc</u>	<u>Tax</u>	<u>Total Cost</u>
S924628MO - Nextran Kansas City	17441	\$1,935.00	\$0.00	\$300.00	\$0.00	2,235.00
Total Charges						2,235.00

<u>Parts</u>	<u>Description</u>	<u>Quantity</u>	<u>Unit Price</u>	<u>Total Cost</u>
IS18091	TIE ROD ASSY REPLACEMENT KIT	1.00	668.42	668.42
630267	ARM STABILIZING BAR	2.00	86.77	173.54
Total Charges				841.96

Repair Notes:

(KBR) Replace sway bar links and busnings
 (MI) The warranty is cancelled byon7/10/2023 10:41:44 AM

Work Order Cost Detail

Work Order: 1153481 Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: 03-015-003 - REPLACE PART STEERING GEAR

Total Job Cost:	2,341.96
------------------------	-----------------

Job Location: STATE OF KS

Labor Hours: 0.00 Labor Cost: 0.00

Repair Reason: DRIVER REPORT

Warranty Violation: Part Failure

Vendor Name	Invoice No.	Labor	Parts	Misc	Tax	Total Cost
S924628MO - Nextran Kansas City	17441	\$0.00	\$0.00	\$0.00	\$0.00	0.00
Total Charges						0.00

Parts	Description	Quantity	Unit Price	Total Cost
661137	GEARBOX-STEERING	1.00	1783.63	1,783.63
660750	PITMAN-STEERRING GEAR BOX	1.00	288.98	288.98
161458	SERVICE KIT, LH DRAGLINK	1.00	269.35	269.35
Total Charges				2,341.96

Repair Notes:

(MI) The warranty is cancelled byon7/10/2023 10:42:01 AM

Contact:	Total Labor Hours:	0.00	Total Labor Cost:	0.00
Notify Date:	Job Count:	4	Total Material Cost:	3,183.92
Picked Up By:	Hours Opened:	363.0	Total Commercial Cost:	6,345.30
Pick Up Date:			Total Work Order Cost:	9,529.22

Work Order Cost Detail

Work Order: 1158300 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed WO Location: KCD Alt Unit No:
Date Opened: 06/30/2023 13:37:09 WO Reason: SERVICE LANE Serial No: 2PCG33495EC735508
Date Complete: 07/01/2023 05:58:37 Meter 1 - M: 1,190,709 License No: K000932
Date Closed: 07/01/2023 05:58:41 Meter 2 - N: 0 Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US Maint. Class: 20

Repair Job: CK-001-000 - CHECK HVAC SYSTEM

Total Job Cost: 35.68

Job Location: KANSAS CITY -SI/AGENCY
Repair Reason: INSPECT, ROUTINE

Labor Hours: 0.71 Labor Cost: 35.68
Warranty Violation: None

Repair Notes:

(CLL) checked hvac - washed cond core - operational - temp output (with controller at 66) is 63.3 degrees.

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY

Total Job Cost: 35.18

Job Location: KANSAS CITY -SI/AGENCY
Repair Reason: PREVENTIVE MAINT

Labor Hours: 0.70 Labor Cost: 35.18
Warranty Violation: None

Contact:	Total Labor Hours:	1.42	Total Labor Cost:	70.86
Notify Date:	Job Count:	2	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	16.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	70.86

Work Order Cost Detail

Work Order: 1159906 Unit No: GLI 86245 2014 PRVST X3-45

WO Status: Closed WO Location: NYG Alt Unit No:
Date Opened: 07/06/2023 01:17:59 WO Reason: SERVICE LANE Serial No: 2PCG33495EC735508
Date Complete: 07/06/2023 04:24:05 Meter 1 - M: 1,193,220 License No: K000932
Date Closed: 07/07/2023 05:37:52 Meter 2 - N: 0 Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US Maint. Class: 20

Repair Job: 06-174-000 - INSPECT BUS BODY **Total Job Cost: 4.44**
Job Location: NEW YORK SI Labor Hours: 0.09 Labor Cost: 4.44
Repair Reason: DRIVER REPORT Warranty Violation: None

Repair Notes:

(U0000568) OBD ,windshield wipers not working, open door button not working on inside of coach
(RUPE) old body damage

Repair Job: 02-999-999 - CLEAN TOTAL VEHICLE ASSEMBLY **Total Job Cost: 48.93**
Job Location: NEW YORK SI Labor Hours: 0.98 Labor Cost: 48.93
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Job: 06-036-013 - INSPECT ADAPTIVE CRUISE BRAKING SYSTEM **Total Job Cost: 3.46**
Job Location: NEW YORK SI Labor Hours: 0.07 Labor Cost: 3.46
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(U0000568) Inspect Adaptive Cruise Braking System for proper operation and complete the test suite.

Adaptive Cruise Braking documentation is attached to this work order or available by copying the link below and pasting into a browser:

[https://fga.sharepoint.com/sites/EmployeePortal/Businesses/Greyhound/Maintenance/Documents/Driver Bulletins/English/DB-173 ACB Data Link Error-v2-5-16.pdf](https://fga.sharepoint.com/sites/EmployeePortal/Businesses/Greyhound/Maintenance/Documents/Driver%20Bulletins/English/DB-173%20ACB%20Data%20Link%20Error-v2-5-16.pdf)

Repair Job: QC-002-035 - QUALITY CHK WINDSHIELD WIPER & WASHER **Total Job Cost: 8.90**
Job Location: NEW YORK SI Labor Hours: 0.18 Labor Cost: 8.90
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(RUPE) wipers not working.check bad motor

Repair Job: QC-042 - QUALITY CHK COOLING SYSTEM **Total Job Cost: 8.32**
Job Location: NEW YORK SI Labor Hours: 0.17 Labor Cost: 8.32
Repair Reason: INSPECT, ROUTINE Warranty Violation: None

Repair Notes:

(RUPE) check cooling system working good

Work Order Cost Detail

Work Order: 1159906 Unit No: GLI 86245 2014 PRVST X3-45

Repair Job: QC-045-023 - QUALITY CHK BELTS

Total Job Cost: 4.13

Job Location: NEW YORK SI

Labor Hours: 0.08 Labor Cost: 4.13

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Repair Notes:

(RUPE) inspected belts looking good

Repair Job: QC-174-032 - QUALITY CHK BUS BODY WHEELCHAIR LIFT
COMPONENTS

Total Job Cost: 7.00

Job Location: NEW YORK SI

Labor Hours: 0.14 Labor Cost: 7.00

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Repair Notes:

(RUPE) old body damage and wheelchair works

Repair Job: XP-999-999 - EXPRESS CK TOTAL VEHICLE ASSEMBLY

Total Job Cost: 6.31

Job Location: NEW YORK SI

Labor Hours: 0.13 Labor Cost: 6.31

Repair Reason: INSPECT, ROUTINE

Warranty Violation: None

Contact:	Total Labor Hours:	1.83	Total Labor Cost:	91.49
Notify Date:	Job Count:	8	Total Material Cost:	0.00
Picked Up By:	Hours Opened:	3.0	Total Commercial Cost:	0.00
Pick Up Date:			Total Work Order Cost:	91.49

Work Order Cost Detail

Work Order: 1161720	Unit No: GLI 86245	2014 PRVST X3-45
WO Status: Open	WO Location: XIN	Alt Unit No:
Date Opened: 07/12/2023 03:46:04	WO Reason: ACCIDENT	Serial No: 2PCG33495EC735508
Date Complete:	Meter 1 - M: 1,195,971	License No: K000932
Date Closed:	Meter 2 - N: 0	Tech Spec: 14PVTX3-45VB
Using Dept: MAINTUS - Greyhound US		Maint. Class: 20

Repair Job: 20-174-000 - TOWING BUS BODY	Total Job Cost: 0.00	
Job Location: STATE OF IN	Labor Hours: 0.00	Labor Cost: 0.00
Repair Reason: ACCIDENT/COLLISION	Warranty Violation: None	

Repair Notes:
(U0000117) major collision

Contact:	Total Labor Hours: 0.00	Total Labor Cost: 0.00
Notify Date:	Job Count: 1	Total Material Cost: 0.00
Picked Up By:	Hours Opened: N/A	Total Commercial Cost: 0.00
Pick Up Date:		Total Work Order Cost: 0.00

Work Order Cost Detail

Work Order Cost Detail

Report Title: WOCOSTDETAIL - Work Order Cost Detail V20.0
Report Author: FleetFocus M5
File Path: C:\SAP BusinessObjects\SAP BusinessObjects Enterprise XI 4.0\Data\procSched\M5GHRPT01.
Data Extracted: Thu Jul 13 2023 11:58:44 Report User: JAKE.FERGUSON
TZ: Central Standard Time
DLL Version: 2018.08.01
Report Comments: 6/1/06 - Focus No 7069 6/15/06 - Focus No 7996 & Focus No. 3053 02/16/07 - Focus No. 13096 03/26/07 - Focus No. 13896 07/02/07 - Focus No. 15696 12/12/07 - Focus No. 17917 04/28/08 - Focus No. 19868 11/10/08 - Focus No. 20917 12/01/08 - Focus No. 22819 01/30/09 - Focus No. 22842 12/10/09 - Focus No. 24193 06/22/09 - Focus No. 25614 08/06/09 - Focus No. 25851 08/04/10 - Focus No. 31071 08/24/10 - Focus No. 28649 28/30/10 - Focus No. 31496 09/23/10 - Focus No. 12/10/10 - Focus No. 31071 03/02/12 - Focus No. 38753 07/05/12 - Focus No. 39906 07/29/14 - FMV-2279 08/24/15 - FMV-3791 09/22/15 - FMV-4217
FMV-3590 07/12/16 - FMV-6654 01/30/17 - FMV-7925 02/13/17 - fmv-4354 07/03/17 - FMV-10050 10/23/19 - FMV-17772

Parameters and Selection Filters

First Grouping: NONE
Second Grouping: NONE
Third Grouping:
Sorted By:
From Date:
To Date:
Show WO Notes: Yes
Show Job Notes: Yes
Selection Filters: isnull({VIEW_JOB_WORKSHEET.ORIG_JOB_ID}) and {VIEW_JOB_WORKSHEET.JOB_STATUS} <> "CAN" and({view_wo_worksheet.open_dt}>= date(2023,4,12) and {view_wo_worksheet.open_dt}<= date(2023,7,12) and {view_udc_main.unit_no} = 'GLI 86245') //Q=M5LG