

National Transportation Safety Board

Office of Aviation Safety  
Central Region



CEN23FA046

# INVESTIGATION PHOTOGRAPHS



**Photograph 1 - Main Wreckage at Accident Site**



**Photograph 2 - Main Wreckage at Accident Site (Left)**



**Photograph 3 - Main Wreckage at Accident Site (Rear)**



**Photograph 4 - Engine at Accident Site**



**Photograph 5 - Propeller**



**Photograph 6 - Wreckage Layout, Left**



**Photograph 7 - Wreckage Layout, Left Side of Empennage**





**Photograph 8 - Wreckage Layout, Right Side of Empennage**



**Photograph 9 - Wreckage Layout, Left Wing**



**Photograph 10 - Wreckage Layout, Right Wing**