

## Communication Summary

July 3, 2019

Information from: Mr. Drew Holmes, FAA IND FSDO



---

Summary & Factual Information: Mr. Holmes, in part, advised that the pilot had performed 2 or 3 landings before the accident flight. Popsicles were brought out to the pilot between flights. A camera was located near the airstrip. A review of a video showed it captured a segment of the accident flight. The airplane can be seen spiraling downward, impacting the runway, and a subsequent ground fire occurs. A hangar at Paoli Municipal Airport, near Paoli, Indiana, was rented by the pilot since January 2019. The airplane departed from the airport on the morning of the accident flight. No logbooks were observed in the hangar.

---

I can attest that the above summary is correct to the best of my knowledge:

**Edward F. Malinowski**  
**National Transportation Safety Board**  
**Air Safety Investigator**