

Ticket Number	Create Date	Problem Reported	Site Name	Prefix	Mile Post
2171843	3/2/2023 6:53:51 PM		VALE	YG	0091.900
		Requires Calibration and/or Inspection			
2179224	4/1/2023 7:20:36 PM	POWER OFF MESSAGE	VALE	YG	0091.900

Resolution Details**Category**

Calibration completed. Followed and performed all maintenance and test procedures outlined in MS 401 and MS 404. Recorded tests on Inspection/maintenance form and left at location.

Detector

Detector