



Photo 1 – Supplied photo with a quartering view of the right rear side of the airplane in a farm field.



Photo 2 - Supplied photo with a quartering view of the left rear side of the airplane in a farm field.



Photo 3 - Supplied photo with a view of the front of the recovered airplane.



Photo 4 - Supplied photo with a view of the left side of the recovered airplane.



Photo 5 - Supplied photo with a view of the aft side of the recovered airplane.



Photo 6 - Supplied photo with a quartering view of the left front side of the recovered airplane.




Photo 7 - Supplied photo of the unsecured oil cap.