



Photo 1 – Supplied photo of the resting airplane with smoke going in the same direction as the windsock indication.



Photo 2 - Supplied quartering view of the right rear of the resting airplane wreckage.



13.06.2020 13:55

Photo 3 - Supplied close-up quartering view of the right rear of the resting airplane wreckage.



Photo 4 - Supplied photo of the rear of the airplane wreckage in the background and a ground scar in the foreground.



Photo 5 - Supplied photo of a linear ground scar about 6 inches deep.



Photo 6 - Supplied photo of a propeller blade exhibiting chordwise abrasion.



Photo 7 - Supplied photo of the front of the resting airplane wreckage.



Photo 8 - Supplied close-up quartering view of the left front of the resting airplane wreckage.



Photo 9 - Supplied close-up photo of the rear seat's cockpit area.



Photo 10 - Supplied photo of the rear seat's cockpit area.