



Motor Carrier Attachment –

Level V Inspections

Andrews, Texas

HWY22MH006

(5 Pages)

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

FEDERAL MOTOR CARRIER SAFETY ADMINISTRATION
New Mexico Division
2440 Louisiana Blvd. NE, Suite 520
Albuquerque, NM 87100
505-346-7875

Report Number: US0937220040
Inspection Date: 03/23/2022
Start: 9:25 AM MT End:09:45 AM MT
Inspection Level: V - Terminal
HM Inspection Type: None

UNIVERSITY OF THE SOUTHWEST
6610 NORTH LOVINGTON HIGHWAY
HOBBS, NM 88240
USDOT#: 00836792 Phone#: (575)492-2106
MC/MX#: 00000000 Fax#:
State#:

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Location: UNIVERSITY OF THE SOUTHWEST MilePost: 0 Shipper: N/A
Highway: 6610 N LOVINGTON HWY Origin: HOBBS, NM Bill of Lading: N/A
County: Destination: HOBBS, NM Cargo: EMPTY

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate #, Equipment ID, VIN, GVWR, CVSA #, New CVSA #, OOS#

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Vio Code, Section, Unit, OOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM Transported.

Placard: No Cargo Tank:

Special Checks:

Vehicle OOS Text

Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000.

Signature Of Repairer X: Facility: Date:

Carrier Verify Text

Signature Of Motor Carrier X: Title: Date:

Report Prepared By: RICHARD RIVERA

Badge #: US0937

Copy Received By:

Page 1 of 2



00836792 NM US0937220040

X

X

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

FEDERAL MOTOR CARRIER SAFETY ADMINISTRATION
New Mexico Division
2440 Louisiana Blvd. NE, Suite 520
Albuquerque, NM 87100
505-346-7875

Report Number: US0937220040
Inspection Date: 03/23/2022
Start: 9:25 AM MT **End:** 09:45 AM MT
Inspection Level: V - Terminal
HM Inspection Type: None

UNIVERSITY OF THE SOUTHWEST
6610 NORTH LOVINGTON HIGHWAY
HOBBS, NM 88240
USDOT#: 00836792 **Phone#:** (575)492-2106
MC/MX#: 00000000 **Fax#:**
State#:

Driver:
License#: **State:**
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:

Inspection Notes

Vehicle is equipped with 29 seats including the driver. No OOS decal available

Special Studies No Special Study Data Recorded

Report Prepared By:
RICHARD RIVERA

Badge #:
US0937

Copy Received By:

Page 2 of 2



00836792 NM US0937220040

X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

FEDERAL MOTOR CARRIER SAFETY ADMINISTRATION
New Mexico Division
2440 Louisiana Blvd. NE, Suite 520
Albuquerque, NM 87100
505-346-7875

Report Number: US0937220041
Inspection Date: 03/23/2022
Start: 9:45 AM MT End:09:52 AM MT
Inspection Level: V - Terminal
HM Inspection Type: None

UNIVERSITY OF THE SOUTHWEST
6610 NORTH LOVINGTON HIGHWAY
HOBBS, NM 88240
USDOT#: 00836792 Phone#: (575)492-2106
MC/MX#: 00000000 Fax#:
State#:

Driver:
License#: State:
Date of Birth:
CoDriver:
License#: State:
Date of Birth:

Location: UNIVERSITY OF THE SOUTHWEST MilePost: 0 Shipper: N/A
Highway: 6610 N LOVINGTON HWY Origin: HOBBS, NM Bill of Lading: N/A
County: Destination: HOBBS, NM Cargo: EMPTY

VEHICLE IDENTIFICATION

Table with columns: Unit, Type, Make, Year, State, Plate #, Equipment ID, VIN, GVWR, CVSA #, New CVSA #, OOS#

BRAKE ADJUSTMENTS

Table with columns: Axle #, Right, Left, Chamber

VIOLATIONS

Table with columns: Vio Code, Section, Unit, OOS, Citation #, Verify, Crash, Violations Discovered

HazMat: No HM Transported.

Placard: No Cargo Tank:

Special Checks:

Failure to return this report with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, up to a total of \$10,000.

Signature Of Repairer X: Facility: Date:

Carrier Verify Text

Signature Of Motor Carrier X: Title: Date:

Report Prepared By: RICHARD RIVERA

Badge #: US0937

Copy Received By:

Page 1 of 2



00836792 NM US0937220041

X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

FEDERAL MOTOR CARRIER SAFETY ADMINISTRATION
New Mexico Division
2440 Louisiana Blvd. NE, Suite 520
Albuquerque, NM 87100
505-346-7875

Report Number: US0937220041
Inspection Date: 03/23/2022
Start: 9:45 AM MT **End:** 09:52 AM MT
Inspection Level: V - Terminal
HM Inspection Type: None

UNIVERSITY OF THE SOUTHWEST
6610 NORTH LOVINGTON HIGHWAY
HOBBS, NM 88240
USDOT#: 00836792 **Phone#:** (575)492-2106
MC/MX#: 00000000 **Fax#:**
State#:

Driver:
License#: **State:**
Date of Birth:
CoDriver:
License#: **State:**
Date of Birth:

Inspection Notes

This vehicle contained 23 seats including the driver.

Special Studies No Special Study Data Recorded

Report Prepared By:
RICHARD RIVERA

Badge #:
US0937

Copy Received By:

Page 2 of 2



00836792 NM US0937220041

X _____

X _____