

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008614830 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: MT	Asset ID: BAB3BWD
Subdivision: HI LINE	Test Date: 2021-09-07
Line Segment / Milepost: 0036 ~ 1014.75 - 1014.75	State: MT
Location / Highway Name: EAST BUELOW	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	B027813
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008549866 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: MT	Asset ID: BAB3BWD
Subdivision: HI LINE	Test Date: 2021-08-16
Line Segment / Milepost: 0036 ~ 1014.75 - 1014.75	State: MT
Location / Highway Name: EAST BUELOW	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	B027813
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008404098 ~ Form Type: FRA SWITCH TEST ~ 360 Days

Division: MT	Asset ID: BAB3BWD
Subdivision: HI LINE	Test Date: 2021-07-29
Line Segment / Milepost: 0036 ~ 1014.75 - 1014.75	State: MT
Location / Highway Name: EAST BUELOW	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
CHECK FOR UNNECESSARY ARCHING BETWEEN BRUSHES AND COMMUTATOR (SI-4.6)..	TESTED OK	B027813
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	B027813
OBSTRUCTION - NORMAL (FRA-236.382). ADJUSTED NORMAL AND REVERSE LOCK ROD.	ADJUSTED/TESTED OK	B027813
OBSTRUCTION - REVERSE (FRA-236.382). ADJUSTED NORMAL AND REVERSE LOCK ROD.	ADJUSTED/TESTED OK	B027813
PT. DET./CC - NORMAL (FRA-236.103). ADJUSTED NORMAL AND REVERSE PD ROD.	ADJUSTED/TESTED OK	B027813
PT. DET./CC - REVERSE (FRA-236.103). ADJUSTED NORMAL AND REVERSE PD ROD.	ADJUSTED/TESTED OK	B027813
SHUNT FOULING (FRA-236.104)	TESTED OK	B027813
TIMING (SI-4.2)	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008218644 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: MT	Asset ID: BAB3BWD
Subdivision: HI LINE	Test Date: 2021-07-06
Line Segment / Milepost: 0036 ~ 1014.75 - 1014.75	State: MT
Location / Highway Name: EAST BUELOW	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382). ADJUSTED NORMAL AND REVERSE LOCK ROD.	ADJUSTED/TESTED OK	B027813
OBSTRUCTION - REVERSE (FRA-236.382). ADJUSTED NORMAL AND REVERSE LOCK ROD.	ADJUSTED/TESTED OK	B027813
PT. DET./CC - NORMAL (FRA-236-103). ADJUSTED NORMAL AND REVERSE PD ROD.	ADJUSTED/TESTED OK	B027813
PT. DET./CC - REVERSE (FRA-236-103). ADJUSTED NORMAL AND REVERSE PD ROD.	ADJUSTED/TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008099192 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: MT	Asset ID: BAB3BWD
Subdivision: HI LINE	Test Date: 2021-06-07
Line Segment / Milepost: 0036 ~ 1014.75 - 1014.75	State: MT
Location / Highway Name: EAST BUELOW	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	B027813
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001008870426 ~ Form Type: GROUNDS ~ 90 DAYS *** Out Of Schedule ***

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-09-23
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B023714 - JAY DUSTERHOFF	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	NOT TESTED	
BATTERY CROSS TEST (TP-107A)	NOT TESTED	
CHECK WATER (SI-10.1)	NOT TESTED	
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	NOT TESTED	
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT (TP-18)..	NOT TESTED	
RECORDER (SI-6.4)	NOT TESTED	
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC REPORTING SYSTEM (SI-1.25)..	NOT TESTED	
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS (S.I. 1.10)..	PENDING UPDATED PRINTS	B023714
VERIFY RECORDER BATTERY (SI-6.4)	NOT TESTED	
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	B023714

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUND	B12	09/23/21	Tested OK			B023714
GROUND	B28	09/23/21	Tested OK			B023714

BNSF Railway

BNSF Inspection Report - Locking Tests & Inspections

Inspection #: 001008870462 ~ Form Type: LOCKING ~ 2 YEAR *** Out Of Schedule ***

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-09-23
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B023714 - JAY DUSTERHOFF	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.
 Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.
 Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
DID YOU VERIFY CONFIGURATION SETTINGS CHECKSUM AND CRC ARE SET PER THE PRINT?...	NOT TESTED	
DID YOU VERIFY INPUT/OUTPUT CIRCUITS TO/FROM THE PROCESSOR UNIT?..	NOT TESTED	
DO THE CURRENT VALUES OF ALL THE BASELINE ITEMS MATCH THOSE RECORDED IN THE.LAST BASELINE TEST?...	NOT TESTED	
WHAT TYPE OF TEST ARE YOU COMPLETING?	NOT TESTED	

Operations With Measurements

Measurement Type	Measure Date	Condition/Test Result	Tested By
<u>LOCKING (FRA-236.377/378/379/380/381)</u>			
INDICATION FRA 236.380	09/23/21	Tested OK	B023714
Route Nomenclature: EA-1.N-W			
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..			
INDICATION FRA 236.380	09/23/21	Tested OK	B023714
Route Nomenclature: EB-1.R-W			
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..			
INDICATION FRA 236.380	09/23/21	Tested OK	B023714
Route Nomenclature: W-1.N-EA			
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..			
INDICATION FRA 236.380	09/23/21	Tested OK	B023714
Route Nomenclature: W-1.R-EB			
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..			

BNSF Railway

BNSF Inspection Report - Insulation Tests & Inspections

Inspection #: 001008870548 ~ Form Type: INSULATION ~ 10 Year *** Out Of Schedule ***

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-09-23
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B023714 - JAY DUSTERHOFF	Gang ID: SINS0164

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations With Measurements

<u>INSULATION (FRA-236.108)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
RESISTANCE	T-10-16-JBX-SWT	09/23/21	Tested OK			B023714
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..						
RESISTANCE	T-4-10-JBX-SWT	09/23/21	Tested OK			B023714
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..						
RESISTANCE	U-12-14-BUNGALOW-S WITCH	09/23/21	Tested OK			B023714
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..						
RESISTANCE	U-3-6-BUNGALOW-SWI TCH	09/23/21	Tested OK			B023714
Comment: INSTALLED NEW M23 SWITCH MACHINE AND TESTED..						

BNSF Railway

BNSF Inspection Report - Defect Detector Tests & Inspections

Inspection #: 001008615477 ~ Form Type: DETECTOR ~ 30 Days

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-09-07
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
TEST OPER OF DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
VERIFY TIME, DATE AND SETUP	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001008218723 ~ Form Type: GROUNDS ~ 90 Days

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-08-25
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	TESTED OK	B027813
BATTERY CROSS TEST (TP-107A)	TESTED OK	B027813
CHECK WATER (SI-10.1)	TESTED OK	B027813
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	TESTED OK	B027813
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	B027813
RECORDER (SI-6.4)	TESTED OK	B027813
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25)..	VERIFIED	B027813
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	B027813
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	B027813
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	B027813

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUNDS	B12	08/25/21	Tested OK			B027813
GROUNDS	B28	08/25/21	Tested OK			B027813

BNSF Railway

BNSF Inspection Report - Defect Detector Tests & Inspections

Inspection #: 001008550452 ~ Form Type: DETECTOR ~ 180 Days

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-08-17
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
CHECK PADDLE DRAGGER PLAY AND TENSION	TESTED OK	B027813
GREASE PADDLE DRAGGER	TESTED OK	B027813
INSPECT DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
TEST OPER OF DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
VERIFY ALARM READOUT	TESTED OK	B027813
VERIFY TIME, DATE AND SETUP	TESTED OK	B027813
VERIFY VERSION OF SOFTWARE	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Defect Detector Tests & Inspections

Inspection #: 001008404764 ~ Form Type: DETECTOR ~ 30 Days

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-07-29
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
TEST OPER OF DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
VERIFY TIME, DATE AND SETUP	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Defect Detector Tests & Inspections

Inspection #: 001008219129 ~ Form Type: DETECTOR ~ 30 Days

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-07-06
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.
 Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.
 Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
TEST OPER OF DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
VERIFY TIME, DATE AND SETUP	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001007732811 ~ Form Type: GROUNDS ~ 360 Days

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-06-07
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
ANNUAL OPERATING LOAD TEST (SI-10.1)	TESTED OK	B027813
BATTERY CARD (TEST + TO -)	TESTED OK	B027813
BATTERY CROSS TEST (TP-107A)	TESTED OK	B027813
CHECK WATER (SI-10.1)	TESTED OK	B027813
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	TESTED OK	B027813
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	B027813
RECORDER (SI-6.4)	TESTED OK	B027813
RESTORE POWER	OK	B027813
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25)..	VERIFIED	B027813
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	B027813
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	B027813
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	B027813

Operations With Measurements

<u>GROUND S (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUND S	B12	06/07/21	Tested OK			B027813
GROUND S	B28	06/07/21	Tested OK			B027813

BNSF Railway

BNSF Inspection Report - Defect Detector Tests & Inspections

Inspection #: 001008099827 ~ Form Type: DETECTOR ~ 90 Days

Division: MT	Asset ID: BACLTTD
Subdivision: HI LINE	Test Date: 2021-06-07
Line Segment / Milepost: 0036 ~ 1014.70 - 1014.70	State: MT
Location / Highway Name: BUELOW_EAST	
County: LIBERTY	
Employee's Name: B027813 - CAMRON SULLIVAN	Gang ID: SMTR0472

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
TEST OPER OF DRAGGING EQUIPMENT DETECTOR	TESTED OK	B027813
VERIFY ALARM READOUT	TESTED OK	B027813
VERIFY TIME, DATE AND SETUP	TESTED OK	B027813
VERIFY VERSION OF SOFTWARE	TESTED OK	B027813

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008870483 ~ Form Type: FRA SWITCH TEST ~ 360 DAYS

Division: MT	Asset ID: BAD58CT
Subdivision: HI LINE	Test Date: 2021-09-23
Line Segment / Milepost: 0036 ~ 1014.75 - 1014.75	State: MT
Location / Highway Name: EAST BUELOW	
County: LIBERTY	
Employee's Name: B023714 - JAY DUSTERHOFF	Gang ID: SINS0164
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
CHECK FOR UNNECESSARY ARCING BETWEEN BRUSHES AND COMMUTATOR (SI-4.6)..	TESTED OK	B023714
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	B023714
OBSTRUCTION - NORMAL (FRA-236.382). INSTALLED NEW M23 SWITCH MACHINE AND TESTED..	ADJUSTED/TESTED OK	B023714
OBSTRUCTION - REVERSE (FRA-236.382). INSTALLED NEW M23 SWITCH MACHINE AND TESTED..	ADJUSTED/TESTED OK	B023714
PT. DET./CC - NORMAL (FRA-236.103). INSTALLED NEW M23 SWITCH MACHINE AND TESTED..	ADJUSTED/TESTED OK	B023714
PT. DET./CC - REVERSE (FRA-236.103). INSTALLED NEW M23 SWITCH MACHINE AND TESTED..	ADJUSTED/TESTED OK	B023714
SHUNT FOULING (FRA-236.104)	TESTED OK	B023714