

BNSF Railway

BNSF Inspection Report - Timing Tests & Inspections

Inspection #: 001011900629 ~ Form Type: TIMER ~ 360 Days

Division: PR	Asset ID: BABYEYR
Subdivision: PIKES PEAK	Test Date: 2023-04-04
Line Segment / Milepost: 0477 ~ 109.66 - 109.66	State: CO
Location / Highway Name: SOUTH_BRAGDON	
County: PUEBLO	
Employee's Name: PII [REDACTED]	Gang ID: PII [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance

Operations With Measurements

<u>TIMING (FRA-236.109)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Design Time (mm:ss)	Tested By
TIMING	LOS	04/04/23	Tested OK	00:10	00:10	B028145
TIMING	TE	04/04/23	Tested OK	08:00	08:00	B028145