



Highway Factors Photographs 1 through 20

Highland, IL

HWY23MH015

(19 pages)



Highway Factors Photo 1 – View of screen shot of two of the five truck-tractor semi-trailer combination units parked on the exit ramp shoulder to the westbound Silver Lake rest stop taken on Saturday, July 15, 2023, at approximately 9:30 p.m. looking to the west



Highway Factors Photo 2 – View of the regulatory speed limit sign posted approximately 2.3 miles prior to the crash, indicating a 70-mph speed limit and 45-mph minimum speed limit looking to the west



Highway Factors Photo 3 – View of the 40-mph advisory speed limit sign for the exit ramp to the westbound Silver Lake rest stop posted approximately 350 feet prior to the crash looking to the west



Highway Factors Photo 4 – View of the exit ramp to the westbound Silver Lake rest stop in the vicinity of the crash location standing on the edge of the paved right shoulder looking to the west



Highway Factors Photo 5 – View of the exit ramp to the westbound Silver Lake rest stop in the vicinity of the crash location standing on the paved right shoulder looking to the east



Highway Factors Photo 6 – View of the exit ramp to the westbound Silver Lake rest stop immediately west of the crash location standing on the exit ramp looking to the east



Highway Factors Photo 7 – View of the exit ramp to the westbound Silver Lake rest stop immediately west of the crash location standing on the exit ramp looking to the northwest



Highway Factors Photo 8 – View of the exit ramp to the westbound Silver Lake rest stop west of the crash location standing on the edge of the paved left shoulder looking to the east with “Wrong Way” signs located in the background



Highway Factors Photo 9 – View of the exit ramp to the westbound Silver Lake rest stop west of the crash location standing on the edge of the paved right shoulder looking to the northwest with directional signs for “Passenger Cars” and “Trucks and Vehicles Towing Trailers” located in the background



Highway Factors Photo 10 – View of the exit ramp to the westbound Silver Lake rest stop west of the crash location standing on the exit ramp looking to the northwest with the rest stop parking lot and building located in the background



Highway Factors Photo 11 – View of the exit ramp to the westbound Silver Lake rest stop west of the crash location standing at the entrance to the rest stop parking lot looking to the east with “Do Not Enter” signs located in the foreground



Highway Factors Photo 12 – View of the westbound Silver Lake rest stop parking lot standing in the aisle adjacent to the truck parking spaces looking to the west with the rest stop building located in the background



Highway Factors Photo 13 – View of the no parking symbol sign on the exit ramp to the Spring Creek rest stop area near Covington, IN on I-74 (Source: Google Street Maps)



Highway Factors Photo 14 – View of the no parking symbol sign on the entrance ramp from the Spring Creek rest stop area near Covington, IN on I-74 (Source: Google Street Maps)



Highway Factors Photo 15 – View of the no parking symbol sign on the entrance ramp from the rest stop area south of St. Augustine, FL on I-95 (Source: Google Street Maps)



Highway Factors Photo 16 – View of the no parking symbol sign on the exit ramp and traffic cones on the shoulder to the Ramapo rest stop area near Sloatsburg, NY on I-87 (Source: Google Street Maps)



Highway Factors Photo 17 – View of the “No Parking” sign on the exit ramp and flexible delineator posts on the shoulder to the Hill County safety rest area south of Hillsboro, Texas on I-35



Highway Factors Photo 18 – View of the “No Parking” sign on the shoulder of the I-35 mainline travel lanes adjacent to the Hill County safety rest area south of Hillsboro, Texas on I-35



Highway Factors Photo 19 – View of the “No Parking Any Time” sign on the exit ramp to the Portage rest stop area northwest of Poynette, WI on I-90 (Source: Google Street Maps)



Highway Factors Photo 20 – View of the “No Parking Any Time” sign on the entrance ramp and plastic drums placed at the edge of the shoulder from the Portage rest stop area northwest of Poynette, WI on I-90 (Source: Google Street Maps)