BNSF Railway BNSF Inspection Report - Locking Tests & Inspections

Inspection #: 001008797734 ~ Form Type: LOCKING ~ 4 Year

Division: PR	Asset ID: BABYEYR	
Subdivision: PIKES PEAK	Test Date: 2022-02-28	
Line Segment / Milepost: 0477 ~ 109.66 - 109.66	State: CO	
Location / Highway Name: SOUTH_BRAGDON		
County: PUEBLO		
Employee's Name:	Gang ID:	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
DID YOU VERIFY CONFIGURATION SETTINGS CHECKSUM AND CRC ARE SET PER THE.PRINT?	YES	B172364
DID YOU VERIFY INPUT/OUTPUT CIRCUITS TO/FROM THE PROCESSOR UNIT?	YES	B172364
DO THE CURRENT VALUES OF ALL THE BASELINE ITEMS MATCH THOSE RECORDED IN.THE LAST BASELINE TEST?	YES	B172364
WHAT TYPE OF TEST ARE YOU COMPLETING?	4 YEAR MALT	B172364