



Photo 1 – N5704R Main Wreckage (FAA Photo)



Photo 2 – Engine and Firewall (FAA Photo)



Photo 3 – Engine Firewall (FAA Photo)



Photo 4 – Lower Fuselage (FAA Photo)



Photo 5 – Landing Gear Strut Attachment (FAA Photo)