



Photo 1 – N214RL Main Wreckage (NTSB Photo)



Photo 2 - N214RL Main Wreckage (NTSB Photo)



Photo 3 - N214RL Aft Fuselage and Empennage (NTSB Photo)



Photo 4 - N214RL Left Wing (NTSB Photo)



Photo 5 - N214RL Left Wing Damage (NTSB Photo)



Photo 6 - N214RL Forward Fuselage (NTSB Photo)



Photo 7 - N214RL Front Windscreen (NTSB Photo)



Photo 8 – N749LA Main Wreckage and Wreckage Debris Field (NTSB Photo)



Photo 9 - N749LA Main Wreckage and Debris Field (NTSB Photo)



Photo 10 - N749LA Main Wreckage (NTSB Photo)



Photo 11 - N749LA Main Wreckage (NTSB Photo)



Photo 12 - N749LA Right Wing and Propeller (NTSB Photo)



Photo 13 - N749LA Main Spar Carry-Through (NTSB Photo)



Photo 14 - N749LA Engine Compartment (NTSB Photo)



Photo 15 - N749LA Right Wing Flap (NTSB Photo)