

NAME/
SIGNATURE

LICENCE:
AME or
AMO/ACA

Dodge Center Aviation, LLC			
Registration		Dodge Center Municipal Airport	
N11HC		802 South Airport Road Dodge Center, MN 55927	
Date	Model	S/N	TSO
10-29-2020	IO360-B1E	0571-SP	
MFG.	Position	Tach	Total Time
Aero Sport Power - ECI		850.3	
Changed oil and filter. No metal in old filter. Took oil sample and sent to Blackstone. Serviced with 7 qts PH 20w50 X/C & 10 oz Camguard. Run up and leak check ok.			

Dodge Center Aviation, LLC			
Registration		Dodge Center Municipal Airport	
N11HC		802 South Airport Road Dodge Center, MN 55927	
Date	Model	S/N	TSO
4-7-21	IO360-B1E	0571-SP	
MFG.	Position	Tach	Total Time
Aero Sport Power - ECI		888.2	
Changed oil and filter. No metal in old filter. Took oil sample and sent to Blackstone. Serviced with 7 qts PH 20w50 X/C & 10 oz Camguard. Comp check: 1) 76, 2) 78, 3) 78, 4) 78. Run up and leak check ok.			

Dodge Center Aviation, LLC			
Registration		Dodge Center Municipal Airport	
N11HC		802 South Airport Road Dodge Center, MN 55927	
Date	Model	S/N	TSO
9-14-2021	IO360-B1E	0571-SP	N/A
MFG.	Position	Tach	Total Time
Aero Sport Power - ECI		914.8	914.8
Changed oil and filter. No metal in old filter. Took oil sample and sent to Blackstone. Serviced with 7 qts PH 20w50 X/C and 10 oz's Camguard. Compression check: 1) 76/80, 2) 77/80, 3) 75/80, 4) 76/80. Serviced spark plugs. Cleaned fuel servo fuel screen. Replaced induction air filter. Tightened alternator belt. I certify that this engine has been inspected on 9-14-2021 in accordance with the scope and detail of appendix D to part 43 and was found to be in a condition for safe operation.			

wo: GA1244



Engine - page 1 of 1

Great Planes Aviation · 7300 Brataas Drive SW · Rochester, MN 55902

N11HC
Hobbs: 1006.1

LYCOMING, IO-360-B1E, S/N: ENGINE SN TBD
TACH: 920.1

October 12, 2021

Troubleshoot starting issue found the left mag not firing. Determined the coil to be failed. Removed and replaced the coil in the left mag with new K3975. Reinstalled mag and timed to engine. Run and ops check performed good. Installed P/N K3975 - Slick Coil.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Great Planes Aviation under work order: GA1244.

Ryan Fay A&P/IA

Section 3A: Engine Service and Maintenance Log

DATE / /	TIME RUN		TIME SINCE OVERHAUL		CYCLES		INSTALLATIONS, INSPECTIONS
	HOURS	min	HOURS	min	Sub Total	TOTAL	

BROUGHT FORWARD

Dodge Center Aviation, LLC					
Registration		Dodge Center Municipal Airport		802 South Airport Road	
N11HC		[REDACTED]		Dodge Center, MN 55927	
Date	Model	S/N	TSO		
9-24-2019	IO360-B1E	0571-SP	N/A		
MFG.	Position	Tach	Total Time		
Aero Sport Power - ECI		743.0	743.0		
Changed oil and filter. No metal in old filter. Serviced with 7 qts PH 20w50 X/C and 10 oz's Camguard. Compression check: all cyl's 78/80. Serviced spark plugs. Cleaned fuel servo fuel screen. Adjusted both mag timing to specs. I certify that this engine has been inspected on 9-24-2019 in accordance with the scope and detail of appendix D to part 43 and was found to be in a condition for safe operation. [REDACTED]					

Dodge Center Aviation, LLC					
Registration		Dodge Center Municipal Airport		802 South Airport Road	
N11HC		[REDACTED]		Dodge Center, MN 55927	
Date	Model	S/N	TSO		
2-4-2020	IO360-B1E	0571-SP			
MFG.	Position	Tach	Total Time		
Aero Sport Power - ECI		784.2			
Changed oil and filter. No metal in old filter. Took oil sample and sent to Blackstone. Serviced with 7 qts PH 20w50 X/C & 10 oz Camguard. Compression check: all 78/80. Run up and leak check ok. [REDACTED]					

Dodge Center Aviation, LLC					
Registration		Dodge Center Municipal Airport		802 South Airport Road	
N11HC		[REDACTED]		Dodge Center, MN 55927	
Date	Model	S/N	TSO		
4-30-2020	IO360-B1E	0571-SP			
MFG.	Position	Tach	Total Time		
Aero Sport Power - ECI		790.4			
Replaced crank seal with new [REDACTED] Reinstalled prop with new o-ring and torqued to Hartzell specs. Run up/leak check ok. [REDACTED]					

Dodge Center Aviation, LLC					
Registration		Dodge Center Municipal Airport		802 South Airport Road	
N11HC		[REDACTED]		Dodge Center, MN 55927	
Date	Model	S/N	TSO		
9-16-2020	IO360-B1E	0571-SP	N/A		
MFG.	Position	Tach	Total Time		
Aero Sport Power - ECI		814.5	814.5		
Changed oil and filter. No metal in old filter. Serviced with 7 qts PH 20w50 X/C and 10 oz's Camguard. Compression check: 1) 78/80, 2) 77/80, 3) 76/80, 4) 78/80. Replaced all push rod tube seals and valve cover gasket on #3 cylinder. Serviced spark plugs. Cleaned fuel servo fuel screen. I certify that this engine has been inspected on 9-16-2020 in accordance with the scope and detail of appendix D to part 43 and was found to be in a condition for safe operation. [REDACTED]					

THIS PAGE TOTALS

PREVIOUS TOTALS

TOTALS SINCE NEW

CARRY FORWARD to Top of Next Page