

WPR22FA148

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of nosed over airplane




Photograph 2 - View of removed ELT



Photograph 3 - View of engine data plate



Photograph 4 - View of altimeter and Kohlmann's window



Photograph 5 - Top view of engine with top case removed during engine examination



Photograph 6 - View of damaged carburetor during engine examination