

Motor Carrier Attachment – Virginia State Police Roadside

Inspection February 9, 2023

Louisville, NY

HWY23FH005

(2 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4 Report Number: VA3927009845 Virginia State Police Motor Carrier Safety Inspection Date: 02/09/2023 P O Box 27472 Start: 9:50 AM ET End: 10:54 AM ET Richmond, VA 23261-7472 Inspection Level: II - Walk-Around Phone: (540) 829-7414 Fax: (804) 254-1635 Email: **HM Inspection Type:** None AERO GLOBAL LOGISTICS Driver: WATSON, TYLER J 2983 SOUTH PLEASANT VALLEY ROA State: PA License#: WINCHESTER, VA 22601 Date of Birth: **USDOT#:** 02447319 Phone#: (201)259-6912 CoDriver: MC/MX#: 00844580 Fax#: License#: State: State#: Date of Birth: Location: 0.3 MILES SOUTH OF TIMBER RIDG MilePost: Shipper: AERO GLOBAL Origin: WINCHESTER, VA Highway: 522 Bill of Lading: FW1-1, 1-4, 1-5 County: **Destination: BUFFALO. NY** Cargo: AUTO PARTS VEHICLE IDENTIFICATION Unit Type Make Year State Equipment ID **GVWR** CVSA# New CVSA # Plate # VIN OOS# TT FRHT 2019 33,000 2763902 230801 3AKBHKDVXKSKS9805 UTIL 2016 IN PB85733 652068 1UYVS2481GG700804 65.000 BRAKE ADJUSTMENTS: No Brake Measurements Required For Level 2 VIOLATIONS Vio Code Section Unit OOS Citation # Verify Crash Violations Discovered ELD - No record of duty status (ELD 395.8A-ELD 395.8A-ELD D Required): None Operating a CMV without proof of a periodic 396.17C 1 N N 396.17C N inspection: Exp. Decal 9-1-22 - No Paperwork Ν Ν Inoperable tail lamp: Left 393.9T 393.9T 1 N 393.9 393.9 2 Ν N Ν Inoperable Required Lamp: Right Front Clearance/Side Marker Placard: No HazMat: No HM Transported. Cargo Tank: **Special Checks:** *Pursuant to the Code of Virginia, I hereby notify and declare TYLER WATSON "Out of Service". No motor carrier shall permit orrequire this driver to drive or operate any motor

vehicle until: DRIVER IS OFF DUTY 10 CONSECUTIVE HOURS.

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears at the top of this report. In instances where a vehicle(s) has been placed out of service, repairs certification is required below. Failure to return thisreport with the required certification can result in penalties up to \$1,000 per day for each day the violation continues, upto a total of \$10.000.

Signature Of Repairer X: Facility: Date:

1) Sign and return this report ONLY if the driver and/or vehicle(s) have been placed Out of Service.RETURN ADDRESS: Virginia State Police Motor Carrier Safety P O Box 27472 Richmond, VA 23261-7472 DO NOT SEND TICKETS/CITATIONS/FINES TO THIS ADDRESS2) CITATIONS/TRAFFIC TICKETS: If issued, MUST be returned to the COURT whose address appears on front of the TICKET/CITATION.3) If the vehicle has NOT been repaired and HAS been permanently removed from service, initial here and sign the report.4) CARRIER CERTIFICATION: The undersigned certifies that all violations on this report have been corrected and action taken to assure compliance with the Motor Carrier Safety and HM Regulations insofar as they are applicable to motor carriers and drivers. This certification MUST BE SIGNED by the Motor Carrier Offical and RETURNED WITHIN 15 DAYS to the above address (#1).

Signature Of Motor Carrier X: Title: Date:

Report Prepared By: KEVIN J TETER

Badge #:

Copy Received By: TYLER WATSON

