

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008454159 ~ Form Type: FRA SWITCH TEST ~ 360 Days

Division: TC	Asset ID: BABDU5Y
Subdivision: MIDWAY	Test Date: 2021-08-16
Line Segment / Milepost: 0022 ~ 0.65 - 0.65	State: MN
Location / Highway Name: 7TH STREET - 1 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
CHECK FOR UNNECESSARY ARCHING BETWEEN BRUSHES AND COMMUTATOR (SI-4.6)..	TESTED OK	
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED ADJUSTMENT.	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). NEEDED ADJUSTMENT..	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008280875 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU5Y
Subdivision: MIDWAY	Test Date: 2021-07-20
Line Segment / Milepost: 0022 ~ 0.65 - 0.65	State: MN
Location / Highway Name: 7TH STREET - 1 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008148408 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU5Y
Subdivision: MIDWAY	Test Date: 2021-06-23
Line Segment / Milepost: 0022 ~ 0.65 - 0.65	State: MN
Location / Highway Name: 7TH STREET - 1 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007996147 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDU5Y
Subdivision: MIDWAY	Test Date: 2021-05-25
Line Segment / Milepost: 0022 ~ 0.65 - 0.65	State: MN
Location / Highway Name: 7TH STREET - 1 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103)	TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103)	TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007833010 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU5Y
Subdivision: MIDWAY	Test Date: 2021-04-27
Line Segment / Milepost: 0022 ~ 0.65 - 0.65	State: MN
Location / Highway Name: 7TH STREET - 1 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007672318 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU5Y
Subdivision: MIDWAY	Test Date: 2021-03-30
Line Segment / Milepost: 0022 ~ 0.65 - 0.65	State: MN
Location / Highway Name: 7TH STREET - 1 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007527066 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDU5Y
Subdivision: MIDWAY	Test Date: 2021-03-01
Line Segment / Milepost: 0022 ~ 0.65 - 0.65	State: MN
Location / Highway Name: 7TH STREET - 1 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.
 Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.
 Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED TO ADJUST FOR MORE SWIPE.	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). NEEDED TO ADJUST FOR MORE SWIPE..	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008454166 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDU6F
Subdivision: MIDWAY	Test Date: 2021-08-16
Line Segment / Milepost: 0022 ~ 0.64 - 0.64	State: MN
Location / Highway Name: 7TH STREET 2A SWITC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). HAD TO ADJUST H-BLOCK. PD NEEDED ADJUSTMENT AFTER..	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). HAD TO ADJUST H-BLOCK. PD NEEDED ADJUSTMENT AFTER..	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008280877 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU6F
Subdivision: MIDWAY	Test Date: 2021-07-20
Line Segment / Milepost: 0022 ~ 0.64 - 0.64	State: MN
Location / Highway Name: 7TH STREET 2A SWITC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008148415 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU6F
Subdivision: MIDWAY	Test Date: 2021-06-23
Line Segment / Milepost: 0022 ~ 0.64 - 0.64	State: MN
Location / Highway Name: 7TH STREET 2A SWITC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007996149 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDU6F
Subdivision: MIDWAY	Test Date: 2021-05-25
Line Segment / Milepost: 0022 ~ 0.64 - 0.64	State: MN
Location / Highway Name: 7TH STREET 2A SWITC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED ADJUSTMENT.	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). NEEDED ADJUSTMENT.	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007833019 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU6F
Subdivision: MIDWAY	Test Date: 2021-04-27
Line Segment / Milepost: 0022 ~ 0.64 - 0.64	State: MN
Location / Highway Name: 7TH STREET 2A SWITC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007672321 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU6F
Subdivision: MIDWAY	Test Date: 2021-03-30
Line Segment / Milepost: 0022 ~ 0.64 - 0.64	State: MN
Location / Highway Name: 7TH STREET 2A SWITC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007527070 ~ Form Type: FRA SWITCH TEST ~ 360 Days

Division: TC	Asset ID: BABDU6F
Subdivision: MIDWAY	Test Date: 2021-03-01
Line Segment / Milepost: 0022 ~ 0.64 - 0.64	State: MN
Location / Highway Name: 7TH STREET 2A SWITC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
CHECK FOR UNNECESSARY ARCHING BETWEEN BRUSHES AND COMMUTATOR (SI-4.6)..	TESTED OK	
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382). ADJUSTED.	ADJUSTED/TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382). ADJUSTED.	ADJUSTED/TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED MORE SWIPE.	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). NEEDED MORE SWIPE..	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008458170 ~ Form Type: FRA SWITCH TEST ~ 360 Days

Division: TC	Asset ID: BABDS5M
Subdivision: ST PAUL	Test Date: 2021-08-18
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH STREET - 2B SWI	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
CHECK FOR UNNECESSARY ARCHING BETWEEN BRUSHES AND COMMUTATOR (SI-4.6)..	TESTED OK	
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382). NEEDED SOME ADJUSTMENT TO PASS ON 1/8..	ADJUSTED/TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED ADJUSTMENT..	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). NEEDED ADJUSTMENT..	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008285033 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDS5M
Subdivision: ST PAUL	Test Date: 2021-07-21
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH STREET - 2B SWI	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008148362 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDS5M
Subdivision: ST PAUL	Test Date: 2021-06-24
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH STREET - 2B SWI	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008010318 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDS5M
Subdivision: ST PAUL	Test Date: 2021-05-26
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH STREET - 2B SWI	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	[REDACTED]
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]
PT. DET./CC - NORMAL (FRA-236.103)	TESTED OK	[REDACTED]
PT. DET./CC - REVERSE (FRA-236.103)	TESTED OK	[REDACTED]
SHUNT FOULING (FRA-236.104)	TESTED OK	[REDACTED]
TIMING (SI-4.2)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007839314 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDS5M
Subdivision: ST PAUL	Test Date: 2021-04-28
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH STREET - 2B SWI	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007676635 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDS5M
Subdivision: ST PAUL	Test Date: 2021-03-31
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH STREET - 2B SWI	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007527064 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDS5M
Subdivision: ST PAUL	Test Date: 2021-03-02
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH STREET - 2B SWI	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED ADJUSTMENT..	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103)	TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008450903 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BACJTGB
Subdivision: ST PAUL	Test Date: 2021-08-16
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH ST #3 SWITCH	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008281476 ~ Form Type: FRA SWITCH TEST ~ 360 Days

Division: TC	Asset ID: BACJTGB
Subdivision: ST PAUL	Test Date: 2021-07-19
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH ST #3 SWITCH	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
CHECK FOR UNNECESSARY ARCHING BETWEEN BRUSHES AND COMMUTATOR (SI-4.6)..	TESTED OK	
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103)	TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). NEEDED ADJUSTMENT..	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008149235 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BACJTGB
Subdivision: ST PAUL	Test Date: 2021-06-23
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH ST #3 SWITCH	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008010883 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BACJTGB
Subdivision: ST PAUL	Test Date: 2021-05-26
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH ST #3 SWITCH	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007840042 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BACJTGB
Subdivision: ST PAUL	Test Date: 2021-04-28
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH ST #3 SWITCH	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	TESTED OK	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED ADJUSTMENT.	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103)	TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007677215 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BACJTGB
Subdivision: ST PAUL	Test Date: 2021-03-31
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH ST #3 SWITCH	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007527831 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BACJTGB
Subdivision: ST PAUL	Test Date: 2021-03-02
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH ST #3 SWITCH	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008454158 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU4S
Subdivision: ST PAUL	Test Date: 2021-08-17
Line Segment / Milepost: 0003 ~ 430.08 - 430.08	State: MN
Location / Highway Name: 7TH STREET - 4 SWIT	
County: RAMSEY	
Employee's Name: B007637 - JOSHUA WERNER	Gang ID: [REDACTED]
Switch Type: [REDACTED]	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008285034 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDU4S
Subdivision: ST PAUL	Test Date: 2021-07-20
Line Segment / Milepost: 0003 ~ 430.08 - 430.08	State: MN
Location / Highway Name: 7TH STREET - 4 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	NOT APPLICABLE	
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). ADJUSTMENT NEEDED..	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). ADJUSTMENT NEEDED..	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008148365 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU4S
Subdivision: ST PAUL	Test Date: 2021-06-24
Line Segment / Milepost: 0003 ~ 430.08 - 430.08	State: MN
Location / Highway Name: 7TH STREET - 4 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001008010319 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU4S
Subdivision: ST PAUL	Test Date: 2021-05-26
Line Segment / Milepost: 0003 ~ 430.08 - 430.08	State: MN
Location / Highway Name: 7TH STREET - 4 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007839315 ~ Form Type: FRA SWITCH TEST ~ 90 Days

Division: TC	Asset ID: BABDU4S
Subdivision: ST PAUL	Test Date: 2021-04-28
Line Segment / Milepost: 0003 ~ 430.08 - 430.08	State: MN
Location / Highway Name: 7TH STREET - 4 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
INSPECT AND LUBRICATE HELPER RODS (SI-4.7)..	NOT APPLICABLE	
OBSTRUCTION - NORMAL (FRA-236.382). NEEDED ADJUSTMENT.	ADJUSTED/TESTED OK	
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	
PT. DET./CC - NORMAL (FRA-236.103). NEEDED ADJUSTMENT.	ADJUSTED/TESTED OK	
PT. DET./CC - REVERSE (FRA-236.103). NEEDED ADJUSTMENT.	ADJUSTED/TESTED OK	
SHUNT FOULING (FRA-236.104)	TESTED OK	
TIMING (SI-4.2)	TESTED OK	

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007676637 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU4S
Subdivision: ST PAUL	Test Date: 2021-03-31
Line Segment / Milepost: 0003 ~ 430.08 - 430.08	State: MN
Location / Highway Name: 7TH STREET - 4 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Switch Tests & Inspections

Inspection #: 001007527065 ~ Form Type: FRA SWITCH TEST ~ 30 Days

Division: TC	Asset ID: BABDU4S
Subdivision: ST PAUL	Test Date: 2021-03-02
Line Segment / Milepost: 0003 ~ 430.08 - 430.08	State: MN
Location / Highway Name: 7TH STREET - 4 SWIT	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]
Switch Type: POWER-OP	

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
OBSTRUCTION - NORMAL (FRA-236.382)	TESTED OK	[REDACTED]
OBSTRUCTION - REVERSE (FRA-236.382)	TESTED OK	[REDACTED]

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001008457118 ~ Form Type: GROUNDS ~ 90 DAYS *** Out Of Schedule ***

Division: TC	Asset ID: BACJK2J
Subdivision: ST PAUL	Test Date: 2021-07-21
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH_ST_CP_AUX_HOUSE	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	NOT TESTED	
BATTERY CROSS TEST (TP-107A)	NOT TESTED	
CHECK WATER (SI-10.1)	NOT TESTED	
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	NOT TESTED	
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT (TP-18)..	NOT TESTED	
RECORDER (SI-6.4)	NOT TESTED	
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC REPORTING SYSTEM (SI-1.25)..	NOT TESTED	
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS (S.I. 1.10)..	NOT TESTED	
VERIFY RECORDER BATTERY (SI-6.4)	NOT TESTED	
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	NOT TESTED	

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUND	B12	07/21/21	Tested OK			[REDACTED]
GROUND	B28	07/21/21	Tested OK			[REDACTED]

BNSF Railway**BNSF Inspection Report - Grounds Tests & Inspections**

Inspection #: 001008433799 ~ Form Type: GROUNDS ~ 90 DAYS *** Out Of Schedule ***

Division: TC	Asset ID: BACJK2J
Subdivision: ST PAUL	Test Date: 2021-07-14
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH_ST_CP_AUX_HOUSE	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	NOT TESTED	
BATTERY CROSS TEST (TP-107A)	TESTED OK	[REDACTED]
CHECK WATER (SI-10.1)	TESTED OK	[REDACTED]
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	TESTED OK	[REDACTED]
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT (TP-18)..	NOT TESTED	
RECORDER (SI-6.4)	NOT TESTED	
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC REPORTING SYSTEM (SI-1.25)..	NOT TESTED	
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS (S.I. 1.10)..	NOT TESTED	
VERIFY RECORDER BATTERY (SI-6.4)	NOT TESTED	
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	[REDACTED]

Operations With Measurements

<u>GROUND (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUND	B12	07/14/21	Tested OK			[REDACTED]
GROUND	B28	07/14/21	Tested OK			[REDACTED]

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001007864443 ~ Form Type: GROUNDS ~ 90 Days

Division: TC	Asset ID: BACJK2J
Subdivision: ST PAUL	Test Date: 2021-07-06
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH_ST_CP_AUX_HOUSE	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.
 Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.
 Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	TESTED OK	
BATTERY CROSS TEST (TP-107A)	TESTED OK	
CHECK WATER (SI-10.1)	TESTED OK	
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	TESTED OK	
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	
RECORDER (SI-6.4)	TESTED OK	
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25)..	VERIFIED	
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUNDS	B12	07/06/21	Tested OK			
GROUNDS	B28	07/06/21	Tested OK			

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001007411691 ~ Form Type: GROUNDS ~ 90 Days

Division: TC	Asset ID: BACJK2J
Subdivision: ST PAUL	Test Date: 2021-04-07
Line Segment / Milepost: 0025 ~ 0.10 - 0.10	State: MN
Location / Highway Name: 7TH_ST_CP_AUX_HOUSE	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	TESTED OK	
BATTERY CROSS TEST (TP-107A)	TESTED OK	
CHECK WATER (SI-10.1). ADDED WATER WHERE NEEDED..	ADJUSTED/TESTED OK	
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1). CLEANED BATTERY TOPS..	ADJUSTED/TESTED OK	
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	
RECORDER (SI-6.4)	TESTED OK	
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25)..	VERIFIED	
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUNDS	B12	04/07/21	Tested OK			
GROUNDS	B28	04/07/21	Tested OK			

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001007868508 ~ Form Type: GROUNDS ~ 90 Days

Division: TC	Asset ID: BACDMSL
Subdivision: ST PAUL	Test Date: 2021-07-07
Line Segment / Milepost: 0025 ~ 0.27 - 0.27	State: MN
Location / Highway Name: 7TH_STREET_INTERFAC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	TESTED OK	
BATTERY CROSS TEST (TP-107A)	NOT APPLICABLE	
CHECK WATER (SI-10.1). ADDED WATER WHERE NEEDED..	ADJUSTED/TESTED OK	
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	TESTED OK	
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	
RECORDER (SI-6.4)	TESTED OK	
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25)..	VERIFIED	
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUNDS	B12	07/07/21	Tested OK			

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001007414262 ~ Form Type: GROUNDS ~ 90 Days

Division: TC	Asset ID: BACDMSL
Subdivision: ST PAUL	Test Date: 2021-04-08
Line Segment / Milepost: 0025 ~ 0.27 - 0.27	State: MN
Location / Highway Name: 7TH_STREET_INTERFAC	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	TESTED OK	[REDACTED]
BATTERY CROSS TEST (TP-107A)	NOT APPLICABLE	[REDACTED]
CHECK WATER (SI-10.1). ADDED WATER WHERE NEEDED..	ADJUSTED/TESTED OK	[REDACTED]
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1). CLEANED BATTERY TOPS AND REPLACED BATTERY VENTS..	ADJUSTED/TESTED OK	[REDACTED]
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	[REDACTED]
RECORDER (SI-6.4)	TESTED OK	[REDACTED]
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25).. ADDED DESCRIPTION AND MODEL NUMBERS TO ASSETS..	CORRECTED/VERIFIED	[REDACTED]
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	[REDACTED]
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	[REDACTED]
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	[REDACTED]

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUNDS	B12	04/08/21	Tested OK			[REDACTED]

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001007883170 ~ Form Type: GROUNDS ~ 90 Days

Division: TC	Asset ID: BACJK4X
Subdivision: ST PAUL	Test Date: 2021-07-09
Line Segment / Milepost: 0025 ~ 0.27 - 0.27	State: MN
Location / Highway Name: 7THST._MAIN_HOUSE	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.
 Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.
 Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	TESTED OK	[REDACTED]
BATTERY CROSS TEST (TP-107A)	TESTED OK	
CHECK WATER (SI-10.1)	TESTED OK	
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1). WIPED DOWN BATTERIES..	ADJUSTED/TESTED OK	
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	
RECORDER (SI-6.4)	TESTED OK	
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25)..	VERIFIED	
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	

Operations With Measurements

<u>GROUNDS (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUND	B12	07/09/21	Tested OK			[REDACTED]
GROUND	B28	07/09/21	Tested OK			[REDACTED]

BNSF Railway**BNSF Inspection Report - Grounds Tests & Inspections**

Inspection #: 001008255257 ~ Form Type: GROUNDS ~ 90 DAYS *** Out Of Schedule ***

Division: TC	Asset ID: BACJK4X
Subdivision: ST PAUL	Test Date: 2021-06-17
Line Segment / Milepost: 0025 ~ 0.27 - 0.27	State: MN
Location / Highway Name: 7THST._MAIN_HOUSE	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	NOT TESTED	[REDACTED]
BATTERY CROSS TEST (TP-107A)	TESTED OK	[REDACTED]
CHECK WATER (SI-10.1)	TESTED OK	[REDACTED]
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	TESTED OK	[REDACTED]
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT (TP-18)..	NOT TESTED	[REDACTED]
RECORDER (SI-6.4)	NOT TESTED	[REDACTED]
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC REPORTING SYSTEM (SI-1.25)..	NOT TESTED	[REDACTED]
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS (S.I. 1.10)..	NOT TESTED	[REDACTED]
VERIFY RECORDER BATTERY (SI-6.4)	NOT TESTED	[REDACTED]
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	[REDACTED]

Operations With Measurements

GROUND (FRA-236.107)						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUND	B12	06/17/21	Tested OK			[REDACTED]
GROUND	B28	06/17/21	Tested OK			[REDACTED]

BNSF Railway

BNSF Inspection Report - Grounds Tests & Inspections

Inspection #: 001007417970 ~ Form Type: GROUNDS ~ 90 Days

Division: TC	Asset ID: BACJK4X
Subdivision: ST PAUL	Test Date: 2021-04-12
Line Segment / Milepost: 0025 ~ 0.27 - 0.27	State: MN
Location / Highway Name: 7THST._MAIN_HOUSE	
County: RAMSEY	
Employee's Name: [REDACTED]	Gang ID: [REDACTED]

Conditions Master Key

Tested OK = Test completed, no exceptions found, and condition left in compliance.

Adjusted/Tested OK = Adjustments made (identified in associated comments), test completed, and condition left in compliance.

Repaired/Tested OK = Repairs and/or Replacements made (identified in associated comments), test completed, and condition left in compliance.

Operations Without Measurements

Test Description & Rule	Condition Left	Tested By
BATTERY CARD (TEST + TO -)	TESTED OK	[REDACTED]
BATTERY CROSS TEST (TP-107A)	TESTED OK	[REDACTED]
CHECK WATER (SI-10.1). ADDED WATER WHERE NEEDED..	ADJUSTED/TESTED OK	[REDACTED]
GENERAL INSPECTION OF BATTERY BANKS (SI-10.1).	TESTED OK	[REDACTED]
IF APPLICABLE VERIFY ALL CMS SOFTWARE CRITICAL ATTRIBUTES ARE CORRECT.(TP-18)..	VERIFIED	[REDACTED]
RECORDER (SI-6.4)	TESTED OK	[REDACTED]
VERIFY ASSET ID'S FOR ALL CHASSIS MATCH THE VALUES IN THE ELECTRONIC.REPORTING SYSTEM (SI-1.25)..	VERIFIED	[REDACTED]
VERIFY LOCATION HAS APPROPRIATE, CORRECT, AND LEGIBLE CIRCUIT PLANS.(S.I. 1.10)..	CURRENT AND LEGIBLE	[REDACTED]
VERIFY RECORDER BATTERY (SI-6.4)	NOT APPLICABLE	[REDACTED]
VISUAL LIGHTNING ARRESTORS & EQUALIZERS (SI14.1).	TESTED OK	[REDACTED]

Operations With Measurements

<u>GROUND (FRA-236.107)</u>						
Measurement Type	Device Type	Measure Date	Condition/Test Result	Measured Value (mm:ss)	Unit of Measure	Tested By
GROUND	B12	04/12/21	Tested OK			[REDACTED]
GROUND	B28	04/12/21	Tested OK			[REDACTED]