

LOCOMOTIVE: NS 006323 ENGINEER: _____
LOCATION: _____ DIVISION: _____ REGION: _____
START DATE: _____ END DATE: _____ GROUP: _____

DATE						FRA
INSPECTED	STATUS	TIME	INSPECTED BY	LOCATION		DEF
02-01-24	REQUIRED			360A DECATUR	MONSA	NO
01-31-24	COMPLETE	08.00	[REDACTED]	363A DECATUR		NO
01-30-24	COMPLETE	18.30	[REDACTED]	363A DECATUR		NO
01-29-24	REQUIRED			363A DECATUR		NO
01-28-24	REQUIRED			363A DECATUR		NO
01-27-24	COMPLETE	18.30	[REDACTED]	363A DECATUR		NO
01-26-24	COMPLETE	18.30	[REDACTED]	363A DECATUR		NO
01-25-24	COMPLETE	18.30	[REDACTED]	363A DECATUR		NO
01-24-24	REQUIRED			363A DECATUR		NO
01-23-24	COMPLETE	17.00	[REDACTED]	363A DECATUR		NO

PRINTER DESTINATION: _____
F1-HELP F2-LIST F6-PRINT F7-BACK F8-FORWARD F11-CLEAR F12-RETURN
UNITS WITH INSPECTIONS COMPLETE OR NOT-IN-USE = 73% OF INQUIRY RESULTS