



Photo 1 – Main Wreckage (NTSB Photo)



Photo 2 – Engine and Propeller (NTSB Photo)



Photo 3 - Main Wreckage (NTSB Photo)



Photo 4 – Forward Fuselage (NTSB Photo)



Photo 5 – Aft Fuselage (NTSB Photo)



Photo 6 – Left Wing (NTSB Photo)



Photo 7 - Left Wing (NTSB Photo)



Photo 8 - Right Wing (NTSB Photo)



Photo 9 - Right Wing (NTSB Photo)



Photo 10 – Recovered Wreckage (Piper Aircraft Photo)



Photo 11 – Section of Right Aileron (FAA Photo)



Photo 12 – Elevator Trim Tab (FAA Photo)



Photo 13 – Elevator (FAA Photo)



Photo 14 – Hobbs Meter (NTSB Photo)



Photo 15 – Fuselage (NTSB Photo)



Photo 16 – Cockpit Controls (NTSB Photo)



Photo 17 – Engine and Propeller (NTSB Photo)



Photo 18 – Engine (NTSB Photo)