

VEHICLE FACTORS ATTACHMENT

Micro Bird Inspection Report

Rushville, IL

HWY24MH005

(2 pages)



Stop Sign Panel

X

This report remains the property of the Illinois Department of Transportation. A copy must be filed numerically and chronologically at the Official Testing Station for a period of eighteen (18) months and must be available for inspection by employees of the Illinois Department of Transportation. Mark each field below Pass or Fail with an "X" If any item on this form does not apply, leave it blank.

School Bus Inspection Report

1. 🔲 F	. Reject over 30 days 3. Sta			ation 4. Tot		Test Fee 5. License Plate		6. Vehicle Identification Number						7. Certificate of Safety Number					
2. Replacement C/S 1107				\$55.00	\$55.00 109212SB			1FDES6PG9LKA46677					500317405						
Company or School District Name 9. City or Cities Served									10. Odomete	r Reading 11. Time Started			Started	b			. Time E	nded	
Schuyler Industry Cusd # 5 Camp Point										43,595			8:30 X AM			1 9:	:00	× AN	I PN
13. Model Year 14. Chassis 15. Body 16. U						16. Unit Nu	. Unit Number		17. Date of Test		18. Date C/S Applied				19	. Time C	S/S Applied		
2021 FORD				BLUEBIRD			89		12/11/23		12/11/23					06	× AN	I PI	
				ST Signature			22. CST ID#			23. Retest CST Name			24. Retest CST Signature					25. Retest CS	
	wAGNE		21. CS1 Sig	latule		10)# 		23. Netesi (JOT INAITIE		-	4. 1\6.651	COT Sign	i iatui c			ZJ. Nelesi CJ	ו וט#
	WAGNE	K				10													
Brakes	F-::	1		System	-	İ	<u> </u>	evices and	Reflectors		pension						nd Rims	1	
Pass	Fail	Absence of Braking	Pas	s Fail			Pass	Fail	Dook I In	Pas	ss	Fail				ass	Fail		
×		Brake Inspection Report	X		Fuel Cap		×		Back Up Clearance				Suspension			×		Cracked or Welde	d Repairs
×		Drums or Rotors	X		Leaks		×		Dome	X			Spring		-	×		Improper Color	
×		Hoses or Tubes	X		Missing or Loose		×		Eight-Ways	X			cks or Struts		-			Lock Rings	
×		Hydraulic Master	X Fran		Tank Guard		×		Eigni-ways Hazards	×			ngs or Shackl	es	<u> </u>	×		Lugs and Fastene	
		Leaks (Air or Fluid)		ass Fail					Headlights	L	Torsion Bar				Windows and Wind		Wheel Locating (Bolt) Hole		
		Missing/Broken/Loose	X	3 I all	Cracked or Broken	/lember	×		Identification									snieia 1	
		Parking Brake	×		Loose or Missing Fa		×		License Plate	Pas		Fail	dition			ass	Fail	A II O# \A/5	_
		Power Assist Unit		uments and In	_	Steriers	×		Parking	×			uition tact with Vehi	ماء		×		All Other Windows Windshield	S
		Other (See Remarks)	Pas				×		Reflectors	X			ıacı witri venii or Leak	cie		X	ld Wipers	vvinasnieia	
Emergen	cv Fxits	Journal (Occ Nemarks)	X	J I all	ABS Indicator Light		×		Side Marker	X			or Leak oper Load			ass	Fail	1	
Pass	Fail	1	×		Brake Failure Indica	tor Light	×		Stepwell	×			oper Load			x	Гаш	Blades	
X		Alarms	×		Eight-Way Indicator		×		Stop				•			$\overline{}$		4	a uta
×		Emergency Exit Operation			Emergency Door Aja	•	×		Stop Arm	X			oper Use natch Radial o	ar Diaa		x x		Missing/Broken P	aris
×		Ignition Interlock			Gauges	ii oi Lookou	×		Strobe	×			naten Radiai (id Depth	or Bias		×		Operation Washer	
×		Locks or Latches	×		Low Pressure Warni	na	×		Tail		s- Steeri		іа Беріп			x heelcha	in 1 if4	wasner	
×		Reflective Tape	×		Noise Suppression S	-	×		Turn Signal	Pas		Fail				ass	Fail	1	
Engine a	nd Underbo	ody Components	×		Odometer	,	Mirrors	<u> </u>	Turri Oigriai	×			or Ply Repair	r	-	400	ı un	Anchors/Restraint	's
Pass	Fail	1 .	×		Parking Brake Indica	ator Light	Pass	Fail		×			tact with Vehic		-	-		Door	
		Air Compressor	<u> </u>		Other (See Remarks	•	×		Condition	×			or Leak	0.0	-	-		Operation	
×		Alternator	Inter	or		,,	×		Missing	×			oper Load		-			Special Light	
×		Battery or Cables	Pas				x		Mounting	×			oper Size					Joposiai Eigin	
×		Belts or Hoses	×		Barrier, Guard	ļ	Steering 9	System	Ü	×			oper Use						
x		Drive Shaft Guard	×		Certification label, F	ederal	Pass	Fail		×			natch Radial o	or Bias					
Exhaust	System	_	×		Communication Dev	ice	×		Ball Joint	×			apped or Retr						
Pass	Fail]	×		Fire Extinguisher		x		Binding or Loose				rooved						
×		Discharge Location	×		First Aid Kit		x		Drag Link	×			Condition						
×		Exhaust Leaks	×		Floor Covering		x		Fluid Leaks	×			d Depth						
×		Heat Shield	×		Heater or Defroster		x		King Pin			(measured i							
×		Secure Attachment (Han	gers) x		Horn		x		Lash	11		ft Front	9	Right Front	t				
Exterior		-	×		Lettering		x		Modification	10	l et	ft Rear Outer	10	Right Rear	Outer		\dashv		
Pass	Fail		×		Seat Anchoring or S	pacing	x		Pitman Arm	10		ft Rear Inner	10	•			-		
x		Bumper	×		Seat Belt		×		Power Assist Uni		Lei	it iNear IIIIIef	10	Right Rear	minei				
x		Color	×		Seat Covers		×		Steering Box	Rema	arks								
×		Crossing Control Arm	×		Steps		×		Steering Column										
×		Hood Latch or Hinges	×		Sun Visor		×		Steering Wheel										
×		Lettering	×		Warning Devices		x		Tie Rod										
×	I	Rub Rail			Other (See Bemerks	.,	~		Mhool Alianmont	For f	urther	informatio	n regardin	a this inc	enection	call	(217) 78	5_1181	

This inspection may not include all the required equipment to x Wheel Bearing BIC 2000 (Rev. 01/30/17) operate a school bus on Illinois' highways. Printed 07/15/24 Formerly TS 2000

Wheel Alignment

Other (See Remarks)

For further information regarding this inspection, call (217) 785-1181.