



VEHICLE FACTORS ATTACHMENT

Micro Bird Driver/Vehicle Inspection Report

Rushville, IL

HWY24MH005

(2 pages)

DRIVER/VEHICLE INSPECTION REPORT (Driver Copy)



ILLINOIS STATE POLICE
 COMMERCIAL VEHICLE SECTION
 801 S. SEVENTH STREET, SUITE 200-N
 SPRINGFIELD IL 62703
 (217)782-6267

Officer No. 5361	Date 03/11/2024	Begin Time 14:45	Time Zone CENTRAL TIME	Inspection Number [REDACTED]
Commerce Type 2 - INTRASTATE		Inspection Level 4 - SPECIAL INSPECTION		Photos Taken? NO
County SCHUYLER		Location Number 999	Location Description 24	
Mile Post #	Special Checks 05	GPS Latitude 40.11600720579	GPS Longitude -90.5838288867	

DRIVER						
DRIVER Name - Last SPIKER		First ANGELA	Middle M	Suffix		
Address [REDACTED]		City RUSHVILLE	State IL	Zip Code 62681		
Driver License Number [REDACTED]	State of License IL	Date of Birth [REDACTED]	CDL Class BM	Endorsement(s) PS	Restriction(s) AUTO W/O A	
Drug Search NO	Arrests 0	Alcohol Test Administered NO		Results	BAC	

CARRIER						
MOTOR CARRIER Name SCHUYLER-INDUSTRY SCHOOL DIST #5						
Address 740 MAPLE AVE			City RUSHVILLE	State IL	Zip Code 62681	
U.S. DOT Number	ICC Number	IL CC Number	Phone Number (217) 322-4311		Fax Number	

VEHICLES									
Unit 001	Company Unit# 89	Year 2020	Vehicle Make FORD	Typ SB	State IL	License # 109212SB	GVWR 11,000	VIN # 1FDES6PG9LKA46677	
Existing CVSA Decal Status		Existing CVSA Decal		CVSA Decal Issued #			OOS Sticker #		
Cargo Seal Removed			Removed Time		Cargo Seal Replaced			Replaced Time	

LOAD										
Origin City RUSHVILLE		State IL	Destination City RUSHVILLE		State IL	Exempt #	HazMat Code	Reportable Qnty.	Haz Waste	
Shipping Paper # 0		Shipper Name NA				Placards Required	HazMat Code	Reportable Qnty.	Haz Waste	
Cargo PASSENGER - 25		Cargo Breakdown		Bulk Materials?		Cargo Tank Specs	HazMat Code	Reportable Qnty.	Haz Waste	

VIOLATIONS										
Identification	Unit No.	Out Of Service	Post Crash	Verification						Document Number
Description										
Additional Description										
Brake Adjustment	Chamber	Axle 1	Axle 2	Axle 3	Axle 4	Axle 5	Axle 6	Axle 7	Surveillance	
		DISC	DISC							
		Right	N/A	N/A						
		Left	N/A	N/A						

COMMENTS									
25 passenger/1 driver capacity. Bus was severely burned making it extremely difficult to make out many of the features.									

DRIVER'S SIGNATURE: I acknowledge being present while the above vehicle was inspected and have been informed of the above infractions and/or deficiencies. [REDACTED]	OFFICER'S SIGNATURE: I hereby note that I certify I conducted the level of inspection noted above unless otherwise indicated in the Notes section. 	Date Completed 03/12/2024 Time Completed 13:46
--	--	---

DRIVER : This report must be furnished to the motor carrier whose name is listed on this report.