



**VEHICLE FACTORS ATTACHMENT**

**Mack Annual Inspection Report**

**Rushville, IL**

**HWY24MH005**  
(2 pages)

# ANNUAL VEHICLE INSPECTION REPORT

REPORT NUMBER	FLEET UNIT NUMBER
37524944	123
DATE <span style="font-size: 1.2em;">3-23</span>	

**CARRIER OPERATOR**  
Beaird Transport Inc.  
**ADDRESS**  
7132 E Seed corn RD  
**STATE ZIP CODE**  
Astoria OR 61501  
**VEHICLE TYPE**  TRACTOR  TRAILER  TRUCK  BUS  
 (OTHER)

**INSPECTOR'S NAME (PRINT OR TYPE)**  
[REDACTED]  
 THIS INSPECTOR MEETS THE QUALIFICATION REQUIREMENTS IN SECTION 396.19  
 YES  
**VEHICLE IDENTIFICATION (✓ AND COMPLETE)**  LIC. PLATE NO.  VIN  OTHER  
1M1AA13481W137002  
**INSPECTION AGENCY/LOCATION (OPTIONAL)**

VEHICLE COMPONENTS INSPECTED		VEHICLE COMPONENTS INSPECTED		VEHICLE COMPONENTS INSPECTED			
ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE
<b>BRAKE SYSTEM</b>			<b>WINDSHIELD (FORWARD)</b>				
a. Service Brakes	1			No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).			
b. Parking Brake System	1			<b>WINDSHIELD (DOWNWARD)</b>			
c. Brake Drums or Rotors	N/A			No missing, damaged, or inoperable wipers.			
d. Brake Hose	1			<b>SEATS (FORWARD)</b>			
e. Brake Tubing	1			Seats securely fastened to the vehicle structure.			
f. Low Pressure Warning Device	1			<b>TIRE ASSEMBLIES (FORWARD)</b>			
g. Tractor Protection Valve	1			In place, securely attached, proper size, proper placement (see 393.86).			
h. Air Compressor	1			<b>OTHER</b>			
i. Electric Brakes	1			List any other condition(s) which may prevent safe operation of this vehicle.			
j. Hydraulic Brakes	1						
k. Vacuum Systems	1						
l. Antilock Brake System	1						
m. Automatic Brake Adjusters	1						
<b>CONNECTING DEVICES</b>			<b>STEERING SYSTEM</b>				
a. Fifth Wheels	1			a. Steering Wheel Free Play	N/A		
b. Pintle Hooks	1			b. Steering Column	1		
c. Drawbar/Towbar Eye	1			c. Front Axle Beam/All Other Steering Components	N/A		
d. Drawbar/Towbar Tongue	1			d. Steering Gear Box	1		
e. Safety Devices	1			e. Pitman Arm	1		
f. Saddle-Mounts	1			f. Power Steering	1		
<b>FLUID SYSTEMS</b>			<b>SAFETY DEVICES</b>				
a. No leaks forward of/ directly below the driver/ sleeper compartment.	1			a. Axle Positioning Parts	1		
b. Bus: No leaking/ discharging in violation of standard.	1			b. Spring Assembly	1		
c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.	1			c. Torque, Radius or Tracking Components	1		
<b>TIRE SYSTEMS</b>			<b>FRAME</b>				
a. No visible leak.	1			a. Frame Members	1		
b. Fuel Tank Filler Cap	1			b. Tire and Wheel Clearance	1		
c. Fuel tank securely attached.	1			c. Adjustable Axle Assemblies (Sliding Subframes)	1		
<b>LIGHTING DEVICES</b>			<b>TIRES</b>				
All required lights/reflectors operable.	1			a. Steer-Axle Tires	1		
	1			b. All Other Tires	1		
	1			c. Speed-Restricted Tires	1		
	1			<b>WHEELS AND RIMS</b>			
	1			a. Lock or Side Ring	1		
	1			b. Wheels and Rims	1		
	1			c. Fasteners	1		
	1			d. Welds	1		

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 396.