



**VEHICLE FACTORS ATTACHMENT**

**End-Dump Semitrailer Annual Inspection Report**

**Rushville, IL**

**HWY24MH005**

(2 pages)

# ANNUAL VEHICLE INSPECTION REPORT

VEHICLE IDENTIFICATION NUMBER (VIN)	
REPORT NUMBER	FLEET UNIT NUMBER
56883326	1201
DATE	3-23

MOTOR CARRIER OPERATOR  
**Reaid Transport LLC**  
 ADDRESS  
**7132 E Seed corn RD**  
 CITY, STATE, ZIP CODE  
**Astoria OR 97103**  
 VEHICLE TYPE  TRACTOR  TRAILER  TRUCK  BUS  
 (OTHER)

INSPECTOR'S NAME (PRINT OR TYPE)  
 [REDACTED]  
 DOES INSPECTOR MEET THE QUALIFICATION REQUIREMENTS IN SECTION 396.19.  
 YES  
 VEHICLE IDENTIFICATION (✓ AND COMPLETE)  LIC. PLATE NO.  VIN  OTHER  
**ATA3791**  
 INSPECTION AGENCY/LOCATION (OPTIONAL)

OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM	OK	NEEDS REPAIR	REPAIRED DATE	ITEM
			<b>1. BRAKING SYSTEMS</b>				<b>16. WARE HOUSING</b>				<b>18. WINDSHIELD (SEE 393.60)</b>
			a. Service Brakes				a. Vehicle parts, load, dunnage, spare tire, etc., secured.				No cracks, discoloration, obstacles, etc. (see 393.60 for exceptions).
			b. Parking Brake System				b. Front End Structure				<b>19. WINDSHIELD WIPERS</b>
			c. Brake Drums or Rotors				c. Intermodal Container Securement Devices				No missing, damaged, or inoperable wipers.
			d. Brake Hose				<b>17. STEERING MECHANISMS</b>				
			e. Brake Tubing				a. Steering Wheel Free Play				No missing, damaged, or inoperable wipers.
			f. Low Pressure Warning Device				b. Steering Column				<b>20. SEATS</b>
			g. Tractor Protection Valve				c. Front Axle Beam/All Other Steering Components				Seats securely fastened to the vehicle structure.
			h. Air Compressor				d. Steering Gear Box				<b>21. INTERIOR FLOOR MATS</b>
			i. Electric Brakes				e. Pitman Arm				In place, securely attached, proper size, proper placement (see 393.86).
			j. Hydraulic Brakes				f. Power Steering				<b>22. OTHER</b>
			k. Vacuum Systems				g. Ball and Socket Joints				List any other condition(s) which may prevent safe operation of this vehicle.
			l. Antilock Brake System				h. Tie Rods and Drag Links				
			m. Automatic Brake Adjusters				i. Nuts				
			<b>2. COUPLING DEVICES</b>				j. Steering System				
			a. Fifth Wheels				<b>15. SUSPENSION</b>				
			b. Pintle Hooks				a. Axle Positioning Parts				
			c. Drawbar/Towbar Eye				b. Spring Assembly				
			d. Drawbar/Towbar Tongue				c. Torque, Radius or Tracking Components				
			e. Safety Devices				<b>14. FRAME</b>				
			f. Saddle-Mounts				a. Frame Members				
			<b>3. EXHAUST SYSTEMS</b>				b. Tire and Wheel Clearance				
			a. No leaks forward of/ directly below the driver/sleeper compartment.				c. Adjustable Axle Assemblies (Sliding Subframes)				
			b. Bus: No leaking/ discharging in violation of standard.				<b>13. TIRES</b>				
			c. Unlikely to burn, char, or damage the electrical wiring, fuel supply, or any combustible part of vehicle.				a. Steer-Axle Tires				
			<b>4. FUEL SYSTEMS</b>				b. All Other Tires				
			a. No visible leak.				c. Speed-Restricted Tires				
			b. Fuel Tank Filler Cap				<b>12. WHEEL STANDARDS</b>				
			c. Fuel tank securely attached.				a. Lock or Side Ring				
			<b>5. LIGHTING DEVICES</b>				b. Wheels and Rims				
			All required lights/reflectors operable.				c. Fasteners				
							d. Welds				

INSTRUCTIONS: MARK COLUMN ENTITIES TO VERIFY INSPECTION:  OK,  NEEDS REPAIR,  N/A IF ITEMS DO NOT APPLY,  REPAIRED BY

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION ACCORDANCE WITH 49 CFR PART 396.